Subject: Paris won't start because of hardware Posted by Tom Bruhl on Wed, 04 Jul 2007 16:41:26 GMT View Forum Message <> Reply to Message

This is a multi-part message in MIME format.

-----=_NextPart_000_00C9_01C7BE38.A2B78290 Content-Type: text/plain; charset="iso-8859-1" Content-Transfer-Encoding: quoted-printable

I was more stable than ever before with Lucid WC, 2 MECs and one 442. Never crashed once. I added a third MEC and that was okay but it's in/outs weren't functional. I tried it in a different position and ever since then I get this after Paris has gotten to the EDS/DX effects part of the start up.

Unhandled Exception:c00000005 at address: 77c35ea

I tried removing the last MEC and putting it in the last working = position. All I get is this error and can't boot up Paris.

Last working configuration: Submix A MEC Submix B 442 Submix C MEC (no working audio) Submix E MEC

I tried swapping hardware between Submix B and C and that's when the = trouble began. I also reseated the eds cards and their cables.

Is it possible it's an effect? I have added nothing new in months and = it was very stable. Maybe a defective default project?

I'll try another one to boot from that happens to be at 48k.

Tips graciously accepted, Tom

I choose Polesoft Lockspam to fight spam, and you? http://www.polesoft.com/refer.html

-----= NextPart 000 00C9 01C7BE38.A2B78290 Content-Type: text/html; charset="iso-8859-1" Content-Transfer-Encoding: quoted-printable <!DOCTYPE HTML PUBLIC "-//W3C//DTD HTML 4.0 Transitional//EN"> <HTML><HEAD> <META http-equiv=3DContent-Type content=3D"text/html; = charset=3Diso-8859-1"> <META content=3D"MSHTML 6.00.2800.1400" name=3DGENERATOR> <STYLE></STYLE> </HEAD> <BODY bgColor=3D#ffffff> <DIV>I was more stable than ever before with = Lucid=20 WC,</DIV> <DIV>2 MECs and one 442. Never crashed = once. =20 I added</DIV> <DIV>a third MEC and that was okay but it's = in/outs=20 weren't</DIV> <DIV>functional. I tried it in a = different=20 position and ever since</DIV> <DIV>then I get this after Paris has gotten = to the=20 EDS/DX effects</DIV> <DIV>part of the start up.</DIV> <DIV> </DIV> <DIV>Unhandled = Exception:c0000005</DIV> <DIV>at address: 77c35ea</DIV> <DIV> :</DIV> <DIV>I tried removing the last MEC and = putting it in the=20 last working position.</DIV> <DIV>All I get is this error and can't boot = up=20 Paris.</DIV> <DIV> </DIV> <DIV>Last working = configuration:</DIV> <DIV>Submix A MEC</DIV> <DIV>Submix B 442</DIV> <DIV>Submix C MEC (no working = audio)</DIV> <DIV>Submix E MEC</DIV>

<DIV> </DIV> <DIV>I tried swapping hardware between = Submix B and=20 C and that's when the trouble began.</DIV> <DIV>I also reseated the eds cards and their = cables.</DIV> <DIV> </DIV> <DIV>Is it possible it's an effect? I = have added=20 nothing new in months and it was very stable.</DIV> <DIV>Maybe a defective default=20 project?</DIV> <DIV> :</DIV> <DIV>I'll try another one to boot from that = happens to=20 be at 48k.</DIV> <DIV> </DIV> <DIV>Tips graciously accepted,</DIV> <DIV>Tom</DIV> <DIV> </DIV> <DIV>

I choose Polesoft Lockspam to fight spam, = and=20 vou?
<A=20 href=3D"http://www.polesoft.com/refer.html">http://www.polesoft.com/refer= ..html </DIV></BODY ></HTML>

-----=_NextPart_000_00C9_01C7BE38.A2B78290--

