Subject: Calibration procedure for 8i cards?
Posted by pbraun on Mon, 23 Nov 2009 22:55:35 GMT

What's the easiest, most accurate way to calibrate the inputs on an 8i card? I've got three of them that I got on the 'bay, and I've never calibrated them.

What do you use for a signal source? And is it safe to assume that you set "actual zero" a tad below "indicated zero" to give yourself a bit of headroom?