Subject: Latency times for UAD-1
Posted by rsi77 on Tue, 19 Jan 2010 15:17:21 GMT
View Forum Message <> Reply to Message

I am trying to understand the chart in Wiki which gives latency for UAD-1 plugs. It seems to say that in order to correct for a single UAD-1 non-Pultec plug-in it is required to "nudge" 4 x 100ms and then add 1536 samples using sample slide. But this gives nowhere near the right correction. It seems to be close at 4700 samples, but this doesn't match the Wiki numbers at all.

Am I misunderstanding the chart or what's up?

Thanks,

ron