Subject: Another UAD 1 question
Posted by cujo on Fri, 15 Sep 2006 12:37:19 GMT
View Forum Message <> Reply to Message

Ever since I installed the 1073, my uad card becomes "disabled" after 45
minutes or so of mixing. I have to restart my computer for it to come back
on.
Morgan suggested it was heat related. I took the cover off my comp and it
did not happen last night (as morgan suggested). it's stange that I have
had this thing for so long and right after using the 1073 it starts..hmm.
Anyone else have this issue? I may be just pushing the thing to hard.
Also anyone notice that increasing their disc I/O in the config gets em more
UAD plugs?