Subject: PSCL for today
Posted by Mike Audet on Wed, 13 Aug 2008 03:01:53 GMT

Hi guys,

I put some locks on the card UART, so the IF2s should now work properly,
if they ever didn't.

I also changed a static buffer to a regular buffer because it was shared
among many purposes, and it looked like they could trip on each other.