

---

Subject: MEC and eds cards under water  
Posted by [Steve L](#) on Fri, 19 Oct 2007 13:48:19 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

My studio in Stamford CT was under five feet of water. Does my paris hardware stand a chance ? I have a mec with two 8in, one 8 out, a c16, and two eds cards.

Thanks,

Steve L.

---

---

Subject: Re: MEC and eds cards under water  
Posted by [TCB](#) on Fri, 19 Oct 2007 14:07:46 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

It probably does. Computer gear (save hard drives) can usually go through a washer and come out OK. The most important thing to do is let everything dry COMPLETELY before turning it on. Take all of the external metal you can off of the MEC so the boards can dry out. Pull the MEC cards (carefully) so the contacts can dry out. Then lay everything out and point a fan at it and let it blow for a day or two, turning everything over to be sure it's dry. (I've used a blow dryer before but that can heat things up too much if you're not careful). After that I'd try turning on the MEC only and seeing if anything works. Then add one card at a time. You might get lucky, or you might not. But if you start firing the stuff up when it's wet you're cooked.

TCB

"Steve L" <[steve@shangk.com](mailto:steve@shangk.com)> wrote:

>

>My studio in Stamford CT was under five feet of water. Does my paris hardware stand a chance ? I have a mec with two 8in, one 8 out, a c16, and two eds cards.

>

>Thanks,

>

>Steve L.

---

---

Subject: Re: MEC and eds cards under water  
Posted by [rick](#) on Fri, 19 Oct 2007 16:51:19 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

+1

On 20 Oct 2007 00:07:46 +1000, "TCB" <nobody@ishere.com> wrote:

>  
>It probably does. Computer gear (save hard drives) can usually go through  
>a washer and come out OK. The most important thing to do is let everything  
>dry COMPLETELY before turning it on. Take all of the external metal you can  
>off of the MEC so the boards can dry out. Pull the MEC cards (carefully)  
>so the contacts can dry out. Then lay everything out and point a fan at it  
>and let it blow for a day or two, turning everything over to be sure it's  
>dry. (I've used a blow dryer before but that can heat things up too much  
>if you're not careful). After that I'd try turning on the MEC only and seeing  
>if anything works. Then add one card at a time. You might get lucky, or you  
>might not. But if you start firing the stuff up when it's wet you're cooked.

>  
>

>TCB

>  
>"Steve L" <steve@shangk.com> wrote:

>>  
>>My studio in Stamford CT was under five feet of water. Does my paris hardware  
>>stand a chance ? I have a mec with two 8in, one 8 out, a c16, and two eds  
>>cards.

>>  
>>Thanks,  
>>  
>>Steve L.