Subject: My 2nd mec is showing signal - No recording ?? Posted by TriSound Recording on Thu, 11 Mar 2010 13:14:40 GMT View Forum Message <> Reply to Message

Ok, I try-ed to get some recording done tonight on the Mec(B) I send a signal to input #1 and #2. I set up the patch bay the same way i did Mec(A). Mec(A) works fine but not Mec(B).

So what's up with this now. Im sure it's something I'm not doing right. Looks like to me you have to map out each Mec by it's self and then they (the Mec's)just buss together at the end to the Master buss. Is this right?

cheers,

Jeff

Not like a 2" recorder, you don't always know if the computer is broke or it's just toying with you....