Subject: Re: ASIO DRIVER current status ? Posted by mikeaudet on Tue, 20 Feb 2018 15:54:39 GMT View Forum Message <> Reply to Message

So...I've been working on a few things...one of which is laying the groundwork for a new scherzo to support a 64 bit ASIO, but I took a bit of a detour and decided to see if I could clean up a couple of things in the 32 bit ASIO...and....

I got 32 sample buffer sizes working!!!

## File Attachments

| Audio/MIDI Setup |  |   |           |          | ×    |
|------------------|--|---|-----------|----------|------|
|                  |  |   |           | New York | 3355 |
|                  |  |   |           |          |      |
|                  | Latency Measu                                  | rement Tool                               |           |          |      |
|                  | Turn down the volur<br>audio equipment to      |   |           |          |      |
| Sele             | ct two channels below and                      | connect them using a cable.               |           |          |      |
| Output channel   | system:playback_4                              |   |           |          |      |
| Input channel    | system:capture_4                               |   |           |          |      |
| Once             | the channels are connected                     | d, click the "Measure" button.            |           |          |      |
| When             | satisfied with the results, o                  | lick the "Use results" button.            |           |          |      |
|                  | ed roundtrip latency:<br>nic latency: -96 samp | 183 samples (4.150 ms)<br>les (-2.177 ms) |           |          |      |
| Measure          | Use results                                    | Back to settings (igno                    | re result | s)       |      |
|                  |  |   |           |          |      |
|                  |  |   |           |          |      |
|                  |  |   |           |          |      |