Subject: Re: ASIO DRIVER current status ? Posted by mikeaudet on Tue, 20 Feb 2018 15:54:39 GMT View Forum Message <> Reply to Message

So...I've been working on a few things...one of which is laying the groundwork for a new scherzo to support a 64 bit ASIO, but I took a bit of a detour and decided to see if I could clean up a couple of things in the 32 bit ASIO...and....

I got 32 sample buffer sizes working!!!

File Attachments

| Audio/MIDI Setup | | | 3 <u>92</u> | | × |
|------------------|--|---|-------------|----|---|
| | | | | | |
| | Latency Measu | rement Tool | | | |
| | Turn down the volur audio equipment to | | | | |
| Sel | ect two channels below and | connect them using a cable. | | | |
| Output channel | system:playback_4 | | | | |
| Input channel | system:capture_4 | | | | |
| Once | the channels are connected | l, click the "Measure" button. | | | |
| When | n satisfied with the results, c | lick the "Use results" button. | | | |
| | ted roundtrip latency: nic latency: -96 sampl | 183 samples (4.150 m les (-2.177 ms) | is) | | |
| Measure | Use results | Back to settings (ig | nore result | s) | |
| | | | | | |
| | | | | | |
| | | | | | |