
Subject: Second EDS not working :(
Posted by [db](#) on Sun, 16 Apr 2006 08:17:39 GMT
[View Forum Message](#) <> [Reply to Message](#)

a mixdown session tomorrow with a client and I really need the second card for the session.

So, my year long struggle to add a second working EDS card continues. First card was dud. Second one has finally arrived. Both cards work by themselves,

Booting paris (boots fine), and checking version info only shows one EDS.

PCI positions I can think of whilst the cables still reach (i.e. no more than one empty slot between them). Still no joy.

In the BIOS, the only options are to enable or disable Plug & Play O/S (determines whether the BIOS or the OS configures PCI) and for IRQs to be Available (to be used by PCI/PnP devices) or Reservecs (specified IRQ is reserved for use and sound card disabled).

In most PCI positions, only one ENSONIQ Scherzo was showing in device manager,

With the cards in slots 4 and 5 (irqs 16 and 18), Schezo shows two instances. However, when I try to boot paris I get Error 1/1 (whether the MEC is connected

My only other thought is that this could be cause by faulty 16 / 10 pin ribbon

2 x 16 pins cross in an X, but the red cable is to the left (rear of computer) when plugged in both plugs. 1 x 10 pin straight across, red cable to left in both sockets. Doubt that this is the problem though since why would this

I think it was Derek that mentioned that in some systems the connection needs

Many, many thanks in advance for any help.

Daniel
