
Subject: Adat BUG confirmed !!! can someone test too ?

Posted by [Dimitrios](#) on Thu, 26 Apr 2007 10:40:41 GMT

[View Forum Message](#) <> [Reply to Message](#)

So I have confirmed that at least under XP ,don't know if it is OS related bug, There is a bug where the track 5 and 6 of ADAT Paris OUT do NOT work. Out of four adat cards I have the three confirm this !

The only case the fourth works is inside the mec where ONLY TWO adat cards are installed without any other in out cards.

I don't know if I would take out my input cards if that would be solved but really cannot take that trouble right now !

I thought in the beginning that one of my adat cards were faulty but three with same 5,6 SEND ONLY adat ports not working ?? nehh

Well the ADAT INS work !! , I mean the 5,5 adat inputs work.

So the problem is you cannot close the adat loop for insert purpose on tracks 5 and 6.

I even changed the eds card as EDNA suggested but same results so this has eliminated the EDS card problem.

Well I don't know if I have 3 out of 4 eds cards malfunctioning ...

I would like someone from you if he could test somehow the above scenario.

I would appreciate.

Regards,

Dimitrios

Subject: Re: Adat BUG confirmed !!! can someone test too ?

Posted by [Rod Lincoln](#) on Thu, 26 Apr 2007 13:48:03 GMT

[View Forum Message](#) <> [Reply to Message](#)

All Adat outs and ins working here. Just tested. 2 mecs, 1 adat in each mec.

Running XP

Also 2 a8it modules and 1 a8ot mod in mec 1, 3 A8it mods and 1 A80t mod in Mec 2.

Rod

"Dimitrios" <musurgio@otenet.gr> wrote:

>

>So I have confirmed that at least under XP ,don't know if it is OS related

>bug, There is a bug where the track 5 and 6 of ADAT Paris OUT do NOT work.

>Out of four adat cards I have the three confirm this !

>The only case the fourth works is inside the mec where ONLY TWO adat cards are installed without any other in out cards.

>I don't know if I would take out my input cards if that would be solved

>but really cannot take that trouble right now !

>I thought in the beginning that one of my adat cards were faulty but three

>with same 5,6 SEND ONLY adat ports not working ?? nehh

>Well the ADAT INS work !! , I mean the 5,5 adat inputs work.

>So the problem is you cannot close the adat loop for insert purpose on tracks

>5 and 6.
>I even changed the eds card as EDNA suggested but same results so this has
>eliminated the EDS card problem.
>Well I don't know if I have 3 out of 4 eds cards malfunctioning ...
>I would like someone from you if he could thest somehow the above scenario.
>I would appreciatte.
>Regards,
>Dimitrios

Subject: Re: Adat BUG confirmed !!! can someone test too ?

Posted by [Deej \[4\]](#) on Thu, 26 Apr 2007 15:02:31 GMT

[View Forum Message](#) <> [Reply to Message](#)

Win ME is your friend if you want to use multiple ADAT cards in multiple MECs. Win XP, not so much. I did get two ADAT cards working properly in 1 of 3 MECs running Win XP, but no more.

Deej

"Dimitrios" <musurgio@otenet.gr> wrote in message news:463081a9\$1@linux...

>

> So I have confirmed that at least under XP ,don't know if it is OS related
> bug, There is a bug where the track 5 and 6 of ADAT Paris OUT do NOT work.
> Out of four adat cards I have the three confirm this !
> The only case the fourth works is inside the mec where ONLY TWO adat cards
> are installed without any other in out cards.
> I don't know if I would take out my input cards if that woukld be solved
> but really cannot take that trouble right now !
> I thought in the beginning that one of my adat cards were faulty but three
> with same 5,6 SEND ONLY adat ports not working ?? nehh
> Well the ADAT INS work !! , I mean the 5,5 adat inputs work.
> So the problem is you cannot close the adat loop for insert purpose on
> tracks
> 5 and 6.
> I even changed the eds card as EDNA suggested but same results so this has
> eliminated the EDS card problem.
> Well I don't know if I have 3 out of 4 eds cards malfunctioning ...
> I would like someone from you if he could thest somehow the above
> scenario.
> I would appreciatte.
> Regards,
> Dimitrios

Subject: Re: Adat BUG confirmed !!! can someone test too ?

Have you tried:

- 1 - Routing something OTHER than Insert Sends to these ADAT outputs (Main Outs, Auxes etc)?
- 2 - Switching the EDS card / MEC assignment in the Master Mixer (ie, if the troublesome ADAT outs are on MEC1 connected to Submix 1 playing off CardA, does the same problem exist when you assign MEC1 / CardA to Submix 2 etc)
- 3 - Changing your EDS cards (basically, label them, pull them out, and put them in the same PCI slots, in a different order - put a different EDS card in the slot for the ADAT MEC).

I had a similar problem, but it was ADAT OUT 3 and 4 on MEC1 connected to EDS Card A in a three card system on WinME. On this same MEC, there were a total of (2) ADAT, (2) 8-input, (2) 8-output.

I had the same symptoms though - swapped ADAT cards and OUT 3 and 4 still didn't wor, but the "bad" card suddenly worked in a different hole. The "good" card displayed the same problem as the "bad" one.

I yanked and moved the EDS cards in my system and connected the MEC to a different Card A and the problem went away with both the original ADAT and the swapped ADAT.

I concluded it to be an EDS Insert problem on a specific EDS card - not an OS thing. Something about the way the Insert Sends were handled on that EDS card. Could be a loose connection on a board, a bad or dying chip etc. I never bothered to check if you could route Auxes or Mains to the same questionable outputs (and if I couldn't, it would be a bigger problem).

Sandy

"Dimitrios" <musurgio@otenet.gr> wrote in message news:463081a9\$1@linux...
>

- > So I have confirmed that at least under XP ,don't know if it is OS related
- > bug, There is a bug where the track 5 and 6 of ADAT Paris OUT do NOT work.
- > Out of four adat cards I have the three confirm this !
- > The only case the fourth works is inside the mec where ONLY TWO adat cards
- > are installed without any other in out cards.
- > I don't know if I would take out my input cards if that woukld be solved
- > but really cannot take that trouble right now !
- > I thought in the beginning that one of my adat cards were faulty but three
- > with same 5,6 SEND ONLY adat ports not working ?? nehh
- > Well the ADAT INS work !! , I mean the 5,5 adat inputs work.
- > So the problem is you cannot close the adat loop for insert purpose on
- > tracks
- > 5 and 6.
- > I even changed the eds card as EDNA suggested but same results so this has

> eliminated the EDS card problem.
> Well I don't know if I have 3 out of 4 eds cards malfunctioning ...
> I would like someone from you if he could thest somehow the above
> scenario.
> I would appreciatte.
> Regards,
> Dimitrios
