

---

Subject: Mixer not working with EDS1000 after reformat and reinstall of windows 98  
Posted by [Cliff Friedel](#) on Fri, 25 May 2007 21:50:13 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hi all. Have a customer who has a PARIS system (black parts with EDS1000 PCI card) and recently reformatted his system and reinstalled Windows 98 second edition. Installed PARIS 2.1 and the 1.05 drivers for the EDS1000 and have run into a problem. Hooked up the MEC to the EDS1000 card (through the 50-pin HD interface) and that seems to work ok, but when I hook up the mixer board (to the RJ45 interface) it doesn't light up. Wiggled the cable and the lights would flicker. Figured this may be a problem with the port. What bothers me though is that this all worked fine a week ago. Looked at the pins and they look a little flimsy so now I am really wondering. Anyone else have this problem or anyone who could suggest another possible solution? If you can offer any help, it would be greatly appreciated. If not, is there any place that will fix them or sell an EDS1000 board? Checked ebay but with no real results. Again, any help is appreciated. Thanks.

Cliff Friedel

---

---

Subject: Re: Mixer not working with EDS1000 after reformat and reinstall of windows 98

Posted by [Ted Gerber](#) on Fri, 25 May 2007 22:58:26 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

"Cliff Friedel" <cfriedel@alltel.net> wrote:

>

>Hi all. Have a customer who has a PARIS system (black parts with EDS1000  
>PCI card) and recently reformatted his system and reinstalled Windows 98  
>second edition. Installed PARIS 2.1 and the 1.05 drivers for the EDS1000  
>and have run into a problem. Hooked up the MEC to the EDS1000 card (through  
>the 50-pin HD interface) and that seems to work ok, but when I hook up the  
>mixer board (to the RJ45 interface) it doesn't light up. Wiggled the cable  
>and the lights would flicker. Figured this may be a problem with the port.  
> What bothers me though is that this all worked fine a week ago. Looked  
>at the pins and they look a little flimsy so now I am really wondering.

>Anyone else have this problem or anyone who could suggest another possible  
>solution? If you can offer any help, it would be greatly appreciated.

If

>not, is there any place that will fix them or sell an EDS1000 board? Checked  
>ebay but with no real results. Again, any help is appreciated. Thanks.

>

>Cliff Friedel

Morgan at Eastcoast Music [www.eastcoastmusic.com](http://www.eastcoastmusic.com) and [www.thesoniq.com](http://www.thesoniq.com)

---