

---

Subject: Re: My Error 7/7 dilemma continued...  
Posted by [Morgan](#) on Sat, 05 Jan 2008 23:28:48 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Hi Kim,  
I tried to respond to another post on this a while back  
and got a posting error, I hope this one makes it.

We had some rigs that would get into a 7/7 error mode,  
this always means the hardware cannot be seen.

We would use a pencil eraser on the contacts of the EDS  
card and clean out the pci slot the best we could with a  
De-Oxit type of spray . That usually would do the trick.  
In a multi card system - do one card at a time :)  
I hope this helps :)

Morgan

"Kim" <hiddenounds@hotmail.com> wrote in message news:47800ece\$1@linux...

>

>

> Mmm... neither the BIOS Defaults reset or the Standard PC thing seem to  
> have fixed it. Same deal.

>

> Gosh damnit. ;o)

>

> I'm just going to be really annoyed if I buy a new MB and that's not it.  
> I've tried a number of things here, many with some confidence of a result,  
> but nuttin' worked. I've got \$4500 I plan to spend on car restorations in  
> the next 6 weeks. I know a MB is only \$70 but I'm runnin' on empty. ;o)

>

> But what I wouldn't do to get Paris up and running. I'm almost considering  
> loading Reaper to get some stuff done... :oS

>

> Cheers,

> Kim.

>

> "Kim" <hiddenounds@hotmail.com> wrote:

>>

>>

>>So..... ;o)

>>

>>It occurred to me that I should put more effort into resolving this on the  
>>existing MB. Just after some comments if you have any. Currently Paris  
>>attempts

>>to load, the MEC or 442 starts its "boot" and stops right at that point

> where

>>the internal sync light and the 48k light come on together. They stay that

>>way for far too long (compared to "normal") and then the 7/7 error  
>>appears.  
>>IIRC that phase is when the MEC is actually attempting to make the audio  
>>link with the EDS card. Presumably this is when EDS comms are going to  
>>suddenly  
>>increase from some minor discussions about the boot process to an actual  
>>stream of audio data traffic, so I can see that an IRQ issue might cause  
>>issues at that point.  
>>  
>>I'm currently exploring the idea that it's just an IRQ conflict, which  
>>seems  
>>possible.  
>>  
>>(\*) I've noted that my "working" Paris install image is in ACPI mode. I'm  
>>just changing to Standard PC to see if we can't sort some stuff out  
>>because...  
>>  
>>(\*) I noted that the Scherzo driver was being allocated to IRQ 19 by  
>>Windows.  
>>It was on its own, but that's not the real IRQ (which was 5, but I've  
>>moved  
>>it to 7), but a virtual Windows one. Why Windows made this crazy  
>>allocation  
>>I'm not sure. Hopefully Standard PC mode will put it back on 7.  
>>  
>>(\*) I'm thinking of doing a BIOS reset, or indeed reload, in case the  
>>crazy  
>>MB has done something silly here.  
>>  
>>In any case, the install image used to work, so this ACPI thingy doesn't  
>>seem the likely cause. A BIOS reset may do it. Or it still could be a MB  
>>hardware fault.  
>>  
>>Annoying... ;o)  
>>  
>>Cheers,  
>>Kim.  
>

---

Subject: My Error 7/7 dilemma continued...  
Posted by [Kim](#) on Sat, 05 Jan 2008 23:56:44 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

So..... ;o)

It occurred to me that I should put more effort into resolving this on the existing MB. Just after some comments if you have any. Currently Paris attempts

to load, the MEC or 442 starts its "boot" and stops right at that point where the internal sync light and the 48k light come on together. They stay that way for far too long (compared to "normal") and then the 7/7 error appears. IIRC that phase is when the MEC is actually attempting to make the audio link with the EDS card. Presumably this is when EDS comms are going to suddenly increase from some minor discussions about the boot process to an actual stream of audio data traffic, so I can see that an IRQ issue might cause issues at that point.

I'm currently exploring the idea that it's just an IRQ conflict, which seems possible.

(\*) I've noted that my "working" Paris install image is in ACPI mode. I'm just changing to Standard PC to see if we can't sort some stuff out because...

(\*) I noted that the Scherzo driver was being allocated to IRQ 19 by Windows. It was on its own, but that's not the real IRQ (which was 5, but I've moved it to 7), but a virtual Windows one. Why Windows made this crazy allocation I'm not sure. Hopefully Standard PC mode will put it back on 7.

(\*) I'm thinking of doing a BIOS reset, or indeed reload, in case the crazy MB has done something silly here.

In any case, the install image used to work, so this ACPI thingy doesn't seem the likely cause. A BIOS reset may do it. Or it still could be a MB hardware fault.

Annoying... ;o)

Cheers,  
Kim.

---

Subject: Re: My Error 7/7 dilemma continued...  
Posted by [Kim](#) on Sun, 06 Jan 2008 00:12:14 GMT  
[View Forum Message](#) <> [Reply to Message](#)

Mmm... neither the BIOS Defaults reset or the Standard PC thing seem to have fixed it. Same deal.

Gosh damnit. ;o)

I'm just going to be really annoyed if I buy a new MB and that's not it. I've tried a number of things here, many with some confidence of a result, but nuttin' worked. I've got \$4500 I plan to spend on car restorations in the next 6 weeks. I know a MB is only \$70 but I'm runnin' on empty. ;o)

But what I wouldn't do to get Paris up and running. I'm almost considering

loading Reaper to get some stuff done... :oS

Cheers,  
Kim.

"Kim" <hiddensounds@hotmail.com> wrote:

>  
>  
>So..... ;o)  
>  
>It occurred to me that I should put more effort into resolving this on the  
>existing MB. Just after some comments if you have any. Currently Paris attempts  
>to load, the MEC or 442 starts its "boot" and stops right at that point  
where  
>the internal sync light and the 48k light come on together. They stay that  
>way for far too long (compared to "normal") and then the 7/7 error appears.  
>IIRC that phase is when the MEC is actually attempting to make the audio  
>link with the EDS card. Presumably this is when EDS comms are going to suddenly  
>increase from some minor discussions about the boot process to an actual  
>stream of audio data traffic, so I can see that an IRQ issue might cause  
>issues at that point.  
>  
>I'm currently exploring the idea that it's just an IRQ conflict, which seems  
>possible.  
>  
>(\*) I've noted that my "working" Paris install image is in ACPI mode. I'm  
>just changing to Standard PC to see if we can't sort some stuff out because...  
>  
>(\*) I noted that the Scherzo driver was being allocated to IRQ 19 by Windows.  
>It was on its own, but that's not the real IRQ (which was 5, but I've moved  
>it to 7), but a virtual Windows one. Why Windows made this crazy allocation  
>I'm not sure. Hopefully Standard PC mode will put it back on 7.  
>  
>(\*) I'm thinking of doing a BIOS reset, or indeed reload, in case the crazy  
>MB has done something silly here.  
>  
>In any case, the install image used to work, so this ACPI thingy doesn't  
>seem the likely cause. A BIOS reset may do it. Or it still could be a MB  
>hardware fault.  
>  
>Annoying... ;o)  
>  
>Cheers,  
>Kim.

---

Subject: Re: My Error 7/7 dilemma continued...

Posted by [Morgan](#) on Sun, 06 Jan 2008 01:02:27 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hi Kim,

Here is the error message I was getting:

Outlook Express could not post your message. Subject 'Re: OK, so my Paris machine is still cactus... ;o)', Account: 'news.parisnewsgroup.com', Server: 'news.parisnewsgroup.com', Protocol: NNTP, Server Response: '441 Message is too old', Port: 119, Secure(SSL): No, Server Error: 441, Error Number: 0x800CCCA9

"Morgan" <morganp@ntplx.net> wrote in message news:47801367@linux...

> Hi Kim,

> I tried to respond to another post on this a while back

> and got a posting error, I hope this one makes it.

>

> We had some rigs that would get into a 7/7 error mode,

> this always means the hardware cannot be seen.

>

> We would use a pencil eraser on the contacts of the EDS

> card and clean out the pci slot the best we could with a

> De-Oxit type of spray . That usually would do the trick.

> In a multi card system - do one card at a time :)

> I hope this helps :)

>

> Morgan

> "Kim" <hiddensounds@hotmail.com> wrote in message news:47800ece\$1@linux...

>>

>>

>> Mmm... neither the BIOS Defaults reset or the Standard PC thing seem to

>> have fixed it. Same deal.

>>

>> Gosh damnit. ;o)

>>

>> I'm just going to be really annoyed if I buy a new MB and that's not it.

>> I've tried a number of things here, many with some confidence of a

>> result,

>> but nuttin' worked. I've got \$4500 I plan to spend on car restorations in

>> the next 6 weeks. I know a MB is only \$70 but I'm runnin' on empty. ;o)

>>

>> But what I wouldn't do to get Paris up and running. I'm almost

>> considering

>> loading Reaper to get some stuff done... :oS

>>

>> Cheers,

>> Kim.

>>  
>> "Kim" <hiddensounds@hotmail.com> wrote:  
>>>  
>>>  
>>>So..... ;o)  
>>>  
>>>It occurred to me that I should put more effort into resolving this on  
>>>the  
>>>existing MB. Just after some comments if you have any. Currently Paris  
>>>attempts  
>>>to load, the MEC or 442 starts its "boot" and stops right at that point  
>> where  
>>>the internal sync light and the 48k light come on together. They stay  
>>>that  
>>>way for far too long (compared to "normal") and then the 7/7 error  
>>>appears.  
>>>IIRC that phase is when the MEC is actually attempting to make the audio  
>>>link with the EDS card. Presumably this is when EDS comms are going to  
>>>suddenly  
>>>increase from some minor discussions about the boot process to an actual  
>>>stream of audio data traffic, so I can see that an IRQ issue might cause  
>>>issues at that point.  
>>>  
>>>I'm currently exploring the idea that it's just an IRQ conflict, which  
>>>seems  
>>>possible.  
>>>  
>>>(\*) I've noted that my "working" Paris install image is in ACPI mode. I'm  
>>>just changing to Standard PC to see if we can't sort some stuff out  
>>>because...  
>>>  
>>>(\*) I noted that the Scherzo driver was being allocated to IRQ 19 by  
>>>Windows.  
>>>It was on its own, but that's not the real IRQ (which was 5, but I've  
>>>moved  
>>>it to 7), but a virtual Windows one. Why Windows made this crazy  
>>>allocation  
>>>I'm not sure. Hopefully Standard PC mode will put it back on 7.  
>>>  
>>>(\*) I'm thinking of doing a BIOS reset, or indeed reload, in case the  
>>>crazy  
>>>MB has done something silly here.  
>>>  
>>>In any case, the install image used to work, so this ACPI thingy doesn't  
>>>seem the likely cause. A BIOS reset may do it. Or it still could be a MB  
>>>hardware fault.  
>>>  
>>>Annoying... ;o)

>>>  
>>>Cheers,  
>>>Kim.  
>>  
>  
>

---

---

Subject: Re: My Error 7/7 dilemma continued... Post error  
Posted by [Kim](#) on Sun, 06 Jan 2008 02:25:58 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Morgan,

That seems to be a local issue with your machine.

<http://support.microsoft.com/kb/297166/en-us>

Let me know if you need help with it.

Cheers,  
Kim.

"Morgan" <morganp@ntplx.net> wrote:

>Hi Kim,

>

>Here is the error message I was getting:

>

>Outlook Express could not post your message. Subject 'Re: OK, so my Paris

>machine is still cactus... ;o)', Account: 'news.parisnewsgroup.com',

>Server: 'news.parisnewsgroup.com', Protocol: NNTP, Server Response: '441

>Message is too old', Port: 119, Secure(SSL): No, Server Error: 441, Error

>Number: 0x800CCCA9

>

>

>"Morgan" <morganp@ntplx.net> wrote in message news:47801367@linux...

>> Hi Kim,

>> I tried to respond to another post on this a while back

>> and got a posting error, I hope this one makes it.

>>

>> We had some rigs that would get into a 7/7 error mode,

>> this always means the hardware cannot be seen.

>>

>> We would use a pencil eraser on the contacts of the EDS

>> card and clean out the pci slot the best we could with a

>> De-Oxit type of spray . That usually would do the trick.  
>> In a multi card system - do one card at a time :)  
>> I hope this helps :)  
>>  
>> Morgan  
>> "Kim" <hiddensounds@hotmail.com> wrote in message news:47800ece\$1@linux...  
>>>  
>>>  
>>> Mmm... neither the BIOS Defaults reset or the Standard PC thing seem  
to  
>>> have fixed it. Same deal.  
>>>  
>>> Gosh damnit. ;o)  
>>>  
>>> I'm just going to be really annoyed if I buy a new MB and that's not  
it.  
>>> I've tried a number of things here, many with some confidence of a  
>>> result,  
>>> but nuttin' worked. I've got \$4500 I plan to spend on car restorations  
in  
>>> the next 6 weeks. I know a MB is only \$70 but I'm runnin' on empty. ;o)  
>>>  
>>> But what I wouldn't do to get Paris up and running. I'm almost  
>>> considering  
>>> loading Reaper to get some stuff done... :oS  
>>>  
>>> Cheers,  
>>> Kim.  
>>>  
>>> "Kim" <hiddensounds@hotmail.com> wrote:  
>>>>  
>>>>  
>>>>So..... ;o)  
>>>>  
>>>>It occurred to me that I should put more effort into resolving this on  
  
>>>>the  
>>>>existing MB. Just after some comments if you have any. Currently Paris  
  
>>>>attempts  
>>>>to load, the MEC or 442 starts its "boot" and stops right at that point  
>>> where  
>>>>the internal sync light and the 48k light come on together. They stay  
  
>>>>that  
>>>>way for far too long (compared to "normal") and then the 7/7 error  
>>>>appears.  
>>>>IIRC that phase is when the MEC is actually attempting to make the audio



>>>>link with the EDS card. Presumably this is when EDS comms are going to

>>>>suddenly

>>>>increase from some minor discussions about the boot process to an actual

>>>>stream of audio data traffic, so I can see that an IRQ issue might cause

>>>>issues at that point.

>>>>

>>>>I'm currently exploring the idea that it's just an IRQ conflict, which

>>>>seems

>>>>possible.

>>>>

>>>>(\*) I've noted that my "working" Paris install image is in ACPI mode.

I'm

>>>>just changing to Standard PC to see if we can't sort some stuff out

>>>>because...

>>>>

>>>>(\*) I noted that the Scherzo driver was being allocated to IRQ 19 by

>>>>Windows.

>>>>It was on its own, but that's not the real IRQ (which was 5, but I've

>>>>moved

>>>>it to 7), but a virtual Windows one. Why Windows made this crazy

>>>>allocation

>>>>I'm not sure. Hopefully Standard PC mode will put it back on 7.

>>>>

>>>>(\*) I'm thinking of doing a BIOS reset, or indeed reload, in case the

>>>>crazy

>>>>MB has done something silly here.

>>>>

>>>>In any case, the install image used to work, so this ACPI thingy doesn't

>>>>seem the likely cause. A BIOS reset may do it. Or it still could be a

MB

>>>>hardware fault.

>>>>

>>>>Annoying... ;o)

>>>>

>>>>Cheers,

>>>>Kim.

>>>>

>>

>>

>

>

Subject: Re: My Error 7/7 dilemma continued...  
Posted by [Kim](#) on Sun, 06 Jan 2008 02:28:06 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Morgan,

Thanks for that. I'll give it a shot. You're not the first to suggest it (Steve did I think). I'm a little pessimistic about it however as I have removed both cards, tried just one, then the other, and different slots, and I would have thought that simply luck of the draw would mean it would have randomly started at some point if that was the issue. You'd have more experience on this level than myself though, so I'll put it next on the list.

I do hate pulling the box apart though... :o(

Cheers,  
Kim.

"Morgan" <morganp@ntplx.net> wrote:

>Hi Kim,

>I tried to respond to another post on this a while back

>and got a posting error, I hope this one makes it.

>

>We had some rigs that would get into a 7/7 error mode,

>this always means the hardware cannot be seen.

>

>We would use a pencil eraser on the contacts of the EDS

>card and clean out the pci slot the best we could with a

>De-Oxit type of spray . That usually would do the trick.

>In a multi card system - do one card at a time :)

>I hope this helps :)

>

>Morgan

>"Kim" <hiddensounds@hotmail.com> wrote in message news:47800ece\$1@linux...

>>

>>

>> Mmm... neither the BIOS Defaults reset or the Standard PC thing seem

to

>> have fixed it. Same deal.

>>

>> Gosh damnit. ;o)

>>

>> I'm just going to be really annoyed if I buy a new MB and that's not it.

>> I've tried a number of things here, many with some confidence of a result,

>> but nuttin' worked. I've got \$4500 I plan to spend on car restorations

in

>> the next 6 weeks. I know a MB is only \$70 but I'm runnin' on empty. ;o)

>>

>> But what I wouldn't do to get Paris up and running. I'm almost considering

>> loading Reaper to get some stuff done... :oS  
>>  
>> Cheers,  
>> Kim.  
>>  
>> "Kim" <hiddensounds@hotmail.com> wrote:  
>>>  
>>>  
>>>So..... ;o)  
>>>  
>>>It occurred to me that I should put more effort into resolving this on  
the  
>>>existing MB. Just after some comments if you have any. Currently Paris  
  
>>>attempts  
>>>to load, the MEC or 442 starts its "boot" and stops right at that point  
>> where  
>>>the internal sync light and the 48k light come on together. They stay  
that  
>>>way for far too long (compared to "normal") and then the 7/7 error  
>>>appears.  
>>>IIRC that phase is when the MEC is actually attempting to make the audio  
>>>link with the EDS card. Presumably this is when EDS comms are going to  
  
>>>suddenly  
>>>increase from some minor discussions about the boot process to an actual  
>>>stream of audio data traffic, so I can see that an IRQ issue might cause  
>>>issues at that point.  
>>>  
>>>I'm currently exploring the idea that it's just an IRQ conflict, which  
  
>>>seems  
>>>possible.  
>>>  
>>>(\*) I've noted that my "working" Paris install image is in ACPI mode.  
I'm  
>>>just changing to Standard PC to see if we can't sort some stuff out  
>>>because...  
>>>  
>>>(\*) I noted that the Scherzo driver was being allocated to IRQ 19 by  
>>>Windows.  
>>>It was on its own, but that's not the real IRQ (which was 5, but I've  
  
>>>moved  
>>>it to 7), but a virtual Windows one. Why Windows made this crazy  
>>>allocation  
>>>I'm not sure. Hopefully Standard PC mode will put it back on 7.  
>>>

>>>(\*) I'm thinking of doing a BIOS reset, or indeed reload, in case the

>>>crazy

>>>MB has done something silly here.

>>>

>>>In any case, the install image used to work, so this ACPI thingy doesn't

>>>seem the likely cause. A BIOS reset may do it. Or it still could be a

MB

>>>hardware fault.

>>>

>>>Annoying... ;o)

>>>

>>>Cheers,

>>>Kim.

>>

>

>

---

Subject: Re: My Error 7/7 dilemma continued...

Posted by [Neil](#) on Sun, 06 Jan 2008 03:01:14 GMT

[View Forum Message](#) <> [Reply to Message](#)

Kimbers, i think you're gonna have to yank the machine apart no matter what... IIRC, that error 7/7 is indeed an EDS-card-related thing, and it COULD be just the connection/connectors.

Best to yank it apart & rule out a bad EDS card by cleaning the connectors & see if that works.

Neil

"Kim" <[hidensounds@hotmail.com](mailto:hidensounds@hotmail.com)> wrote:

>

>

>Morgan,

>

>Thanks for that. I'll give it a shot. You're not the first to suggest it  
>(Steve did I think). I'm a little pessimistic about it however as I have  
>removed both cards, tried just one, then the other, and different slots,  
>and I would have thought that simply luck of the draw would mean it would  
>have randomly started at some point if that was the issue. You'd have more  
>experience on this level than myself though, so I'll put it next on the  
list.

>

>I do hate pulling the box apart though... :o(

>

>Cheers,  
>Kim.  
>  
>"Morgan" <morganp@ntplx.net> wrote:  
>>Hi Kim,  
>>I tried to respond to another post on this a while back  
>>and got a posting error, I hope this one makes it.  
>>  
>>We had some rigs that would get into a 7/7 error mode,  
>>this always means the hardware cannot be seen.  
>>  
>>We would use a pencil eraser on the contacts of the EDS  
>>card and clean out the pci slot the best we could with a  
>>De-Oxit type of spray . That usually would do the trick.  
>>In a multi card system - do one card at a time :)  
>>I hope this helps :)  
>>  
>>Morgan  
>>"Kim" <hiddensounds@hotmail.com> wrote in message news:47800ece\$1@linux...  
>>>  
>>>  
>>> Mmm... neither the BIOS Defaults reset or the Standard PC thing seem  
>to  
>>> have fixed it. Same deal.  
>>>  
>>> Gosh damnit. ;o)  
>>>  
>>> I'm just going to be really annoyed if I buy a new MB and that's not  
it.  
>>> I've tried a number of things here, many with some confidence of a result,  
>>> but nuttin' worked. I've got \$4500 I plan to spend on car restorations  
>in  
>>> the next 6 weeks. I know a MB is only \$70 but I'm runnin' on empty. ;o)  
>>>  
>>> But what I wouldn't do to get Paris up and running. I'm almost considering  
>>> loading Reaper to get some stuff done... :oS  
>>>  
>>> Cheers,  
>>> Kim.  
>>>  
>>> "Kim" <hiddensounds@hotmail.com> wrote:  
>>>>  
>>>>  
>>>>So..... ;o)  
>>>>  
>>>>It occurred to me that I should put more effort into resolving this on  
>the  
>>>>existing MB. Just after some comments if you have any. Currently Paris

>  
>>>>attempts  
>>>>to load, the MEC or 442 starts its "boot" and stops right at that point  
>>> where  
>>>>the internal sync light and the 48k light come on together. They stay  
>that  
>>>>way for far too long (compared to "normal") and then the 7/7 error  
>>>>appears.  
>>>>IIRC that phase is when the MEC is actually attempting to make the audio  
>>>>link with the EDS card. Presumably this is when EDS comms are going to  
>  
>>>>suddenly  
>>>>increase from some minor discussions about the boot process to an actual  
>>>>stream of audio data traffic, so I can see that an IRQ issue might cause  
>>>>issues at that point.  
>>>>  
>>>>I'm currently exploring the idea that it's just an IRQ conflict, which  
>  
>>>>seems  
>>>>possible.  
>>>>  
>>>>(\*) I've noted that my "working" Paris install image is in ACPI mode.  
>I'm  
>>>>just changing to Standard PC to see if we can't sort some stuff out  
>>>>because...  
>>>>  
>>>>(\*) I noted that the Scherzo driver was being allocated to IRQ 19 by  
  
>>>>Windows.  
>>>>It was on its own, but that's not the real IRQ (which was 5, but I've  
>  
>>>>moved  
>>>>it to 7), but a virtual Windows one. Why Windows made this crazy  
>>>>allocation  
>>>>I'm not sure. Hopefully Standard PC mode will put it back on 7.  
>>>>  
>>>>(\*) I'm thinking of doing a BIOS reset, or indeed reload, in case the  
>  
>>>>crazy  
>>>>MB has done something silly here.  
>>>>  
>>>>In any case, the install image used to work, so this ACPI thingy doesn't  
>>>>seem the likely cause. A BIOS reset may do it. Or it still could be a  
>MB  
>>>>hardware fault.  
>>>>  
>>>>Annoying... ;o)  
>>>>

>>>>Cheers,  
>>>>Kim.  
>>>  
>>  
>>  
>

---

---

Subject: Re: My Error 7/7 dilemma continued...  
Posted by [tonehouse](#) on Sun, 06 Jan 2008 04:53:42 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

That's what I did, and it fixed my problem.....although it did not say "7/7"  
it said "Paris engine not responding".

"Neil" <OIUIU@OI.com> wrote in message news:4780366a\$1@linux...

>  
> Kimmers, i think you're gonna have to yank the machine apart  
> no matter what... IIRC, that error 7/7 is indeed an EDS-card-  
> related thing, and it COULD be just the connection/connectors.

>  
> Best to yank it apart & rule out a bad EDS card by cleaning  
> the connectors & see if that works.

>  
> Neil

>  
>  
> "Kim" <hiddensounds@hotmail.com> wrote:

> >  
> >  
> >Morgan,  
> >  
> >Thanks for that. I'll give it a shot. You're not the first to suggest it  
> >(Steve did I think). I'm a little pessimistic about it however as I have  
> >removed both cards, tried just one, then the other, and different slots,  
> >and I would have thought that simply luck of the draw would mean it would  
> >have randomly started at some point if that was the issue. You'd have  
more

> >experience on this level than myself though, so I'll put it next on the  
> list.

> >  
> >I do hate pulling the box apart though... :o(

> >  
> >Cheers,  
> >Kim.

> >  
> >"Morgan" <morganp@ntplx.net> wrote:

> >>Hi Kim,  
> >>I tried to respond to another post on this a while back

> >>and got a posting error, I hope this one makes it.  
> >>  
> >>We had some rigs that would get into a 7/7 error mode,  
> >>this always means the hardware cannot be seen.  
> >>  
> >>We would use a pencil eraser on the contacts of the EDS  
> >>card and clean out the pci slot the best we could with a  
> >>De-Oxit type of spray . That usually would do the trick.  
> >>In a multi card system - do one card at a time :)  
> >>I hope this helps :)  
> >>  
> >>Morgan  
> >>"Kim" <hiddensounds@hotmail.com> wrote in message  
news:47800ece\$1 @linux...  
> >>>  
> >>>  
> >>> Mmm... neither the BIOS Defaults reset or the Standard PC thing seem  
> >to  
> >>> have fixed it. Same deal.  
> >>>  
> >>> Gosh damnit. ;o)  
> >>>  
> >>> I'm just going to be really annoyed if I buy a new MB and that's not  
> >it.  
> >>> I've tried a number of things here, many with some confidence of a  
> >result,  
> >>> but nuttin' worked. I've got \$4500 I plan to spend on car restorations  
> >in  
> >>> the next 6 weeks. I know a MB is only \$70 but I'm runnin' on empty.  
> > ;o)  
> >>>  
> >>> But what I wouldn't do to get Paris up and running. I'm almost  
considering  
> >>> loading Reaper to get some stuff done... :oS  
> >>>  
> >>> Cheers,  
> >>> Kim.  
> >>>  
> >>> "Kim" <hiddensounds@hotmail.com> wrote:  
> >>>>  
> >>>>  
> >>>>So..... ;o)  
> >>>>  
> >>>>It occurred to me that I should put more effort into resolving this on  
> >the  
> >>>>existing MB. Just after some comments if you have any. Currently Paris  
> >  
> >>>>attempts



> >>>>to load, the MEC or 442 starts its "boot" and stops right at that point  
> >>> where  
> >>>>the internal sync light and the 48k light come on together. They stay  
> >that  
> >>>>way for far too long (compared to "normal") and then the 7/7 error  
> >>>>appears.  
> >>>>IIRC that phase is when the MEC is actually attempting to make the audio  
> >>>>link with the EDS card. Presumably this is when EDS comms are going to  
> >  
> >>>>suddenly  
> >>>>increase from some minor discussions about the boot process to an actual  
> >>>>stream of audio data traffic, so I can see that an IRQ issue might cause  
> >>>>issues at that point.  
> >>>>  
> >>>>I'm currently exploring the idea that it's just an IRQ conflict, which  
> >  
> >>>>seems  
> >>>>possible.  
> >>>>  
> >>>>(\*) I've noted that my "working" Paris install image is in ACPI mode.  
> >I'm  
> >>>>just changing to Standard PC to see if we can't sort some stuff out  
> >>>>because...  
> >>>>  
> >>>>(\*) I noted that the Scherzo driver was being allocated to IRQ 19 by  
> >  
> >>>>Windows.  
> >>>>It was on its own, but that's not the real IRQ (which was 5, but I've  
> >  
> >>>>moved  
> >>>>it to 7), but a virtual Windows one. Why Windows made this crazy  
> >>>>allocation  
> >>>>I'm not sure. Hopefully Standard PC mode will put it back on 7.  
> >>>>  
> >>>>(\*) I'm thinking of doing a BIOS reset, or indeed reload, in case the  
> >  
> >>>>crazy  
> >>>>MB has done something silly here.  
> >>>>  
> >>>>In any case, the install image used to work, so this ACPI thingy doesn't  
> >>>>seem the likely cause. A BIOS reset may do it. Or it still could be a  
> >MB  
> >>>>hardware fault.



>IIRC that phase is when the MEC is actually attempting to make the audio  
>link with the EDS card. Presumably this is when EDS comms are going to suddenly  
>increase from some minor discussions about the boot process to an actual  
>stream of audio data traffic, so I can see that an IRQ issue might cause  
>issues at that point.  
>  
>I'm currently exploring the idea that it's just an IRQ conflict, which seems  
>possible.  
>  
>(\*) I've noted that my "working" Paris install image is in ACPI mode. I'm  
>just changing to Standard PC to see if we can't sort some stuff out because...  
>  
>(\*) I noted that the Scherzo driver was being allocated to IRQ 19 by Windows.  
>It was on its own, but that's not the real IRQ (which was 5, but I've moved  
>it to 7), but a virtual Windows one. Why Windows made this crazy allocation  
>I'm not sure. Hopefully Standard PC mode will put it back on 7.  
>  
>(\*) I'm thinking of doing a BIOS reset, or indeed reload, in case the crazy  
>MB has done something silly here.  
>  
>In any case, the install image used to work, so this ACPI thingy doesn't  
>seem the likely cause. A BIOS reset may do it. Or it still could be a MB  
>hardware fault.  
>  
>Annoying... ;o)  
>  
>Cheers,  
>Kim.

---

---

Subject: Re: My Error 7/7 dilemma continued...  
Posted by [Deej](#) on Tue, 08 Jan 2008 05:21:12 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Neil and Tonehouse are right. Sometimes a connouter valve will spontaneously crossthread some of the PVC fittings that are wired to the flush handle and when that happens, you can sometimes try to fumigate the blowhole sprocket with a steam iron, but usually it's quicker to just reseal the PCI cards.

;o)

"tonehouse" <[zmcleod@comcast.net](mailto:zmcleod@comcast.net)> wrote in message [news:47805cb8\\$1@linux...](mailto:news:47805cb8$1@linux...)  
> That's what I did, and it fixed my problem.....although it did not say  
> "7/7"  
> it said "Paris engine not responding".  
> "Neil" <[OIUIU@OI.com](mailto:OIUIU@OI.com)> wrote in message [news:4780366a\\$1@linux...](mailto:news:4780366a$1@linux...)  
>>  
>> Kimmers, i think you're gonna have to yank the machine apart

>> no matter what... IIRC, that error 7/7 is indeed an EDS-card-  
>> related thing, and it COULD be just the connection/connectors.  
>>  
>> Best to yank it apart & rule out a bad EDS card by cleaning  
>> the connectors & see if that works.  
>>  
>> Neil  
>>  
>>  
>> "Kim" <hiddensounds@hotmail.com> wrote:  
>> >  
>> >  
>> >Morgan,  
>> >  
>> >Thanks for that. I'll give it a shot. You're not the first to suggest it  
>> >(Steve did I think). I'm a little pessimistic about it however as I have  
>> >removed both cards, tried just one, then the other, and different slots,  
>> >and I would have thought that simply luck of the draw would mean it  
>> >would  
>> >have randomly started at some point if that was the issue. You'd have  
> more  
>> >experience on this level than myself though, so I'll put it next on the  
>> list.  
>> >  
>> >I do hate pulling the box apart though... :o(  
>> >  
>> >Cheers,  
>> >Kim.  
>> >  
>> >"Morgan" <morganp@ntplx.net> wrote:  
>> >>Hi Kim,  
>> >>I tried to respond to another post on this a while back  
>> >>and got a posting error, I hope this one makes it.  
>> >>  
>> >>We had some rigs that would get into a 7/7 error mode,  
>> >>this always means the hardware cannot be seen.  
>> >>  
>> >>We would use a pencil eraser on the contacts of the EDS  
>> >>card and clean out the pci slot the best we could with a  
>> >>De-Oxit type of spray . That usually would do the trick.  
>> >>In a multi card system - do one card at a time :)  
>> >>I hope this helps :)  
>> >>  
>> >>Morgan  
>> >>"Kim" <hiddensounds@hotmail.com> wrote in message  
> news:47800ece\$1@linux...  
>> >>>  
>> >>>

>> >>> Mmm... neither the BIOS Defaults reset or the Standard PC thing seem  
>> >to  
>> >>> have fixed it. Same deal.  
>> >>>  
>> >>> Gosh damnit. ;o)  
>> >>>  
>> >>> I'm just going to be really annoyed if I buy a new MB and that's not  
>> it.  
>> >>> I've tried a number of things here, many with some confidence of a  
> result,  
>> >>> but nuttin' worked. I've got \$4500 I plan to spend on car  
>> >>> restorations  
>> >in  
>> >>> the next 6 weeks. I know a MB is only \$70 but I'm runnin' on empty.  
> ;o)  
>> >>>  
>> >>> But what I wouldn't do to get Paris up and running. I'm almost  
> considering  
>> >>> loading Reaper to get some stuff done... :oS  
>> >>>  
>> >>> Cheers,  
>> >>> Kim.  
>> >>>  
>> >>> "Kim" <hiddensounds@hotmail.com> wrote:  
>> >>>>  
>> >>>>  
>> >>>>So..... ;o)  
>> >>>>  
>> >>>>It occurred to me that I should put more effort into resolving this  
>> >>>>on  
>> >the  
>> >>>>existing MB. Just after some comments if you have any. Currently  
>> >>>>Paris  
>> >  
>> >>>>attempts  
>> >>>>to load, the MEC or 442 starts its "boot" and stops right at that  
> point  
>> >>> where  
>> >>>>the internal sync light and the 48k light come on together. They stay  
>> >that  
>> >>>>way for far too long (compared to "normal") and then the 7/7 error  
>> >>>>appears.  
>> >>>>IIRC that phase is when the MEC is actually attempting to make the  
> audio  
>> >>>>link with the EDS card. Presumably this is when EDS comms are going  
>> >>>>to  
>> >  
>> >>>>suddenly



>

---

---

Subject: Re: My Error 7/7 dilemma continued...  
Posted by [Kim](#) on Tue, 08 Jan 2008 10:23:55 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Deej,

Nobody but other smartasses likes a smartass.

;o)

"Deej" <noway@jose.org> wrote:

>Neil and Tonehouse are right. Sometimes a connouter valve will spontaneously

>crosstread some of the PVC fittings that are wired to the flush handle  
and

>when that happens, you can sometimes try to fumigate the blowhole sprocket

>with a steam iron, but usually it's quicker to just reseal the PCI cards.

>

>;o)

>

>"tonehouse" <zmcleod@comcast.net> wrote in message news:47805cb8\$1@linux...

>> That's what I did, and it fixed my problem.....although it did not say

>> "7/7"

>> it said "Paris engine not responding".

>> "Neil" <OIUIU@OI.com> wrote in message news:4780366a\$1@linux...

>>>

>>> Kimmers, i think you're gonna have to yank the machine apart

>>> no matter what... IIRC, that error 7/7 is indeed an EDS-card-

>>> related thing, and it COULD be just the connection/connectors.

>>>

>>> Best to yank it apart & rule out a bad EDS card by cleaning

>>> the connectors & see if that works.

>>>

>>> Neil

>>>

>>>

>>> "Kim" <hiddensounds@hotmail.com> wrote:

>>> >

>>> >

>>> >Morgan,

>>> >

>>> >Thanks for that. I'll give it a shot. You're not the first to suggest

it

>>> >(Steve did I think). I'm a little pessimistic about it however as I have  
>>> >removed both cards, tried just one, then the other, and different slots,  
>>> >and I would have thought that simply luck of the draw would mean it  
  
>>> >would  
>>> >have randomly started at some point if that was the issue. You'd have  
>> more  
>>> >experience on this level than myself though, so I'll put it next on the  
>>> list.  
>>> >  
>>> >I do hate pulling the box apart though... :o(  
>>> >  
>>> >Cheers,  
>>> >Kim.  
>>> >  
>>> >"Morgan" <morganp@ntplx.net> wrote:  
>>> >>Hi Kim,  
>>> >>I tried to respond to another post on this a while back  
>>> >>and got a posting error, I hope this one makes it.  
>>> >>  
>>> >>We had some rigs that would get into a 7/7 error mode,  
>>> >>this always means the hardware cannot be seen.  
>>> >>  
>>> >>We would use a pencil eraser on the contacts of the EDS  
>>> >>card and clean out the pci slot the best we could with a  
>>> >>De-Oxit type of spray . That usually would do the trick.  
>>> >>In a multi card system - do one card at a time :)  
>>> >>I hope this helps :)  
>>> >>  
>>> >>Morgan  
>>> >>"Kim" <hiddensounds@hotmail.com> wrote in message  
>> news:47800ece\$1@linux...  
>>> >>>  
>>> >>>  
>>> >>> Mmm... neither the BIOS Defaults reset or the Standard PC thing seem  
>>> >to  
>>> >>> have fixed it. Same deal.  
>>> >>>  
>>> >>> Gosh damnit. ;o)  
>>> >>>  
>>> >>> I'm just going to be really annoyed if I buy a new MB and that's not  
>>> it.  
>>> >>> I've tried a number of things here, many with some confidence of a



>> result,  
>>> >>> but nuttin' worked. I've got \$4500 I plan to spend on car  
>>> >>> restorations  
>>> >in  
>>> >>> the next 6 weeks. I know a MB is only \$70 but I'm runnin' on empty.  
>> ;o)  
>>> >>>  
>>> >>> But what I wouldn't do to get Paris up and running. I'm almost  
>> considering  
>>> >>> loading Reaper to get some stuff done... :oS  
>>> >>>  
>>> >>> Cheers,  
>>> >>> Kim.  
>>> >>>  
>>> >>> "Kim" <hiddensounds@hotmail.com> wrote:  
>>> >>>>  
>>> >>>>  
>>> >>>>So..... ;o)  
>>> >>>>  
>>> >>>>It occurred to me that I should put more effort into resolving this  
  
>>> >>>>on  
>>> >the  
>>> >>>>existing MB. Just after some comments if you have any. Currently  
  
>>> >>>>Paris  
>>> >  
>>> >>>>attempts  
>>> >>>>to load, the MEC or 442 starts its "boot" and stops right at that  
>> point  
>>> >>> where  
>>> >>>>the internal sync light and the 48k light come on together. They  
stay  
>>> >that  
>>> >>>>way for far too long (compared to "normal") and then the 7/7 error  
>>> >>>>appears.  
>>> >>>>IIRC that phase is when the MEC is actually attempting to make the  
>> audio  
>>> >>>>link with the EDS card. Presumably this is when EDS comms are going  
  
>>> >>>>to  
>>> >  
>>> >>>>suddenly  
>>> >>>>increase from some minor discussions about the boot process to an  
>> actual  
>>> >>>>stream of audio data traffic, so I can see that an IRQ issue might  
>> cause  
>>> >>>>issues at that point.



>>  
>  
>

---

Subject: Re: My Error 7/7 dilemma continued...  
Posted by [Deej](#) on Wed, 09 Jan 2008 06:04:53 GMT  
[View Forum Message](#) <> [Reply to Message](#)

"Kim" <hiddensounds@Hotmail.com> wrote in message news:4783412b\$1@linux...

>  
>  
> Deej,  
>  
> Nobody but other smartasses likes a smartass.  
>  
> ;o)  
>

Sheesh!!!.what an ingrate!!!! See if I come to the rescue the next time the silicon in the transdermal metering guages starts to bubble and send off fumes and you're wondering why a bunch of pasty faced reptilian'esque humanoids come slithering around with glass pipes topped with aluminum foil wanting to smoke the stuff. No more tech support calls for you dude.

;o)

---

Subject: Re: My Error 7/7 dilemma continued...  
Posted by [Mike Audet](#) on Wed, 09 Jan 2008 14:05:14 GMT  
[View Forum Message](#) <> [Reply to Message](#)

Hi Kim,

Are you on skype? Maybe we could chat about this and see if we can come up with something.

Hope to talk to you soon,

Mike

"Deej" <noway@jose.org> wrote:

>  
> "Kim" <hiddensounds@Hotmail.com> wrote in message news:4783412b\$1@linux...  
>>  
>>

>> Deej,  
>>  
>> Nobody but other smartasses likes a smartass.  
>>  
>> ;o)  
>>  
>  
>Sheesh!!!.what an ingrate!!!! See if I come to the rescue the next time  
the  
>silicon in the transdermal metering guages starts to bubble and send off  
  
>fumes and you're wondering why a bunch of pasty faced reptilian'esque  
>humanoids come slithering around with glass pipes topped with aluminum foil  
  
>wanting to smoke the stuff. No more tech support calls for you dude.  
>  
>;o)  
>  
>

---

---

Subject: Re: My Error 7/7 dilemma continued...  
Posted by [Kim](#) on Wed, 09 Jan 2008 20:59:50 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Not Skype as such, but I have a VOIP router and hence can call O.S. generally for under \$2 an hour, which isn't going to break the bank.

Shoot me an email perhaps with your number, however I probably should, at least, do some actual cleaning of the contacts on the EDS as everyone seems to have unanimously suggested. I have two things on my todo list before I panic. ;o)

- 1) Clean the EDS contacts and
- 2) I think that one particular PCI slot has been involved in every test, so I want to try at least one EDS in a different slot.

The EDS contacts don't look dirty, which is why I haven't given them a good clean. I did look. Also, I would think that of TWO EDS cards, after being reseated, it seems unlikely that neither would work even intermittantly. Could be wrong. If I'm going to ask advice though I'd best follow it. ;o)

But from my end the plausible idea that one of the PCI slots has been involved in every test seems very much to be a possible cause.

Cheers,  
Kim.

"Mike Audet" <mike@...> wrote:

>

>Hi Kim,

>

>Are you on skype? Maybe we could chat about this and see if we can come  
>up with something.

>

>Hope to talk to you soon,

>

>Mike

>

>

>"Deej" <noway@jose.org> wrote:

>>

>>"Kim" <hiddensounds@Hotmail.com> wrote in message news:4783412b\$1@linux...

>>>

>>>

>>> Deej,

>>>

>>> Nobody but other smartasses likes a smartass.

>>>

>>> ;o)

>>>

>>

>>Sheesh!!!.what an ingrate!!!! See if I come to the rescue the next time

>the

>>silicon in the transdermal metering guages starts to bubble and send off

>

>>fumes and you're wondering why a bunch of pasty faced reptilian'esque

>>humanoids come slithering around with glass pipes topped with aluminum

foil

>

>>wanting to smoke the stuff. No more tech support calls for you dude.

>>

>>;o)

>>

>>

>

---

Subject: Re: My Error 7/7 dilemma continued...

Posted by [Kim](#) on Wed, 09 Jan 2008 21:03:17 GMT

[View Forum Message](#) <> [Reply to Message](#)

"Deej" <noway@jose.org> wrote:

>Sheesh!!!.what an ingrate!!!! See if I come to the rescue the next time

the

>silicon in the transdermal metering guages starts to bubble and send off

>fumes and you're wondering why a bunch of pasty faced reptilian'esque  
>humanoids come slithering around with glass pipes topped with aluminum foil

>wanting to smoke the stuff. No more tech support calls for you dude.

>

>;o)

Right! That's it! I'm blocking your IP! EVERYBODY knows lizards only smoke  
from wooden pipes!

Yee dawgies.

;o)

---