

---

Subject: ADAT sync with RME interface

Posted by [n0samples](#) on Fri, 31 Jul 2015 14:28:03 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

For some reason my patchbay does not recognize the ADAT card.

Paris is set to 48 khz and the connecting device (rme babyface) as well but the sync button does not light up.

Sometimes the second light in the ADAT blinks, other times it stays dark.

Is it common for the MEC to not see the ADAT on the patchbay?

What am I missing?

---