

---

Subject: Wordclock question

Posted by [dnafe](#) on Fri, 05 Nov 2010 13:28:59 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Without getting into details we have discovered out two MOTU 828's will no longer sync via firewire.

Were looking at buying an RME 9652 to get the audio from the two MOTU converters and a presonus digimax into the computer vial lightpipe

Question is will the master wordclock in the 9652 be able to sync the two MOTUs and the Digimax or will I need to get a master wordclock OR a wordclock splitter / distribution amp box .

If anyone is familiar with this please contact me at [dnafe@rogers.com](mailto:dnafe@rogers.com) ASAP because this little glitch caught us totally unprepared and as these converters are central to our studio's operation we need a fix ASAP

Thanks

---