

---

Subject: Bingo!!!!...figured out why the GForce 5500 won't work in my Paris rig!  
Posted by [animix](#) on Thu, 26 Oct 2006 04:18:01 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

It's a 1.5v AGP mobo. The GEForce card is 3.3v. Now I wonder if the reason I'm having all of these other problems is because I fried the mobo (and/or the video cards). would running the cards undervoltage ruin them? this could explain some other wierdness. I had those 3.3v cards running great in the Paris mobo for about 3 days before things started going south. CRAP!!!!....I hope the video cards and the mobo aren't all damaged. I need to take an electrical engineering course.....I'm gonna get a gimme hat with "dumbass" in big block letters.

(sigh)

;o}

---

---

Subject: Re: Bingo!!!!...figured out why the GForce 5500 won't work in my Paris rig!  
Posted by [Kim](#) on Thu, 26 Oct 2006 06:29:26 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

This depends on PCI compatibility versions, but...

I was under the impression that all but the very last version of PCI would accept 3.3v cards and run them at 3.3v. The final version of PCI (2.3???) doesn't, but 3.3v cards don't fit in it as I recall.

I wouldn't have thought a 3.3v card would even run at 1.5...

Cheers,  
Kim.

"DJ" <notachance@net.net> wrote:

>It's a 1.5v AGP mobo. The GEForce card is 3.3v. Now I wonder if the reason  
>I'm having all of these other problems is because I fried the mobo (and/or  
>the video cards). would running the cards undervoltage ruin them? this could  
>explain some other wierdness. I had those 3.3v cards running great in the  
>Paris mobo for about 3 days before things started going south. CRAP!!!!....I  
>hope the video cards and the mobo aren't all damaged. I need to take an  
>electrical engineering course.....I'm gonna get a gimme hat with "dumbass"  
>in big block letters.

>

>(sigh)

>

>;o}

>

>

---

Subject: Re: Bingo!!!!...figured out why the GEFORCE 5500 won't work in my Paris rig!  
Posted by [Kim](#) on Thu, 26 Oct 2006 06:30:24 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Can that, you're talking about AGP...

....love has my brain frazzled at the moment. ;o)

Cheers,  
Kim.

"Kim" <hiddenounds@hotmail.com> wrote:

>

>

>This depends on PCI compatibility versions, but...

>

>I was under the impression that all but the very last version of PCI would  
>accept 3.3v cards and run them at 3.3v. The final version of PCI (2.3???)  
>doesn't, but 3.3v cards don't fit in it as I recall.

>

>I wouldn't have thought a 3.3v card would even run at 1.5...

>

>Cheers,

>Kim.

>

>"DJ" <notachance@net.net> wrote:

>>It's a 1.5v AGP mobo. The GEFORCE card is 3.3v. Now I wonder if the reason  
>>I'm having all of these other problems is because I fried the mobo (and/or  
>>the video cards). would running the cards undervoltage ruin them? this  
could

>>explain some other wierdness. I had those 3.3v cards running great in the  
>>Paris mobo for about 3 days before things started going south. CRAP!!!!....I  
>>hope the video cards and the mobo aren't all damaged. I need to take an  
>>electrical engineering course.....I'm gonna get a gimme hat with "dumbass"  
>>in big block letters.

>>

>>(sigh)

>>

>>;o}

>>

>>

>

---

Subject: Re: Bingo!!!!...figured out why the GEFORCE 5500 won't work in my Paris rig!  
Posted by [Tom Bruhl](#) on Thu, 26 Oct 2006 07:48:42 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

This is a multi-part message in MIME format.

-----=\_NextPart\_000\_00C2\_01C6F8B1.A16B6E30

Content-Type: text/plain;

charset="iso-8859-1"

Content-Transfer-Encoding: quoted-printable

Kim,

Hopefully more than just your brain.

Tom

"Kim" <hiddensounds@hotmail.com> wrote in message =  
news:45405600\$1@linux...

Can that, you're talking about AGP...

...love has my brain frazzled at the moment. ;o)

Cheers,

Kim.

"Kim" <hiddensounds@hotmail.com> wrote:

>

>

>This depends on PCI compatibility versions, but...

>

>I was under the impression that all but the very last version of PCI =  
would

>accept 3.3v cards and run them at 3.3v. The final version of PCI =  
(2.3???)

>doesn't, but 3.3v cards don't fit in it as I recall.

>

>I wouldn't have thought a 3.3v card would even run at 1.5...

>

>Cheers,

>Kim.

>

>"DJ" <notachance@net.net> wrote:

>>It's a 1.5v AGP mobo. The GEFORCE card is 3.3v. Now I wonder if the =  
reason

>>I'm having all of these other problems is because I fried the mobo =  
(and/or

>>the video cards). would running the cards undervoltage ruin them? =  
this

could

>>explain some other wierdness. I had those 3.3v cards running great =  
in the

>>Paris mobo for about 3 days before things started going south. =

CRAP!!!!....I

>>hope the video cards and the mobo aren't all damaged. I need to take =  
an

>>electrical engineering course.....I'm gonna get a gimme hat with =  
"dumbass"

>>in big block letters.

>>

>>(sigh)

>>

>>;o}

>>

>>

>

I choose Polesoft Lockspam to fight spam, and you?

<http://www.polesoft.com/refer.html>

-----=\_NextPart\_000\_00C2\_01C6F8B1.A16B6E30

Content-Type: text/html;

charset="iso-8859-1"

Content-Transfer-Encoding: quoted-printable

```
<!DOCTYPE HTML PUBLIC "-//W3C//DTD HTML 4.0 Transitional//EN">
```

```
<HTML><HEAD>
```

```
<META http-equiv=3DContent-Type content=3D"text/html; =  
charset=3Diso-8859-1">
```

```
<META content=3D"MSHTML 6.00.2800.1400" name=3DGENERATOR>
```

```
<STYLE></STYLE>
```

```
</HEAD>
```

```
<BODY bgColor=3D#ffffff>
```

```
<DIV><FONT face=3DArial size=3D2>Kim,</FONT></DIV>
```

```
<DIV><FONT face=3DArial size=3D2>Hopefully more than just your =  
brain.</FONT></DIV>
```

```
<DIV><FONT face=3DArial size=3D2>Tom</FONT></DIV>
```

```
<BLOCKQUOTE=20
```

```
style=3D"PADDING-RIGHT: 0px; PADDING-LEFT: 5px; MARGIN-LEFT: 5px; =  
BORDER-LEFT: #000000 2px solid; MARGIN-RIGHT: 0px">
```

```
<DIV>"Kim" &lt;<A=20
```

```
=
```

```
href=3D"mailto:hiddensounds@hotmail.com">hiddensounds@hotmail.com</A>&gt;=
```

```
wrote=20
```

```
in message <A=20
```

```
=
```

```
href=3D"news:45405600$1 @linux">news:45405600$1 @linux</A>...</DIV><BR><BR>=
```

```
Can=20
```

```
that, you're talking about AGP...<BR><BR>...love has my brain frazzled =  
at the=20
```

moment. ;o)<BR><BR>Cheers,<BR>Kim.<BR><BR>"Kim" &lt;<A=20  
=  
href=3D"mailto:hiddeNSounds@hotmail.com">hiddeNSounds@hotmail.com</A>&gt;=  
=20  
wrote:<BR>&gt;<BR>&gt;<BR>&gt;This depends on PCI compatibility =  
versions,=20  
but...<BR>&gt;<BR>&gt;I was under the impression that all but the very =  
last=20  
version of PCI would<BR>&gt;accept 3.3v cards and run them at 3.3v. =  
The final=20  
version of PCI (2.3???)<BR>&gt;doesn't, but 3.3v cards don't fit in it =  
as I=20  
recall.<BR>&gt;<BR>&gt;I wouldn't have thought a 3.3v card would even =  
run at=20  
1.5...<BR>&gt;<BR>&gt;Cheers,<BR>&gt;Kim.<BR>&gt;<BR>&gt;"DJ" &lt;<A=20  
href=3D"mailto:notaChance@net.net">notaChance@net.net</A>&gt;=20  
wrote:<BR>&gt;&gt;It's a 1.5v AGP mobo. The GeForce card is 3.3v. Now =  
I wonder=20  
if the reason<BR>&gt;&gt;I'm having all of these other problems is =  
because I=20  
fried the mobo (and/or<BR>&gt;&gt;the video cards). would running the =  
cards=20  
undervoltage ruin them? this<BR>&gt;&gt;explain some other =  
wierdness.=20  
I had those 3.3v cards running great in the<BR>&gt;&gt;Paris mobo for =  
about 3=20  
days before things started going south. CRAP!!!!....I<BR>&gt;&gt;hope =  
the=20  
video cards and the mobo aren't all damaged. I need to take=20  
an<BR>&gt;&gt;electrical engineering course....I'm gonna get a gimme =  
hat with=20  
"dumbass"<BR>&gt;&gt;in big block=20  
=  
letters.<BR>&gt;&gt;<BR>&gt;&gt;(sigh)<BR>&gt;&gt;<BR>&gt;&gt;<BR>&gt;&gt;o)<BR>&gt;&gt;=  
&gt;&gt;<BR>&gt;&gt;<BR>&gt;<BR></BLOCKQUOTE >  
<DIV><FONT size=3D2><BR><BR>I choose Polesoft Lockspam to fight spam, =  
and=20  
you?<BR><A=20  
href=3D"http://www.polesoft.com/refer.html">http://www.polesoft.com/refer=  
..html</A>&nbsp;&nbsp;&nbsp;&nbsp;&nbsp;&nbsp;&nbsp;</FONT></DIV></BODY ></HTML>  
  
-----=\_NextPart\_000\_00C2\_01C6F8B1.A16B6E30--

---

Subject: Re: Bingo!!!!...figured out why the Geforce 5500 won't work in my Paris rig!  
Posted by [animix](#) on Thu, 26 Oct 2006 14:12:48 GMT  
[View Forum Message](#) <> [Reply to Message](#)

Hey.....that's OK...you've given me an idea.....now if I can just cram one of these AGP cards into a PCI slot.....

;o)

"Kim" <hiddensounds@hotmail.com> wrote in message news:45405600\$1@linux...

>

>

> Can that, you're talking about AGP...

>

> ...love has my brain frazzled at the moment. ;o)

>

> Cheers,

> Kim.

>

> "Kim" <hiddensounds@hotmail.com> wrote:

>>

>>

>>This depends on PCI compatibility versions, but...

>>

>>I was under the impression that all but the very last version of PCI would

>>accept 3.3v cards and run them at 3.3v. The final version of PCI (2.3???)

>>doesn't, but 3.3v cards don't fit in it as I recall.

>>

>>I wouldn't have thought a 3.3v card would even run at 1.5...

>>

>>Cheers,

>>Kim.

>>

>>"DJ" <notachance@net.net> wrote:

>>>It's a 1.5v AGP mobo. The GEForce card is 3.3v. Now I wonder if the reason

>>>I'm having all of these other problems is because I fried the mobo (and/or

>>>the video cards). would running the cards undervoltage ruin them? this > could

>>>explain some other wierdness. I had those 3.3v cards running great in the

>>>Paris mobo for about 3 days before things started going south.

CRAP!!!!....I

>>>hope the video cards and the mobo aren't all damaged. I need to take an

>>>electrical engineering course.....I'm gonna get a gimme hat with "dumbass"

>>>in big block letters.

>>>

>>>(sigh)

>>>

> >>;o}  
> >>  
> >>  
> >>  
> >  
>

---

---

Subject: Re: Bingo!!!!...figured out why the GEForce 5500 won't work in my Paris rig!  
Posted by [AlexPlasko](#) on Thu, 26 Oct 2006 14:57:31 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

use the dremel and cut a new slot. works every time!

"DJ" <notachance@net.net> wrote in message news:4540c227@linux...

> Hey.....that's OK...you've given me an idea.....now if I can just cram

> one

> of these AGP cards into a PCI slot.....

>

> ;o)

>

> "Kim" <hiddensounds@hotmail.com> wrote in message news:45405600\$1@linux...

>>

>>

>> Can that, you're talking about AGP...

>>

>> ...love has my brain frazzled at the moment. ;o)

>>

>> Cheers,

>> Kim.

>>

>> "Kim" <hiddensounds@hotmail.com> wrote:

>>>

>>>

>>> This depends on PCI compatibility versions, but...

>>>

>>> I was under the impression that all but the very last version of PCI

> would

>>> accept 3.3v cards and run them at 3.3v. The final version of PCI

>>> (2.3???)

>>> doesn't, but 3.3v cards don't fit in it as I recall.

>>>

>>> I wouldn't have thought a 3.3v card would even run at 1.5...

>>>

>>> Cheers,

>>> Kim.

>>>

>>> "DJ" <notachance@net.net> wrote:

>>>> It's a 1.5v AGP mobo. The GEForce card is 3.3v. Now I wonder if the

> reason  
>> >>I'm having all of these other problems is because I fried the mobo  
> (and/or  
>> >>the video cards). would running the cards undervoltage ruin them? this  
>> could  
>> >>explain some other wierdness. I had those 3.3v cards running great in  
> the  
>> >>Paris mobo for about 3 days before things started going south.  
> CRAP!!!!....I  
>> >>hope the video cards and the mobo aren't all damaged. I need to take an  
>> >>electrical engineering course.....I'm gonna get a gimme hat with  
> "dumbass"  
>> >>in big block letters.  
>> >>  
>> >>(sigh)  
>> >>  
>> >>;o}  
>> >>  
>> >>  
>> >>  
>> >  
>>  
>  
>

---

---

Subject: Re: Bingo!!!!...figured out why the Gforce 5500 won't work in my Paris rig!  
Posted by [Tyrone Corbett](#) on Thu, 26 Oct 2006 15:16:38 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

"alex plasko" <[alex.plasko@snet.net](mailto:alex.plasko@snet.net)> wrote:  
>use the dremel and cut a new slot. works every time!

Nah Deej, just pull out the ole trusty the SAWZAL!

Tyrone

---

---

Subject: Re: Bingo!!!!...figured out why the Gforce 5500 won't work in my Paris rig!  
Posted by [gene lennon](#) on Thu, 26 Oct 2006 15:22:49 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

This is a multi-part message in MIME format.

---=\_linux4540d2c9  
Content-Type: text/plain  
Content-Transfer-Encoding: 7bit



"Tyrone Corbett" <tyronecorbett@comcast.net> wrote:

>

>"alex plasko" <alex.plasko@snet.net> wrote:

>>use the dremel and cut a new slot. works every time!

>

>Nah Deej, just pull out the ole trusty the SAWZAL!

>

>Tyrone

>

>

>

This is DJ !!

---=\_linux4540d2c9

Content-Type: image/jpeg; name="millingmachines1\_02.jpg"

Content-Transfer-Encoding: base64

Content-Disposition: attachment; filename="millingmachines1\_02.jpg"

/9j/4AAQSkZJRgABAQAAZABkAAD/7AARRHVja3kAAQAEAAAAPAAA/+4ADkFk  
b2JIAGTAAAAAAf/bAIQABgQEBAUEBgUFBgkGBQYJCwgGBggLDAoKCwoKDBAM  
DAwMDAwQDA4PEA8ODBMTFBQTExwbGxscHx8fHx8fHx8fHwEHBwNDA0YEBAY  
GhURFRofHx8fHx8fHx8fHx8fHx8fHx8fHx8fHx8fHx8fHx8fHx8fHx8fHx8f  
Hx8fHx8fHx8f/8AAEQgA2QCmAwERAAIRAQMRAF/EALIAAQACAwEBAQAAAAAA  
AAAAAAAFBgMEBwIIAQEBAQEBAQEBAQAAAAAAAAAAAAAAAAAECAwQFBhAAQMDAglE  
CAsGAwcfAQAAAQIDBAARBRIGIQcxQSITUXEy0hSUVhdhoSOTtNQVdRY2CIGR  
QlJygrFiJJKywjNDg8PRonOzNEQRAQABAglGCAMIAgMAAAAAAAAAABEQISAYEx  
kIMEFEFRYbFyotlzgRMF8KHB0SlyQmJxkVIVBv/aAAwDAQACEQMRAD8A+qaB  
QKBQ  
vplC203HZPR0VMMPrcVHGZFMd18V/tP5tjZ0fk/vCC/OwOCxsiNHd7h1S8c0  
0QvSFWsttJ6FCmGGeKv4vlu2++6Jn+0/m0N6ZXkZs6Q1FzWHxaJrye8REZx  
zLrmgm2pQS3Zl4cLnj1Uww6cJZxufFbLr6deKfzb2zWuTW8YLSzA4XFSEMKC  
JDSsey242pQukLSpdNuBHCmGHPiruMyLqX33xX+0/msHu+2F7NYr1KP5IMM  
PLz2fvL9qUbuTb/LDbuEIZrJbcxqYMNIU8puBHWqyIBAskl48VCmGHbl4jic  
2+LLb7qz/aXrAba5Z57DRMxj9uYxUKa2HWCuBHSopJtxTo4dFMMJncTxOXfN  
l199Y/tKQ932wvZrFepR/Mphhy57P3l+1J7vthezWK9Sj+ZTDBz2fvL9qT3f  
bC9msV6IH8ymGDns/eX7Unu+2F7NYr1KP5IMMHPZ+8v2pPd9sL2axXqUfzKY  
YOez95ftSe77YXs1ivUo/mUwwc9n7y/ak932wvZrFepR/Mphg57P3l+1J7vt  
hezWK9Sj+ZTDBz2fvL9qT3fC9msV6IH8ymGDns/eX7Unu+2F7NYr1KP5IMM  
HPZ+8v2pPd9sL2axXqUfzKYYOez95ftSe77YXs1ivUo/mUwwc9n7y/ak932w  
vZrFepR/Mphg57P3l+1J7vthezWK9Sj+ZTDBz2fvL9qXzByrmSdmSMDvgrlw  
uQmv4XMXPZbQQ2tKzb+rX/ZVfsPqNscRF+T/ADtti637fd8XUP0o/k3L/eJ/  
+huj4/8A6P3bfD+Mo3mvtbdTfM87o2miWanljoEvDOFh+Q1obCCTFcOooUgp  
IKO1c+DpOv03iMqeG+Xm4rlrou0xE/FCYPm1DwO1NzT8ftuPgd6B9iPLS2l1  
LCIOqcusx3FHu1NFK+x0XI8VHozvps5mbZbdfN+VSZjr6Onpr1tzbXNreTOR  
MVzPOZ5idi5T633MelvoU5qM48glJQEuo1NgXPZP8o6zHEfTcqba4MExfEfu  
ritrEfBr43e3OTL8ucpu2bllqsRAbcYSlyPHLrz5eaAcLXcKaUIGvTtxt4j00  
azOE4SziLcqLZxXds6lpPTWrLk+cG50QNoYNnKpwoY5M3LZhmEh9wFanQID  
cZtISB8l/AkdPSADRMv6XI4sy+bcdLqRbip1dPxZlc3eZjnLjJO48rm5PGZJ

MZecTE0qVAcQ4pD5YUjSkITdiop4Ai/a40Z/6zh44i2Lft1tcNf5aNfVz5I  
7xzOelZJiXueNuGE22hyMFsGJKWVEgK71kIDZRC21JdX1ceNqPn/AFbhbMuL  
ZiybJ/zW2fjr+6HWaPiFAoFAoFAoFAoFAoFBzHF8j4UXIIP2NKyXpYlvqIM5  
H0fuyy6dGhQb7xV9Jb49sXBtR9jM+rzdxEZ0W0pFKV1/cl+VHLT8AYaZjftL  
7S9Lkek973PcaewlGnT3jt/Jve9HD6lx/M3xdhw0imuv4Qht9cmJeb3Z+LNV  
bge2/mXG0tSXGkFQCUCUHAIUhbak9gBJBUdYUd+D+qxI5XysyyL7GnC/Tthk7  
ZzGOyWVfyGZzTiHn80tHbQ60orSpKFKWVXUpWvUu6r9VHS/65f8AMtutti2y  
z+P2+5tYrIFum6vt/eUnJMSQHcbj4rTXo7CEOMqZS48hC7PFAXftcSQLqoxm  
fU8v+GXFv6sUzWs666Or7aG1juTvoXKubsL7X7z0xal/aXo9tOp1Llu57038  
i3I0YzPqmLiYz8Oror+NPwR0vkXLZb23NwW4VY3ce3lvobeS9GSStDzd19LKI  
kJNnjiVXBtR1t+sROOL7MwXmTWldXx+DYd5M5I3b/cObwnr3F6aMiMuvUps  
LAPySY3eaQ3c3ftf+Ds0Zj6rZF9f12/Lw4cP41prb3L3ITJ23uTJ7pzGYOYz  
2UbLLzyGERmkoUpKldhBIJJaT0AW8FHLjfqMZuXblWW4bLe2rodHyggUCgUC  
gUCgUCgUCgUCgUCgUCgJ89nsXgcTlyUeDEOMm61niSTwCUjrUo8AKJM0c1j  
8299Z1Ppm1dnyZeKXcMS3ghAc/zJU46yCP6QR8NWgzDdXPJ3ydnpr/VliJ/x  
eVTQaWvN3fzoiKaTKwUaKp86WggZHKIH4A2I0/ttViBtonc+HUhSMbBQk8QT  
MZII8PZjqqADS9BHP9f8OLbHgVJv/uxKaDS9fZ3Plzypmlb/AO68f8I6aaCk  
vB27zwX5WXxSP+5M/wCElpWckvz8I86VeVn8aj+k5A+/VNkwUek7V5zxrVlz  
mOmrRxEZZntBVurv09dA/ag1awIE5s7fT2QnOYXMXlwM3HV3b0V3SVhegrA1  
IshaVoBW24mwUARYEVJhYXOopQKBQKBQKBQKASACsbAcSTQch5pOQt2bm2lt  
1uU3Jwr8pL84MrSsLteyFaSfKbSsf3Vu2HO+XXGmm2m0NNIDbTYCUISEpSB  
YAAAFYdHgggJ8WGrNrKzRrS0wr0dChdN1AC4HRfyv31qNTMt/BuFWMacWey  
u6kE8OyTwPHw9NSVhuKIRk+U6geNQqUWr9Ehg9DiD4ICg9ggi44igUCg5PzV  
dVj9+bUnRpk5MspZfch8SGp0UIB8QkOD+41qNTM64dYrLRQKBQKBQKBQUPmA  
jmkvN41GyH4LLSmHhNM9OpsHUnQbJovV06bC3TerCSquW2z+pF/HyXF7uxkX  
S2o93HjjjYXtqUySL/BTQRmub7VkO4LO7cl5EOJXDdL0nUhTYUISinUQoJPY  
aFgfAARXXocel9CjdUx0nQhCQOFxc1ijs8qzmSX/ANTT4gKURrOy5DytTjhU  
ei58FB4LiyPKNh8NBhISxHZ1qSV3IAA8P7aqUYhPToK+6UAPF/60KLNtecl1  
pxjtBSO2kK8B4f41m5q1OVISg5LzZQqTvraqGkqcTEUI2TpBKW0KnRFxWoeT  
dLSjx6hWo1M9LrVzaKBQKBQKBQV6fnss1IamLHdzxqQW3VLWpLveXHbTYFJS  
kX7PSfCOvUWszc1MnkZUa2WecV3cZBUptJNwLni3YknpAqxCVaUhdz+Zbkt  
NIbWjsOtPiShVli4sAVGx6jVm2hVw/f8+LkN4y5Hp4eiwK4DLafDSSHAA6qQ  
18KwpPEdVSJ00Lo0V6I65b5jJz8WhEiG76I22BGySiCl/QooULdRTp4mtSIs  
1hkynNzIziMivG5HMJT2192uMtl/WFXtb/I1IpJ7o3vt/bDDcnMqfajOnSI  
9phx5sKKtlSpTYUEm56DVH5ure2I2xj/ALRyDEp6EkqS4/DaEhLZSbEOaVDT  
x4ceug5xkP1L7CILAixluSWpxWkqUy23YngmxLv+NSotMDfGLyCynHvGaltY  
bkLjPw8EKVY6SpsLF/20V0zZcPLIWZUhaTEfa+Tue3fUCApJAIsLjjUmRa6y  
qicz4ZzbnKdl4sNrkB6O0228m6NLlys8CD0JrVNGhLZiv6tXY49u/8AUDmo  
ePgSmIKJE1ZQJvpcCoYSstpcHcqakISiNX8QFNWhYsmbcX8a0r2pdr9Q27Tm  
cFjjCirGTmMRJK1MOs6C6tAV3d3nLkJc6xU6KtX2TbOGdEvoUdAqMIAoFAoM  
M4vCFILJs8G1Is+Bwk2+OgoTeQ3CxJhs+gokwnEf62QHNC2nbXCkolstHCx4  
3ua6MUVzffNHA7UI4+Nklul6e4A8lgBfcxydJffB6GtRA8J6uigrum5w4WTI  
5sZuEsKjNFbuTaDfdPntqU22hNyHVanDZISDb99WiVXibjGmtgnGgy3rkskh  
QQm6XVouFXtwN+uosqdy/lbrjRpe3shiTAx2MivOlmoEh1bj7qJQnSpSbJB  
Ub+KrKWqfzR2xImy4b0WKH3ERVPvPkaICGAIrcUtR4WA66jN9axRZeXG68Lu  
7CzsG7CRDkNrdfehELstTzheddCXbqAU4sqHxdFWOtuJrrTG0M9h5k/MbWU3  
HanRJDrsuM0bpW5IUXVrUIRVxWSSR46THUQoe7uUuychuN3G4ubGjZpaO+Xi  
krCV6enVo8XG3gqxMTrSbep2nkVsFOztoORYvU7NfU+sX4DT2B0f01i+Yroa

tjQ6PWGigofNPb2TymBmmK6iO2wUSnXXC5YtMIUVgBkLcv1gAcbVqJYuhyqB  
yR5gy2YE1GTx86A4ylwd6XAXe9QClwhUdWm2q6Rbo4fDWZd7L7YpWK29VafF  
t4rlbutO6MfCcmYx+bhprWUngNKLvorkhZbCVrj6Qru29KUHQtbp66xFt8XT  
Mz+mej7drv8APyJyJtm2Zz6/vrop1UfQ1beQoFAoFB+LQlaFIULpUCCPgNBw  
+XyY3fNM5j7QegwV5ASYLDMx1xKI7fZS1dZ12Wkdu6umtRLNOI2HHYHEQYTE  
Vii2IDDaWkaviVBKegFxzUtXjUalWnEOcMDaWz9/wN3TFhlp6Op5GMjt2L09  
jS226dA49hSQL8Bpv0mt2amLtah57bTuVkbTzuNSqL6bMfXisc2pTLZ7kl5Y  
cSjScbCxrVImaM3TMRV1TI1hWsftLUWi27kVvS3kqUpfB1xXdpBWSdKW9ISP  
BUnWts1iJbW5MJHyG3J8RMxMSS/FWwytfkkqlsFWBNiRaosuY7ExW9vxGxlz  
eVbx0aG2Ftd6nvlvuC6U8QIJAKSdQK6kJSVx2Jy/yE7dL+Wj5kM4192ROage  
jNlxLq1+SqRwWtGpRNUFK0aonJvJbJ/iHJZZWYb+y5y1SX4rUFpycFFACm2J  
LhXYHTwug1mqzDpe2MMMLgYWM7xbpjNhK3HFFaionUq6iBfifBUVJ0CgEAagg  
i4PAg0Ggzg8awyGWW1tNJSEIbQ66IKUpFkpSArsgDwUGeNj4cZ115lvS8/pD  
zhKIKUECyQVKJNkjooNigUCggOX35C2191Qvo6Klup6uO9/M8d3en6ryIAoF  
ByfnFt4ZjMwFB5cdyLHJbeb06klxZ42UFJPK9YrrlzoYuiqs4nameiJcyWbz  
b2TbixnEQYq0NNNoa7xlSVnukl1K0DTxrUa2b/wBsprCZaJidjQHstkwmlqia  
0OSFts3FiUpSDovpBA8NZu1rbqhzndPMvbq/RgzmyyloBJLboVoWDxBCb+Cs  
rKpuc2sLLdPzQ3oULkhSgog+UnSFdfGIYJq61y6598qIWNjx5eY7qY2hYdT  
6O+RxXcdollqSsRLs21914HdOKGVwcoS4KlraDoSpHbQbKBSsJV8VZaS1AoF  
AoFAoFAoFBACvvyFtr7qhfR0VLdT1cd7+Z47u9P1XIKBQCQOk2oKPvZCHMs3  
psT3KAojwa12rdupJV3NT4gw8plDqVPKbKUNpuVFRtw4Vq2dLnmTWJhyLmvh  
39zbl2vDxJRlyEFvRLZbfZCm7tlSpKwpQ/iTWbtMtW3Q5S3yh3gwbtw1pURZ  
VnEk2i420g1lccNmFyn3ggyXw20llsR1eHoJ01KwuJL43klmXkl1/P4yFpN  
u7fJ1j9+mtRHak5IHe+S8/A8vdsycRINyQ8guRKVKb7kLGjUhKCnh3l76L8K  
kkXwuj/OrZDV/wDWaz1aG3Vf8lqGOEXK/UJs5nyEyXj1BDB/4lJqszmwi5X6  
k8C2dKMbMN+hRDSB8alUZ+dDVP6iFuh0wsepZaTrWHFIUEpHC6u7sQPhqL8x  
q4n9TEiZkocFWLjOGU+2yXGn18A4sJvp0r6L+GhGZPUu28907+CmDtVeHilb  
uZgzHfnVxsAITJSEJ+FV61R0qk+VvMRjfo3nch6Olk2FlchT46VhxAeatdT  
a5SFX4Hx+OpMELjUUoIDI9+QttfdUL6OipbqerjvzPHd3p+q8pQfO3O/wDU  
huPZnMFja+AiwngmmzOfmhavln+KQNCk6UoQUk9N7/BSEumkLztPeMTdMVy  
Y3/+1oA5FhtanG2XF3JSIZCQtF+gjqrqc7L8dsTqTDoaeaP/UbWCCT0W8YN  
Gql2c9t9KiZsilniSpL7rXEkdYWerqqFHJeZW7cQxmW28dMhvREMIspuZHda  
F3UDp7SiFAW6qzKUC7174aUolzJs6R0JEI54/wDsbt8dGcMrJtfb+5t2437T  
wsQNY1Z0NvS1Xlik8FKRctHRfo4VmbW6aE6xyc3w6r5SZEZJ6Nluf/JVwsYG  
fHcrJcxTqW9yMSHYjgYkNxEdJdcQ7ewbKUoSQq/C1WhhS2S5UxG+6D2TfU672  
e6ccLni2kuOXOXJOINTiTerhWYV6dy+5fYZ8rz0zKvRHtTq8khtRhx20qUEN  
uuJDqk+Se0Rx+CICkLZieT3LSdHYksRXpER1IW2684sBaCLpKbBBsatFwoPm  
nsPljt7BpfddXiFbalMrHrC3kvPEf8AOZcVdaUpQbFKk2JqTBEQkOSewNs8  
wdr5LLbpivSMjGnSsUy+iQ80BHZQgNq0tLda3E6z8oU3NuupLURCs8xf0tbz  
x0BiDsWQvLxZRP2o5MfQ1KKtWpAJVobLSQB0G+rrq10FNLq/6ceWu4+X+18j  
ic8y2mZlliUmQy8HULSppKNATZJTOKovpvWWnWqBQQHL78hba+6oX0dFS3U9  
XHe/meO7vT9V5Sg+H/1XYI3Fc3ZGTVHQ61kl7L6C4FFJu13AvxAulTKiLfto  
LXyEyfNMbJZENiNKwD0iQW1OvBp86lpDyeKT2SUcDW4YmJXyRyw2pLjOSspj  
/wDVLQVuRmpD3ozagnobQISEdXE6eJ41ZWhB5U8uUMajt6ltRue2tKIKsDa1  
yonqqUNagc4+U7czbkSVs7Fx40jHS5Akw4iEMqeZPG4ltqLfd8Ek9B4VJhXD  
sG9teNkmUbjjTGmG3Qt1KBqUdJ6CFFBt4asU6WdM9L6p25zf5Yt4iLHYnqip  
S2nuozkZ5CtNrJ0hKVJtw8NakrELjJY7deKlxI3pUeM6IKTKeaWwCkm/wAn  
qKFHgKiRNUdsDEQ8ZEyxS6G33Mo+oOpCQsJYOho2TcG4ur+41ErCYy7OJlss



Ca86TGdD7LjZKF96BYL1JA4/FQxQ9HJ4lcJcdSe8jIbBbU04OytJFtJvfgeih  
i7GrtqZg4MBqDNieiRWg6UsQwppnUtRVdIToKeJPAUaiW9vriFhtycvMpAwT  
EdjNZRph+PkXytZU606mQnU6rvFpSspINvD0VmZWlaPLrD8xdh4FOGTtWPkG  
3H3ZT8mJkWkkuPruRoebasEiw4XvaixV10EkAkWPWKilAoFBAcvvyFtr7qhf  
R0VLdT1cd7+Z47u9P1XIQ+69tI3Hi/s5eRnYtPeJcMnGPmM+dII0FYCuydXE  
WoKJL/TVyunMpRk2chknqoFcqXkLJlqhcnQSV2Cbm/ZAoM0vHY3bmOXj8PGb  
iQYALMOMng2hOuwuT47kn9tcuKz5ysq6+Im6bY1RpWyKzRIW42pguDi2Uav7  
SL16ImJisMsDCgWezxGpVvEVE1ZZsnQqG/5WSj7QIKxjoYnuT/RmHVJKwUI  
ZZKtI8AcuKLLiea2y3jMSw3mZaH8y5FEgRiIS+9Gk2uSmySSLXURW6x0udGL  
bGKk7ayTbrjSnFBCe9dLms6/gaKkEAHh2TVi2hV1eRv6Hk9tT0T87jO8iNK  
dahtpdhSi62m6Ud2+5q/i4hKa5y1M6FQ2NuKYp14tzVFjUkhJcJbsGnlW6eA  
ukVlysrT2694zMLttrOelxXUurU0ywgJUts0JCImwKjYXAtflqujk8Hn1u  
j7VQMmltWOUsJfQ2FJdSkmxKVg9I6bWrNW4h3dO0dxTFGNBeiyHFqQFoMkB9  
tghKvSO7cAUU6VXsnia0y+gMVFMTFw4pUFIhhtorT5J0ICbi/UbVh0bVAoFA  
oFBAcvvyFtr7qhfR0VLdT1cd7+Z47u9P1XIKBQUfMEDKSbfznh463CI2SbsO  
cOGhX+FUYYoWGRrFIdKuriRSUt1NdqHGkMPofbS6IEpbiUqANlp4pUL9Y6qK  
gt1cvNuZ5UR2ehSX4rfchxtZQS00Em3Dsr7QqpMKg9y8IQZSnMTIXGwggob  
kAPJ4f7JrUMYUG5tmHBz+R3DvCCzkY5Q0G0MhViEp0rCbEFKyUpIPVWZida9  
CyLZ5YyIOPyOXjJx6VD0Ragg91JkON2KVOtpKNaSLiy+J4UrKxEOXc8ce9DI  
4qHDhLx0XGJcYK27Ljd2taVJdSoAKCiq+vVx6KI/WW61U9AROZEnIrYVko6a  
iQm47YDeIccIClosIKrjtFfQLVmlZxaXV0cs1s7fh74O43ZL+MnQzuLGABSo  
8cuJ0kOIOq/dIK7EEEGrMUIYpGmX1Lldo4fLQw0HZcRBstp3Hy5EQjhwKe5W  
IJHHoll+Cs1bolYMQQ4TEUOuPhhCWw8+ouOr0i2paz5Sj1morPQKBQKCA5ff  
kLbX3VC+joqW6nq4738zx3d6fqvKUCg5q5i0wxcnHg646qfNXJX3nHSdCWgl  
P+UJaHTW4R7cYdcjuaEKUCIQBANujw1RXc8+s5ODCRIEVwJ9ICIEgr7vSktg  
dHEHpN7dXhqfTRIQMjCEfIPqeQllh51bjhIACQgKJPiqOiFm8wMS7Ebew7T  
2WW6IDgbZSUaUueTrKwCIR/lterEMTf1aWSUsOyVlabOtaRbUUIKVcergePX  
xqtlPeEGMxKhpy0czMFNQly4yS4IPpS76FrLZ1JANjq6qzplm5c8LGcf2nBj  
5FkR3vRkplNBQUW1hNidZv2kEXCvDxo10MU/buOmxnO9Sh5lxhSVKWO8CkqT  
5RPHV4asSTD5g3Ng8Fjcr3qY0f7Miu909HjqUmRpaV3altLN1a1q6BbTwrMx  
Slnrqkx+qkdERX/M6af6p/t3XJws6OTeenYQwnNv5KEkyEyUOx5wDcZpDToc  
CnUuLKUpQUKSmx46uNSdbUO6bXbDe2cQ2L2RCjpGrp4NJHGsrKToFAoFAoId  
I9+QttfdUL6OipbqerjvzPHd3p+q8pQKCizUbHuvNd/paWApXck2GhCRa6r  
9lQueAVwrUJL583LzwwLG6pmLynp8fGw5JZZygJcbWlry1Lba7aCpadKeBGn  
jw6K3qTWxZjmpsxYBhZKkOZLGZeQuLGkOthUI1paUqcUVkLSkFdrjiamJmbW  
7lg4/MbHy2Qi492BkmkykNR/SFuFtccqTq4IKLqDeoXHgrWKWZsiYa20NzbS  
mwW/s5pTBiQ09/JUg3sCtVlquo8FLUq/Hp6atGopEUWXbmTx+QfVJgyWpjAC  
Sp2M6I7gL31JQRULfCKktLUuOzIZQFJU3wUkHhwtw6ayqOnbgx+GymNxxzU0  
jMuqYgPW+S79KdQYWr+FSx5Hh6OqoJwrShKlqISICSQpAAAXv8AsoOT7n5Y  
8tpW5DlpORXFmLdEp2I04FtqIWFOANo7YLh6r+EgUw1Z0RNXQs7Jxs3ITmdt  
4iz+ZXFWhjDpcbRKstQU3pQsp8luygPgt00mFbGE51YaDDxcHd2Jye1p7zbl  
I9MhPeiKdICQuL2ISOJ6lWt11lp0+oFAoFAoIdI9+QttfdUL6Oipbqerjv  
zPHd3p+q8pQKCub6gxn9vzVyHvR2VMKZfeA1WQ4QL6euxNasnSzdD54zHK56  
d8oibBfjDgqV32qyP6QnvCf8tq7TMMUakvlbKyMnFRliHleEwjakRFIKe8dc  
cVrcdU2RoTrX0DVcCs6FpK9RMM43Cm412QtByHfF9xtluDICgSL9kadfCixD  
5n3rsff+zpD+G71+ZipykhqRF1KQ+hF9CVpTdSDx4oPX4emsaWtCG2tiMxH3  
fi4jyXYMhcplTtd1MugKWB1WUOmlsaUmXc+YG7uY+x9z46JjZbk+FKZSpCNx  
oSj2LBZTw7wHxKrcsxoXTB83dpZRpDU+QmJOR2izJaLLjbgB7SUr1gEdRph6

lxLJBzWEz8QtRnmchHRZLhJDhuBwK02TYnxUw0WtWc4WOpvuYyvQW/5omlpX  
7bCiSjUZ2NFbkqkuKmt4m/eOcVH+q5iNjvSLU/FkZKCAGnmkDoQo627Dq0r  
1JH7LViWkzF3hMRYSGUPp61tnu1fuOoH94qUEvE3RipC0NqUqO6shKUOptcn  
gAFC6fjqUWqWqBQKCA5ffkLbX3VC+joqW6nq4738zx3d6fqvKUCgh934jJzF  
b0uBjpKIs11PyLjqdTRUDfS4B2tKusp4jpFWJHFfxTE2rlkYLecMYTKrQHI8  
orEiG82oOpt9I1J7SSLOJHw1utWdSztJTLQHoq7sO8UPIcUpKgetJSSk/so  
rL9jsEhS3HFm9xqWo2+OIRFSdqpeUrW6Sk9BUST0+OtRcmFEyuVuDIOeocBT  
JQQUSEHStNj1GmNMLOjYbTueenZF5U1BaYTD9JJWEONEKkrHr1JCvHTEUbgU  
223lck5AyUNt/HtMIW24ptCluOrKtdlqSpSQkAcAatRHYXlrExWSddwMqXi2  
9ASoJWHUKWDFSW3QpJQAF30qYVzx8LLMi0ksyLdDjQLKj40KKk/uNZmVSTkh  
hhvXJWI6QLITxCE/7ROn46ggsnzK2jBbKTL9IWnpDKbov/8AlrSj46sWyzWG  
ZqJvvLqCoGDaxbKv/wCnlOdqx6+6RY00QuLZNUbDnQ56J+Zyy8i62CWYjaZ  
GQs/xFKfLI6tXR09NZm7qWIXGsNFAoIDI9+QttfdUL6OipbqerjvzfPHd3p+  
q8pQKBQcm5+7Xg5SBjZshoLLS1x1LtxAWNaf9w11y5YuhwiJA3btZ5UjbGQc  
ZaUdS4iu2yr+ptV0/FetzazVcNvc9GtYi7pgnHvjh6XHBWyT4VNm60/2IVYm  
1qLnS8dlsdk4qZcCS1MjK6HmFhafEbeSfgPGstNo36vGKD9uDw6fg6aCNyG5  
cLi7+i5BlhQ/6SIBSsz/Ym6/ixEpMqzl+eO24CCiMyuQ6OhThDKP2JOpw/7N  
awszco+X567mmG2PT6Mk9AZQEfvW7rX+4CtRbDM3OpYDIJt47EgZTI5We1m  
ckwh8zA4h7ulnpShLqFjT8fwiuc3zGpuLYIR4P6Wd3xOYOGnT8s1m9vRZaJE  
h5xS23gho6gksL1p7VrdIRoJqj6grKIAoFAoIDI9+QttfdUL6Oipbqerjvf  
zPHd3p+q8pQKBQQW9sC7nNvSILGn0klJGo2GpCr9Pwi4rVs0IJhwPLYfKYq  
QY2QirjOnydY4H4UKHA+MGU8TVzog5+HgS0FLyEkn+KwqorSNu7pxWVYOz1P  
Lyktzu48VhwNI3ShTik9ohJ7KDwVcVi6KLDdP6hdzYwO4vMQfR8xFOh1EmIt  
t1Kh/OgLQm/9orETA1pQ+S5o7rzTSVNvv9y8CbFXcN9NjZpm3g/iUa3HYzMo  
dDOVlf8AOelSrpQ32E/Fx/fWqSxVc8NyY3nMjSy4+GfUy+R3bhARcEXCu2Un  
Sf5uilbYWky6Rt39NuTXoXmJjMJHAqaZHfOeK/ZQP3mszmx0NRlu54DDRsjh  
oeJkUtiE2Gm1uW1EJ6zYAVxmay6RFG/UUoFAoFAoIDI9+QttfdUL6Oipbqe  
rjvzfPHd3p+q8pQKBQKDXn46Dkl6o01hEhhXS24kKHj49BpEjmm5+SzTmqRt  
9/u1cT6E+SUH4EOdl/uv46625nWxNqp7N2xmYfM3AszoL0cxFyZLhKSUBKYy  
2wrWLpsVO2BvVvmKJEaXVN9cr9lB4idzn8eh19AsxPbs3Jb/AKXQL2/yqun4  
K4xLcwoGJ/TJhIncsSMo47DjgpbS20IDqklaldpZKk3sq3BNdfmaGPIr9gOV  
WxMGUryYtt19PRIk/Lr/AGa7pT/aBWZvmWotiFsAAAAFgOgVhooFAoFAoFAo  
FBRdjbgyzWytvtN7ZyT6G8bDSI9tzGhCwGEALSHJiF2V0jUkHwgVi2dD6fGZ  
Fk518/Mtj9V3/Pr8Kb/EuZ9IMr87i/r1ar2PNy9m8s8/oPxLmfZTK/O4v69S  
vYcvZvLPP6D8S5n2UyvzuL+vUr2HL2byzz+g/EuZ9IMr87i/r1K9hy9m8s8/  
oPxLmfZTK/O4v69SvYcvZvLPP6D8S5n2UyvzuL+vUr2HL2byzz+g/EuZ9IMr  
87i/r1K9hy9m8s8/oPxLmfZTK/O4v69SvYcvZvLPP6D8S5n2UyvzuL+vUr2H  
L2byzz+g/EuZ9IMr87i/r1K9hy9m8s8/oPxLmfZTK/O4v69SvYcvZvLPP6D8  
S5n2UyvzuL+vUr2HL2byzz+g/EuZ9IMr87i/r1K9hy9m8s8/oPxLmfZTK/O4  
v69SvYcvZvLPP6D8S5n2UyvzuL+vUr2HL2byzz+g/EuZ9IMr87i/r1K9hy9m  
8s8/oPxLmfZTK/O4v69SvYcvZvLPP6D8S5n2UyvzuL+vUr2HL2byzz+g/EuZ  
9IMr87i/r1K9hy9m8s8/oPxLmfZTK/O4v69SvYcvZvLPP6DI9+QttfdUL6Oi  
luo4738zx3d6fqvK1cq641i5jrailxthxSFDpBCCQaCm4vceSdbIOCStao+E  
9IstJA9ISCSuygL/AOFB+RMxl0QcjqmOuqGKYmtrXYqQ643qUUKAcL9VBgbz  
2VGKzS25j6vR40NxpTo0ulcdA7wpCglWk9XV4KCdmSJity4mHFIOguoMqc3q  
ugNISakabfxqFjQReDzWXdnQVvS3HEzki60rToSWCdGgADTa1BpbM3Flspk  
mlMqY6q7b/ekGxIskoVe3SLm1Bvs5bJp2WuWJbq8jLkejMOKNyIXfFA0i38o  
NBkiZ3JPYrby1PqEh2cl008Lr0IQIV47Cgmt6zZULbMyTFcLL7fdaHE9I1Oo

SfiNBVcnuDNxMDi8oZSy5NILfcbSQUhm90tD4AkUGePnJ7uKwjr0x4IITH25  
DrdytTaSrSOyCeHioJUzVndjcJcuQlghsuMoTqupwr03cskkXHTqtQeOY2Uy  
OOxcV2A+phxb+ISkdJToUbfFQRsDcuRm5/N6JCxEagOuxWx5KV0CAFJ4eG9B  
I4fKZB7IYFt19S0Scep19J6FuC3aPw0HtmZnJMHcalbqlzl8pxuEDbspASdK  
b8Oi9qDb2hJelRpD6pq5TSlpShI4WeYWINnG3OA46qCfoIDi9+QttfdUL6Oi  
pbqerjvzPHd3p+q8rDOjmTckRgrSX21thXTbWkpv8dBARNnqaS4hySFldxg  
xqtKbEdN3Bc/D0UHiNs6SiJMaemIW5IhNwGllbKUpQ0nSFKBUq5P7KA9sx1y  
NPZ9KSDNjRowOg9kxgAVdPHVag24uBnx869k0yGlpeQ0zoW2rUhpsDUIBCgO  
0RfiKDVxmznoctlxctLjERMgRkBspX/qTc61aiDpv1AUGPAbHvicpHnelBzu  
mCy4gll1KJPavc9VqDI3sw+gY+C/IS7HhylynkFHBy5UUp6eFtRoPCdmSGAk  
RZTaENZE5CO2psIKQRbu+ChwFBLZ3EP5fAvY5byW3ngjU6lJKQULSs2STfjp  
8NBEObGU5CagmUPRGH33GUaDdLT6SA30/wAJUTeg9RNnS4mPxcdmW2Xsa+4+  
FrbJSvXfhYKB4X8NBIDD5FOdGVQ+zqXHRHfbLaiDpVqUUEL4X6r3oP3cu3/t  
pmM13oaSy73iwU6tQKckjpH81BE4bYjmOLxMtLinoLsNRCCO064V6+nqHC1B  
uM7ZnRnsY/Gktd7j4pinvG1FK727XZUm3RQPw3IEJyjeeLhGSeW+HUIWHm1  
KtbSoLH8vGg3MFhX8e9NkyH0vyJy0Lc0IKEDQnSLAqUbnpPGglqCA932wvZr  
FepR/MqYYerns/eX7Unu+2F7NYr1KP5IMMHPZ+8v2pPd9sL2axXqUfzKYYOe  
z95ftSe77YXs1ivUo/mUwwc9n7y/ak932wvZrFepR/Mphg57P3l+1J7vthez  
WK9Sj+ZTDBz2fvL9qT3fbC9msV6IH8ymGDns/eX7Unu+2F7NYr1KP5IMMHPZ  
+8v2pPd9sL2axXqUfzKYYOez95ftSe77YXs1ivUo/mUwwc9n7y/ak932wvZr  
FepR/Mphg57P3l+1J7vthezWK9Sj+ZTDBz2fvL9qT3fbC9msV6IH8ymGDns/  
eX7Unu+2F7NYr1KP5IMMHPZ+8v2pPd9sL2axXqUfzKYYOez95ftSe77YXs1i  
vUo/mUwwc9n7y/ak932wvZrFepR/Mphg57P3l+1J7vthezWK9Sj+ZTDBz2fv  
L9qT3fbC9msV6IH8ymGDns/eX7Unu+2F7NYr1KP5IMMHPZ+8v2pPd9sL2axX  
qUfzKYYOez95ftSn6rylAoFAoFAoFAoFAoFAoFAoFAoFAoFAoFAoP/Z

---=\_linux4540d2c9--

---

Subject: Re: Bingo!!!!...figured out why the GEforce 5500 won't work in my Paris rig!  
Posted by [animix](#) on Thu, 26 Oct 2006 15:39:16 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

;o)....seriously.....do you think I could have damaged the mobo by running a  
3.3v card in a 1.5v slot...and/or damaged the video card?

"Gene Lennon" <glennon@NOSPmyrealbox.com> wrote in message  
news:4540d2c9\$1@linux...

>  
> "Tyrone Corbett" <tyronecorbett@comcast.net> wrote:  
> >  
> >"alex plasko" <alex.plasko@snet.net> wrote:  
> >>use the dremel and cut a new slot. works every time!  
> >  
> >Nah Deej, just pull out the ole trusty the SAWZAL!  
> >  
> >Tyrone  
> >

> >  
> >  
> This is DJ !!

---

Subject: Re: Bingo!!!!...figured out why the GEforce 5500 won't work in my Paris rig!  
Posted by [Kim](#) on Thu, 26 Oct 2006 16:23:44 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

"Tom Bruhl" <arpegio@comcast.net> wrote:  
>Kim,  
>Hopefully more than just your brain.

....well, one would think, but apparently not in this case...

---

Subject: Re: Bingo!!!!...figured out why the GEforce 5500 won't work in my Paris rig!  
Posted by [gene lennon](#) on Fri, 27 Oct 2006 00:15:39 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

"DJ" <notachance@net.net> wrote:  
>;o)....seriously.....do you think I could have damaged the mobo by running  
>a  
>3.3v card in a 1.5v slot...and/or damaged the video card?  
>  
>No.  
>But anything is possible.  
>Gene

---

Subject: Re: Bingo!!!!...figured out why the GEforce 5500 won't work in my Paris rig!  
Posted by [Dubya Mark Wilson](#) on Fri, 27 Oct 2006 06:48:23 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Deej, if the 3v cards are pulling their operating voltage from an onboard regulator IC, it is possible to damage components on the vid card AND the mobo. When the reg can't get what it wants for V, it tries to up the voltage which requires more current. The reg IC on the card gets hot while the mobo gets siphoned for more current than it perhaps can deliver.

MW

"DJ" <notachance@net.net> wrote in message news:4540d673@linux...  
> ;o)....seriously.....do you think I could have damaged the mobo by running  
> a  
> 3.3v card in a 1.5v slot...and/or damaged the video card?  
>

> "Gene Lennon" <glennon@NOSPmyrealbox.com> wrote in message  
> news:4540d2c9\$1@linux...  
>>  
>> "Tyrone Corbett" <tyronecorbett@comcast.net> wrote:  
>> >  
>> >"alex plasko" <alex.plasko@snet.net> wrote:  
>> >>use the dremel and cut a new slot. works every time!  
>> >  
>> >Nah Deej, just pull out the ole trusty the SAWZAL!  
>> >  
>> >Tyrone  
>> >  
>> >  
>> >  
>> This is DJ !!  
>  
>

---

---

Subject: Re: Bingo!!!!...figured out why the GeForce 5500 won't work in my Paris rig!  
Posted by [animix](#) on Sat, 28 Oct 2006 04:20:34 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Thanks Mark,

The Paris rig appears to be intact. No damage to the mobo. I've got it up and running again and it's stable so far with the old Matrox G450 cards.

Deej

"Dubya Mark Wilson" <mark.xspam@avidrecording.com> wrote in message  
news:4541a9a5@linux...  
> Deej, if the 3v cards are pulling their operating voltage from an onboard  
> regulator IC, it is possible to damage components on the vid card AND the  
> mobo. When the reg can't get what it wants for V, it tries to up the  
> voltage which requires more current. The reg IC on the card gets hot  
while  
> the mobo gets siphoned for more current than it perhaps can deliver.  
>  
> MW  
>  
> "DJ" <notachance@net.net> wrote in message news:4540d673@linux...  
> > ;o)....seriously.....do you think I could have damaged the mobo by  
running  
> > a  
> > 3.3v card in a 1.5v slot...and/or damaged the video card?  
> >  
> > "Gene Lennon" <glennon@NOSPmyrealbox.com> wrote in message



> > news:4540d2c9\$1@linux...  
> >>  
> >> "Tyrone Corbett" <tyronecorbett@comcast.net> wrote:  
> >>>  
> >> >"alex plasko" <alex.plasko@snet.net> wrote:  
> >> >>use the dremel and cut a new slot. works every time!  
> >>>  
> >> >Nah Deej, just pull out the ole trusty the SAWZAL!  
> >>>  
> >> >Tyrone  
> >>>  
> >>>  
> >>>  
> >> This is DJ !!  
> >  
> >  
>  
>

---

---

Subject: Re: Bingo!!!!...figured out why the Gforce 5500 won't work in my Paris rig!  
Posted by [AlexPlasko](#) on Sat, 28 Oct 2006 04:34:56 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

thanks dude, i can sleep now:-)  
"DJ" <notachance@net.net> wrote in message news:4542da29@linux...  
> Thanks Mark,  
>  
> The Paris rig appears to be intact. No damage to the mobo. I've got it up  
> and running again and it's stable so far with the old Matrox G450 cards.  
>  
> Deej  
>  
> "Dubya Mark Wilson" <mark.xspam@avidrecording.com> wrote in message  
> news:4541a9a5@linux...  
>> Deej, if the 3v cards are pulling their operating voltage from an onboard  
>> regulator IC, it is possible to damage components on the vid card AND the  
>> mobo. When the reg can't get what it wants for V, it tries to up the  
>> voltage which requires more current. The reg IC on the card gets hot  
> while  
>> the mobo gets siphoned for more current than it perhaps can deliver.  
>>  
>> MW  
>>  
>> "DJ" <notachance@net.net> wrote in message news:4540d673@linux...  
>> > ;o)....seriously.....do you think I could have damaged the mobo by  
> running  
>> > a

>> > 3.3v card in a 1.5v slot...and/or damaged the video card?  
>> >  
>> > "Gene Lennon" <glennon@NOSPmyrealbox.com> wrote in message  
>> > news:4540d2c9\$1@linux...  
>> >>  
>> >> "Tyrone Corbett" <tyronecorbett@comcast.net> wrote:  
>> >> >  
>> >> > "alex plasko" <alex.plasko@snet.net> wrote:  
>> >> >> use the dremel and cut a new slot. works every time!  
>> >> >  
>> >> > Nah Deej, just pull out the ole trusty the SAWZAL!  
>> >> >  
>> >> > Tyrone  
>> >> >  
>> >> >  
>> >> >  
>> >> > This is DJ !!  
>> >  
>> >  
>>  
>>  
>  
>

---

---

Subject: Re: Bingo!!!!...figured out why the GeForce 5500 won't work in my Paris rig!  
Posted by [animix](#) on Sat, 28 Oct 2006 06:01:13 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Yeah....me too.

;o)

"alex plasko" <alex.plasko@snet.net> wrote in message  
news:4542dbd1\$1@linux...  
> thanks dude, i can sleep now:-)  
> "DJ" <notachance@net.net> wrote in message news:4542da29@linux...  
> > Thanks Mark,  
> >  
> > The Paris rig appears to be intact. No damage to the mobo. I've got it  
up  
> > and running again and it's stable so far with the old Matrox G450 cards.  
> >  
> > Deej  
> >  
> > "Dubya Mark Wilson" <mark.xspam@avidrecording.com> wrote in message  
> > news:4541a9a5@linux...  
> >> Deej, if the 3v cards are pulling their operating voltage from an

onboard

> >> regulator IC, it is possible to damage components on the vid card AND the

> >> mobo. When the reg can't get what it wants for V, it tries to up the > >> voltage which requires more current. The reg IC on the card gets hot > > while

> >> the mobo gets siphoned for more current than it perhaps can deliver.

> >>

> >> MW

> >>

> >> "DJ" <notachance@net.net> wrote in message news:4540d673@linux...

> >>> > ;o)....seriously.....do you think I could have damaged the mobo by

> > running

> >>> > a

> >>> > 3.3v card in a 1.5v slot...and/or damaged the video card?

> >>> >

> >>> > "Gene Lennon" <glennon@NOSPmyrealbox.com> wrote in message

> >>> > news:4540d2c9\$1@linux...

> >>>>

> >>>> "Tyrone Corbett" <tyronecorbett@comcast.net> wrote:

> >>>>>

> >>>>> > "alex plasko" <alex.plasko@snet.net> wrote:

> >>>>>> use the dremel and cut a new slot. works every time!

> >>>>>>

> >>>>>> > Nah DeeJ, just pull out the ole trusty the SAWZAL!

> >>>>>>>

> >>>>>>> Tyrone

> >>>>>>>>

> >>>>>>>>

> >>>>>>>>

> >>>>>>>> This is DJ !!

> >>> >

> >>> >

> >>>

> >>>

> >

> >

>

>

---

Subject: Re: Bingo!!!!...figured out why the Gforce 5500 won't work in my Paris rig!

Posted by [Neil](#) on Sat, 28 Oct 2006 14:52:21 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

"DJ" <notachance@net.net> wrote:

>Thanks Mark,

>

>The Paris rig appears to be intact. No damage to the mobo. I've got it up  
>and running again and it's stable so far with the old Matrox G450 cards.

So now that means you've got a spare video card... why don't  
you have your programmer guru buddy write some plugins for it?  
After all, EDS, UAD, and maybe even Pulsar - who knows? - are  
basically video card architecture.

(just trying to melt DeeJ's brain with yet another possibility  
to consider)

:D

---