Subject: Re: ASIO DRIVER current status ? Posted by mikeaudet on Tue, 20 Feb 2018 15:54:39 GMT View Forum Message <> Reply to Message

So...I've been working on a few things...one of which is laying the groundwork for a new scherzo to support a 64 bit ASIO, but I took a bit of a detour and decided to see if I could clean up a couple of things in the 32 bit ASIO...and....

I got 32 sample buffer sizes working!!!

File Attachments

Audio/MIDI Setup					×
	Latency Measu	rement Tool			
	Turn down the volur audio equipment to				
Sel	ect two channels below and	connect them using a	cable.		
Output channel	system:playback_4				
Input channel	system:capture_4				
Once	the channels are connected	l, click the "Measure"	button.		
When	n satisfied with the results, c	lick the "Use results"	button.		
	ted roundtrip latency: nic latency: -96 sampl		.150 ms)		
Measure	Use results	Back to settin	gs (ignore results)	
J					