Subject: Re: ASIO DRIVER current status ? Posted by mikeaudet on Tue, 20 Feb 2018 15:54:39 GMT View Forum Message <> Reply to Message

So...I've been working on a few things...one of which is laying the groundwork for a new scherzo to support a 64 bit ASIO, but I took a bit of a detour and decided to see if I could clean up a couple of things in the 32 bit ASIO...and....

I got 32 sample buffer sizes working!!!

## File Attachments

Audio/MIDI Setup			1 <u>9975</u>		×
	Latency Measu	irement Tool			
	Turn down the volu audio equipment to				
Se	ect two channels below and	connect them using a cable.			
Output channel	system:playback_4				
Input channel	system:capture_4				
Onc	e the channels are connecte	d, click the "Measure" button.			
Whe	n satisfied with the results, (	click the "Use results" button.			
	ted roundtrip latency: mic latency: -96 samp	183 samples (4.150 ms les (-2.177 ms)	;)		
Measure	Use results	Back to settings (ign	ore result	s)	