Subject: Bad Luck Hard Drives! Posted by Tony Benson on Mon, 19 Dec 2005 19:14:47 GMT

View Forum Message <> Reply to Message

```
like
>> =
>>>this=20
>>> happens (another hidden Paris 'feature'). The other thing to check is
>> =
>>>that=20
>>> you have a good wordclock BNC cable running from MEC #1 to MEC #2.
>>> AA
>>>
>>>
>>> "Deadmeat" <scott@postmodernblues.com> wrote in message=20
>>> news:43a59445$1@linux...
>>> >
>>> > Hi all -
>>> > Been messing with V3 for a bit and noticed a real problem.
>>> > Testing on a 3-card system, 2 MECs installed (on A and B
>>> > cards), 2 ADAT and one Sync on MEC A, 1 8-input on MEC B.
>>> >
>>> > Can record fine with MIX A, MEC A. Getting no sound at all
>>> > on any inputs for MEC B, Mix B. Tried to load V2.2, and all
>>> > is fine - can record on MEC B inputs all day long. When using
>>> > V3, see input lights on module, but have no meters in mixer
>>> > and no sound - MEC B syncing to WC fine - plays sound accross
>>> > all submixes just fine from projects recorded on V2.
>>> >
>>> > Any Thoughts?=20
>>>
>>>
>>><!DOCTYPE HTML PUBLIC "-//W3C//DTD HTML 4.0 Transitional//EN">
>>><HTML><HEAD>
>>><META http-equiv=3DContent-Type content=3D"text/html; =
>>>charset=3Diso-8859-1">
>>><META content=3D"MSHTML 6.00.2800.1400" name=3DGENERATOR>
>>><STYLE></STYLE>
>>></HEAD>
>>><
```