

---

Subject: Problem loading up 3.0  
Posted by [Ron Bloom](#) on Tue, 29 Jul 2008 00:43:30 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Hi all,

So I rushed home to do the install of 3.0. Says to blow away the old version (that was working fine last night) before I went on with the install. So I did that. Files seem to down load right, but right after the opening screen says it can't find the master card and that I should check connections and make sure they are tight. They are all tight. I can't get any further in the install. Any thoughts.....everytime I try and make something better.....

---

---

Subject: Re: Problem loading up 3.0  
Posted by [Ron Bloom](#) on Tue, 29 Jul 2008 01:11:51 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Me Again,

to be more specific the error says this "Error in initializing Paris Engine. No interface was found connected to the master card.

Before I turned it off and deleted 2.0 it was connected and ran the two eds cards fine. It wasn't moved or anything during install....HELP

"Ron" <[concerts4u@prodigy.net](mailto:concerts4u@prodigy.net)> wrote:

>  
>Hi all,  
>  
>So I rushed home to do the install of 3.0. Says to blow away the old version  
>(that was working fine last night) before I went on with the install. So  
>I did that. Files seem to down load right, but right after the opening screen  
>says it can't find the master card and that I should check connections and  
>make sure they are tight. They are all tight. I can't get any further in  
>the install. Any thoughts.....everytime I try and make something better.....  
>  
>

---

---

Subject: Re: Problem loading up 3.0  
Posted by [Ron Bloom](#) on Tue, 29 Jul 2008 01:33:12 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Fixed - it seems it wanted the other card to be the master now for some reason. This NG is great. I must have been close enough to the screen to get the wisdom of others before they typed. I heard loud and clear check the other

card.  
thanks

"Ron" <concerts4u@prodigy.net> wrote:

>  
>Me Again,  
>  
>to be more specific the error says this "Error in initializing Paris Engine.  
>No interface was found connected to the master card.

>  
>Before I turned it off and deleted 2.0 it was connected and ran the two  
eds  
>cards fine. It wasn't moved or anything during install....HELP

>  
>"Ron" <concerts4u@prodigy.net> wrote:

>>  
>>Hi all,  
>>  
>>So I rushed home to do the install of 3.0. Says to blow away the old version  
>>(that was working fine last night) before I went on with the install. So  
>>I did that. Files seem to down load right, but right after the opening  
screen  
>>says it can't find the master card and that I should check connections  
and  
>>make sure they are tight. They are all tight. I can't get any further in  
>>the install. Any thoughts.....everytime I try and make something better.....  
>>  
>>  
>

---

Subject: Re: Problem loading up 3.0

Posted by [Aaron Allen](#) on Tue, 29 Jul 2008 01:34:28 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

yup. Here's the deal. Your 'master' card changed positions, although I thought for some reason that was a PCI bus Windows 95/98 versus ME/XP deal. Put on ONE interface (442 or MEC) and move the plug around the EDS cards (the SCSI one) until you get a hit. Then you've found your master card and can add any other interfaces.

AA

"Ron" <concerts4u@prodigy.net> wrote in message news:488e6e57\$1@linux...

>  
> Me Again,  
>  
> to be more specific the error says this "Error in initializing Paris

> Engine.  
> No interface was found connected to the master card.  
>  
> Before I turned it off and deleted 2.0 it was connected and ran the two  
> eds  
> cards fine. It wasn't moved or anything during install....HELP  
>  
> "Ron" <concerts4u@prodigy.net> wrote:  
>>  
>>Hi all,  
>>  
>>So I rushed home to do the install of 3.0. Says to blow away the old  
>>version  
>>(that was working fine last night) before I went on with the install. So  
>>I did that. Files seem to download right, but right after the opening  
>>screen  
>>says it can't find the master card and that I should check connections and  
>>make sure they are tight. They are all tight. I can't get any further in  
>>the install. Any thoughts.....everytime I try and make something  
>>better.....  
>>  
>>  
>

---

Subject: Re: Problem loading up 3.0  
Posted by [Morgan](#) on Tue, 29 Jul 2008 18:15:33 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Hey Ron,  
Glad to hear you got it :)  
Call me if you have any further issues !  
Morgan

"Aaron Allen" <know-spam@not\_here.dude> wrote in message  
news:488e757d@linux...  
> yup. Here's the deal. Your 'master' card changed positions, although I  
> thought for some reason that was a PCI bus Windows 95/98 versus ME/XP  
> deal. Put on ONE interface (442 or MEC) and move the plug around the EDS  
> cards (the SCSI one) until you get a hit. Then you've found your master  
> card and can add any other interfaces.  
>  
> AA  
>  
> "Ron" <concerts4u@prodigy.net> wrote in message news:488e6e57\$1@linux...  
>>  
>> Me Again,  
>>

>> to be more specific the error says this "Error in initializing Paris  
>> Engine.  
>> No interface was found connected to the master card.  
>>  
>> Before I turned it off and deleted 2.0 it was connected and ran the two  
>> eds  
>> cards fine. It wasn't moved or anything during install....HELP  
>>  
>> "Ron" <concerts4u@prodigy.net> wrote:  
>>>  
>>>Hi all,  
>>>  
>>>So I rushed home to do the install of 3.0. Says to blow away the old  
>>>version  
>>>(that was working fine last night) before I went on with the install. So  
>>>I did that. Files seem to down load right, but right after the opening  
>>>screen  
>>>says it can't find the master card and that I should check connections  
>>>and  
>>>make sure they are tight. They are all tight. I can't get any further in  
>>>the install. Any thoughts.....everytime I try and make something  
>>>better.....  
>>>  
>>>  
>>  
>  
>

---