

---

Subject: Re: Paris Problems on new machine: HELP!!!!  
Posted by [Chris Ludwig](#) on Tue, 28 Feb 2006 16:37:26 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Hi Lamont,  
Sorry to here your having trouble.  
What exact model of the Gigabyte board do you mean. The description you have here is vague. Is it a K8NS Ultra -939?

When you say you rebuilt do you mean you reinstalled windows from scratch?

LaMont wrote:

> Hi gang:  
> I 'm having problems getting Paris to ip and running. Paris will sometimes  
> star, only to just freeze up and crash the whole system. So, I thought my  
> Asus-Amd XP combo(with SATA-Firwire) was cause too much IRQ problems for  
> PARIS.  
>  
> So, I rebuilt with my favorite stable mobo(Gigabyte).  
>  
> Here's the skinny: I just build a new Paris/Nuendo PC. Great very very fast:  
> Here are the configs:  
>  
> -gigabyte mobo 939 Ultra250  
> -Dual core opteron 165  
> -2gig ddr400  
> -sata (onboard) 3 300 gig drives  
> -(1) RME Digi 96  
> -(1)Magma card (4 card EDS)  
> -Matrox g450  
>  
> Well, Nuendo runs like a Deer!!! WOW.. But PArIs is hit and miss. I disabled:  
> USB, SATA raid..A little better, but I', starting to think that My either  
> my EdS cards or Mec/442 are the problem. Just 2 weeks prior, the system was  
> working fine.  
>  
> Note: In my studio I have a master power switch that start up the FUrman  
> power unit..The Magama and Mec units were on when I started up the system.  
> Maybe PArIs got a Jolt ??? I don;t know..  
> Please help..Thanks  
>

Chris

--

Chris Ludwig

ADK Pro Audio  
(859) 635-5762  
www.adkproaudio.com  
chrisl@adkproaudio.com

---

---

Subject: Paris Problems on new machine: HELP!!!!  
Posted by [LaMont](#) on Tue, 28 Feb 2006 16:56:00 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Hi gang:

I 'm having problems getting Paris to ip and running. Paris will sometimes star, only to just freeze up and crash the whole system. So, I thought my Asus-Amd XP combo(with SATA-Firwire) was cause too much IRQ problems for PAris.

So, I rebuilt with my favorite stable mobo(Gigabyte).

Here's the skinny: I just build a new Paris/Nuendo PC. Great very very fast:  
Here are the configs:

- gigabyte mobo 939 Ultra250
- Dual core opteron 165
- 2gig ddr400
- sata (onboard) 3 300 gig drives
- (1) RME Digi 96
- (1)Magma card (4 card EDS)
- Matrox g450

Well, Nuendo runs like a Deer!!! WOW.. But PAris is hit and miss. I disabled: USB, SATA raid..A little better, but I', starting to think that My either my EdS cards or Mec/442 are the problem. Just 2 weeks prior, the system was working fine.

Note: In my studio I have a master power switch that start up the FUrman power unit..The Magama and Mec units were on when I started up the system. Maybe PAris got a Jolt ??? I don;t know..  
Please help..Thanks

---

---

Subject: Re: Paris Problems on new machine: HELP!!!!  
Posted by [LaMont](#) on Tue, 28 Feb 2006 18:11:13 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Hi Chris,(I was gonna call you) :)

The mobo-GA-K8NSC-939 [http://www.gigabyte.com.tw/Products/Motherboard/Products\\_Overview.aspx?ProductID=1881&ProductName=GA-K8NSC-939](http://www.gigabyte.com.tw/Products/Motherboard/Products_Overview.aspx?ProductID=1881&ProductName=GA-K8NSC-939)

Chris Ludwig <chrisl@adkproaudio.com> wrote:

>HI Lamont,

>Sorry to here your having trouble.

>What exact model of the Gigabyte board do you mean. The description you

>have here is vague. Is it a K8NS Ultra -939?

>

>When you say you rebuilt do you mean you reinstalled windows from scratch?

>

>

>LaMont wrote:

>> Hi gang:

>> I 'm having problems getting Paris to ip and running. Paris will sometimes

>> star, only to just freeze up and crash the whole system. So, I thought

my

>> Asus-Amd XP combo(with SATA-Firwire) was cause too much IRQ problems for

>> PAris.

>>

>> So, I rebuilt with my favorite stable mobo(Gigabyte).

>>

>> Here's the skinny: I just build a new Paris/Nuendo PC. Great very very fast:

>> Here are the configs:

>>

>> -gigabyte mobo 939 Ultra250

>> -Dual core opteron 165

>> -2gig ddr400

>> -sata (onboard) 3 300 gig drives

>> -(1) RME Digi 96

>> -(1)Magma card (4 card EDS)

>> -Matrox g450

>>

>> Well, Nuendo runs like a Deer!!! WOW.. But PAris is hit and miss. I disabled:

>> USB, SATA raid..A little better, but I', starting to think that My either

>> my EdS cards or Mec/442 are the problem. Just 2 weeks prior, the system was

>> working fine.

>>

>> Note: In my studio I have a master power switch that start up the FUrman

>> power unit..The Magama and Mec units were on when I started up the system.

>> Maybe PARIS got a Jolt ??? I don;t know..  
>> Please help..Thanks  
>>  
>  
>  
>  
>  
>Chris  
>  
>--  
>Chris Ludwig  
>  
>ADK Pro Audio  
>(859) 635-5762  
>www.adkproaudio.com  
>chrisl@adkproaudio.com

---

---

Subject: Re: Paris Problems on new machine: HELP!!!!  
Posted by [Tom Bruhl](#) on Wed, 01 Mar 2006 00:29:35 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

This is a multi-part message in MIME format.

-----=\_NextPart\_000\_00CF\_01C63C9D.4ED03DC0  
Content-Type: text/plain;  
 charset="iso-8859-1"  
Content-Transfer-Encoding: quoted-printable

LaMont,  
EDS1 with Matrox is a bad thing. I'd try different slots within  
the Magma to correct that. Have you tried any other slots on  
the mobo for the Magma card? That might be the first thing unless  
you know that won't help.

Tom  
"LaMont" <jjdpro@ameritech.net> wrote in message =  
news:4404e5bf\$1@linux...

Hi Chris,  
Fresh install of win Xp/sp1. New drives, new everything. I'm using =  
Apci,  
not Standard PC. Mother Board GA-K8NSC-939  
nforce-3 ultra 250gb.

-Maybe moving the magma(13 slot) to a differnt slot.(It's currently =  
residing  
in PCI slot 4. According to the manual, slot 4 and 2 are not shared. =  
Plus

even with the SATA controllers activated, each of the (4) EDS cards had =  
their  
own IRQ. However, 1 EDS card shared (IRQ 16) with the Matrox G450. =  
Strange..

I've been looking into this PCI latency issues and download an app to =  
look  
and change some of the PCI latency settings.=20

The SATA controller had a setting of 0(zero). EDS scherzo (32) matrox =  
(64)..IDE  
controller (0)..

Thanks for your help ..LaMont

Ahris Ludwig <chrisl@adkproaudio.com> wrote:  
>Hi Lamont,  
>Sorry to here your having trouble.  
>What exact model of the Gigabyte board do you mean. The description =  
you

>have here is vague. Is it a K8NS Ultra -939?  
>  
>When you say you rebuilt do you mean you reinstalled windows from =  
scratch?

>  
>  
>LaMont wrote:  
>> Hi gang:  
>> I 'm having problems getting Paris to ip and running. Paris will =  
sometimes  
>> star, only to just freeze up and crash the whole system. So, I =  
thought  
my  
>> Asus-Amd XP combo(with SATA-Firwire) was cause too much IRQ =  
problems for  
>> Paris.  
>>=20  
>> So, I rebuilt with my favorite stable mobo(Gigabyte).  
>>=20  
>> Here's the skinny: I just build a new Paris/Nuendo PC. Great very =  
very  
fast:  
>> Here are the configs:  
>>=20  
>> -gigabyte mobo 939 Ultra250

>> -Dual core opteron 165  
>> -2gig ddr400  
>> -sata (onboard) 3 300 gig drives  
>> -(1) RME Digi 96=20  
>> -(1)Magma card (4 card EDS)=20  
>> -Matrox g450  
>>=20  
>> Well, Nuendo runs like a Deer!!! WOW.. But PARIS is hit and miss. I =  
disabled:  
>> USB, SATA raid..A little better, but I', starting to think that My =  
either  
>> my EdS cards or Mec/442 are the problem. Just 2 weeks prior, the =  
system  
was  
>> working fine.=20  
>>=20  
>> Note: In my studio I have a master power switch that start up the =  
FURman  
>> power unit..The Magama and Mec units were on when I started up the =  
system.  
>> Maybe PARIS got a Jolt ??? I don;t know..  
>> Please help..Thanks  
>>=20  
>  
>  
>  
>  
>Chris  
>  
>--=20  
>Chris Ludwig  
>  
>ADK Pro Audio  
>(859) 635-5762  
>www.adkproaudio.com  
>chrisl@adkproaudio.com

-----=\_NextPart\_000\_00CF\_01C63C9D.4ED03DC0

Content-Type: text/html;

charset="iso-8859-1"

Content-Transfer-Encoding: quoted-printable

<!DOCTYPE HTML PUBLIC "-//W3C//DTD HTML 4.0 Transitional//EN">

<HTML><HEAD>

<META http-equiv=3DContent-Type content=3D"text/html; =  
charset=3Diso-8859-1">

<META content=3D"MSHTML 6.00.2800.1400" name=3DGENERATOR>

<STYLE></STYLE>

```
</HEAD>
<BODY bgColor=#ffffff>
<DIV><FONT face=Arial size=2>LaMont,</FONT></DIV>
<DIV><FONT face=Arial size=2>EDS1 with Matrox is a bad thing.&nbsp; =
I'd try=20
different slots within</FONT></DIV>
<DIV><FONT face=Arial size=2>the Magma to correct that.&nbsp; Have =
you tried any=20
other slots on</FONT></DIV>
<DIV><FONT face=Arial size=2>the mobo for the Magma card?&nbsp; That =
might be=20
the first thing unless</FONT></DIV>
<DIV><FONT face=Arial size=2>you know that won't help.</FONT></DIV>
<DIV><FONT face=Arial size=2>Tom</FONT></DIV>
<BLOCKQUOTE=20
style=3D"PADDING-RIGHT: 0px; PADDING-LEFT: 5px; MARGIN-LEFT: 5px; =
BORDER-LEFT: #000000 2px solid; MARGIN-RIGHT: 0px">
  <DIV>"LaMont" &lt;<A=20
    href=3D"mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A>&gt; =
wrote in=20
  message <A=20
    =
href=3D"news:4404e5bf$1@linux">news:4404e5bf$1@linux</A>...</DIV><BR>Hi=20
  Chris,<BR>Fresh install of win Xp/sp1. New drives, new everything. I'm =
using=20
  Apci,<BR>not Standard PC. Mother Board GA-K8NSC-939<BR>nforce-3 ultra=20
  250gb.<BR><BR>-Maybe moving the magma(13 slot) to a differnt =
slot.(It's=20
  currently residing<BR>in PCI slot 4. According to the manual, slot 4 =
and 2 are=20
  not shared. Plus<BR>even with the Sata controllers activated, each of =
the=20
  (4)eds cards had their<BR>own IRQ. However, 1 EDS card shared (IRQ 16) =
with=20
  the Matrox G450. Strange..<BR><BR>I've been looking into this PCI =
latency=20
  issues and download an app to look<BR>and change soem of the PCI =
latency=20
  settings. <BR><BR>The Sata controller had a setting of 0(zero). EDS =
scherzo=20
  (32) matrox (64)..IDE<BR>controller (0)..<BR><BR>Thanks for your help=20
  ..LaMont<BR><BR><BR><BR>&nbsp;Ahris Ludwig &lt;<A=20
    href=3D"mailto:chris@adkproaudio.com">chris@adkproaudio.com</A>&gt;=20
  wrote:<BR>&gt;Hi Lamont,<BR>&gt;Sorry to here your having =
trouble.<BR>&gt;What=20
  exact model of the Gigabyte board do you mean. The description=20
  you<BR><BR>&gt;have here is vague. Is it a K8NS Ultra=20
  -939?<BR>&gt;<BR>&gt;When you say you rebuilt do you mean you =
```

reinstalled=20  
windows from scratch?<BR>&gt;<BR>&gt;<BR>&gt;LaMont wrote:<BR>&gt;&gt; =  
Hi=20  
gang:<BR>&gt;&gt; I 'm having problems getting Paris to ip and =  
running. Paris=20  
will sometimes<BR>&gt;&gt; star, only to just freeze up and crash the =  
whole=20  
system. So, I thought<BR>my<BR>&gt;&gt; Asus-Amd XP combo(with =  
SATA-Firwire)=20  
was cause too much IRQ problems for<BR>&gt;&gt; PAris.<BR>&gt;&gt;=20  
<BR>&gt;&gt; So, I rebuilt with my favorite stable =  
mobo(Gigabyte).<BR>&gt;&gt;=20  
<BR>&gt;&gt; Here's the skinny: I just build a new Paris/Nuendo PC. =  
Great very=20  
very<BR>fast:<BR>&gt;&gt; Here are the configs:<BR>&gt;&gt; =  
<BR>&gt;&gt;=20  
-gigabyte mobo 939 Ultra250<BR>&gt;&gt; -Dual core opteron =  
165<BR>&gt;&gt;=20  
-2gig ddr400<BR>&gt;&gt; -sata (onboard) 3 300 gig drives<BR>&gt;&gt; =  
-(1) RME=20  
Digi 96 <BR>&gt;&gt; -(1)Magma card (4 card EDS) <BR>&gt;&gt; -Matrox=20  
g450<BR>&gt;&gt; <BR>&gt;&gt; Well, Nuendo runs like a Deer!!! WOW.. =  
But PARIS=20  
is hit and miss. I disabled:<BR>&gt;&gt; USB, SATA raid..A little =  
better, but=20  
I', starting to think that My either<BR>&gt;&gt; my EdS cards or =  
Mec/442 are=20  
the problem. Just 2 weeks prior, the system<BR>was<BR>&gt;&gt; working =  
fine.=20  
<BR>&gt;&gt; <BR>&gt;&gt; Note: In my studio I have a master power =  
switch that=20  
start up the FURman<BR>&gt;&gt; power unit..The Magama and Mec units =  
were on=20  
when I started up the system.<BR>&gt;&gt; Maybe PAris got a Jolt ??? I =  
don;t=20  
know..<BR>&gt;&gt; Please help..Thanks<BR>&gt;&gt;=20  
<BR>&gt;&gt;<BR>&gt;&gt;<BR>&gt;&gt;<BR>&gt;&gt;<BR>&gt;&gt;Chris <BR>&gt;&gt;<BR>&gt;&gt;-- =  
<BR>&gt;&gt;Chris=20  
Ludwig<BR>&gt;&gt;<BR>&gt;&gt;ADK Pro Audio<BR>&gt;&gt;(859)=20  
=  
635-5762<BR>&gt;&gt;www.adkproaudio.com<BR>&gt;&gt;chrisl@adkproaudio.com<BR></BL=  
OCKQUOTE></BODY></HTML>

-----=\_NextPart\_000\_00CF\_01C63C9D.4ED03DC0--

---

Subject: Re: Paris Problems on new machine: HELP!!!!



Posted by [LaMont](#) on Wed, 01 Mar 2006 01:07:27 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hi Chris,

Fresh install of win Xp/sp1. New drives, new everything. I'm using Apci, not Standard PC. Mother Board GA-K8NSC-939 nforce-3 ultra 250gb.

-Maybe moving the magma(13 slot) to a differnt slot.(It's currently residing in PCI slot 4. According to the manual, slot 4 and 2 are not shared. Plus even with the Sata controllers activated, each of the (4)eds cards had their own IRQ. However, 1 EDS card shared (IRQ 16) with the Matrox G450. Strange..

I've been looking into this PCI latency issues and download an app to look and change soem of the PCI latency settings.

The Sata controller had a setting of 0(zero). EDS scherzo (32) matrox (64)..IDE controller (0)..

Thanks for your help ..LaMont

Ahris Ludwig <chrisl@adkproaudio.com> wrote:

>HI Lamont,

>Sorry to here your having trouble.

>What exact model of the Gigabyte board do you mean. The description you

>have here is vague. Is it a K8NS Ultra -939?

>

>When you say you rebuilt do you mean you reinstalled windows from scratch?

>

>

>LaMont wrote:

>> Hi gang:

>> I 'm having problems getting Paris to ip and running. Paris will sometimes

>> star, only to just freeze up and crash the whole system. So, I thought

my

>> Asus-Amd XP combo(with SATA-Firwire) was cause too much IRQ problems for

>> Paris.

>>

>> So, I rebuilt with my favorite stable mobo(Gigabyte).

>>

>> Here's the skinny: I just build a new Paris/Nuendo PC. Great very very fast:

>> Here are the configs:

>>

>> -gigabyte mobo 939 Ultra250

>> -Dual core opteron 165

>> -2gig ddr400  
>> -sata (onboard) 3 300 gig drives  
>> -(1) RME Digi 96  
>> -(1)Magma card (4 card EDS)  
>> -Matrox g450  
>>  
>> Well, Nuendo runs like a Deer!!! WOW.. But PARis is hit and miss. I disabled:  
>> USB, SATA raid..A little better, but I', starting to think that My either  
>> my EdS cards or Mec/442 are the problem. Just 2 weeks prior, the system  
was  
>> working fine.  
>>  
>> Note: In my studio I have a master power switch that start up the FUrman  
>> power unit..The Magama and Mec units were on when I started up the system.  
>> Maybe PARis got a Jolt ??? I don;t know..  
>> Please help..Thanks  
>>  
>  
>  
>  
>  
>  
>Chris  
>  
>--  
>Chris Ludwig  
>  
>ADK Pro Audio  
>(859) 635-5762  
>www.adkproaudio.com  
>chrisl@adkproaudio.com

---

---

Subject: Re: Paris Problems on new machine: HELP!!!!  
Posted by [LaMont](#) on Wed, 01 Mar 2006 05:37:54 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

HEY Tom,  
I'm in the Prcess of moving th magma card to differnt slots..I'll let you  
know what happens..

"Tom Bruhl" <arpeggio@comcast.net> wrote:

>  
>  
>LaMont,  
>EDS1 with Matrox is a bad thing. I'd try different slots within  
>the Magma to correct that. Have you tried any other slots on  
>the mobo for the Magma card? That might be the first thing unless  
>you know that won't help.

>Tom  
> "LaMont" <jjdpro@ameritech.net> wrote in message =  
>news:4404e5bf\$1@linux...  
>  
> Hi Chris,  
> Fresh install of win Xp/sp1. New drives, new everything. I'm using =  
>Apci,  
> not Standard PC. Mother Board GA-K8NSC-939  
> nforce-3 ultra 250gb.  
>  
> -Maybe moving the magma(13 slot) to a differnt slot.(It's currently =  
>residing  
> in PCI slot 4. According to the manual, slot 4 and 2 are not shared. =  
>Plus  
> even with the Sata controllers activated, each of the (4)eds cards had  
=  
>their  
> own IRQ. However, 1 EDS card shared (IRQ 16) with the Matrox G450. =  
>Strange..  
>  
> I've been looking into this PCI latency issues and download an app to  
=  
>look  
> and change soem of the PCI latency settings.=20  
>  
> The Sata controller had a setting of 0(zero). EDS scherzo (32) matrox  
=  
>(64)..IDE  
> controller (0)..  
>  
> Thanks for your help ..LaMont  
>  
>  
>  
> Ahris Ludwig <chrisl@adkproaudio.com> wrote:  
> >Hi Lamont,  
> >Sorry to here your having trouble.  
> >What exact model of the Gigabyte board do you mean. The description =  
>you  
>  
> >have here is vague. Is it a K8NS Ultra -939?  
> >  
> >When you say you rebuilt do you mean you reinstalled windows from =  
>scratch?  
> >  
> >  
> >LaMont wrote:  
> >> Hi gang:

> >> I'm having problems getting Paris to ip and running. Paris will =  
> sometimes  
> >> star, only to just freeze up and crash the whole system. So, I =  
> thought  
> my  
> >> Asus-Amd XP combo(with SATA-Firwire) was cause too much IRQ =  
> problems for  
> >> PAris.  
> >>=20  
> >> So, I rebuilt with my favorite stable mobo(Gigabyte).  
> >>=20  
> >> Here's the skinny: I just build a new Paris/Nuendo PC. Great very =  
> very  
> fast:  
> >> Here are the configs:  
> >>=20  
> >> -gigabyte mobo 939 Ultra250  
> >> -Dual core opteron 165  
> >> -2gig ddr400  
> >> -sata (onboard) 3 300 gig drives  
> >> -(1) RME Digi 96=20  
> >> -(1)Magma card (4 card EDS)=20  
> >> -Matrox g450  
> >>=20  
> >> Well, Nuendo runs like a Deer!!! WOW.. But PAris is hit and miss. I  
=  
> disabled:  
> >> USB, SATA raid..A little better, but I', starting to think that My  
=  
> either  
> >> my EdS cards or Mec/442 are the problem. Just 2 weeks prior, the =  
> system  
> was  
> >> working fine.=20  
> >>=20  
> >> Note: In my studio I have a master power switch that start up the =  
> FUrman  
> >> power unit..The Magama and Mec units were on when I started up the  
=  
> system.  
> >> Maybe PAris got a Jolt ??? I don;t know..  
> >> Please help..Thanks  
> >>=20  
> >  
> >  
> >  
> >  
> >  
> >Chris

```

> >
> >--=20
> >Chris Ludwig
> >
> >ADK Pro Audio
> >(859) 635-5762
> >www.adkproaudio.com
> >chrisl@adkproaudio.com
>
>
><!DOCTYPE HTML PUBLIC "-//W3C//DTD HTML 4.0 Transitional//EN">
><HTML><HEAD>
><META http-equiv=3DContent-Type content=3D"text/html; =
>charset=3Diso-8859-1">
><META content=3D"MSHTML 6.00.2800.1400" name=3DGENERATOR>
><STYLE></STYLE>
></HEAD>
><BODY bgColor=3D#ffffff>
><DIV><FONT face=3DArial size=3D2>LaMont,</FONT></DIV>

>I'd try=20
>different slots within</FONT></DIV>

>you tried any=20
>other slots on</FONT></DIV>

>might be=20
>the first thing unless</FONT></DIV>
><DIV><FONT face=3DArial size=3D2>you know that won't help.</FONT></DIV>
><DIV><FONT face=3DArial size=3D2>Tom</FONT></DIV>
><BLOCKQUOTE=20
>style=3D"PADDING-RIGHT: 0px; PADDING-LEFT: 5px; MARGIN-LEFT: 5px; =
>BORDER-LEFT: #000000 2px solid; MARGIN-RIGHT: 0px">
> <DIV>"LaMont" <<A=20
> href=3D"mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A>> =
>wrote in=20
> message <A=20
> =
>href=3D"news:4404e5bf$1@linux">news:4404e5bf$1@linux</A>...</DIV><BR>Hi=20
> Chris,<BR>Fresh install of win Xp/sp1. New drives, new everything. I'm
=
>using=20
> Apci,<BR>not Standard PC. Mother Board GA-K8NSC-939<BR>nforce-3 ultra=20
> 250gb.<BR><BR>-Maybe moving the magma(13 slot) to a differnt =
>slot.(It's=20
> currently residing<BR>in PCI slot 4. According to the manual, slot 4 =
>and 2 are=20
> not shared. Plus<BR>even with the SATA controllers activated, each of

```

=  
>the=20  
> (4)eds cards had their<BR>own IRQ. However, 1 EDS card shared (IRQ 16)  
=  
>with=20  
> the Matrox G450. Strange..<BR><BR>I've been looking into this PCI =  
>latency=20  
> issues and download an app to look<BR>and change soem of the PCI =  
>latency=20  
> settings. <BR><BR>The Sata controller had a setting of 0(zero). EDS =  
>scherzo=20  
> (32) matrox (64)..IDE<BR>controller (0)..<BR><BR>Thanks for your help=20  
  
> href=3D"mailto:chrisl@adkproaudio.com">chrisl@adkproaudio.com</A>=20  
> wrote:<BR>>HI Lamont,<BR>>Sorry to here your having =  
>trouble.<BR>>What=20  
> exact model of the Gigabyte board do you mean. The description=20  
> you<BR><BR>>have here is vague. Is it a K8NS Ultra=20  
> -939?<BR>><BR>>When you say you rebuilt do you mean you =  
>reinstalled=20  
> windows from scratch?<BR>><BR>><BR>>LaMont wrote:<BR>>> =  
>Hi=20  
> gang:<BR>>> I 'm having problems getting Paris to ip and =  
>running. Paris=20  
> will sometimes<BR>>> star, only to just freeze up and crash the =  
>whole=20  
> system. So, I thought<BR>my<BR>>> Asus-Amd XP combo(with =  
>SATA-Firwire)=20  
> was cause too much IRQ problems for<BR>>> PAris.<BR>>>=20  
> <BR>>> So, I rebuilt with my favorite stable =  
>mobo(Gigabyte).<BR>>>=20  
> <BR>>> Here's the skinny: I just build a new Paris/Nuendo PC. =  
>Great very=20  
> very<BR>fast:<BR>>> Here are the configs:<BR>>> =  
><BR>>>=20  
> -gigabyte mobo 939 Ultra250<BR>>> -Dual core opteron =  
>165<BR>>>=20  
> -2gig ddr400<BR>>> -sata (onboard) 3 300 gig drives<BR>>> =  
>-(1) RME=20  
> Digi 96 <BR>>> -(1)Magma card (4 card EDS) <BR>>> -Matrox=20  
> g450<BR>>> <BR>>> Well, Nuendo runs like a Deer!!! WOW.. =  
>But PAris=20  
> is hit and miss. I disabled:<BR>>> USB, SATA raid..A little =  
>better, but=20  
> I', starting to think that My either<BR>>> my EdS cards or =  
>Mec/442 are=20  
> the problem. Just 2 weeks prior, the system<BR>was<BR>>> working =  
>fine.=20

> <BR>>> <BR>>> Note: In my studio I have a master power =  
>switch that=20  
> start up the FURman<BR>>> power unit..The Magama and Mec units =  
>were on=20  
> when I started up the system.<BR>>> Maybe PAris got a Jolt ??? I =  
>don;t=20  
> know..<BR>>> Please help..Thanks<BR>>>=20  
> <BR>><BR>><BR>><BR>><BR>><BR>>Chris<BR>><BR>>-- =  
><BR>>Chris=20  
> Ludwig<BR>><BR>>ADK Pro Audio<BR>>(859)=20  
> =  
>635-5762<BR>>www.adkproaudio.com<BR>>chrisl@adkproaudio.com<BR></BL=  
>OCKQUOTE></BODY></HTML>  
>  
>

---

---

Subject: Re: Paris Problems on new machine: HELP!!!!  
Posted by [Tom Bruhl](#) on Wed, 01 Mar 2006 08:06:12 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

This is a multi-part message in MIME format.

-----=\_NextPart\_000\_0152\_01C63CDD.18655190  
Content-Type: text/plain;  
charset="iso-8859-1"  
Content-Transfer-Encoding: quoted-printable

LM,  
Can't wait to hear.  
T.

"LaMont" <jjdpro@ameritech.net> wrote in message =  
news:44052522@linux...

HEY Tom,  
I'm in the Prcess of moving th magma card to differnt slots..I'll let =  
you  
know what happens..

"Tom Bruhl" <arpeggio@comcast.net> wrote:

>  
>  
>LaMont,  
>EDS1 with Matrox is a bad thing. I'd try different slots within  
>the Magma to correct that. Have you tried any other slots on  
>the mobo for the Magma card? That might be the first thing unless  
>you know that won't help.  
>Tom

> "LaMont" <jjdpro@ameritech.net> wrote in message =3D  
>news:4404e5bf\$1 @linux...  
>  
> Hi Chris,  
> Fresh install of win Xp/sp1. New drives, new everything. I'm using =  
=3D  
>Apci,  
> not Standard PC. Mother Board GA-K8NSC-939  
> nforce-3 ultra 250gb.  
>  
> -Maybe moving the magma(13 slot) to a differnt slot.(It's currently =  
=3D  
>residing  
> in PCI slot 4. According to the manual, slot 4 and 2 are not =  
shared. =3D  
>Plus  
> even with the Sata controllers activated, each of the (4)eds cards =  
had  
=3D  
>their  
> own IRQ. However, 1 EDS card shared (IRQ 16) with the Matrox G450. =  
=3D  
>Strange..  
>  
> I've been looking into this PCI latency issues and download an app =  
to  
=3D  
>look  
> and change soem of the PCI latency settings.=3D20  
>  
> The Sata controller had a setting of 0(zero). EDS scherzo (32) =  
matrox  
=3D  
>(64)..IDE  
> controller (0)..  
>  
> Thanks for your help ..LaMont  
>  
>  
>  
> Ahris Ludwig <chrisl@adkproaudio.com> wrote:  
> >Hi Lamont,  
> >Sorry to here your having trouble.  
> >What exact model of the Gigabyte board do you mean. The =  
description =3D  
>you  
>  
> >have here is vague. Is it a K8NS Ultra -939?



> >  
> >When you say you rebuilt do you mean you reinstalled windows from =  
=3D  
>scratch?  
> >  
> >  
> >LaMont wrote:  
> >> Hi gang:  
> >> I 'm having problems getting Paris to ip and running. Paris will =  
=3D  
>sometimes  
> >> star, only to just freeze up and crash the whole system. So, I =  
=3D  
>thought  
> my  
> >> Asus-Amd XP combo(with SATA-Firwire) was cause too much IRQ =3D  
>problems for  
> >> PAris.  
> >>=3D20  
> >> So, I rebuilt with my favorite stable mobo(Gigabyte).  
> >>=3D20  
> >> Here's the skinny: I just build a new Paris/Nuendo PC. Great =  
very =3D  
>very  
> fast:  
> >> Here are the configs:  
> >>=3D20  
> >> -gigabyte mobo 939 Ultra250  
> >> -Dual core opteron 165  
> >> -2gig ddr400  
> >> -sata (onboard) 3 300 gig drives  
> >> -(1) RME Digi 96=3D20  
> >> -(1)Magma card (4 card EDS)=3D20  
> >> -Matrox g450  
> >>=3D20  
> >> Well, Nuendo runs like a Deer!!! WOW.. But PAris is hit and =  
miss. I  
=3D  
>disabled:  
> >> USB, SATA raid..A little better, but I', starting to think that =  
My  
=3D  
>either  
> >> my EdS cards or Mec/442 are the problem. Just 2 weeks prior, the =  
=3D  
>system  
> was  
> >> working fine.=3D20

> >>=3D20  
> >> Note: In my studio I have a master power switch that start up =  
the =3D  
>FUrman  
> >> power unit..The Magama and Mec units were on when I started up =  
the  
=3D  
>system.  
> >> Maybe PArIs got a Jolt ??? I don;t know..  
> >> Please help..Thanks  
> >>=3D20  
> >  
> >  
> >  
> >  
> >Chris  
> >  
> >=3D20  
> >Chris Ludwig  
> >  
> >ADK Pro Audio  
> >(859) 635-5762  
> >www.adkproaudio.com  
> >chrisl@adkproaudio.com  
>  
>  
><!DOCTYPE HTML PUBLIC "-//W3C//DTD HTML 4.0 Transitional//EN">  
><HTML><HEAD>  
><META http-equiv=3D3DContent-Type content=3D3D"text/html; =3D  
>charset=3D3Diso-8859-1">  
><META content=3D3D"MSHTML 6.00.2800.1400" name=3D3DGENERATOR>  
><STYLE></STYLE>  
></HEAD>  
><BODY bgColor=3D3D#ffffff>  
><DIV><FONT face=3D3DArial size=3D3D2>LaMont,</FONT></DIV>  
><DIV><FONT face=3D3DArial size=3D3D2>EDS1 with Matrox is a bad thing. =  
=3D  
>I'd try=3D20  
>different slots within</FONT></DIV>  
><DIV><FONT face=3D3DArial size=3D3D2>the Magma to correct that. Have =  
=3D  
>you tried any=3D20  
>other slots on</FONT></DIV>  
><DIV><FONT face=3D3DArial size=3D3D2>the mobo for the Magma card? =  
That =3D  
>might be=3D20  
>the first thing unless</FONT></DIV>  
><DIV><FONT face=3D3DArial size=3D3D2>you know that won't =

```

help.</FONT></DIV>
><DIV><FONT face=3D3DArial size=3D3D2>Tom</FONT></DIV>
><BLOCKQUOTE=3D20
>style=3D3D"PADDING-RIGHT: 0px; PADDING-LEFT: 5px; MARGIN-LEFT: 5px; =
=3D
>BORDER-LEFT: #000000 2px solid; MARGIN-RIGHT: 0px">
> <DIV>"LaMont" <<A=3D20
> href=3D3D"mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A>> =
=3D
>wrote in=3D20
> message <A=3D20
> =3D
=
>href=3D3D"news:4404e5bf$1@linux">news:4404e5bf$1@linux</A>...</DIV><BR>H=
i=3D20
> Chris,<BR>Fresh install of win Xp/sp1. New drives, new everything. =
I'm
=3D
>using=3D20
> Apci,<BR>not Standard PC. Mother Board GA-K8NSC-939<BR>nforce-3 =
ultra=3D20
> 250gb.<BR><BR>-Maybe moving the magma(13 slot) to a differnt =3D
>slot.(It's=3D20
> currently residing<BR>in PCI slot 4. According to the manual, slot =
4 =3D
>and 2 are=3D20
> not shared. Plus<BR>even with the SATA controllers activated, each =
of
=3D
>the=3D20
> (4)eds cards had their<BR>own IRQ. However, 1 EDS card shared (IRQ =
16)
=3D
>with=3D20
> the Matrox G450. Strange..<BR><BR>I've been looking into this PCI =
=3D
>latency=3D20
> issues and download an app to look<BR>and change soem of the PCI =
=3D
>latency=3D20
> settings. <BR><BR>The SATA controller had a setting of 0(zero). EDS =
=3D
>scherzo=3D20
> (32) matrox (64)..IDE<BR>controller (0)..<BR><BR>Thanks for your =
help=3D20
> ..LaMont<BR><BR><BR><BR> Ahris Ludwig <<A=3D20
> =
href=3D3D"mailto:chrisl@adkproaudio.com">chrisl@adkproaudio.com</A>>=3D20=

```

> wrote:<BR>>HI Lamont,<BR>>Sorry to here your having =3D  
>trouble.<BR>>What=3D20  
> exact model of the Gigabyte board do you mean. The description=3D20  
> you<BR><BR>>have here is vague. Is it a K8NS Ultra=3D20  
> -939?<BR>><BR>>When you say you rebuilt do you mean you =3D  
>reinstalled=3D20  
> windows from scratch?<BR>><BR>><BR>>LaMont wrote:<BR>>> =3D  
>Hi=3D20  
> gang:<BR>>> I 'm having problems getting Paris to ip and =3D  
>running. Paris=3D20  
> will sometimes<BR>>> star, only to just freeze up and crash the =3D  
>whole=3D20  
> system. So, I thought<BR>my<BR>>> Asus-Amd XP combo(with =3D  
>SATA-Firwire)=3D20  
> was cause too much IRQ problems for<BR>>> PARIS.<BR>>>=3D20  
> <BR>>> So, I rebuilt with my favorite stable =3D  
>mobo(Gigabyte).<BR>>>=3D20  
> <BR>>> Here's the skinny: I just build a new Paris/Nuendo PC. =3D  
>Great very=3D20  
> very<BR>fast:<BR>>> Here are the configs:<BR>>> =3D  
><BR>>>=3D20  
> -gigabyte mobo 939 Ultra250<BR>>> -Dual core opteron =3D  
>165<BR>>>=3D20  
> -2gig ddr400<BR>>> -sata (onboard) 3 300 gig drives<BR>>> =3D  
>-(1) RME=3D20  
> Digi 96 <BR>>> -(1)Magma card (4 card EDS) <BR>>> -Matrox=3D20  
> g450<BR>>> <BR>>> Well, Nuendo runs like a Deer!!! WOW.. =3D  
>But PARIS=3D20  
> is hit and miss. I disabled:<BR>>> USB, SATA raid..A little =3D  
>better, but=3D20  
> I', starting to think that My either<BR>>> my EdS cards or =3D  
>Mec/442 are=3D20  
> the problem. Just 2 weeks prior, the system<BR>was<BR>>> working =  
=3D  
>fine.=3D20  
> <BR>>> <BR>>> Note: In my studio I have a master power =3D  
>switch that=3D20  
> start up the FURman<BR>>> power unit..The Magama and Mec units =3D  
>were on=3D20  
> when I started up the system.<BR>>> Maybe PARIS got a Jolt ??? I =  
=3D  
>don;t=3D20  
> know..<BR>>> Please help..Thanks<BR>>>=3D20  
> <BR>>><BR>>><BR>>><BR>>><BR>>>Chris<BR>>><BR>>>-- =3D  
><BR>>>Chris=3D20  
> Ludwig<BR>>><BR>>>ADK Pro Audio<BR>>>(859)=3D20  
> =3D

=  
>635-5762<BR>>www.adkproaudio.com<BR>>chrisl@adkproaudio.com<BR></BL=3D  
>OCKQUOTE></BODY></HTML>  
>  
>

-----=\_NextPart\_000\_0152\_01C63CDD.18655190

Content-Type: text/html;

charset="iso-8859-1"

Content-Transfer-Encoding: quoted-printable

<!DOCTYPE HTML PUBLIC "-//W3C//DTD HTML 4.0 Transitional//EN">

<HTML><HEAD>

<META http-equiv=3DContent-Type content=3D"text/html; =

charset=3Diso-8859-1">

<META content=3D"MSHTML 6.00.2800.1400" name=3DGENERATOR>

<STYLE></STYLE>

</HEAD>

<BODY bgColor=3D#ffffff>

<DIV><FONT face=3DArial size=3D2>LM,</FONT></DIV>

<DIV><FONT face=3DArial size=3D2>Can't wait to hear.</FONT></DIV>

<DIV><FONT face=3DArial size=3D2>T.</FONT></DIV>

<BLOCKQUOTE=20

style=3D"PADDING-RIGHT: 0px; PADDING-LEFT: 5px; MARGIN-LEFT: 5px; =

BORDER-LEFT: #000000 2px solid; MARGIN-RIGHT: 0px">

<DIV>"LaMont" &lt;<A=20

href=3D"mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A>&gt; =

wrote in=20

message <A =

href=3D"news:44052522@linux">news:44052522@linux</A>...</DIV><BR>HEY=20

Tom,<BR>I'm in the Prcess of moving th magma card to differnt =

slots..I'll let=20

you<BR>know what happens..<BR><BR>"Tom Bruhl" &lt;<A=20

href=3D"mailto:arpegio@comcast.net">arpegio@comcast.net</A>&gt;=20

wrote:<BR>&gt;<BR>&gt;<BR>&gt;LaMont,<BR>&gt;EDS1 with Matrox is a bad =

thing.&nbsp; I'd try different slots within<BR>&gt;the Magma to =

correct=20

that.&nbsp; Have you tried any other slots on<BR>&gt;the mobo for the =

Magma=20

card?&nbsp; That might be the first thing unless<BR>&gt;you know that =

won't=20

help.<BR>&gt;Tom<BR>&gt;&nbsp; "LaMont" &lt;<A=20

href=3D"mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A>&gt; =

wrote in=20

message =3D<BR>&gt;news:4404e5bf\$1@linux...<BR>&gt;<BR>&gt;&nbsp; Hi=20

Chris,<BR>&gt;&nbsp; Fresh install of win Xp/sp1. New drives, new =

everything.=20

I'm using [Apci](#), not Standard PC. Mother Board = GA-K8NSC-939 [nforce-3 ultra 250gb](#). Maybe moving the magma(13 slot) to a differnt slot.(It's currently residing in PCI slot 4. According to the manual, slot 4 and 2 are not shared. Plus even with the SATA controllers activated, each of the (4) EDS cards had their own IRQ. However, 1 EDS card shared (IRQ 16) with the Matrox G450. Strange.. I've been looking into this PCI latency issues and download an app to look and change soem of the PCI latency settings. [The SATA controller had a setting of 0\(zero\)](#). EDS scherzo (32) matrox [\(64\)](#).. IDE controller (0).. Thanks for your help ..LaMont & Ahris Ludwig & [chrisl@adkproaudio.com](mailto:chrisl@adkproaudio.com) wrote: & Hi Lamont, & Sorry to here = having trouble. & What exact model of the Gigabyte board do you mean. The description you have here is vague. Is it a K8NS Ultra -939? & When you say you rebuilt do you mean you reinstalled windows from scratch? & LaMont wrote: & Hi gang: & I 'm having problems getting Paris to ip and running. Paris will sometimes star, only to just freeze = up and crash the whole system. So, I thought & my & & Asus-Amd XP combo(with SATA-Firwire) was cause too much IRQ = & problems for & & Paris.& & So, I rebuilt with my favorite = stable mobo(Gigabyte). & & &

Here's the=20  
skinny: I just build a new Paris/Nuendo PC. Great very=20  
=3D<BR>&gt;very<BR>&gt;&nbsp; fast:<BR>&gt;&nbsp; &gt;&gt; Here are =  
the=20  
configs:<BR>&gt;&nbsp; &gt;&gt;=3D20<BR>&gt;&nbsp; &gt;&gt; -gigabyte =  
mobo 939=20  
Ultra250<BR>&gt;&nbsp; &gt;&gt; -Dual core opteron 165<BR>&gt;&nbsp; =  
&gt;&gt;=20  
-2gig ddr400<BR>&gt;&nbsp; &gt;&gt; -sata (onboard) 3 300 gig=20  
drives<BR>&gt;&nbsp; &gt;&gt; -(1) RME Digi 96=3D20<BR>&gt;&nbsp; =  
&gt;&gt;=20  
-(1)Magma card (4 card EDS)=3D20<BR>&gt;&nbsp; &gt;&gt; -Matrox=20  
g450<BR>&gt;&nbsp; &gt;&gt;=3D20<BR>&gt;&nbsp; &gt;&gt; Well, Nuendo =  
runs like a=20  
Deer!!! WOW.. But PARis is hit and miss. =  
l<BR>=3D<BR>&gt;disabled:<BR>&gt;&nbsp;=20  
&gt;&gt; USB, SATA raid..A little better, but I', starting to think =  
that=20  
My<BR>=3D<BR>&gt;either<BR>&gt;&nbsp; &gt;&gt; my EdS cards or Mec/442 =  
are the=20  
problem. Just 2 weeks prior, the =3D<BR>&gt;system<BR>&gt;&nbsp;=20  
was<BR>&gt;&nbsp; &gt;&gt; working fine.=3D20<BR>&gt;&nbsp;=20  
&gt;&gt;=3D20<BR>&gt;&nbsp; &gt;&gt; Note: In my studio I have a =  
master power=20  
switch that start up the =3D<BR>&gt;Furman<BR>&gt;&nbsp; &gt;&gt; =  
power=20  
unit..The Magama and Mec units were on when I started up=20  
the<BR>=3D<BR>&gt;system.<BR>&gt;&nbsp; &gt;&gt; Maybe PARis got a =  
Jolt ??? I=20  
don;t know..<BR>&gt;&nbsp; &gt;&gt; Please help..Thanks<BR>&gt;&nbsp;=20  
&gt;&gt;=3D20<BR>&gt;&nbsp; &gt;<BR>&gt;&nbsp; &gt;<BR>&gt;&nbsp;=20  
&gt;<BR>&gt;&nbsp; &gt;<BR>&gt;&nbsp; &gt;Chris<BR>&gt;&nbsp;=20  
&gt;<BR>&gt;&nbsp; &gt;--=3D20<BR>&gt;&nbsp; &gt;Chris =  
Ludwig<BR>&gt;&nbsp;=20  
&gt;<BR>&gt;&nbsp; &gt;ADK Pro Audio<BR>&gt;&nbsp; &gt;(859)=20  
635-5762<BR>&gt;&nbsp; &gt;www.adkproaudio.com<BR>&gt;&nbsp;=20  
&gt;chrisl@adkproaudio.com<BR>&gt;<BR>&gt;<BR>&gt;&lt;!DOCTYPE HTML =  
PUBLIC=20  
"/W3C//DTD HTML 4.0=20  
Transitional//EN"&gt;<BR>&gt;&lt;HTML&gt;&lt;HEAD&gt; <BR>&gt;&lt;META=20  
http-equiv=3D3DContent-Type content=3D3D"text/html;=20  
=3D<BR>&gt;charset=3D3Diso-8859-1"&gt;<BR>&gt;&lt;META =  
content=3D3D"MSHTML=20  
6.00.2800.1400"=20  
=  
name=3D3DGENERATOR&gt;<BR>&gt;&lt;STYLE&gt;&lt;/STYLE&gt; <BR>&gt;&lt;/HEA=  
D&gt;<BR>&gt;&lt;BODY=20  
bgColor=3D3D#ffffff&gt;<BR>&gt;&lt;DIV&gt;&lt;FONT face=3D3DArial=20

=  
size=3D3D2&gt;LaMont,&lt;/FONT&gt;&lt;/DIV&a mp;gt; <BR>&gt;&lt;/DIV&gt;&lt;/FONT=  
=20  
face=3D3DArial size=3D3D2&gt;EDS1 with Matrox is a bad thing. =  
=3D<BR>&gt;l'd=20  
try=3D20<BR>&gt;different slots=20  
within&lt;/FONT&gt;&lt;/DIV&gt;<BR>&gt;&lt;/DIV&gt;&lt;/FONT =  
face=3D3DArial=20  
size=3D3D2&gt;the Magma to correct that. Have =3D<BR>&gt;you tried=20  
any=3D20<BR>&gt;other slots=20  
on&lt;/FONT&gt;&lt;/DIV&gt;<BR>&gt;&lt;/DIV&gt;&lt;/FONT face=3D3DArial=20  
size=3D3D2&gt;the mobo for the Magma card? That =3D<BR>&gt;might =  
be=3D20<BR>&gt;the=20  
first thing unless&lt;/FONT&gt;&lt;/DIV&gt;<BR>&gt;&lt;/DIV&gt;&lt;/FONT =  
  
face=3D3DArial size=3D3D2&gt;you know that won't=20  
help.&lt;/FONT&gt;&lt;/DIV&gt;<BR>&gt;&lt;/DIV&gt;&lt;/FONT =  
face=3D3DArial=20  
=  
size=3D3D2&gt;Tom&lt;/FONT&gt;&lt;/DIV&g t; <BR>&gt;&lt;/BLOCKQUOTE=3D20<BR>=  
&gt;&gt;style=3D3D"PADDING-RIGHT:=20  
0px; PADDING-LEFT: 5px; MARGIN-LEFT: 5px; =3D<BR>&gt;BORDER-LEFT: =  
#000000 2px=20  
solid; MARGIN-RIGHT: 0px"&gt;<BR>&gt;&nbsp; &lt;/DIV&gt;"LaMont"=20  
&lt;&lt;/A=3D20<BR>&gt;&nbsp; href=3D3D"<A=20  
=  
href=3D'mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A'>mailto:jjdp=  
ro@ameritech.net"&gt;jjdpro@ameritech.net&lt;/A</A>&gt;&gt;=20  
=3D<BR>&gt;wrote in=3D20<BR>&gt;&nbsp; message =  
&lt;/A=3D20<BR>&gt;&nbsp;=20  
=3D<BR>&gt;href=3D3D"<A=20  
=  
href=3D'news:4404e5bf\$1 @linux">news:4404e5bf\$1 @linux</A>...</DIV><BR>Hi=3D=  
20'>news:4404e5bf\$1 @linux"&gt;news:4404e5bf\$1 @linux&lt;/A&gt;...&lt;/DIV&=  
gt;&lt;/BR&gt;Hi=3D20</A><BR>&gt;&nbsp;=20  
Chris,&lt;/BR&gt;Fresh install of win Xp/sp1. New drives, new =  
everything.=20  
I'm<BR>=3D<BR>&gt;using=3D20<BR>&gt;&nbsp; Apci,&lt;/BR&gt;not Standard =  
PC. Mother=20  
Board GA-K8NSC-939&lt;/BR&gt;nforce-3 ultra=3D20<BR>&gt;&nbsp;=20  
250gb.&lt;/BR&gt;&lt;/BR&gt;-Maybe moving the magma(13 slot) to a =  
differnt=20  
=3D<BR>&gt;slot.(It's=3D20<BR>&gt;&nbsp; currently =  
residing&lt;/BR&gt;in PCI slot=20  
4. According to the manual, slot 4 =3D<BR>&gt;and 2 =  
are=3D20<BR>&gt;&nbsp; not=20  
shared. Plus&lt;/BR&gt;even with the Sata controllers activated, each=20  
of<BR>=3D<BR>&gt;the=3D20<BR>&gt;&nbsp; (4)eds cards had =



their own IRQ.

However, 1 EDS card shared (IRQ = 16)  
Matrox G450. Strange. I've been looking into this = PCI

issues and download an app to look and change some of the PCI settings. The SATA controller had a setting of 0 (zero).  
EDS (32) matrox (64) IDE controller (0). Thanks for your =

help =  
... LaMont  
Ludwig  
= [chrisl@adkproaudio.com](mailto:chrisl@adkproaudio.com) =  
mailto:chrisl@adkproaudio.com

wrote: HI Lamont, Sorry to here your having trouble. What exact model of the Gigabyte board do you mean. The description you have here is vague. Is it a K8NS Ultra -939? When you say you

rebuilt do you mean you reinstalled windows from scratch? LaMont wrote: Hi = gang:

I'm having problems getting Paris to ip and Paris will sometimes star, only = to just freeze up and crash the whole system. = So, I

thought my ; Asus-Amd XP combo (with SATA-Firwire) = was cause too much IRQ = problems for Paris. = So, I rebuilt with my favorite stable mobo (Gigabyte).

Here's the skinny: I just build a new Paris/Nuendo PC. = Great very fast; Here are = the

configs: <br>>> =  
=3D<br>>><br>>>=3D20<br >>>&nbsp;=20  
-gigabyte mobo 939 Ultra250<br>>>> -Dual core opteron=20  
=3D<br>>>165<br>>>>=3D20<br >>>&nbsp;-2gig =  
ddr400<br>>>>=20  
-sata (onboard) 3 300 gig drives<br>>>> =3D<br>>>-(1)=20  
RME=3D20<br>>>&nbsp;Digi 96 <br>>>> -(1)Magma card (4 =  
card EDS)=20  
<br>>>> -Matrox=3D20<br>>>&nbsp;g450<br>>>>=20  
<br>>>> Well, Nuendo runs like a Deer!!! WOW.. =  
=3D<br>>>But=20  
PAris=3D20<br>>>&nbsp;is hit and miss. I =  
disabled:<br>>>> USB,=20  
SATA raid..A little =3D<br>>>better, but=3D20<br>>>&nbsp;I', =  
starting to=20  
think that My either<br>>>> my EdS cards or =  
=3D<br>>>Mec/442=20  
are=3D20<br>>>&nbsp;the problem. Just 2 weeks prior, the=20  
system<br>>>was<br>>>> ; working =  
=3D<br>>>fine.=3D20<br>>>&nbsp;=20  
<br>>>> <br>>>> Note: In my studio I have a =  
master power=20  
=3D<br>>>switch that=3D20<br>>>&nbsp;start up the =  
FUrman<br>>>>=20  
power unit..The Magama and Mec units =3D<br>>>were =  
on=3D20<br>>>&nbsp;when I=20  
started up the system.<br>>>> Maybe PAris got a Jolt ??? I=20  
=3D<br>>>don;t=3D20<br>>>&nbsp;know..<br>>>> Please=20  
help..Thanks<br>>>>=3D20<br>>>&nbsp;=20  
=  
<br>>>><br>>>><br>>>><br>>>><br>>>><br>>>><br>>>>Chr=  
is<br>>>><br>>>>--=20  
=3D<br>>><br>>>>Chris=3D20<br>>>&nbsp;=20  
Ludwig<br>>>><br>>>>AD K Pro=20  
Audio<br>>>>(859)=3D20<br>>>&nbsp;=20  
=  
=3D<br>>> >635-5762<br>>>>www.adkproaudio.co m<br>>>>chrisl@=  
adkproaudio.com<br>>>>/BL=3D<br>>>>O&quot;>><br>>>>/BODY>><br>>>>HTML<br>>>><br>>>><br>>>>/BLOCKQUOTE></BODY ></HTML>

-----=\_NextPart\_000\_0152\_01C63CDD.18655190--

---

Subject: Re: Paris Problems on new machine: HELP!!!!  
Posted by [Chris Ludwig](#) on Wed, 01 Mar 2006 14:25:09 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Hi Lamont,

Wow weird stuff. Glad its working now.

Chris

LaMont wrote:

> Tom & Chris,

>

> I got it solved. It was the Magma Chasis's power supply was not "seated"

> into slot properly. Paris is working fine now.

> Thanks

>

> "Tom Bruhl" <arpegio@comcast.net> wrote:

>

>>

>>LM,

>>Can't wait to hear.

>>T.

>> "LaMont" <jjdpro@ameritech.net> wrote in message =

>>news:44052522@linux...

>>

>> HEY Tom,

>> I'm in the Prcess of moving th magma card to differnt slots..I'll let

>

> =

>

>>you

>> know what happens..

>>

>> "Tom Bruhl" <arpegio@comcast.net> wrote:

>> >

>> >

>> >LaMont,

>> >EDS1 with Matrox is a bad thing. I'd try different slots within

>> >the Magma to correct that. Have you tried any other slots on

>> >the mobo for the Magma card? That might be the first thing unless

>> >you know that won't help.

>> >Tom

>> > "LaMont" <jjdpro@ameritech.net> wrote in message =3D

>> >news:4404e5bf\$1@linux...

>> >

>> > Hi Chris,

>> > Fresh install of win Xp/sp1. New drives, new everything. I'm using

>

> =

>

>>=3D

>> >Apci,

>> > not Standard PC. Mother Board GA-K8NSC-939  
>> > nforce-3 ultra 250gb.  
>> >  
>> > -Maybe moving the magma(13 slot) to a differnt slot.(It's currently  
>  
> =  
>  
>>=3D  
>> >residing  
>> > in PCI slot 4. According to the manual, slot 4 and 2 are not =  
>>shared. =3D  
>> >Plus  
>> > even with the Sata controllers activated, each of the (4)eds cards  
>  
> =  
>  
>>had  
>> =3D  
>> >their  
>> > own IRQ. However, 1 EDS card shared (IRQ 16) with the Matrox G450.  
>  
> =  
>  
>>=3D  
>> >Strange..  
>> >  
>> > I've been looking into this PCI latency issues and download an app  
>  
> =  
>  
>>to  
>> =3D  
>> >look  
>> > and change soem of the PCI latency settings.=3D20  
>> >  
>> > The Sata controller had a setting of 0(zero). EDS scherzo (32) =  
>>matrox  
>> =3D  
>> >(64)..IDE  
>> > controller (0)..  
>> >  
>> > Thanks for your help ..LaMont  
>> >  
>> >  
>> >  
>> > Ahris Ludwig <chrisl@adkproaudio.com> wrote:  
>> > >HI Lamont,  
>> > >Sorry to here your having trouble.

>> > >What exact model of the Gigabyte board do you mean. The =  
>>description =3D  
>> >you  
>> >  
>> > >have here is vague. Is it a K8NS Ultra -939?  
>> > >  
>> > >When you say you rebuilt do you mean you reinstalled windows from  
>  
> =  
>  
>>=3D  
>> >scratch?  
>> > >  
>> > >  
>> > >LaMont wrote:  
>> > >> Hi gang:  
>> > >> I 'm having problems getting Paris to ip and running. Paris will  
>  
> =  
>  
>>=3D  
>> >sometimes  
>> > >> star, only to just freeze up and crash the whole system. So, I =  
>>=3D  
>> >thought  
>> > my  
>> > >> Asus-Amd XP combo(with SATA-Firwire) was cause too much IRQ =3D  
>> >problems for  
>> > >> PAris.  
>> > >>=3D20  
>> > >> So, I rebuilt with my favorite stable mobo(Gigabyte).  
>> > >>=3D20  
>> > >> Here's the skinny: I just build a new Paris/Nuendo PC. Great =  
>>very =3D  
>> >very  
>> > fast:  
>> > >> Here are the configs:  
>> > >>=3D20  
>> > >> -gigabyte mobo 939 Ultra250  
>> > >> -Dual core opteron 165  
>> > >> -2gig ddr400  
>> > >> -sata (onboard) 3 300 gig drives  
>> > >> -(1) RME Digi 96=3D20  
>> > >> -(1)Magma card (4 card EDS)=3D20  
>> > >> -Matrox g450  
>> > >>=3D20  
>> > >> Well, Nuendo runs like a Deer!!! WOW.. But PAris is hit and =  
>>miss. I

```

>> =3D
>> >disabled:
>> > >> USB, SATA raid..A little better, but I', starting to think that
>
> =
>
>>My
>> =3D
>> >either
>> > >> my EdS cards or Mec/442 are the problem. Just 2 weeks prior, the
>
> =
>
>>=3D
>> >system
>> > was
>> > >> working fine.=3D20
>> > >>=3D20
>> > >> Note: In my studio I have a master power switch that start up =
>>the =3D
>> >FUrman
>> > >> power unit..The Magama and Mec units were on when I started up =
>>the
>> =3D
>> >system.
>> > >> Maybe PARis got a Jolt ??? I don;t know..
>> > >> Please help..Thanks
>> > >>=3D20
>> > >
>> > >
>> > >
>> > >
>> > >Chris
>> > >
>> > >--=3D20
>> > >Chris Ludwig
>> > >
>> > >ADK Pro Audio
>> > >(859) 635-5762
>> > >www.adkproaudio.com
>> > >chrisl@adkproaudio.com
>> >
>> >
>> ><!DOCTYPE HTML PUBLIC "-//W3C//DTD HTML 4.0 Transitional//EN">
>> ><HTML><HEAD>
>> ><META http-equiv=3D3DContent-Type content=3D3D"text/html; =3D
>> >charset=3D3Diso-8859-1">
>> ><META content=3D3D"MSHTML 6.00.2800.1400" name=3D3DGENERATOR>

```

```

>> <<STYLE></STYLE>
>> </HEAD>
>> <<BODY bgColor=#ffffff>
>> <<DIV><FONT face=Arial size=2>LaMont,</FONT></DIV>
>> <<DIV><FONT face=Arial size=2>EDS1 with Matrox is a bad thing.
>
> =
>
>>=3D
>> >l'd try=20
>> >different slots within</FONT></DIV>
>> <<DIV><FONT face=Arial size=2>the Magma to correct that. Have
>
> =
>
>>=3D
>> >you tried any=20
>> >other slots on</FONT></DIV>
>> <<DIV><FONT face=Arial size=2>the mobo for the Magma card? =
>>That =3D
>> >might be=20
>> >the first thing unless</FONT></DIV>
>> <<DIV><FONT face=Arial size=2>you know that won't =
>>help.</FONT></DIV>
>> <<DIV><FONT face=Arial size=2>Tom</FONT></DIV>
>> <<BLOCKQUOTE=20
>> >style="PADDING-RIGHT: 0px; PADDING-LEFT: 5px; MARGIN-LEFT: 5px; =
>>=3D
>> >BORDER-LEFT: #000000 2px solid; MARGIN-RIGHT: 0px">
>> > <DIV>"LaMont" <<A=20
>> > href="mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A>> =
>>=3D
>> >wrote in=20
>> > message <A=20
>> > =3D
>> =
>>
>>>href="news:4404e5bf$1@linux">news:4404e5bf$1@linux</A>...</DIV><BR>H=
>>
>>i=20
>> > Chris,<BR>Fresh install of win Xp/sp1. New drives, new everything.
>
> =
>
>>l'm
>>=3D
>> >using=20
>> > Apci,<BR>not Standard PC. Mother Board GA-K8NSC-939<BR>nforce-3 =

```

>>ultra=3D20  
>> > 250gb.<BR><BR>-Maybe moving the magma(13 slot) to a differnt =3D  
>> >slot.(It's=3D20  
>> > currently residing<BR>in PCI slot 4. According to the manual, slot  
>  
> =  
>  
>>4 =3D  
>> >and 2 are=3D20  
>> > not shared. Plus<BR>even with the Sata controllers activated, each  
>  
> =  
>  
>>of  
>> =3D  
>> >the=3D20  
>> > (4)eds cards had their<BR>own IRQ. However, 1 EDS card shared (IRQ  
>  
> =  
>  
>>16)  
>> =3D  
>> >with=3D20  
>> > the Matrox G450. Strange..  
>>=3D  
>> >latency=3D20  
>> > issues and download an app to look<BR>and change soem of the PCI =  
>>=3D  
>> >latency=3D20  
>> > settings. <BR><BR>The Sata controller had a setting of 0(zero). EDS  
>  
> =  
>  
>>=3D  
>> >scherzo=3D20  
>> > (32) matrox (64)..IDE<BR>controller (0)..<BR><BR>Thanks for your =  
>>help=3D20  
>> > ..LaMont<BR><BR><BR><BR> Ahris Ludwig <<A=3D20  
>> > =  
>>href=3D3D"mailto:chrisl@adkproaudio.com">chrisl@adkproaudio.com</A>>=3D20=  
>>  
>> > wrote:<BR>>HI Lamont,<BR>>Sorry to here your having =3D  
>> >trouble.<BR>>What=3D20  
>> > exact model of the Gigabyte board do you mean. The description=3D20  
>> > you<BR><BR>>have here is vague. Is it a K8NS Ultra=3D20  
>> > -939?<BR>><BR>>When you say you rebuilt do you mean you =3D  
>> >reinstalled=3D20  
>> > windows from scratch?<BR>><BR>><BR>>LaMont wrote:<BR>>> =3D



>> >Hi=3D20  
>> > gang:<BR>>> I 'm having problems getting Paris to ip and =3D  
>> >running. Paris=3D20  
>> > will sometimes<BR>>> star, only to just freeze up and crash the =3D  
>> >whole=3D20  
>> > system. So, I thought<BR>my<BR>>> Asus-Amd XP combo(with =3D  
>> >SATA-Firwire)=3D20  
>> > was cause too much IRQ problems for<BR>>> PAris.<BR>>>=3D20  
>> > <BR>>> So, I rebuilt with my favorite stable =3D  
>> >mobo(Gigabyte).<BR>>>=3D20  
>> > <BR>>> Here's the skinny: I just build a new Paris/Nuendo PC. =3D  
>> >Great very=3D20  
>> > very<BR>fast:<BR>>> Here are the configs:<BR>>> =3D  
>> ><BR>>>=3D20  
>> > -gigabyte mobo 939 Ultra250<BR>>> -Dual core opteron =3D  
>> >165<BR>>>=3D20  
>> > -2gig ddr400<BR>>> -sata (onboard) 3 300 gig drives<BR>>> =3D  
>> >-(1) RME=3D20  
>> > Digi 96 <BR>>> -(1)Magma card (4 card EDS) <BR>>> -Matrox=3D20  
>> > g450<BR>>> <BR>>> Well, Nuendo runs like a Deer!!! WOW.. =3D  
>> >But PAris=3D20  
>> > is hit and miss. I disabled:<BR>>> USB, SATA raid..A little =3D  
>> >better, but=3D20  
>> > I', starting to think that My either<BR>>> my EdS cards or =3D  
>> >Mec/442 are=3D20  
>> > the problem. Just 2 weeks prior, the system<BR>was<BR>>> working =  
>> >=3D  
>> >fine.=3D20  
>> > <BR>>> <BR>>> Note: In my studio I have a master power =3D  
>> >switch that=3D20  
>> > start up the FURman<BR>>> power unit..The Magama and Mec units =3D  
>> >were on=3D20  
>> > when I started up the system.<BR>>> Maybe PAris got a Jolt ??? I =  
>> >=3D  
>> >don;t=3D20  
>> > know..<BR>>> Please help..Thanks<BR>>>=3D20  
>> > <BR>><BR>><BR>><BR>><BR>>Chris<BR>><BR>>-- =3D  
>> ><BR>>Chris=3D20  
>> > Ludwig<BR>><BR>>ADK Pro Audio<BR>>(859)=3D20  
>> > =3D  
>> =  
>>  
>>>635-5762<BR>>www.adkproaudio.com<BR>>chrisl@adkproaudio.com<BR></BL=3D  
>>  
>> >OCKQUOTE></BODY></HTML>  
>> >  
>> >  
>>

```

>>
>><!DOCTYPE HTML PUBLIC "-//W3C//DTD HTML 4.0 Transitional//EN">
>><HTML><HEAD>
>><META http-equiv=3DContent-Type content=3D"text/html; =
>> charset=3Diso-8859-1">
>><META content=3D"MSHTML 6.00.2800.1400" name=3DGENERATOR>
>><STYLE></STYLE>
>></HEAD>
>><BODY bgColor=3D#ffffff>
>><DIV><FONT face=3DArial size=3D2>LM,</FONT></DIV>
>><DIV><FONT face=3DArial size=3D2>Can't wait to hear.</FONT></DIV>
>><DIV><FONT face=3DArial size=3D2>T.</FONT></DIV>
>><BLOCKQUOTE=20
>> style=3D"PADDING-RIGHT: 0px; PADDING-LEFT: 5px; MARGIN-LEFT: 5px; =
>> BORDER-LEFT: #000000 2px solid; MARGIN-RIGHT: 0px">
>> <DIV>"LaMont" <<A=20
>> href=3D"mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A>> =
>> wrote in=20
>> message <A =
>> href=3D"news:44052522@linux">news:44052522@linux</A>...</DIV><BR>HEY=20
>> Tom,<BR>I'm in the Prcess of moving th magma card to differnt =
>> slots..I'll let=20
>> you<BR>know what happens..<BR><BR>"Tom Bruhl" <<A=20
>> href=3D"mailto:arpegio@comcast.net">arpegio@comcast.net</A>>=20
>> wrote:<BR>><BR>><BR>>LaMont,<BR>>EDS1 with Matrox is a bad =
>>
>> thing. I'd try different slots within<BR>>the Magma to =
>> correct=20
>> that. Have you tried any other slots on<BR>>the mobo for the =
>> Magma=20
>> card? That might be the first thing unless<BR>>you know that =
>> won't=20
>> help.<BR>>Tom<BR>> "LaMont" <<A=20
>> href=3D"mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A>> =
>> wrote in=20
>> message =3D<BR>>news:4404e5bf$1@linux...<BR>><BR>> Hi=20
>> Chris,<BR>> Fresh install of win Xp/sp1. New drives, new =
>> everything.=20
>> I'm using =3D<BR>>Apci,<BR>> not Standard PC. Mother Board =
>>
>> GA-K8NSC-939<BR>> nforce-3 ultra 250gb.<BR>><BR>> =
>> -Maybe=20
>> moving the magma(13 slot) to a differnt slot.(It's currently=20
>> =3D<BR>>residing<BR>> in PCI slot 4. According to the =
>> manual, slot 4=20
>> and 2 are not shared. =3D<BR>>Plus<BR>> even with the Sata =
>>
>> controllers activated, each of the (4)eds cards=20

```

>> had<BR>=3D<BR>>their<BR>> own IRQ. However, 1 EDS card =  
>>shared (IRQ=20  
>> 16) with the Matrox G450. =3D<BR>>Strange..  
>>I've been=20  
>> looking into this PCI latency issues and download an app=20  
>> to<BR>=3D<BR>>look<BR>> and change soem of the PCI latency =  
>>  
>> settings.=3D20<BR>><BR>> The SATA controller had a setting =  
>>of=20  
>> 0(zero). EDS scherzo (32) matrox<BR>=3D<BR>>(64)..IDE<BR>> =  
>>  
>> controller (0)..<BR>><BR>> Thanks for your help=20  
>> ..LaMont<BR>><BR>><BR>><BR>> Ahris Ludwig =  
>><<A=20  
>> href=3D"mailto:chrisl@adkproaudio.com">chrisl@adkproaudio.com</A>=20  
>> wrote:<BR>> >HI Lamont,<BR>> >Sorry to here =  
>>your=20  
>> having trouble.<BR>> >What exact model of the Gigabyte =  
>>board do=20  
>> you mean. The description =3D<BR>>you<BR>><BR>> =  
>>  
>>>have here is=20  
>>  
>> vague. Is it a K8NS Ultra -939?<BR>> ><BR>> =  
>>  
>>>When you=20  
>>  
>> say you rebuilt do you mean you reinstalled windows from=20  
>> =3D<BR>>scratch?<BR>> ><BR>> =  
>>  
>>><BR>> =20  
>>  
>> >LaMont wrote:<BR>> >> Hi gang:<BR>> =  
>>  
>>>>I 'm=20  
>>  
>> having problems getting Paris to ip and running. Paris will=20  
>> =3D<BR>>>sometimes<BR>> >> star, only to just freeze =  
>>up and=20  
>> crash the whole system. So, I =3D<BR>>>thought<BR>> =  
>>my<BR>> =20  
>> >> Asus-Amd XP combo(with SATA-Firwire) was cause too much IRQ=20  
>> =3D<BR>>>problems for<BR>> >> PAris.<BR>> =20  
>> >>=3D20<BR>> >> So, I rebuilt with my favorite =  
>>stable=20  
>> mobo(Gigabyte).<BR>> >>=3D20<BR>> >> =  
>>Here's the=20  
>> skinny: I just build a new Paris/Nuendo PC. Great very=20

```

>> =3D<BR>>very<BR>> fast:<BR>> >> Here are =
>>the=20
>> configs:<BR>> >>=3D20<BR>> >> -gigabyte =
>>mobo 939=20
>> Ultra250<BR>> >> -Dual core opteron 165<BR>> =
>>
>>>=20
>>
>> -2gig ddr400<BR>> >> -sata (onboard) 3 300 gig=20
>> drives<BR>> >> -(1) RME Digi 96=3D20<BR>> =
>>
>>>=20
>>
>> -(1)Magma card (4 card EDS)=3D20<BR>> >> -Matrox=20
>> g450<BR>> >>=3D20<BR>> >> Well, Nuendo =
>>runs like a=20
>> Deer!!! WOW.. But PARis is hit and miss. =
>>I<BR>=3D<BR>>disabled:<BR>> =20
>> >> USB, SATA raid..A little better, but I', starting to think =
>>that=20
>> My<BR>=3D<BR>>either<BR>> >> my EdS cards or Mec/442 =
>>are the=20
>> problem. Just 2 weeks prior, the =3D<BR>>system<BR>> =20
>> was<BR>> >> working fine.=3D20<BR>> =20
>> >>=3D20<BR>> >> Note: In my studio I have a =
>>master power=20
>> switch that start up the =3D<BR>>Furman<BR>> >> =
>>power=20
>> unit..The Magma and Mec units were on when I started up=20
>> the<BR>=3D<BR>>system.<BR>> >> Maybe PARis got a =
>>Jolt ??? I=20
>> don;t know..<BR>> >> Please help..Thanks<BR>> =20
>> >>=3D20<BR>> ><BR>> ><BR>> =20
>> ><BR>> ><BR>> >Chris<BR>> =20
>> ><BR>> >--=3D20<BR>> >Chris =
>>Ludwig<BR>> =20
>> ><BR>> >ADK Pro Audio<BR>> >(859)=20
>> 635-5762<BR>> >www.adkproaudio.com<BR>> =20
>> >chrisl@adkproaudio.com<BR>><BR>><BR>><BR>><!DOCTYPE HTML =
>>PUBLIC=20
>> "-//W3C//DTD HTML 4.0=20
>> Transitional//EN"><BR>><HTML><HEAD><BR>><META=20
>> http-equiv=3D3DContent-Type content=3D3D"text/html";=20
>> =3D<BR>>charset=3D3Diso-8859-1"><BR>><META =
>>content=3D3D"MSHTML=20
>> 6.00.2800.1400"=20
>> =
>>name=3D3DGENERATOR><BR>><STYLE></STYLE><BR>></HEA=

```

```

>>D><BR>><BODY=20
>> bgColor=3D3D#ffffff><BR>><DIV><FONT face=3D3DArial=20
>> =
>>size=3D3D2>LaMont,</FONT></DIV><BR>><DIV><FONT=
>>=20
>> face=3D3DArial size=3D3D2>EDS1 with Matrox is a bad thing. =
>>=3D<BR>>l'd=20
>> try=3D20<BR>>different slots=20
>> within</FONT></DIV><BR>><DIV><FONT =
>>face=3D3DArial=20
>> size=3D3D2>the Magma to correct that. Have =3D<BR>>you tried=20
>> any=3D20<BR>>other slots=20
>> on</FONT></DIV><BR>><DIV><FONT face=3D3DArial=20
>> size=3D3D2>the mobo for the Magma card? That =3D<BR>>might =
>>be=3D20<BR>>the=20
>> first thing unless</FONT></DIV><BR>><DIV><FONT =
>>
>> face=3D3DArial size=3D3D2>you know that won't=20
>> help.</FONT></DIV><BR>><DIV><FONT =
>>face=3D3DArial=20
>> =
>>size=3D3D2>Tom</FONT></DIV><BR>><BLOCKQUOTE=3D20<BR>=
>>
>>>style=3D3D"PADDING-RIGHT:=20
>>
>> 0px; PADDING-LEFT: 5px; MARGIN-LEFT: 5px; =3D<BR>>BORDER-LEFT: =
>>#000000 2px=20
>> solid; MARGIN-RIGHT: 0px"><BR>> <DIV>"LaMont"=20
>> <<A=3D20<BR>> href=3D3D"<A=20
>> =
>>href=3D'mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A'>mailto:jjdp=
>>ro@ameritech.net">jjdpro@ameritech.net</A</A>>>=20
>> =3D<BR>>wrote in=3D20<BR>> message =
>><A=3D20<BR>> =20
>> =3D<BR>>href=3D3D"<A=20
>> =
>>href=3D'news:4404e5bf$1@linux">news:4404e5bf$1@linux</A>...</DIV><BR>Hi=3D=
>>20'>news:4404e5bf$1@linux">news:4404e5bf$1@linux</A>...</DIV&=
>>gt;<BR>Hi=3D20</A><BR>> =20
>> Chris,<BR>Fresh install of win Xp/sp1. New drives, new =
>>everything.=20
>> I'm<BR>=3D<BR>>using=3D20<BR>> Apci,<BR>not Standard =
>>PC. Mother=20
>> Board GA-K8NSC-939<BR>nforce-3 ultra=3D20<BR>> =20
>> 250gb.<BR><BR>-Maybe moving the magma(13 slot) to a =
>>different=20
>> =3D<BR>>slot.(It's=3D20<BR>> currently =
>>residing<BR>in PCI slot=20

```

>> 4. According to the manual, slot 4 =3D<BR>>and 2 =  
>>are=3D20<BR>> not=20  
>> shared. Plus<BR>even with the Sata controllers activated, each=20  
>> of<BR>=3D<BR>>the=3D20<BR>> (4)eds cards had =  
>>their<BR>own IRQ.=20  
>> However, 1 EDS card shared (IRQ =  
>>16)<BR>=3D<BR>>with=3D20<BR>> the=20  
>> Matrox G450. Strange..<BR><BR>I've been looking into this =  
>>PCI=20  
>> =3D<BR>>latency=3D20<BR>> issues and download an app to=20  
>> look<BR>and change soem of the PCI =  
>>=3D<BR>>latency=3D20<BR>> =20  
>> settings. <BR><BR>The Sata controller had a setting of =  
>>0(zero).=20  
>> EDS =3D<BR>>scherzo=3D20<BR>> (32) matrox=20  
>> (64)..IDE<BR>controller (0)..<BR><BR>Thanks for your =  
>>  
>> help=3D20<BR>> =  
>>..LaMont<BR><BR><BR><BR> Ahris=20  
>> Ludwig <<A=3D20<BR>> href=3D3D"<A=20  
>> =  
>>href=3D'mailto:chrisl@adkproaudio.com">chrisl@adkproaudio.com</A>=>=3D20'>=  
>>mailto:chrisl@adkproaudio.com">chrisl@adkproaudio.com</A>=>=3D=  
>>20</A><BR>> =20  
>> wrote:<BR>>HI Lamont,<BR>>Sorry to here your having=20  
>> =3D<BR>>trouble.<BR>>What=3D20<BR>> exact model =  
>>of the=20  
>> Gigabyte board do you mean. The description=3D20<BR>> =20  
>> you<BR><BR>>have here is vague. Is it a K8NS=20  
>> Ultra=3D20<BR>> -939?<BR>><BR>>When you say =  
>>you=20  
>> rebuilt do you mean you =3D<BR>>reinstalled=3D20<BR>> =  
>>windows from=20  
>> scratch?<BR>><BR>><BR>>LaMont=20  
>> wrote:<BR>>> =3D<BR>>Hi=3D20<BR>> =  
>>gang:<BR>>>=20  
>> I 'm having problems getting Paris to ip and =3D<BR>>running.=20  
>> Paris=3D20<BR>> will sometimes<BR>>> star, only =  
>>to just=20  
>> freeze up and crash the =3D<BR>>whole=3D20<BR>> system. =  
>>So, I=20  
>> thought<BR>my<BR>>> Asus-Amd XP combo(with=20  
>> =3D<BR>>SATA-Firwire)=3D20<BR>> was cause too much IRQ =  
>>problems=20  
>> for<BR>>> PAris.<BR>>>=3D20<BR>> =20  
>> <BR>>> So, I rebuilt with my favorite stable=20  
>> =3D<BR>>mobo(Gigabyte).<BR>>>=3D20<BR>> =  
>><BR>>>=20

>> Here's the skinny: I just build a new Paris/Nuendo PC. =  
>>=3D<BR>>Great=20  
>> very=3D20<BR>> very<BR>fast:<BR>>> Here are =  
>>the=20  
>> configs:<BR>>> =  
>>=3D<BR>><BR>>>=3D20<BR>> =20  
>> -gigabyte mobo 939 Ultra250<BR>>> -Dual core opteron=20  
>> =3D<BR>>165<BR>>>=3D20<BR>> -2gig =  
>>ddr400<BR>>>=20  
>> -sata (onboard) 3 300 gig drives<BR>>> =3D<BR>>-(1)=20  
>> RME=3D20<BR>> Digi 96 <BR>>> -(1)Magma card (4 =  
>>card EDS)=20  
>> <BR>>> -Matrox=3D20<BR>> g450<BR>>>=20  
>> <BR>>> Well, Nuendo runs like a Deer!!! WOW.. =  
>>=3D<BR>>But=20  
>> PAris=3D20<BR>> is hit and miss. I =  
>>disabled:<BR>>> USB,=20  
>> SATA raid..A little =3D<BR>>better, but=3D20<BR>> 'I', =  
>>starting to=20  
>> think that My either<BR>>> my EdS cards or =  
>>=3D<BR>>Mec/442=20  
>> are=3D20<BR>> the problem. Just 2 weeks prior, the=20  
>> system<BR>was<BR>>> working =  
>>=3D<BR>>fine.=3D20<BR>> =20  
>> <BR>>> <BR>>> Note: In my studio I have a =  
>>master power=20  
>> =3D<BR>>switch that=3D20<BR>> start up the =  
>>FUrman<BR>>>=20  
>> power unit..The Magama and Mec units =3D<BR>>were =  
>>on=3D20<BR>> when I=20  
>> started up the system.<BR>>> Maybe PAris got a Jolt ??? I=20  
>> =3D<BR>>don;t=3D20<BR>> know..<BR>>> Please=20  
>> help..Thanks<BR>>>=3D20<BR>> =20  
>> =  
>><BR>><BR>><BR>><BR>><BR>><BR>>Chr=  
>>is<BR>><BR>>---=20  
>> =3D<BR>><BR>>Chris=3D20<BR>> =20  
>> Ludwig<BR>><BR>>ADK Pro=20  
>> Audio<BR>>(859)=3D20<BR>> =20  
>> =  
>>=3D<BR>>635-5762<BR>>www.adkproaudio.com<BR>>chrisI@=  
>>adkproaudio.com<BR></BL=3D<BR>>OCKQUOTE></BODY></=  
>>HTML><BR>><BR>><BR></BLOCKQUOTE></BODY></HTML>  
>>  
>>  
>

Chris Ludwig  
ADK  
chrisl@adkproaudio.com <mailto:chrisl@adkproaudio.com>  
www.adkproaudio.com <http://www.adkproaudio.com/>  
(859) 635-5762

---

---

Subject: Re: Paris Problems on new machine: HELP!!!!  
Posted by [LaMont](#) on Wed, 01 Mar 2006 15:10:45 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Tom & Chris,

I got it solved. It was the Magma Chasis's power supply was not "seated" into slot properly. Paris is working fine now.  
Thanks

"Tom Bruhl" <arpeggio@comcast.net> wrote:

>  
>  
>LM,  
>Can't wait to hear.  
>T.  
> "LaMont" <jjdpro@ameritech.net> wrote in message =  
>news:44052522@linux...  
>  
> HEY Tom,  
> I'm in the Prcess of moving th magma card to differnt slots..I'll let  
=  
>you  
> know what happens..  
>  
> "Tom Bruhl" <arpeggio@comcast.net> wrote:  
> >  
> >  
> >LaMont,  
> >EDS1 with Matrox is a bad thing. I'd try different slots within  
> >the Magma to correct that. Have you tried any other slots on  
> >the mobo for the Magma card? That might be the first thing unless  
> >you know that won't help.  
> >Tom  
> > "LaMont" <jjdpro@ameritech.net> wrote in message =3D  
> >news:4404e5bf\$1@linux...  
> >  
> > Hi Chris,  
> > Fresh install of win Xp/sp1. New drives, new everything. I'm using  
=  
>=3D



> >Apci,  
> > not Standard PC. Mother Board GA-K8NSC-939  
> > nforce-3 ultra 250gb.  
> >  
> > -Maybe moving the magma(13 slot) to a differnt slot.(It's currently  
=  
>=3D  
> >residing  
> > in PCI slot 4. According to the manual, slot 4 and 2 are not =  
>shared. =3D  
> >Plus  
> > even with the Sata controllers activated, each of the (4)eds cards  
=  
>had  
> =3D  
> >their  
> > own IRQ. However, 1 EDS card shared (IRQ 16) with the Matrox G450.  
=  
>=3D  
> >Strange..  
> >  
> > I've been looking into this PCI latency issues and download an app  
=  
>to  
> =3D  
> >look  
> > and change soem of the PCI latency settings.=3D20  
> >  
> > The Sata controller had a setting of 0(zero). EDS scherzo (32) =  
>matrox  
> =3D  
> >(64)..IDE  
> > controller (0)..  
> >  
> > Thanks for your help ..LaMont  
> >  
> >  
> >  
> > Ahris Ludwig <chrisl@adkproaudio.com> wrote:  
> > >Hi Lamont,  
> > >Sorry to here your having trouble.  
> > >What exact model of the Gigabyte board do you mean. The =  
>description =3D  
> >you  
> >  
> > >have here is vague. Is it a K8NS Ultra -939?  
> > >  
> > >When you say you rebuilt do you mean you reinstalled windows from

=  
>=3D  
> >scratch?  
> > >  
> > >  
> > >LaMont wrote:  
> > >> Hi gang:  
> > >> I 'm having problems getting Paris to ip and running. Paris will  
=  
>=3D  
> >sometimes  
> > >> star, only to just freeze up and crash the whole system. So, I =  
>=3D  
> >thought  
> > my  
> > >> Asus-Amd XP combo(with SATA-Firwire) was cause too much IRQ =3D  
> >problems for  
> > >> PAris.  
> > >>=3D20  
> > >> So, I rebuilt with my favorite stable mobo(Gigabyte).  
> > >>=3D20  
> > >> Here's the skinny: I just build a new Paris/Nuendo PC. Great =  
>very =3D  
> >very  
> > fast:  
> > >> Here are the configs:  
> > >>=3D20  
> > >> -gigabyte mobo 939 Ultra250  
> > >> -Dual core opteron 165  
> > >> -2gig ddr400  
> > >> -sata (onboard) 3 300 gig drives  
> > >> -(1) RME Digi 96=3D20  
> > >> -(1)Magma card (4 card EDS)=3D20  
> > >> -Matrox g450  
> > >>=3D20  
> > >> Well, Nuendo runs like a Deer!!! WOW.. But PAris is hit and =  
>miss. I  
> =3D  
> >disabled:  
> > >> USB, SATA raid..A little better, but I', starting to think that  
=  
>My  
> =3D  
> >either  
> > >> my EdS cards or Mec/442 are the problem. Just 2 weeks prior, the  
=  
>=3D  
> >system

> > was  
 > > >> working fine.=3D20  
 > > >>=3D20  
 > > >> Note: In my studio I have a master power switch that start up =  
 >the =3D  
 > >Furman  
 > > >> power unit..The Magama and Mec units were on when I started up =  
 >the  
 > =3D  
 > >system.  
 > > >> Maybe PAris got a Jolt ??? I don;t know..  
 > > >> Please help..Thanks  
 > > >>=3D20  
 > > >  
 > > >  
 > > >  
 > > >  
 > > >Chris  
 > > >  
 > > >--=3D20  
 > > >Chris Ludwig  
 > > >  
 > > >ADK Pro Audio  
 > > >(859) 635-5762  
 > > >www.adkproaudio.com  
 > > >chrisl@adkproaudio.com  
 > >  
 > >  
 > ><!DOCTYPE HTML PUBLIC "-//W3C//DTD HTML 4.0 Transitional//EN">  
 > ><HTML><HEAD>  
 > ><META http-equiv=3D3DContent-Type content=3D3D"text/html; =3D  
 > >charset=3D3Diso-8859-1">  
 > ><META content=3D3D"MSHTML 6.00.2800.1400" name=3D3DGENERATOR>  
 > ><STYLE></STYLE>  
 > ></HEAD>  
 > ><BODY bgColor=3D3D#ffffff>  
 > ><DIV><FONT face=3D3DArial size=3D3D2>LaMont,</FONT></DIV>  
 > ><DIV><FONT face=3D3DArial size=3D3D2>EDS1 with Matrox is a bad thing.  
 =  
 >=3D  
 > >I'd try=3D20  
 > >different slots within</FONT></DIV>  
 > ><DIV><FONT face=3D3DArial size=3D3D2>the Magma to correct that. Have  
 =  
 >=3D  
 > >you tried any=3D20  
 > >other slots on</FONT></DIV>  
 > ><DIV><FONT face=3D3DArial size=3D3D2>the mobo for the Magma card? =

```

>That =3D
> >might be=3D20
> >the first thing unless</FONT></DIV>
> ><DIV><FONT face=3D3DArial size=3D3D2>you know that won't =
>help.</FONT></DIV>
> ><DIV><FONT face=3D3DArial size=3D3D2>Tom</FONT></DIV>
> ><BLOCKQUOTE=3D20
> >style=3D3D"PADDING-RIGHT: 0px; PADDING-LEFT: 5px; MARGIN-LEFT: 5px; =
>=3D
> >BORDER-LEFT: #000000 2px solid; MARGIN-RIGHT: 0px">
> > <DIV>"LaMont" <<A=3D20
> > href=3D3D"mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A>> =
>=3D
> >wrote in=3D20
> > message <A=3D20
> > =3D
> =
>>href=3D3D"news:4404e5bf$1@linux">news:4404e5bf$1@linux</A>...</DIV><BR>H=
>i=3D20
> > Chris,<BR>Fresh install of win Xp/sp1. New drives, new everything.
=
>I'm
> =3D
> >using=3D20
> > Apci,<BR>not Standard PC. Mother Board GA-K8NSC-939<BR>nforce-3 =
>ultra=3D20
> > 250gb.<BR><BR>-Maybe moving the magma(13 slot) to a differnt =3D
> >slot.(It's=3D20
> > currently residing<BR>in PCI slot 4. According to the manual, slot
=
>4 =3D
> >and 2 are=3D20
> > not shared. Plus<BR>even with the Sata controllers activated, each
=
>of
> =3D
> >the=3D20
> > (4)eds cards had their<BR>own IRQ. However, 1 EDS card shared (IRQ
=
>16)
> =3D
> >with=3D20
> > the Matrox G450. Strange..<BR><BR>I've been looking into this PCI =
>=3D
> >latency=3D20
> > issues and download an app to look<BR>and change soem of the PCI =
>=3D
> >latency=3D20

```

> > settings. <BR><BR>The Sata controller had a setting of 0(zero). EDS  
 =  
 >=3D  
 > >scherzo=3D20  
 > > (32) matrox (64)..IDE<BR>controller (0)..<BR><BR>Thanks for your =  
 >help=3D20  
 > > ..LaMont<BR><BR><BR><BR> Ahris Ludwig <<A=3D20  
 > > =  
 >href=3D3D"mailto:chrisl@adkproaudio.com">chrisl@adkproaudio.com</A>=3D20=  
 >  
 > > wrote:<BR>>HI Lamont,<BR>>Sorry to here your having =3D  
 > >trouble.<BR>>What=3D20  
 > > exact model of the Gigabyte board do you mean. The description=3D20  
 > > you<BR><BR>>have here is vague. Is it a K8NS Ultra=3D20  
 > > -939?<BR>><BR>>When you say you rebuilt do you mean you =3D  
 > >reinstalled=3D20  
 > > windows from scratch?<BR>><BR>><BR>>LaMont wrote:<BR>>> =3D  
 > >Hi=3D20  
 > > gang:<BR>>> I 'm having problems getting Paris to ip and =3D  
 > >running. Paris=3D20  
 > > will sometimes<BR>>> star, only to just freeze up and crash the =3D  
 > >whole=3D20  
 > > system. So, I thought<BR>my<BR>>> Asus-Amd XP combo(with =3D  
 > >SATA-Firwire)=3D20  
 > > was cause too much IRQ problems for<BR>>> PAris.<BR>>>=3D20  
 > > <BR>>> So, I rebuilt with my favorite stable =3D  
 > >mobo(Gigabyte).<BR>>>=3D20  
 > > <BR>>> Here's the skinny: I just build a new Paris/Nuendo PC. =3D  
 > >Great very=3D20  
 > > very<BR>fast:<BR>>> Here are the configs:<BR>>> =3D  
 > ><BR>>>=3D20  
 > > -gigabyte mobo 939 Ultra250<BR>>> -Dual core opteron =3D  
 > >165<BR>>>=3D20  
 > > -2gig ddr400<BR>>> -sata (onboard) 3 300 gig drives<BR>>> =3D  
 > >-(1) RME=3D20  
 > > Digi 96 <BR>>> -(1)Magma card (4 card EDS) <BR>>> -Matrox=3D20  
 > > g450<BR>>> <BR>>> Well, Nuendo runs like a Deer!!! WOW.. =3D  
 > >But PAris=3D20  
 > > is hit and miss. I disabled:<BR>>> USB, SATA raid..A little =3D  
 > >better, but=3D20  
 > > I', starting to think that My either<BR>>> my EdS cards or =3D  
 > >Mec/442 are=3D20  
 > > the problem. Just 2 weeks prior, the system<BR>was<BR>>> working =  
 > >=3D  
 > >fine.=3D20  
 > > <BR>>> <BR>>> Note: In my studio I have a master power =3D  
 > >switch that=3D20  
 > > start up the FUrman<BR>>> power unit..The Magama and Mec units =3D

```

> >were on=3D20
> > when I started up the system.<BR>>> Maybe PAris got a Jolt ??? I =
>=3D
> >don;t=3D20
> > know..<BR>>> Please help..Thanks<BR>>>=3D20
> > <BR>><BR>><BR>><BR>><BR>>Chris<BR>><BR>>-- =3D
> ><BR>>Chris=3D20
> > Ludwig<BR>><BR>>ADK Pro Audio<BR>>(859)=3D20
> > =3D
> =
>>635-5762<BR>>www.adkproaudio.com<BR>>chrisl@adkproaudio.com<BR></BL=3D
> >OCKQUOTE></BODY></HTML>
> >
> >
>
>
><!DOCTYPE HTML PUBLIC "-//W3C//DTD HTML 4.0 Transitional//EN">
><HTML><HEAD>
><META http-equiv=3DContent-Type content=3D"text/html; =
>charset=3Diso-8859-1">
><META content=3D"MSHTML 6.00.2800.1400" name=3DGENERATOR>
><STYLE></STYLE>
></HEAD>
><BODY bgColor=3D#ffffff>
><DIV><FONT face=3DArial size=3D2>LM,</FONT></DIV>
><DIV><FONT face=3DArial size=3D2>Can't wait to hear.</FONT></DIV>
><DIV><FONT face=3DArial size=3D2>T.</FONT></DIV>
><BLOCKQUOTE=20
>style=3D"PADDING-RIGHT: 0px; PADDING-LEFT: 5px; MARGIN-LEFT: 5px; =
>BORDER-LEFT: #000000 2px solid; MARGIN-RIGHT: 0px">
> <DIV>"LaMont" <<A=20
> href=3D"mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A>> =
>wrote in=20
> message <A =
>href=3D"news:44052522@linux">news:44052522@linux</A>...</DIV><BR>HEY=20
> Tom,<BR>I'm in the Prcess of moving th magma card to differnt =
>slots..I'll let=20
> you<BR>know what happens..<BR><BR>"Tom Bruhl" <<A=20
> href=3D"mailto:arpegio@comcast.net">arpegio@comcast.net</A>>=20
> wrote:<BR>><BR>><BR>>LaMont,<BR>>EDS1 with Matrox is a bad =
>
>
>correct=20
>Magma=20
>won't=20

```

> href="mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A>> =  
>wrote in=20

>everything.=20

>

>-Maybe=20

> moving the magma(13 slot) to a differnt slot.(It's currently=20

>manual, slot 4=20

>

> controllers activated, each of the (4)eds cards=20

>shared (IRQ=20

>I've been=20

> looking into this PCI latency issues and download an app=20

>

>of=20

>

><<A=20

> href="mailto:chrisl@adkproaudio.com">chrisl@adkproaudio.com</A>>=20

>your=20

>board do=20

>>have here is=20

>>When you=20

> say you rebuilt do you mean you reinstalled windows from=20

>>> I 'm=20

> having problems getting Paris to ip and running. Paris will=20

>up and=20

> >> Asus-Amd XP combo(with SATA-Firwire) was cause too much IRQ=20

>stable=20

>Here's the=20

> skinny: I just build a new Paris/Nuendo PC. Great very=20

>the=20

>mobo 939=20

>>>=20

>>>=20

>runs like a=20

> Deer!!! WOW.. But PARIS is hit and miss. =

> >> USB, SATA raid..A little better, but I', starting to think =

>that=20

>are the=20

>master power=20

>power=20

> unit..The Magama and Mec units were on when I started up=20

>Jolt ??? I=20

> >chrisl@adkproaudio.com<BR>><BR>><BR>><!DOCTYPE HTML =

>PUBLIC=20

> "-//W3C//DTD HTML 4.0=20

> Transitional//EN"><BR>><HTML><HEAD><BR>><META=20

> http-equiv=3D3DContent-Type content=3D3D"text/html;=20

> =3D<BR>>charset=3D3Diso-8859-1"><BR>><META =

>content=3D3D"MSHTML=20



```

> 6.00.2800.1400"=20
> =
>name=3D3DGENERATOR><BR>><STYLE></STYLE><BR>></HEA=
>D><BR>><BODY=20
> bgColor=3D3D#ffffff><BR>><DIV><FONT face=3D3DArial=20
> =
>size=3D3D2>LaMont,</FONT></DIV><BR>><DIV><FONT=
>=20
> face=3D3DArial size=3D3D2>EDS1 with Matrox is a bad thing. =
>=3D<BR>>'I'd=20
> try=3D20<BR>>different slots=20
> within</FONT></DIV><BR>><DIV><FONT =
>face=3D3DArial=20
> size=3D3D2>the Magma to correct that. Have =3D<BR>>you tried=20
> any=3D20<BR>>other slots=20
> on</FONT></DIV><BR>><DIV><FONT face=3D3DArial=20
> size=3D3D2>the mobo for the Magma card? That =3D<BR>>might =
>be=3D20<BR>>the=20
> first thing unless</FONT></DIV><BR>><DIV><FONT =
>
> face=3D3DArial size=3D3D2>you know that won't=20
> help.</FONT></DIV><BR>><DIV><FONT =
>face=3D3DArial=20
> =
>size=3D3D2>Tom</FONT></DIV><BR>><BLOCKQUOTE=3D20<BR>=
>>style=3D3D"PADDING-RIGHT:=20
> 0px; PADDING-LEFT: 5px; MARGIN-LEFT: 5px; =3D<BR>>BORDER-LEFT: =
>#000000 2px=20

> =
>href=3D'mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A'>mailto:jjdp=
>ro@ameritech.net">jjdpro@ameritech.net</A</A>>>=20

> =3D<BR>>href=3D3D"<A=20
> =
>href=3D'news:4404e5bf$1 @linux">news:4404e5bf$1 @linux</A>...</DIV>><BR>Hi=3D=
>20'>news:4404e5bf$1 @linux">news:4404e5bf$1 @linux</A>...</DIV&=

> Chris,<BR>Fresh install of win Xp/sp1. New drives, new =
>everything.=20

>PC. Mother=20

> 250gb.<BR><BR>-Maybe moving the magma(13 slot) to a =
>differnt=20

```

>residing<BR>in PCI slot=20  
> 4. According to the manual, slot 4 =3D<BR>>and 2 =  
> shared. Plus<BR>even with the Sata controllers activated, each=20  
>their<BR>own IRQ.=20  
> However, 1 EDS card shared (IRQ =  
> Matrox G450. Strange..  
>>I've been looking into this =  
>PCI=20  
> look<BR>and change soem of the PCI =  
> settings. <BR><BR>The Sata controller had a setting of =  
>0(zero).=20  
> (64)..IDE<BR>controller (0)..<BR><BR>Thanks for your =  
>  
>..LaMont<BR><BR><BR><BR> Ahris=20  
> =  
><mailto:chrisl@adkproaudio.com></A>=3D20'>=  
><mailto:chrisl@adkproaudio.com></A>=3D=  
> wrote:<BR>>HI Lamont,<BR>>Sorry to here your having=20  
>of the=20  
> you<BR><BR>>have here is vague. Is it a K8NS=20  
>you=20  
>windows from=20  
> scratch?<BR>><BR>><BR>>LaMont=20  
>gang:<BR>>>=20  
> I 'm having problems getting Paris to ip and =3D<BR>>running.=20  
>to just=20  
>So, I=20  
> thought<BR>my<BR>>> Asus-Amd XP combo(with=20  
>problems=20  
> <BR>>> So, I rebuilt with my favorite stable=20

><BR>>>=20  
> Here's the skinny: I just build a new Paris/Nuendo PC. =  
>=3D<BR>>>Great=20

>the=20  
> configs:<BR>>> =

> -gigabyte mobo 939 Ultra250<BR>>> -Dual core opteron=20  
>ddr400<BR>>>=20  
> -sata (onboard) 3 300 gig drives<BR>>> =3D<BR>>>-(1)=20

>card EDS)=20

> <BR>>> Well, Nuendo runs like a Deer!!! WOW.. =  
>=3D<BR>>>But=20

>disabled:<BR>>> USB,=20

>starting to=20  
> think that My either<BR>>> my EdS cards or =  
>=3D<BR>>>Mec/442=20

> system<BR>was<BR>>> working =

> <BR>>> <BR>>> Note: In my studio I have a =  
>master power=20

>FUrman<BR>>>=20  
> power unit..The Magama and Mec units =3D<BR>>>were =

> started up the system.<BR>>> Maybe PARis got a Jolt ??? I=20

> =  
><BR>><BR>><BR>><BR>><BR>><BR>>Chr=  
>is<BR>><BR>>--=20

> Ludwig<BR>><BR>>ADK Pro=20

> =  
>=3D<BR>>>635-5762<BR>>>www.adkproaudio.com<BR>>>chrisl@=  
>adkproaudio.com<BR></BL=3D<BR>>>OOCKQUOTE></BODY></=  
>HTML><BR>><BR>><BR></BLOCKQUOTE></BODY></HTML>  
>  
>

---

---

Subject: Re: Paris Problems on new machine: HELP!!!!  
Posted by [Tom Bruhl](#) on Wed, 01 Mar 2006 15:16:57 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

This is a multi-part message in MIME format.

-----=\_NextPart\_000\_0029\_01C63D19.45777050  
Content-Type: text/plain;  
charset="iso-8859-1"  
Content-Transfer-Encoding: quoted-printable

LaMont,  
I'm glad it was that easy!  
Tom  
"Chris Ludwig" <[chrisl@adkproaudio.com](mailto:chrisl@adkproaudio.com)> wrote in message =  
news:4405b024@linux...  
Hi Lamont,  
Wow weird stuff. Glad its working now.

Chris

LaMont wrote:  
> Tom & Chris,  
>=20  
> I got it solved. It was the Magma Chasis's power supply was not =  
"seated"  
> into slot properly. Paris is working fine now.  
> Thanks  
>=20  
> "Tom Bruhl" <[arpeggio@comcast.net](mailto:arpeggio@comcast.net)> wrote:  
>=20  
>>  
>>LM,  
>>Can't wait to hear.  
>>T.  
>> "LaMont" <[jjdpro@ameritech.net](mailto:jjdpro@ameritech.net)> wrote in message =3D  
>>news:44052522@linux...  
>>  
>> HEY Tom,  
>> I'm in the Prcess of moving th magma card to differnt slots..I'll =  
let  
>=20  
> =3D  
>=20  
>>you  
>> know what happens..  
>>  
>> "Tom Bruhl" <[arpeggio@comcast.net](mailto:arpeggio@comcast.net)> wrote:

>> >  
>> >  
>> >LaMont,  
>> >EDS1 with Matrox is a bad thing. I'd try different slots within  
>> >the Magma to correct that. Have you tried any other slots on  
>> >the mobo for the Magma card? That might be the first thing unless  
>> >you know that won't help.  
>> >Tom  
>> > "LaMont" <jjdpro@ameritech.net> wrote in message =3D3D  
>> >news:4404e5bf\$1@linux...  
>> >  
>> > Hi Chris,  
>> > Fresh install of win Xp/sp1. New drives, new everything. I'm =  
using  
>=20  
> =3D  
>=20  
>>=3D3D  
>> >Apci,  
>> > not Standard PC. Mother Board GA-K8NSC-939  
>> > nforce-3 ultra 250gb.  
>> >  
>> > -Maybe moving the magma(13 slot) to a differnt slot.(It's =  
currently  
>=20  
> =3D  
>=20  
>>=3D3D  
>> >residing  
>> > in PCI slot 4. According to the manual, slot 4 and 2 are not =3D  
>>>shared. =3D3D  
>> >Plus  
>> > even with the Sata controllers activated, each of the (4)eds =  
cards  
>=20  
> =3D  
>=20  
>>had  
>> =3D3D  
>> >their  
>> > own IRQ. However, 1 EDS card shared (IRQ 16) with the Matrox =  
G450.  
>=20  
> =3D  
>=20  
>>=3D3D  
>> >Strange..  
>> >

>> > I've been looking into this PCI latency issues and download an =  
app  
>=20  
> =3D  
>=20  
>>to  
>> =3D3D  
>> >look  
>> > and change soem of the PCI latency settings.=3D3D20  
>> >  
>> > The Sata controller had a setting of 0(zero). EDS scherzo (32) =  
=3D  
>>matrox  
>> =3D3D  
>> >(64)..IDE  
>> > controller (0)..  
>> >  
>> > Thanks for your help ..LaMont  
>> >  
>> >  
>> >  
>> > Ahris Ludwig <chrisl@adkproaudio.com> wrote:  
>> > >HI Lamont,  
>> > >Sorry to here your having trouble.  
>> > >What exact model of the Gigabyte board do you mean. The =3D  
>>description =3D3D  
>> >you  
>> >  
>> > >have here is vague. Is it a K8NS Ultra -939?  
>> > >  
>> > >When you say you rebuilt do you mean you reinstalled windows =  
from  
>=20  
> =3D  
>=20  
>>=3D3D  
>> >scratch?  
>> > >  
>> > >  
>> > >LaMont wrote:  
>> > >> Hi gang:  
>> > >> I 'm having problems getting Paris to ip and running. Paris =  
will  
>=20  
> =3D  
>=20  
>>=3D3D  
>> >sometimes

>> >> star, only to just freeze up and crash the whole system. So, =  
 I =3D  
 >>=3D3D  
 >> >thought  
 >> > my  
 >> >> Asus-Amd XP combo(with SATA-Firwire) was cause too much IRQ =  
 =3D3D  
 >> >problems for  
 >> >> PAris.  
 >> >>=3D3D20  
 >> >> So, I rebuilt with my favorite stable mobo(Gigabyte).  
 >> >>=3D3D20  
 >> >> Here's the skinny: I just build a new Paris/Nuendo PC. Great =  
 =3D  
 >>very =3D3D  
 >> >very  
 >> > fast:  
 >> >> Here are the configs:  
 >> >>=3D3D20  
 >> >> -gigabyte mobo 939 Ultra250  
 >> >> -Dual core opteron 165  
 >> >> -2gig ddr400  
 >> >> -sata (onboard) 3 300 gig drives  
 >> >> -(1) RME Digi 96=3D3D20  
 >> >> -(1)Magma card (4 card EDS)=3D3D20  
 >> >> -Matrox g450  
 >> >>=3D3D20  
 >> >> Well, Nuendo runs like a Deer!!! WOW.. But PAris is hit and =  
 =3D  
 >>miss. I  
 >> =3D3D  
 >> >disabled:  
 >> >> USB, SATA raid..A little better, but I', starting to think =  
 that  
 >=20  
 > =3D  
 >=20  
 >>My  
 >> =3D3D  
 >> >either  
 >> >> my EdS cards or Mec/442 are the problem. Just 2 weeks prior, =  
 the  
 >=20  
 > =3D  
 >=20  
 >>=3D3D  
 >> >system  
 >> > was

>> > > working fine.=3D3D20  
>> > >=3D3D20  
>> > > Note: In my studio I have a master power switch that start up =  
=3D  
>>the =3D3D  
>> >Furman  
>> > > power unit..The Magama and Mec units were on when I started =  
up =3D  
>>the  
>> =3D3D  
>> >system.  
>> > > Maybe PAris got a Jolt ??? I don;t know..  
>> > > Please help..Thanks  
>> > >=3D3D20  
>> > >  
>> > >  
>> > >  
>> > >  
>> > >Chris  
>> > >  
>> > >=3D3D20  
>> > >Chris Ludwig  
>> > >  
>> > >ADK Pro Audio  
>> > >(859) 635-5762  
>> > >www.adkproaudio.com  
>> > >chrisl@adkproaudio.com  
>> >  
>> >  
>> ><!DOCTYPE HTML PUBLIC "-//W3C//DTD HTML 4.0 Transitional//EN">  
>> ><HTML><HEAD>  
>> ><META http-equiv=3D3D3DContent-Type content=3D3D3D"text/html; =  
=3D3D  
>> > charset=3D3D3Diso-8859-1">  
>> ><META content=3D3D3D"MSHTML 6.00.2800.1400" name=3D3D3DGENERATOR>  
>> ><STYLE></STYLE>  
>> ></HEAD>  
>> ><BODY bgColor=3D3D3D#ffffff>  
>> ><DIV><FONT face=3D3D3DArial size=3D3D3D2>LaMont,</FONT></DIV>  
>> ><DIV><FONT face=3D3D3DArial size=3D3D3D2>EDS1 with Matrox is a bad =  
thing.  
>=20  
> =3D  
>=20  
>>=3D3D  
>> >I'd try=3D3D20  
>> >different slots within</FONT></DIV>  
>> ><DIV><FONT face=3D3D3DArial size=3D3D3D2>the Magma to correct =



that. Have

```
>=20
> =3D
>=20
>>=3D3D
>> >you tried any=3D3D20
>> >other slots on</FONT></DIV>
>> ><DIV><FONT face=3D3D3DArial size=3D3D3D2>the mobo for the Magma =
card? =3D
>>That =3D3D
>> >might be=3D3D20
>> >the first thing unless</FONT></DIV>
>> ><DIV><FONT face=3D3D3DArial size=3D3D3D2>you know that won't =3D
>>help.</FONT></DIV>
>> ><DIV><FONT face=3D3D3DArial size=3D3D3D2>Tom</FONT></DIV>
>> ><BLOCKQUOTE=3D3D20
>> >style=3D3D3D"PADDING-RIGHT: 0px; PADDING-LEFT: 5px; MARGIN-LEFT: =
5px; =3D
>>=3D3D
>> >BORDER-LEFT: #000000 2px solid; MARGIN-RIGHT: 0px">
>> > <DIV>"LaMont" <<A=3D3D20
>> > =
href=3D3D3D"mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A>> =3D
>>=3D3D
>> >wrote in=3D3D20
>> > message <A=3D3D20
>> > =3D3D
>> =3D
>>
=
>>>href=3D3D3D"news:4404e5bf$1 @linux">news:4404e5bf$1 @linux</A>...</DIV><=
BR>H=3D
>>
>>=i=3D3D20
>> > Chris,<BR>Fresh install of win Xp/sp1. New drives, new =
everything.
>=20
> =3D
>=20
>>I'm
>> =3D3D
>> >using=3D3D20
>> > Apci,<BR>not Standard PC. Mother Board GA-K8NSC-939<BR>nforce-3 =
=3D
>>ultra=3D3D20
>> > 250gb.<BR><BR>-Maybe moving the magma(13 slot) to a differnt =
=3D3D
>> >slot.(It's=3D3D20
```

>> > currently residing in PCI slot 4. According to the manual, =  
slot  
>=20  
> =3D  
>=20  
>>4 =3D3D  
>> >and 2 are=3D3D20  
>> > not shared. Plus even with the SATA controllers activated, =  
each  
>=20  
> =3D  
>=20  
>>of  
>> =3D3D  
>> >the=3D3D20  
>> > (4)eds cards had their own IRQ. However, 1 EDS card shared =  
(IRQ  
>=20  
> =3D  
>=20  
>>16)  
>> =3D3D  
>> >with=3D3D20  
>> > the Matrox G450. Strange.. I've been looking into this =  
PCI =3D  
>>=3D3D  
>> >latency=3D3D20  
>> > issues and download an app to look and change soem of the PCI =  
=3D  
>>=3D3D  
>> >latency=3D3D20  
>> > settings. The SATA controller had a setting of 0(zero). =  
EDS  
>=20  
> =3D  
>=20  
>>=3D3D  
>> >scherzo=3D3D20  
>> > (32) matrox (64)..IDE controller (0).. Thanks for your =  
=3D  
>>help=3D3D20  
>> > ..LaMont  
>> > =3D  
=<br>
>>href="mailto:chrisl@adkproaudio.com">chrisl@adkproaudio.com</A>=3D=  
3D20=3D  
>>  
>> > wrote: HI Lamont, Sorry to here your having =3D3D

>> >trouble.<BR>>What=3D3D20  
>> > exact model of the Gigabyte board do you mean. The =  
description=3D3D20  
>> > you<BR><BR>>have here is vague. Is it a K8NS Ultra=3D3D20  
>> > -939?<BR>><BR>>When you say you rebuilt do you mean you =3D3D  
>> >reinstalled=3D3D20  
>> > windows from scratch?<BR>><BR>><BR>>LaMont wrote:<BR>>> =3D3D  
>> >Hi=3D3D20  
>> > gang:<BR>>> I 'm having problems getting Paris to ip and =3D3D  
>> >running. Paris=3D3D20  
>> > will sometimes<BR>>> star, only to just freeze up and crash the =  
=3D3D  
>> >whole=3D3D20  
>> > system. So, I thought<BR>my<BR>>> Asus-Amd XP combo(with =3D3D  
>> >SATA-Firwire)=3D3D20  
>> > was cause too much IRQ problems for<BR>>> PAris.<BR>>>=3D3D20  
>> > <BR>>> So, I rebuilt with my favorite stable =3D3D  
>> >mobo(Gigabyte).<BR>>>=3D3D20  
>> > <BR>>> Here's the skinny: I just build a new Paris/Nuendo PC. =  
=3D3D  
>> >Great very=3D3D20  
>> > very<BR>fast:<BR>>> Here are the configs:<BR>>> =3D3D  
>> ><BR>>>=3D3D20  
>> > -gigabyte mobo 939 Ultra250<BR>>> -Dual core opteron =3D3D  
>> >165<BR>>>=3D3D20  
>> > -2gig ddr400<BR>>> -sata (onboard) 3 300 gig drives<BR>>> =3D3D  
>> >-(1) RME=3D3D20  
>> > Digi 96 <BR>>> -(1)Magma card (4 card EDS) <BR>>> -Matrox=3D3D20  
>> > g450<BR>>> <BR>>> Well, Nuendo runs like a Deer!!! WOW.. =3D3D  
>> >But PAris=3D3D20  
>> > is hit and miss. I disabled:<BR>>> USB, SATA raid..A little =  
=3D3D  
>> >better, but=3D3D20  
>> > I', starting to think that My either<BR>>> my EdS cards or =3D3D  
>> >Mec/442 are=3D3D20  
>> > the problem. Just 2 weeks prior, the system<BR>was<BR>>> working =  
=3D  
>>=3D3D  
>> >fine.=3D3D20  
>> > <BR>>> <BR>>> Note: In my studio I have a master power =3D3D  
>> >switch that=3D3D20  
>> > start up the FUrman<BR>>> power unit..The Magama and Mec units =  
=3D3D  
>> >were on=3D3D20  
>> > when I started up the system.<BR>>> Maybe PAris got a Jolt ??? I =  
=3D  
>>=3D3D  
>> >don;t=3D3D20

```

>> > know..<BR>>> Please help..Thanks<BR>>>=3D3D20
>> > <BR>><BR>><BR>><BR>><BR>>Chris<BR>><BR>>-- =3D3D
>> ><BR>>Chris=3D3D20
>> > Ludwig<BR>><BR>>ADK Pro Audio<BR>>(859)=3D3D20
>> > =3D3D
>> =3D
>>
=
>>>635-5762<BR>>www.adkproaudio.com<BR>>chrisl@adkproaudio.com<BR></BL=3D=
3D
>>
>> >OCKQUOTE></BODY></HTML>
>> >
>> >
>>
>>
>><!DOCTYPE HTML PUBLIC "-//W3C//DTD HTML 4.0 Transitional//EN">
>><HTML><HEAD>
>><META http-equiv=3D3DContent-Type content=3D3D"text/html; =3D
>>charset=3D3Diso-8859-1">
>><META content=3D3D"MSHTML 6.00.2800.1400" name=3D3DGENERATOR>
>><STYLE></STYLE>
>></HEAD>
>><BODY bgColor=3D3D#ffffff>
>><DIV><FONT face=3D3DArial size=3D3D2>LM,</FONT></DIV>
>><DIV><FONT face=3D3DArial size=3D3D2>Can't wait to =
hear.</FONT></DIV>
>><DIV><FONT face=3D3DArial size=3D3D2>T.</FONT></DIV>
>><BLOCKQUOTE=3D20
>>style=3D3D"PADDING-RIGHT: 0px; PADDING-LEFT: 5px; MARGIN-LEFT: 5px; =
=3D
>>BORDER-LEFT: #000000 2px solid; MARGIN-RIGHT: 0px">
>> <DIV>"LaMont" <<A=3D20
>> href=3D3D"mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A>> =
=3D
>>wrote in=3D20
>> message <A =3D
=
>>href=3D3D"news:44052522@linux">news:44052522@linux</A>...</DIV><BR>HEY=3D=
20
>> Tom,<BR>>I'm in the Prcess of moving th magma card to differnt =3D
>>slots..I'll let=3D20
>> you<BR>>know what happens..<BR>><BR>>"Tom Bruhl" <<A=3D20
>> href=3D3D"mailto:arpegio@comcast.net">arpegio@comcast.net</A>>=3D20
>> wrote:<BR>><BR>><BR>>LaMont,<BR>>EDS1 with Matrox is a bad =3D
>>
>> thing. I'd try different slots within<BR>>the Magma to =3D
>>correct=3D20

```

>> that. Have you tried any other slots on<BR>>the mobo for the =3D  
>>Magma=3D20  
>> card? That might be the first thing unless<BR>>you know that =3D  
>>won't=3D20  
>> help.<BR>>Tom<BR>> "LaMont" <<A=3D20  
>> href=3D3D"mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A>> =  
=3D  
>>wrote in=3D20  
>> message =3D3D<BR>>news:4404e5bf\$1@linux...<BR>><BR>> Hi=3D20  
>> Chris,<BR>> Fresh install of win Xp/sp1. New drives, new =3D  
>>everything.=3D20  
>> I'm using =3D3D<BR>>Apci,<BR>> not Standard PC. Mother Board =3D  
>>  
>> GA-K8NSC-939<BR>> nforce-3 ultra 250gb.<BR>><BR>> =3D  
>>-Maybe=3D20  
>> moving the magma(13 slot) to a differnt slot.(It's currently=3D20  
>> =3D3D<BR>>residing<BR>> in PCI slot 4. According to the =3D  
>>manual, slot 4=3D20  
>> and 2 are not shared. =3D3D<BR>>Plus<BR>> even with the Sata =3D  
>>  
>> controllers activated, each of the (4)eds cards=3D20  
>> had<BR>=3D3D<BR>>their<BR>> own IRQ. However, 1 EDS card =3D  
>>shared (IRQ=3D20  
>> 16) with the Matrox G450. =3D3D<BR>>Strange..<BR>><BR>> =3D  
>>I've been=3D20  
>> looking into this PCI latency issues and download an app=3D20  
>> to<BR>=3D3D<BR>>look<BR>> and change soem of the PCI latency =3D  
>>  
>> settings.=3D3D20<BR>><BR>> The Sata controller had a setting =3D  
>>of=3D20  
>> 0(zero). EDS scherzo (32) matrox<BR>=3D3D<BR>>(64)..IDE<BR>> =3D  
>>  
>> controller (0)..<BR>><BR>> Thanks for your help=3D20  
>> ..LaMont<BR>><BR>><BR>><BR>> Ahris Ludwig =3D  
>><<A=3D20  
>> =  
href=3D3D"mailto:chrisl@adkproaudio.com">chrisl@adkproaudio.com</A>>=3D20=

>> wrote:<BR>> >HI Lamont,<BR>> >Sorry to here =3D  
>>your=3D20  
>> having trouble.<BR>> >What exact model of the Gigabyte =3D  
>>board do=3D20  
>> you mean. The description =3D3D<BR>>you<BR>><BR>> =3D  
>>  
>>>have here is=3D20  
>>  
>> vague. Is it a K8NS Ultra -939?<BR>> ><BR>> =3D  
>>

>>>When you=3D20  
>>  
>> say you rebuilt do you mean you reinstalled windows from=3D20  
>> =3D3D<BR>>scratch?<BR>> ><BR>> =3D  
>>  
>>><BR>> =3D20  
>>  
>> >LaMont wrote:<BR>> >> Hi gang:<BR>> =3D  
>>  
>>>>I 'm=3D20  
>>  
>> having problems getting Paris to ip and running. Paris will=3D20  
>> =3D3D<BR>>sometimes<BR>> >> star, only to just freeze =3D  
>>up and=3D20  
>> crash the whole system. So, I =3D3D<BR>>thought<BR>> =3D  
>>my<BR>> =3D20  
>> >> Asus-Amd XP combo(with SATA-Firwire) was cause too much IRQ=3D20  
>> =3D3D<BR>>problems for<BR>> >> Paris.<BR>> =3D20  
>> >>=3D3D20<BR>> >> So, I rebuilt with my favorite =3D  
>>stable=3D20  
>> mobo(Gigabyte).<BR>> >>=3D3D20<BR>> >> =3D  
>>Here's the=3D20  
>> skinny: I just build a new Paris/Nuendo PC. Great very=3D20  
>> =3D3D<BR>>very<BR>> fast:<BR>> >> Here are =3D  
>>the=3D20  
>> configs:<BR>> >>=3D3D20<BR>> >> -gigabyte =3D  
>>mobo 939=3D20  
>> Ultra250<BR>> >> -Dual core opteron 165<BR>> =3D  
>>  
>>>>=3D20  
>>  
>> -2gig ddr400<BR>> >> -sata (onboard) 3 300 gig=3D20  
>> drives<BR>> >> -(1) RME Digi 96=3D3D20<BR>> =3D  
>>  
>>>>=3D20  
>>  
>> -(1)Magma card (4 card EDS)=3D3D20<BR>> >> -Matrox=3D20  
>> g450<BR>> >>=3D3D20<BR>> >> Well, Nuendo =3D  
>>runs like a=3D20  
>> Deer!!! WOW.. But Paris is hit and miss. =3D  
>>I<BR>=3D3D<BR>>disabled:<BR>> =3D20  
>> >> USB, SATA raid..A little better, but I', starting to think =3D  
>>that=3D20  
>> My<BR>=3D3D<BR>>either<BR>> >> my EdS cards or Mec/442 =3D  
>>are the=3D20  
>> problem. Just 2 weeks prior, the =3D3D<BR>>system<BR>> =3D20  
>> was<BR>> >> working fine.=3D3D20<BR>> =3D20  
>> >>=3D3D20<BR>> >> Note: In my studio I have a =3D

```

>>master power=3D20
>> switch that start up the =3D3D<BR>>FUrman<BR>> >> =3D
>>power=3D20
>> unit..The Magama and Mec units were on when I started up=3D20
>> the<BR>=3D3D<BR>>system.<BR>> >> Maybe PAris got a =3D
>>Jolt ??? l=3D20
>> don;t know..<BR>> >> Please help..Thanks<BR>> =3D20
>> >>=3D3D20<BR>> ><BR>> ><BR>> =3D20
>> ><BR>> ><BR>> >Chris<BR>> =3D20
>> ><BR>> >--=3D3D20<BR>> >Chris =3D
>>Ludwig<BR>> =3D20
>> ><BR>> >ADK Pro Audio<BR>> >(859)=3D20
>> 635-5762<BR>> >www.adkproaudio.com<BR>> =3D20
>> >chrisl@adkproaudio.com<BR>><BR>><BR>><!DOCTYPE HTML =3D
>>PUBLIC=3D20
>> "-//W3C//DTD HTML 4.0=3D20
>> Transitional//EN"><BR>><HTML><HEAD><BR>><META=3D20
>> http-equiv=3D3D3DContent-Type content=3D3D3D"text/html;=3D20
>> =3D3D<BR>>charset=3D3D3Diso-8859-1"><BR>><META =3D
>>content=3D3D3D"MSHTML=3D20
>> 6.00.2800.1400"=3D20
>> =3D
>>name=3D3D3DGENERATOR><BR>><STYLE></STYLE><BR>></HEA=3D
>>D><BR>><BODY=3D20
>> bgColor=3D3D3D#ffffff><BR>><DIV><FONT face=3D3D3DArial=3D20
>> =3D
>>size=3D3D3D2>LaMont,</FONT></DIV><BR>><DIV><FONT=3D
>>=3D20
>> face=3D3D3DArial size=3D3D3D2>EDS1 with Matrox is a bad thing. =3D
>>=3D3D<BR>>>l'd=3D20
>> try=3D3D20<BR>>>different slots=3D20
>> within</FONT></DIV><BR>><DIV><FONT =3D
>>face=3D3D3DArial=3D20
>> size=3D3D3D2>the Magma to correct that. Have =3D3D<BR>>>you =
tried=3D20
>> any=3D3D20<BR>>>other slots=3D20
>> on</FONT></DIV><BR>><DIV><FONT face=3D3D3DArial=3D20
>> size=3D3D3D2>the mobo for the Magma card? That =3D3D<BR>>>might =3D
>>be=3D3D20<BR>>>the=3D20
>> first thing unless</FONT></DIV><BR>><DIV><FONT =3D
>>
>> face=3D3D3DArial size=3D3D3D2>you know that won't=3D20
>> help.</FONT></DIV><BR>><DIV><FONT =3D
>>face=3D3D3DArial=3D20
>> =3D
>>size=3D3D3D2>Tom</FONT></DIV><BR>><BLOCKQUOTE=3D3D20<BR >=3D
>>
>>>style=3D3D3D"PADDING-RIGHT:=3D20

```

```

>>
>> 0px; PADDING-LEFT: 5px; MARGIN-LEFT: 5px; <BR>>BORDER-LEFT: =
=3D
>>#000000 2px=3D20
>> solid; MARGIN-RIGHT: 0px"><BR>> <DIV>"LaMont"=3D20
>> <<A=3D3D20<BR>> href=3D3D3D"<A=3D20
>> =3D
=
>>href=3D3D'mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A'>mailto:=
jjdp=3D
>>ro@ameritech.net">jjdpro@ameritech.net</A</A>>>=3D20
>> =3D3D<BR>>wrote in=3D3D20<BR>> message =3D
>><A=3D3D20<BR>> =3D20
>> =3D3D<BR>>href=3D3D3D"<A=3D20
>> =3D
=
>>href=3D3D'news:4404e5bf$1 @linux">news:4404e5bf$1 @linux</A>...</DIV><BR>=
Hi=3D3D=3D
>>20">news:4404e5bf$1 @linux">news:4404e5bf$1 @linux</A>...</DIV&=3D
>>gt;<BR>Hi=3D3D20</A><BR>> =3D20
>> Chris,<BR>Fresh install of win Xp/sp1. New drives, new =3D
>>everything.=3D20
>> I'm<BR>=3D3D<BR>>using=3D3D20<BR>> Apci,<BR>not Standard =3D
>>PC. Mother=3D20
>> Board GA-K8NSC-939<BR>nforce-3 ultra=3D3D20<BR>> =3D20
>> 250gb.<BR><BR>-Maybe moving the magma(13 slot) to a =3D
>>different=3D20
>> =3D3D<BR>>slot.(It's=3D3D20<BR>> currently =3D
>>residing<BR>in PCI slot=3D20
>> 4. According to the manual, slot 4 =3D3D<BR>>and 2 =3D
>>are=3D3D20<BR>> not=3D20
>> shared. Plus<BR>even with the Sata controllers activated, each=3D20
>> of<BR>=3D3D<BR>>the=3D3D20<BR>> (4)eds cards had =3D
>>their<BR>own IRQ.=3D20
>> However, 1 EDS card shared (IRQ =3D
>>16)<BR>=3D3D<BR>>with=3D3D20<BR>> the=3D20
>> Matrox G450. Strange..<BR><BR>I've been looking into this =3D
>>PCI=3D20
>> =3D3D<BR>>latency=3D3D20<BR>> issues and download an app to=3D20
>> look<BR>and change soem of the PCI =3D
>>=3D3D<BR>>latency=3D3D20<BR>> =3D20
>> settings. <BR><BR>The Sata controller had a setting of =3D
>>0(zero).=3D20
>> EDS =3D3D<BR>>scherzo=3D3D20<BR>> (32) matrox=3D20
>> (64)..IDE<BR>controller (0)..<BR><BR>Thanks for your =3D
>>
>> help=3D3D20<BR>> =3D
>>..LaMont<BR><BR><BR><BR> Ahris=3D20

```



>> Ludwig <<A=3D3D20<BR>> href=3D3D3D"<A=3D20  
>> =3D  
=  
>>href=3D3D'mailto:chrisl@adkproaudio.com">chrisl@adkproaudio.com</A>>=3D=  
3D20'>=3D  
>>mailto:chrisl@adkproaudio.com">chrisl@adkproaudio.com</A>>=3D3D=3D  
>>20</A><BR>> =3D20  
>> wrote:<BR>>HI Lamont,<BR>>Sorry to here your having=3D20  
>> =3D3D<BR>>trouble.<BR>>What=3D3D20<BR>> exact model =3D  
>>of the=3D20  
>> Gigabyte board do you mean. The description=3D3D20<BR>> =3D20  
>> you<BR><BR>>have here is vague. Is it a K8NS=3D20  
>> Ultra=3D3D20<BR>> -939?<BR>><BR>>When you say =3D  
>>you=3D20  
>> rebuilt do you mean you =3D3D<BR>>reinstalled=3D3D20<BR>> =3D  
>>windows from=3D20  
>> scratch?<BR>><BR>><BR>>LaMont=3D20  
>> wrote:<BR>>> =3D3D<BR>>Hi=3D3D20<BR>> =3D  
>>gang:<BR>>>=3D20  
>> I 'm having problems getting Paris to ip and =  
=3D3D<BR>>running.=3D20  
>> Paris=3D3D20<BR>> will sometimes<BR>>> star, only =3D  
>>to just=3D20  
>> freeze up and crash the =3D3D<BR>>whole=3D3D20<BR>> system. =3D  
>>So, I=3D20  
>> thought<BR>my<BR>>> Asus-Amd XP combo(with=3D20  
>> =3D3D<BR>>SATA-Firwire)=3D3D20<BR>> was cause too much IRQ =3D  
>>problems=3D20  
>> for<BR>>> PARis.<BR>>>=3D3D20<BR>> =3D20  
>> <BR>>> So, I rebuilt with my favorite stable=3D20  
>> =3D3D<BR>>mobo(Gigabyte).<BR>>>=3D3D20<BR>> =3D  
>><BR>>>=3D20  
>> Here's the skinny: I just build a new Paris/Nuendo PC. =3D  
>>=3D3D<BR>>Great=3D20  
>> very=3D3D20<BR>> very<BR>fast:<BR>>> Here are =3D  
>>the=3D20  
>> configs:<BR>>> =3D  
>>=3D3D<BR>><BR>>>=3D3D20<BR>> =3D20  
>> -gigabyte mobo 939 Ultra250<BR>>> -Dual core opteron=3D20  
>> =3D3D<BR>>165<BR>>>=3D3D20<BR>> -2gig =3D  
>>ddr400<BR>>>=3D20  
>> -sata (onboard) 3 300 gig drives<BR>>> =3D3D<BR>>-(1)=3D20  
>> RME=3D3D20<BR>> Digi 96 <BR>>> -(1)Magma card (4 =3D  
>>card EDS)=3D20  
>> <BR>>> -Matrox=3D3D20<BR>> g450<BR>>>=3D20  
>> <BR>>> Well, Nuendo runs like a Deer!!! WOW.. =3D  
>>=3D3D<BR>>But=3D20  
>> PARis=3D3D20<BR>> is hit and miss. I =3D

>>disabled:<BR>>> USB,=3D20  
>> SATA raid..A little =3D3D<BR>>>better, but=3D3D20<BR>> I', =3D  
>>starting to=3D20  
>> think that My either<BR>>> my EdS cards or =3D  
>>=3D3D<BR>>Mec/442=3D20  
>> are=3D3D20<BR>> the problem. Just 2 weeks prior, the=3D20  
>> system<BR>was<BR>>> working =3D  
>>=3D3D<BR>>fine.=3D3D20<BR>> =3D20  
>> <BR>>> <BR>>> Note: In my studio I have a =3D  
>>master power=3D20  
>> =3D3D<BR>>switch that=3D3D20<BR>> start up the =3D  
>>Furman<BR>>>=3D20  
>> power unit..The Magama and Mec units =3D3D<BR>>were =3D  
>>on=3D3D20<BR>> when I=3D20  
>> started up the system.<BR>>> Maybe PArIs got a Jolt ??? I=3D20  
>> =3D3D<BR>>don;t=3D3D20<BR>> know..<BR>>> Please=3D20  
>> help..Thanks<BR>>>=3D3D20<BR>> =3D20  
>> =3D  
>><BR>><BR>><BR>><BR>><BR>>Chr=3D  
>>is<BR>><BR>>--=3D20  
>> =3D3D<BR>><BR>>Chris=3D3D20<BR>> =3D20  
>> Ludwig<BR>><BR>>ADK Pro=3D20  
>> Audio<BR>>(859)=3D3D20<BR>> =3D20  
>> =3D  
>>=3D3D<BR>>635-5762<BR>>www.adkproaudio.com<BR>>chrisl@=3D  
>>adkproaudio.com<BR></BL=3D3D<BR>>OCKQUOTE></BODY></=3D  
>>HTML><BR>><BR>><BR></BLOCKQUOTE></BODY></HTML>  
>>  
>>  
>=20

--=20  
Chris Ludwig  
ADK  
chrisl@adkproaudio.com <mailto:chrisl@adkproaudio.com>  
www.adkproaudio.com <http://www.adkproaudio.com/>  
(859) 635-5762

-----=\_NextPart\_000\_0029\_01C63D19.45777050

Content-Type: text/html;  
charset="iso-8859-1"  
Content-Transfer-Encoding: quoted-printable

```
<!DOCTYPE HTML PUBLIC "-//W3C//DTD HTML 4.0 Transitional//EN">
<HTML><HEAD>
<META http-equiv=3DContent-Type content=3D"text/html; =
charset=3Diso-8859-1">
<META content=3D"MSHTML 6.00.2800.1400" name=3DGENERATOR>
<STYLE></STYLE>
```

```
</HEAD>
<BODY bgColor=#ffffff>
<DIV><FONT face=Arial size=2>LaMont,</FONT></DIV>
<DIV><FONT face=Arial size=2>I'm glad it was that easy!</FONT></DIV>
<DIV><FONT face=Arial size=2>Tom</FONT></DIV>
<BLOCKQUOTE style="padding-right: 0px; padding-left: 5px; margin-left: 5px; border-left: 1px solid black; margin-right: 0px;">
  <DIV>"Chris Ludwig" &lt;<A href="mailto:chrisl@adkproaudio.com">chrisl@adkproaudio.com</A>&gt; =
wrote in=20
  message <A href="news:4405b024@linux">news:4405b024@linux</A>...</DIV>Hi=20
  Lamont,<BR>Wow weird stuff. Glad its working=20
  now.<BR><BR>Chris<BR><BR><BR>LaMont wrote:<BR>&gt; Tom & amp; =
Chris,<BR>&gt;=20
  <BR>&gt; I got it solved. It was the Magma Chasis's power supply was =
not=20
  "seated"<BR>&gt; into slot properly.&nbsp; Paris is working fine =
now.<BR>&gt;=20
  Thanks<BR>&gt; <BR>&gt; "Tom Bruhl" &lt;<A href="mailto:arpegio@comcast.net">arpegio@comcast.net</A>&gt; =
wrote:<BR>&gt;=20
  <BR>&gt;&gt;<BR>&gt;&gt;LM,<BR>&gt;&gt;Can't wait to=20
  hear.<BR>&gt;&gt;T.<BR>&gt;&gt; "LaMont" &lt;<A href="mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A>&gt; =
wrote in=20
  message =3D<BR>&gt;&gt;news:44052522@linux...<BR>&gt;&gt;<BR>&gt;&gt; =
HEY=20
  Tom,<BR>&gt;&gt; I'm in the Prcess of moving th magma card to differnt =

  slots..I'll let<BR>&gt; <BR>&gt; =3D<BR>&gt; =
<BR>&gt;&gt;you<BR>&gt;&gt; know=20
  what happens..<BR>&gt;&gt;<BR>&gt;&gt; "Tom Bruhl" &lt;<A href="mailto:arpegio@comcast.net">arpegio@comcast.net</A>&gt;=20
  wrote:<BR>&gt;&gt; &gt;<BR>&gt;&gt; &gt;<BR>&gt;&gt; =
&gt;LaMont,<BR>&gt;&gt;=20
  &gt;EDS1 with Matrox is a bad thing.&nbsp; I'd try different slots=20
  within<BR>&gt;&gt; &gt;the Magma to correct that.&nbsp; Have you tried =
any=20
  other slots on<BR>&gt;&gt; &gt;the mobo for the Magma card?&nbsp; That =
might=20
  be the first thing unless<BR>&gt;&gt; &gt;you know that won't=20
  help.<BR>&gt;&gt; &gt;Tom<BR>&gt;&gt; &gt;&nbsp; "LaMont" &lt;<A href="mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A>&gt; =
wrote in=20
  message =3D3D<BR>&gt;&gt; &gt;news:4404e5bf$1 @linux...<BR>&gt;&gt;=20
  &gt;<BR>&gt;&gt; &gt;&nbsp; Hi Chris,<BR>&gt;&gt; &gt;&nbsp; Fresh =
```

install of=20  
 win Xp/sp1. New drives, new everything. I'm using<BR>&gt; <BR>&gt; =  
 =3D<BR>&gt;=20  
 <BR>&gt;&gt;=3D3D<BR>&gt;&gt; &gt;&gt;Apci,<BR>&gt;&gt; &gt;&nbsp; not =  
 Standard PC.=20  
 Mother Board GA-K8NSC-939<BR>&gt;&gt; &gt;&nbsp; nforce-3 ultra=20  
 250gb.<BR>&gt;&gt; &gt;<BR>&gt;&gt; &gt;&nbsp; -Maybe moving the =  
 magma(13=20  
 slot) to a differnt slot.(It's currently<BR>&gt; <BR>&gt; =3D<BR>&gt;=20  
 <BR>&gt;&gt;=3D3D<BR>&gt;&gt; &gt;&residing<BR>&gt;&gt; &gt;&nbsp; in =  
 PCI slot 4.=20  
 According to the manual, slot 4 and 2 are not =3D<BR>&gt;&gt;shared.=20  
 =3D3D<BR>&gt;&gt; &gt;&Plus<BR>&gt;&gt; &gt;&nbsp; even with the SATA =  
 controllers=20  
 activated, each of the (4)eds cards<BR>&gt; <BR>&gt; =3D<BR>&gt;=20  
 <BR>&gt;&gt;had<BR>&gt;&gt; =3D3D<BR>&gt;&gt; &gt;&their<BR>&gt;&gt; =  
 &gt;&nbsp;=20  
 own IRQ. However, 1 EDS card shared (IRQ 16) with the Matrox =  
 G450.<BR>&gt;=20  
 <BR>&gt; =3D<BR>&gt;&gt; <BR>&gt;&gt;=3D3D<BR>&gt;&gt; =  
 &gt;&Strange..<BR>&gt;&gt;=20  
 &gt;<BR>&gt;&gt; &gt;&nbsp; I've been looking into this PCI latency =  
 issues and=20  
 download an app<BR>&gt; <BR>&gt; =3D<BR>&gt;=20  
 <BR>&gt;&gt;to<BR>&gt;&gt;=20  
 =3D3D<BR>&gt;&gt; &gt;&look<BR>&gt;&gt; &gt;&nbsp; and change soem of =  
 the PCI=20  
 latency settings.=3D3D20<BR>&gt;&gt; &gt;<BR>&gt;&gt; &gt;&nbsp; The =  
 SATA=20  
 controller had a setting of 0(zero). EDS scherzo (32)=20  
 =3D<BR>&gt;&gt;matrox<BR>&gt;&gt; =3D3D<BR>&gt;&gt; =  
 &gt;(64)..IDE<BR>&gt;&gt;=20  
 &gt;&nbsp; controller (0)..<BR>&gt;&gt; &gt;<BR>&gt;&gt; &gt;&nbsp; =  
 Thanks for=20  
 your help ..LaMont<BR>&gt;&gt; &gt;<BR>&gt;&gt; &gt;<BR>&gt;&gt;=20  
 &gt;<BR>&gt;&gt; &gt;&nbsp;&nbsp;&nbsp; Ahris Ludwig &lt;<A=20  
 href=3D"mailto:chrisl@adkproaudio.com">chrisl@adkproaudio.com</A>&gt;=20  
 wrote:<BR>&gt;&gt; &gt;&nbsp; &gt;HI Lamont,<BR>&gt;&gt; &gt;&nbsp; =  
 &gt;Sorry=20  
 to here your having trouble.<BR>&gt;&gt; &gt;&nbsp; &gt;What exact =  
 model of=20  
 the Gigabyte board do you mean. The =3D<BR>&gt;&gt;description =  
 =3D3D<BR>&gt;&gt;=20  
 &gt;you<BR>&gt;&gt; &gt;<BR>&gt;&gt; &gt;&nbsp; &gt;have here is =  
 vague. Is it=20  
 a K8NS Ultra -939?<BR>&gt;&gt; &gt;&nbsp; &gt;<BR>&gt;&gt; &gt;&nbsp; =  
 &gt;When=20  
 you say you rebuilt do you mean you reinstalled windows from<BR>&gt;&gt; =

<BR>&gt;=20  
 =3D<BR>&gt; <BR>&gt;&gt;=3D3D<BR>&gt;&gt; &gt;&gt;scratch?<BR>&gt;&gt; =  
 &gt;&nbsp;&nbsp;&nbsp;=20  
 &gt;&lt;BR>&gt;&gt; &gt;&nbsp;&nbsp;&nbsp; &gt;&lt;BR>&gt;&gt; &gt;&nbsp;&nbsp;&nbsp; &gt;&LaMont=20  
 wrote:<BR>&gt;&gt; &gt;&nbsp;&nbsp;&nbsp; &gt;&gt;&gt; Hi gang:<BR>&gt;&gt; &gt;&nbsp;&nbsp;&nbsp; =

&gt;&gt; I 'm having problems getting Paris to ip and running. Paris=20  
 will<BR>&gt; <BR>&gt;=3D<BR>&gt; <BR>&gt;&gt;=3D3D<BR>&gt;&gt;=20  
 &gt;&sometimes<BR>&gt;&gt; &gt;&nbsp;&nbsp;&nbsp; &gt;&gt;&gt; star, only to just =  
 freeze up and=20  
 crash the whole system. So, I =3D<BR>&gt;&gt;=3D3D<BR>&gt;&gt;=20  
 &gt;&thought<BR>&gt;&gt; &gt;&nbsp;&nbsp;&nbsp; my<BR>&gt;&gt; &gt;&nbsp;&nbsp;&nbsp; &gt;&gt;&gt; =  
 Asus-Amd=20  
 XP combo(with SATA-Firwire) was cause too much IRQ =3D3D<BR>&gt;&gt;=20  
 &gt;&problems for<BR>&gt;&gt; &gt;&nbsp;&nbsp;&nbsp; &gt;&gt;&gt; PARis.<BR>&gt;&gt; =  
 &gt;&nbsp;&nbsp;&nbsp;=20  
 &gt;&gt;&gt;=3D3D20<BR>&gt;&gt; &gt;&nbsp;&nbsp;&nbsp; &gt;&gt;&gt; So, I rebuilt with my =  
 favorite=20  
 stable mobo(Gigabyte).<BR>&gt;&gt; &gt;&nbsp;&nbsp;&nbsp; =  
 &gt;&gt;&gt;=3D3D20<BR>&gt;&gt;=20  
 &gt;&nbsp;&nbsp;&nbsp; &gt;&gt;&gt; Here's the skinny: I just build a new Paris/Nuendo =  
 PC.=20  
 Great =3D<BR>&gt;&gt;very =3D3D<BR>&gt;&gt; &gt;&very<BR>&gt;&gt; =  
 &gt;&nbsp;&nbsp;&nbsp;=20  
 fast:<BR>&gt;&gt; &gt;&nbsp;&nbsp;&nbsp; &gt;&gt;&gt; Here are the =  
 configs:<BR>&gt;&gt;=20  
 &gt;&nbsp;&nbsp;&nbsp; &gt;&gt;&gt;=3D3D20<BR>&gt;&gt; &gt;&nbsp;&nbsp;&nbsp; &gt;&gt;&gt; -gigabyte =  
 mobo 939=20  
 Ultra250<BR>&gt;&gt; &gt;&nbsp;&nbsp;&nbsp; &gt;&gt;&gt; -Dual core opteron =  
 165<BR>&gt;&gt;=20  
 &gt;&nbsp;&nbsp;&nbsp; &gt;&gt;&gt; -2gig ddr400<BR>&gt;&gt; &gt;&nbsp;&nbsp;&nbsp; &gt;&gt;&gt; -sata =  
 (onboard) 3 300 gig drives<BR>&gt;&gt; &gt;&nbsp;&nbsp;&nbsp; &gt;&gt;&gt; -(1) RME =  
 Digi=20  
 96=3D3D20<BR>&gt;&gt; &gt;&nbsp;&nbsp;&nbsp; &gt;&gt;&gt; -(1)Magma card (4 card=20  
 EDS)=3D3D20<BR>&gt;&gt; &gt;&nbsp;&nbsp;&nbsp; &gt;&gt;&gt; -Matrox g450<BR>&gt;&gt; =  
 &gt;&nbsp;&nbsp;&nbsp;=20  
 &gt;&gt;&gt;=3D3D20<BR>&gt;&gt; &gt;&nbsp;&nbsp;&nbsp; &gt;&gt;&gt; Well, Nuendo runs like =  
 a Deer!!!=20  
 WOW.. But PARis is hit and =3D<BR>&gt;&gt;miss. I<BR>&gt;&gt; =  
 =3D3D<BR>&gt;&gt;=20  
 &gt;&disabled:<BR>&gt;&gt; &gt;&nbsp;&nbsp;&nbsp; &gt;&gt;&gt; USB, SATA raid..A little =  
 better,=20  
 but I', starting to think that<BR>&gt; <BR>&gt;=3D<BR>&gt;=20  
 <BR>&gt;&gt;My<BR>&gt;&gt;=3D3D<BR>&gt;&gt; &gt;&either<BR>&gt;&gt; =  
 &gt;&nbsp;&nbsp;&nbsp;=20  
 &gt;&gt;&gt; my EdS cards or Mec/442 are the problem. Just 2 weeks prior,=20  
 the<BR>&gt; <BR>&gt;=3D<BR>&gt; <BR>&gt;&gt;=3D3D<BR>&gt;&gt;=20

&gt;system<BR>&gt;&gt; &gt;&nbsp; was<BR>&gt;&gt; &gt;&nbsp; &gt;&gt; =  
working=20  
fine.=3D3D20<BR>&gt;&gt; &gt;&nbsp; &gt;&gt;=3D3D20<BR>&gt;&gt; =  
&gt;&nbsp;=20  
&gt;&gt; Note: In my studio I have a master power switch that start up =  
  
=3D<BR>&gt;&gt;the =3D3D<BR>&gt;&gt; &gt;Furman<BR>&gt;&gt; &gt;&nbsp; =  
&gt;&gt;=20  
power unit..The Magama and Mec units were on when I started up=20  
=3D<BR>&gt;&gt;the<BR>&gt;&gt; =3D3D<BR>&gt;&gt; =  
&gt;system.<BR>&gt;&gt;=20  
&gt;&nbsp; &gt;&gt; Maybe PAris got a Jolt ??? I don;t =  
know..<BR>&gt;&gt;=20  
&gt;&nbsp; &gt;&gt; Please help..Thanks<BR>&gt;&gt; &gt;&nbsp;=20  
&gt;&gt;=3D3D20<BR>&gt;&gt; &gt;&nbsp; &gt;<BR>&gt;&gt; &gt;&nbsp;=20  
&gt;<BR>&gt;&gt; &gt;&nbsp; &gt;<BR>&gt;&gt; &gt;&nbsp; =  
&gt;<BR>&gt;&gt;=20  
&gt;&nbsp; &gt;Chris<BR>&gt;&gt; &gt;&nbsp; &gt;<BR>&gt;&gt; =  
&gt;&nbsp;=20  
&gt;--=3D3D20<BR>&gt;&gt; &gt;&nbsp; &gt;Chris Ludwig<BR>&gt;&gt; =  
&gt;&nbsp;=20  
&gt;<BR>&gt;&gt; &gt;&nbsp; &gt;ADK Pro Audio<BR>&gt;&gt; &gt;&nbsp; =  
&gt;(859)=20  
635-5762<BR>&gt;&gt; &gt;&nbsp; &gt;www.adkproaudio.com<BR>&gt;&gt; =  
&gt;&nbsp;=20  
&gt;chrisl@adkproaudio.com<BR>&gt;&gt; &gt;<BR>&gt;&gt; =  
&gt;<BR>&gt;&gt;=20  
&gt;&lt;!DOCTYPE HTML PUBLIC "-//W3C//DTD HTML 4.0=20  
Transitional//EN"&gt;<BR>&gt;&gt; =  
&gt;&lt;HTML&gt;&lt;HEAD&gt;<BR>&gt;&gt;=20  
&gt;&lt;META http-equiv=3D3D3DContent-Type content=3D3D3D"text/html;=20  
=3D3D<BR>&gt;&gt; &gt; charset=3D3D3Diso-8859-1"&gt;<BR>&gt;&gt; =  
&gt;&lt;META=20  
content=3D3D3D"MSHTML 6.00.2800.1400" =  
name=3D3D3DGENERATOR&gt;<BR>&gt;&gt;=20  
&gt;&lt;STYLE&gt;&lt;/STYLE&gt;<BR>&gt;&gt; =  
&gt;&lt;/HEAD&gt;<BR>&gt;&gt;=20  
&gt;&lt;BODY bgColor=3D3D3D#ffffff&gt;<BR>&gt;&gt; =  
&gt;&lt;DIV&gt;&lt;FONT=20  
face=3D3D3DArial =  
size=3D3D3D2&gt;LaMont,&lt;/FONT&gt;&lt;/DIV &gt; <BR>&gt;&gt;=20  
&gt;&lt;DIV&gt;&lt;FONT face=3D3D3DArial size=3D3D3D2&gt;EDS1 with =  
Matrox is a bad=20  
thing.<BR>&gt;&gt; <BR>&gt;&gt; =3D<BR>&gt;&gt; <BR>&gt;&gt;=3D3D<BR>&gt;&gt; =  
&gt;&lt;div=20  
try=3D3D20<BR>&gt;&gt; &gt;different slots=20  
within&lt;/FONT&gt;&lt;/DIV&gt;<BR>&gt;&gt; &gt;&lt;DIV&gt;&lt;FONT=20  
face=3D3D3DArial size=3D3D3D2&gt;the Magma to correct that. =

Have  
=3D<BR>&gt; <BR>&gt;=20  
=3D<BR>&gt; <BR>&gt;&gt;=3D3D<BR>&gt;&gt; &gt;&gt;you tried =  
any=3D3D20<BR>&gt;&gt;=20  
&gt;&gt;other slots on&lt;/FONT&gt;&lt;/DIV&gt;<BR>&gt;&gt;=20  
&gt;&lt;DIV&gt;&lt;FONT face=3D3D3DArial size=3D3D3D2&gt;&gt;the mobo for =  
the Magma=20  
card? =3D<BR>&gt;&gt;That =3D3D<BR>&gt;&gt; &gt;&gt;might =  
be=3D3D20<BR>&gt;&gt; &gt;&gt;the=20  
first thing unless&lt;/FONT&gt;&lt;/DIV&gt;<BR>&gt;&gt;=20  
&gt;&lt;DIV&gt;&lt;FONT face=3D3D3DArial size=3D3D3D2&gt;&gt;you know that =  
won't=20  
=3D<BR> &gt;&gt;help.&lt;/FONT&gt;&lt;/DIV&g t; <BR>&gt;&gt;=20  
&gt;&lt;DIV&gt;&lt;FONT face=3D3D3DArial=20  
size=3D3D3D2&gt;&gt;Tom&lt;/FONT&gt;&lt;/DIV& &gt;&gt; <BR>&gt;&gt;=20  
&gt;&lt;BLOCKQUOTE=3D3D20<BR>&gt;&gt; &gt;&gt;style=3D3D3D"PADDING-RIGHT: =  
0px;=20  
PADDING-LEFT: 5px; MARGIN-LEFT: 5px; =3D<BR>&gt;&gt;=3D3D<BR>&gt;&gt;=20  
&gt;&gt;BORDER-LEFT: #000000 2px solid; MARGIN-RIGHT: 0px"&gt;&gt; <BR>&gt;&gt; =  
&gt;&nbsp; &lt;DIV&gt;"LaMont" &lt;&lt;A=3D3D20<BR>&gt;&gt; &gt;&nbsp; =  
href=3D3D3D"<A=20  
=  
href=3D'mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A>mailto:jjdp-  
ro@ameritech.net"&gt;jjdpro@ameritech.net&lt;/A</A>&gt;&gt;=20  
=3D<BR>&gt;&gt;=3D3D<BR>&gt;&gt; &gt;&gt;wrote in=3D3D20<BR>&gt;&gt; =  
&gt;&nbsp; message=20  
&lt;A=3D3D20<BR>&gt;&gt; &gt;&nbsp; =3D3D<BR>&gt;&gt;=20  
=3D<BR>&gt;&gt;<BR>&gt;&gt;&gt;href=3D3D3D "<A=20  
=  
href=3D'news:4404e5bf\$1 @linux">news:4404e5bf\$1 @linux</A>...</DIV><BR>H'>n=  
ews:4404e5bf\$1 @linux"&gt;news:4404e5bf\$1 @linux&lt;/A&gt;...&lt;/DIV&gt;&lt;=  
t;BR&gt;H</A>=3D<BR>&gt;&gt;<BR>&gt;&gt;&gt;i=3D3D20 <BR>&gt;&gt;=20  
&gt;&nbsp; Chris,&lt;BR&gt;Fresh install of win Xp/sp1. New drives, =  
new=20  
everything.<BR>&gt; <BR>&gt;&gt;=3D<BR>&gt;&gt; <BR>&gt;&gt;&gt;I'm<BR>&gt;&gt;=20  
=3D3D<BR>&gt;&gt; &gt;&gt;using=3D3D20<BR>&gt;&gt; &gt;&nbsp; =  
Apci,&lt;BR&gt;not=20  
Standard PC. Mother Board GA-K8NSC-939&lt;BR&gt;nforce-3=20  
=3D<BR>&gt;&gt;ultra=3D3D20<BR>&gt;&gt; &gt;&nbsp;=20  
250gb.&lt;BR&gt;&lt;BR&gt;-Maybe moving the magma(13 slot) to a =  
differnt=20  
=3D3D<BR>&gt;&gt; &gt;&gt;slot.(It's=3D3D20<BR>&gt;&gt; &gt;&nbsp; =  
currently=20  
residing&lt;BR&gt;in PCI slot 4. According to the manual, slot<BR>&gt; =  
<BR>&gt;=3D<BR>&gt;&gt; <BR>&gt;&gt;&gt;4 =3D3D<BR>&gt;&gt; &gt;&gt;and 2=20  
are=3D3D20<BR>&gt;&gt; &gt;&nbsp; not shared. Plus&lt;BR&gt;even with =

the Sata=20

controllers activated, each<BR>&gt; <BR>&gt; =3D<BR>&gt;=20  
<BR>&gt;&gt;of<BR>&gt;&gt; =3D3D<BR>&gt;&gt; =  
&gt;the=3D3D20<BR>&gt;&gt; &gt;&nbsp;=20

(4)eds cards had their&lt;BR&gt;own IRQ. However, 1 EDS card shared=20  
(IRQ<BR>&gt; <BR>&gt; =3D<BR>&gt; <BR>&gt;&gt;16)<BR>&gt;&gt; =  
=3D3D<BR>&gt;&gt;=20

&gt;with=3D3D20<BR>&gt;&gt; &gt;&nbsp; the Matrox G450.=20  
Strange..&lt;BR&gt;&lt;BR&gt;I've been looking into this PCI=20  
=3D<BR>&gt;&gt;=3D3D<BR>&gt;&gt; &gt;latency=3D3D20<BR>&gt;&gt; =  
&gt;&nbsp; issues=20

and download an app to look&lt;BR&gt;and change soem of the PCI=20  
=3D<BR>&gt;&gt;=3D3D<BR>&gt;&gt; &gt;latency=3D3D20<BR>&gt;&gt; =  
&gt;&nbsp; settings.=20

&lt;BR&gt;&lt;BR&gt;The Sata controller had a setting of 0(zero). =  
EDS<BR>&gt;=20

<BR>&gt; =3D<BR>&gt; <BR>&gt;&gt;=3D3D<BR>&gt;&gt; =  
&gt;scherzo=3D3D20<BR>&gt;&gt;=20

&gt;&nbsp; (32) matrox (64)..IDE&lt;BR&gt;controller=20  
(0)..&lt;BR&gt;&lt;BR&gt;Thanks for your =

=3D<BR>&gt;&gt;help=3D3D20<BR>&gt;&gt;=20  
&gt;&nbsp; ..LaMont&lt;BR&gt;&lt;BR&gt;&lt;BR&gt; t;&lt;BR&gt; Ahris =  
Ludwig=20

&lt;A=3D3D20<BR>&gt;&gt; &gt;&nbsp; =3D<BR>&gt;&gt;href=3D3D3D"<A=20  
=  
href=3D'mailto:chrisl@adkproaudio.com">chrisl@adkproaudio.com</A>=>=3D3D20=  
'>mailto:chrisl@adkproaudio.com"&gt;chrisl@adkproaudio.com&lt;/A&gt;&gt;=3D=  
3D20</A>=3D<BR>&gt;&gt;<BR>&gt;&gt;=20

&gt;&nbsp; wrote:&lt;BR&gt;&gt;Hi Lamont,&lt;BR&gt;&gt;Sorry to here =  
your=20

having =3D3D<BR>&gt;&gt; =  
&gt;trouble.&lt;BR&gt;&gt;What=3D3D20<BR>&gt;&gt;=20  
&gt;&nbsp; exact model of the Gigabyte board do you mean. The=20  
description=3D3D20<BR>&gt;&gt; &gt;&nbsp; =

you&lt;BR&gt;&lt;BR&gt;&gt;have here=20  
is vague. Is it a K8NS Ultra=3D3D20<BR>&gt;&gt; &gt;&nbsp;=20  
-939?&lt;BR&gt;&gt;&lt;BR&gt;&gt;Whe n you say you rebuilt do you mean =  
you=20

=3D3D<BR>&gt;&gt; &gt;reinstalled=3D3D20<BR>&gt;&gt; &gt;&nbsp; =  
windows from=20  
scratch?&lt;BR&gt;&gt;&lt;BR&gt;&gt; &lt;BR&gt;&gt;LaMont=20  
wrote:&lt;BR&gt;&gt;&gt; =3D3D<BR>&gt;&gt; &gt;Hi=3D3D20<BR>&gt;&gt; =  
&gt;&nbsp;=20

gang:&lt;BR&gt;&gt;&gt; I 'm having problems getting Paris to ip and=20  
=3D3D<BR>&gt;&gt; &gt;running. Paris=3D3D20<BR>&gt;&gt; &gt;&nbsp; =  
will=20

sometimes&lt;BR&gt;&gt;&gt; star, only to just freeze up and crash the =



=3D3D<BR>&gt; &gt;whole=3D3D20<BR>&gt; &gt;&nbsp; system. So, =  
 l=20  
 thought<BR>&gt;my<BR>&gt;&gt;&gt; ; Asus-Amd XP combo(with =  
 =3D3D<BR>&gt;&gt;=20  
 &gt;SATA-Firwire)=3D3D20<BR>&gt; &gt;&nbsp; was cause too much IRQ =  
 problems=20  
 for<BR>&gt;&gt;&gt; PAris.<BR>&gt;&gt;&gt;=3D3D20<BR>&gt;&gt; =  
 &gt;&nbsp;=20  
 &lt;BR>&gt;&gt;&gt; So, I rebuilt with my favorite stable =  
 =3D3D<BR>&gt;&gt;=20  
 &gt;mobo(Gigabyte).<BR>&gt;&gt;&gt;=3D 3D20 <BR>&gt;&gt; &gt;&nbsp;=20  
 &lt;BR>&gt;&gt;&gt; Here's the skinny: I just build a new Paris/Nuendo =  
 PC.=20  
 =3D3D<BR>&gt;&gt; &gt;Great very=3D3D20<BR>&gt;&gt; &gt;&nbsp;=20  
 very<BR>&gt;fast:<BR>&gt;&gt;&gt; ; Here are the =  
 configs:<BR>&gt;&gt;&gt;=20  
 =3D3D<BR>&gt;&gt; &gt;&lt;BR>&gt;&gt;&gt;=3D3D20<BR>&gt;&gt; &gt;&nbsp; =  
 -gigabyte=20  
 mobo 939 Ultra250<BR>&gt;&gt;&gt; -Dual core opteron =  
 =3D3D<BR>&gt;&gt;=20  
 &gt;165<BR>&gt;&gt;&gt;=3D3D20<BR>&gt;&gt; &gt;&nbsp; -2gig=20  
 ddr400<BR>&gt;&gt;&gt; -sata (onboard) 3 300 gig =  
 drives<BR>&gt;&gt;&gt;=20  
 =3D3D<BR>&gt;&gt; &gt;-(1) RME=3D3D20<BR>&gt;&gt; &gt;&nbsp; Digi 96=20  
 &lt;BR>&gt;&gt;&gt; -(1)Magma card (4 card EDS) &lt;BR>&gt;&gt;&gt;=20  
 -Matrox=3D3D20<BR>&gt;&gt; &gt;&nbsp; g450<BR>&gt;&gt;&gt; =  
 &lt;BR>&gt;&gt;&gt;=20  
 Well, Nuendo runs like a Deer!!! WOW.. =3D3D<BR>&gt;&gt; &gt;But=20  
 PAris=3D3D20<BR>&gt;&gt; &gt;&nbsp; is hit and miss. l=20  
 disabled:<BR>&gt;&gt;&gt; USB, SATA raid..A little =3D3D<BR>&gt;&gt; &gt; =  
  
 &gt;better, but=3D3D20<BR>&gt;&gt; &gt;&nbsp; I', starting to think =  
 that My=20  
 either<BR>&gt;&gt;&gt; my EdS cards or =3D3D<BR>&gt;&gt; &gt;Mec/442 =  
  
 are=3D3D20<BR>&gt;&gt; &gt;&nbsp; the problem. Just 2 weeks prior, the =  
  
 system<BR>&gt;was<BR>&gt;&gt;&gt; ; working =  
 =3D<BR>&gt;&gt;=3D3D<BR>&gt;&gt;=20  
 &gt;fine.=3D3D20<BR>&gt;&gt; &gt;&nbsp; &lt;BR>&gt;&gt;&gt; =  
 &lt;BR>&gt;&gt;&gt;=20  
 Note: In my studio I have a master power =3D3D<BR>&gt;&gt; &gt;switch=20  
 that=3D3D20<BR>&gt;&gt; &gt;&nbsp; start up the =  
 FUrman<BR>&gt;&gt;&gt; power=20  
 unit..The Magma and Mec units =3D3D<BR>&gt;&gt; &gt;were =  
 on=3D3D20<BR>&gt;&gt;=20  
 &gt;&nbsp; when I started up the system.<BR>&gt;&gt;&gt; Maybe PAris =  
 got a=20



=3D<BR>&gt;&gt;wrote in=3D20<BR>&gt;&gt; message &lt;A =  
=3D<BR>&gt;&gt;href=3D3D"<A=20  
=  
href=3D'news:44052522@linux">news:44052522@linux</A>...</DIV><BR>HEY=3D20=  
'>news:44052522@linux"&gt;news:44052522@linux&lt;/A&gt;...&lt;/DIV&gt;&lt;=  
&gt;&gt;BR&gt;&gt;HEY=3D20</A><BR>&gt;&gt;=20  
Tom,&lt;BR&gt;&gt;I'm in the Prcess of moving th magma card to differnt=20  
=3D<BR>&gt;&gt;slots..I'll let=3D20<BR>&gt;&gt; you&lt;BR&gt;&gt;know what =  
  
happens..&lt;BR&gt;&gt;&lt;BR&gt;&gt;"Tom Bruhl" &lt;&lt;A=3D20<BR>&gt;&gt; =  
href=3D3D"<A=20  
=  
href=3D'mailto:arpegio@comcast.net">arpegio@comcast.net</A>>=3D20'>mailto=  
:arpegio@comcast.net"&gt;arpegio@comcast.net&lt;/A&gt;&gt;=3D20</A><BR>&gt;&gt;=  
&gt;&gt;=20  
=  
wrote:&lt;BR&gt;&gt;&gt;&lt;BR&gt;&gt;&gt;&a mp;&lt;BR&gt;&gt;&gt;LaMont,&lt;BR&gt;&gt;&gt;EDS 1=  
with=20  
Matrox is a bad =3D<BR>&gt;&gt;<BR>&gt;&gt; thing.&nbsp;I'd try =  
different slots=20  
within&lt;BR&gt;&gt;&gt;the Magma to =  
=3D<BR>&gt;&gt;correct=3D20<BR>&gt;&gt;=20  
that.&nbsp;Have you tried any other slots on&lt;BR&gt;&gt;&gt;the mobo =  
for the=20  
=3D<BR>&gt;&gt;Magma=3D20<BR>&gt;&gt; card?&nbsp;That might be the =  
first thing=20  
unless&lt;BR&gt;&gt;&gt;you know that =  
=3D<BR>&gt;&gt;won't=3D20<BR>&gt;&gt;=20  
help.&lt;BR&gt;&gt;&gt;Tom&lt;BR&gt;&gt;&gt; &nbsp;"LaMont" =  
&lt;&lt;A=3D20<BR>&gt;&gt;=20  
href=3D3D"<A=20  
=  
href=3D'mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A'>mailto:jjdp=  
ro@ameritech.net"&gt;jjdpro@ameritech.net&lt;/A</A>&gt;&gt;=20  
=3D<BR>&gt;&gt;wrote in=3D20<BR>&gt;&gt; message=20  
=  
=3D3D&lt;BR&gt;&gt;&gt;news:4404e5bf\$1@linux...&lt;BR&gt;&gt;&gt;&lt;BR&gt;&gt;&gt;&n=  
bsp;=20  
Hi=3D20<BR>&gt;&gt; Chris,&lt;BR&gt;&gt;&gt;&nbsp; Fresh install of win =  
Xp/sp1. New=20  
drives, new =3D<BR>&gt;&gt;everything.=3D20<BR>&gt;&gt; I'm using=20  
=3D3D&lt;BR&gt;&gt;&gt;Apci,&lt;BR&gt;&gt;&gt; &nbsp; not Standard PC. Mother =  
Board=20  
=3D<BR>&gt;&gt;<BR>&gt;&gt; GA-K8NSC-939&lt;BR&gt;&gt;&gt;&nbsp; nforce-3 =  
ultra=20  
250gb.&lt;BR&gt;&gt;&gt;&lt;BR&gt;&gt;&gt;&a mp;&nbsp; =  
=3D<BR>&gt;&gt;-Maybe=3D20<BR>&gt;&gt;=20  
moving the magma(13 slot) to a differnt slot.(It's =

currently=3D20<BR>&gt;=20  
=3D3D<BR>&gt;residing<BR>&am p;gt;&nbsp; in PCI slot 4. =  
According to the=20  
=3D<BR>&gt;manual, slot 4=3D20<BR>&gt; and 2 are not shared.=20  
=3D3D<BR>&gt;Plus<BR>&gt; ;&nbsp; even with the Sata=20  
=3D<BR>&gt;<BR>&gt; controllers activated, each of the (4)eds=20  
cards=3D20<BR>&gt; =  
had<BR>=3D3D<BR>&gt;their& am p;lt;BR>&gt;&nbsp;=20  
own IRQ. However, 1 EDS card =3D<BR>&gt;shared =  
(IRQ=3D20<BR>&gt; 16) with=20  
the Matrox G450. =  
=3D3D<BR>&gt;Strange.<BR>& am p;gt;<BR>&gt;&nbsp;=20  
=3D<BR>&gt;'ve been=3D20<BR>&gt; looking into this PCI =  
latency issues and=20  
download an app=3D20<BR>&gt;=20  
to<BR>=3D3D<BR>&gt;look& lt;BR>&gt;&nbsp; and change =  
soem of the=20  
PCI latency =3D<BR>&gt;<BR>&gt;=20  
settings.=3D3D20<BR>&gt;<BR>&gt; &nbsp; The Sata controller =  
had a=20  
setting =3D<BR>&gt;of=3D20<BR>&gt; 0(zero). EDS scherzo (32)=20  
matrox<BR>=3D3D<BR>&gt;(64). .IDE<BR>&gt;&nbsp;=20  
=3D<BR>&gt;<BR>&gt; controller =  
(0)..<BR>&gt;& am p;gt;=20  
Thanks for your help=3D20<BR>&gt;=20  
=  
...LaMont<BR>&gt;<BR>&gt; ;<BR>&gt;&nbsp; sp;&nb  
sp;=20  
Ahris Ludwig =3D<BR>&gt;&lt;A=3D20<BR>&gt; href=3D3D"<A=20  
=  
href=3D'mailto:chrisl@adkproaudio.com">chrisl@adkproaudio.com</A>=>=3D20'>=  
mailto:chrisl@adkproaudio.com"&gt;chrisl@adkproaudio.com</A>&gt;=3D=  
20</A><BR>&gt;=20  
wrote:<BR>&gt;&nbsp; &gt;Hi Lamont,<BR>&gt;&nbsp; =  
&gt;Sorry to=20  
here =3D<BR>&gt;your=3D20<BR>&gt; having =  
trouble.<BR>&gt;&nbsp;=20  
&gt;What exact model of the Gigabyte =3D<BR>&gt;board =  
do=3D20<BR>&gt; you=20  
mean. The description =  
=3D3D<BR>&gt;you<BR>&gt; &lt;BR>&gt;&nbsp;=20  
=3D<BR>&gt;<BR>&gt;have here =  
is=3D20<BR>&gt;<BR>&gt; vague. Is=20  
it a K8NS Ultra -939?<BR>&gt;&nbsp; &gt;<BR>&gt;&nbsp;=20  
=3D<BR>&gt;<BR>&gt;&gt;When you=3D20<BR>&gt;<BR>&gt; =  
say you=20  
rebuilt do you mean you reinstalled windows from=3D20<BR>&gt;=20  
=3D3D<BR>&gt;scratch?<BR>& am p;gt;&nbsp; =

&lt;BR>&gt;&nbsp;=20  
=3D<BR>&gt;&lt;BR>&gt;&gt;&lt;BR>&gt;& =  
=3D20<BR>&gt;&lt;BR>&gt;&=20  
&gt;LaMont wrote:&lt;BR>&gt;&nbsp; &gt;&gt; Hi =  
gang:&lt;BR>&gt;&nbsp;=20  
=3D<BR>&gt;&lt;BR>&gt;&gt;&lt;BR>&gt;& I 'm=3D20<BR>&gt;&lt;BR>&gt;& =  
having=20  
problems getting Paris to ip and running. Paris will=3D20<BR>&gt;&=20  
=3D3D&lt;BR>&gt;&sometimes&lt;BR>&gt;& a mp;&gt;&nbsp; &gt;&gt; star, only =  
to just=20  
freeze =3D<BR>&gt;&up and=3D20<BR>&gt;& crash the whole system. =  
So, I=20  
=3D3D&lt;BR>&gt;&thought&lt;BR>&gt;& &gt;&nbsp; =  
=3D<BR>&gt;&my&lt;BR>&gt;&=20  
=3D20<BR>&gt;& &gt;&gt; Asus-Amd XP combo(with SATA-Firwire) was =  
cause too=20  
much IRQ=3D20<BR>&gt;& =3D3D&lt;BR>&gt;&problems =  
for&lt;BR>&gt;&nbsp;=20  
&gt;&gt; PAris.&lt;BR>&gt;& =3D20<BR>&gt;&=20  
&gt;&gt;=3D3D20&lt;BR>&gt;&&nbsp; &gt;&gt; So, I rebuilt with my =  
favorite=20  
=3D<BR>&gt;&stable=3D20<BR>&gt;& =  
mobo(Gigabyte).&lt;BR>&gt;&&nbsp;=20  
&gt;&gt;=3D3D20&lt;BR>&gt;&&nbsp; &gt;&gt; =3D<BR>&gt;&Here's=20  
the=3D20<BR>&gt;& skinny: I just build a new Paris/Nuendo PC. Great =  
  
very=3D20<BR>&gt;& =3D3D&lt;BR>&gt;&very&lt;BR>&gt;& &nbsp;=20  
fast:&lt;BR>&gt;&&nbsp; &gt;&gt; Here are =  
=3D<BR>&gt;&the=3D20<BR>&gt;&=20  
configs:&lt;BR>&gt;&&nbsp; &gt;&gt;=3D3D20&lt;BR>&gt;&&nbsp; =  
&gt;&gt;=20  
-gigabyte =3D<BR>&gt;&mobo 939=3D20<BR>&gt;& =  
Ultra250&lt;BR>&gt;&&nbsp;=20  
&gt;&gt; -Dual core opteron 165&lt;BR>&gt;&&nbsp;=20  
=3D<BR>&gt;&& &gt;&gt;=3D20 <BR>&gt;&& &gt;&gt; -2gig =  
  
ddr400&lt;BR>&gt;&&nbsp; &gt;&gt; -sata (onboard) 3 300 =  
gig=3D20<BR>&gt;&=20  
drives&lt;BR>&gt;&&nbsp; &gt;&gt; -(1) RME Digi =  
96=3D3D20&lt;BR>&gt;&&nbsp;=20  
=3D<BR>&gt;&& &gt;&gt;=3D20 <BR>&gt;&& &gt;&gt; =  
-(1)Magma card (4=20  
card EDS)=3D3D20&lt;BR>&gt;&&nbsp; &gt;&gt; -Matrox=3D20<BR>&gt;&& =  
  
g450&lt;BR>&gt;&&nbsp; &gt;&gt;=3D3D20&lt;BR>&gt;&&nbsp; &gt;&gt; =  
Well,=20  
Nuendo =3D<BR>&gt;&runs like a=3D20<BR>&gt;& Deer!!! WOW.. But =  
PARis is hit=20

and miss. =  
=3D<BR> &gt;&gt;l&lt;BR&gt;=3D3D&lt;BR&gt;&a mp;gt;disabled:&lt;BR&gt;&gt;=20  
=3D20<BR>&gt;&gt; &gt;&gt; USB, SATA raid..A little better, but l', =  
starting to=20  
think =3D<BR>&gt;&gt;that=3D20<BR>&gt;&gt;=20  
My&lt;BR&gt;=3D3D&lt;BR&gt;&gt;either&am p;lt;BR&gt;&gt;&nbsp; &gt;&gt; my =  
EdS cards=20  
or Mec/442 =3D<BR>&gt;&gt;are the=3D20<BR>&gt;&gt; problem. Just 2 =  
weeks prior,=20  
the =3D3D&lt;BR&gt;&gt;system&lt;BR&gt;& gt; =3D20<BR>&gt;&gt;=20  
was&lt;BR&gt;&gt;&nbsp; &gt;&gt; working fine.=3D3D20&lt;BR&gt;&gt;=20  
=3D20<BR>&gt;&gt; &gt;&gt;=3D3D20&lt;BR&gt;&gt;&nbsp; &gt;&gt; Note =  
In my studio=20  
I have a =3D<BR>&gt;&gt;master power=3D20<BR>&gt;&gt; switch that =  
start up the=20  
=3D3D&lt;BR&gt;&gt;Furman&lt;BR&gt;& gt;&nbsp; &gt;&gt;=20  
=3D<BR>&gt;&gt;power=3D20<BR>&gt;&gt; unit..The Magama and Mec units =  
were on when=20  
I started up=3D20<BR>&gt;&gt;=20  
the&lt;BR&gt;=3D3D&lt;BR&gt;&gt;system.& amp;lt;BR&gt;&gt;&nbsp; &gt;&gt; =  
Maybe Paris=20  
got a =3D<BR>&gt;&gt;Jolt ??? l=3D20<BR>&gt;&gt; don;t =  
know..&lt;BR&gt;&gt;&nbsp;=20  
&gt;&gt; Please help..Thanks&lt;BR&gt;&gt; =3D20<BR>&gt;&gt;=20  
&gt;&gt;=3D3D20&lt;BR&gt;&gt;&nbsp; &gt;&lt;BR&gt;&gt;&nbsp; =  
&gt;&lt;BR&gt;&gt;=20  
=3D20<BR>&gt;&gt; &gt;&lt;BR&gt;&gt;&nbsp; &gt;&lt;BR&gt;&gt;&nbsp;=20  
&gt;Chris&lt;BR&gt;&gt; =3D20<BR>&gt;&gt; &gt;&lt;BR&gt;&gt;&nbsp;=20  
&gt;--=3D3D20&lt;BR&gt;&gt;&nbsp; &gt;Chris =  
=3D<BR>&gt;&gt;Ludwig&lt;BR&gt;&gt;=20  
=3D20<BR>&gt;&gt; &gt;&lt;BR&gt;&gt;&nbsp; &gt;ADK Pro =  
Audio&lt;BR&gt;&gt;&nbsp;=20  
&gt;(859)=3D20<BR>&gt;&gt; 635-5762&lt;BR&gt;&gt;&nbsp;=20  
&gt;www.adkproaudio.com&lt;BR&gt;&gt; =3D20<BR>&gt;&gt;=20  
=  
&gt;chrisl@adkproaudio.com &lt;BR&gt;&gt;&lt;BR&gt;&gt;&lt; BR&gt;&gt;&lt;!=  
DOCTYPE=20  
HTML =3D<BR>&gt;&gt;PUBLIC=3D20<BR>&gt;&gt; "-//W3C//DTD HTML =  
4.0=3D20<BR>&gt;&gt;=20  
=  
Transitional//EN" &gt;&lt;BR&gt;&gt;&lt;HTML&gt;&l t;HEAD&gt;&lt;BR&gt;&gt;=  
&lt;META=3D20<BR>&gt;&gt;=20  
http-equiv=3D3D3DContent-Type =  
content=3D3D3D"text/html;=3D20<BR>&gt;&gt;=20  
=3D3D&lt;BR&gt;&gt;&gt;charset=3D3D3Diso-8859-1"&gt;&lt;BR&gt;&gt;&lt;META =  
=3D<BR>&gt;&gt;content=3D3D3D"MSHTML=3D20<BR>&gt;&gt; =  
6.00.2800.1400"=3D20<BR>&gt;&gt;=20

=  
=3D<BR> &gt;&gt;name=3D3D3DGENERATOR&gt;&lt;BR&g t;&gt;&lt;STYLE&gt;&lt;/ST=  
YLE&gt;&lt;BR&gt;&gt;&lt;/HEA=3D<BR> &gt;&gt;D&gt;&lt;BR&gt;&gt;&lt;B ODY=3D=  
20<BR>&gt;&gt;=20  
bgColor=3D3D3D#ffffff&gt;&lt;BR&gt;&gt;& lt;DIV&gt;&lt;FONT=20  
face=3D3D3DArial=3D20<BR>&gt;&gt;=20  
=  
=3D<BR> &gt;&gt;size=3D3D3D2&gt;&lt;LaMont,&lt;/FONT&amp ;gt;&lt;/DIV&gt;&lt;BR&gt;=  
&gt;&lt;DIV&gt;&lt;FONT=3D<BR>&gt;&gt;=3D20 <BR>&gt;&gt;=20  
face=3D3D3DArial size=3D3D3D2&gt;&lt;EDS1 with Matrox is a bad thing.=20  
=3D<BR>&gt;&gt;=3D3D&lt;BR&gt;&gt;&lt;d=3D20 <BR>&gt;&gt;=20  
try=3D3D20&lt;BR&gt;&gt;&lt;different slots=3D20<BR>&gt;&gt;=20  
within&lt;/FONT&gt;&lt;/DIV&gt;&lt;BR&am p;gt;&gt;&lt;DIV&gt;&lt;FONT=20  
=3D<BR>&gt;&gt;face=3D3D3DArial=3D20<BR>&gt;&gt; size=3D3D3D2&gt;&lt;the =  
Magma to correct=20  
that. Have =3D3D&lt;BR&gt;&gt;you tried=3D20<BR>&gt;&gt;=20  
any=3D3D20&lt;BR&gt;&gt;&lt;other slots=3D20<BR>&gt;&gt;=20  
on&lt;/FONT&gt;&lt;/DIV&gt;&lt;BR&gt ;&gt;&lt;DIV&gt;&lt;FONT=20  
face=3D3D3DArial=3D20<BR>&gt;&gt; size=3D3D3D2&gt;&lt;the mobo for the =  
Magma card? That=20  
=3D3D&lt;BR&gt;&gt;might =  
=3D<BR>&gt;&gt;be=3D3D20&lt;BR&gt;&gt;&lt;the=3D20 <BR>&gt;&gt;=20  
first thing =  
unless&lt;/FONT&gt;&lt;/DIV&gt;&lt;BR&am p;gt;&gt;&lt;DIV&gt;&lt;FONT=20  
=3D<BR>&gt;&gt;<BR>&gt;&gt; face=3D3D3DArial size=3D3D3D2&gt;&lt;you know =  
that=20  
won't=3D20<BR>&gt;&gt;=20  
help.&lt;/FONT&gt;&lt;/DIV&gt;&lt;BR&amp ;gt;&gt;&lt;DIV&gt;&lt;FONT=20  
=3D<BR>&gt;&gt;face=3D3D3DArial=3D20<BR>&gt;&gt;=20  
=  
=3D<BR> &gt;&gt;size=3D3D3D2&gt;&lt;Tom&lt;/FONT&gt; &lt;/DIV&gt;&lt;BR&gt;&gt;=  
&lt;BLOCKQUOTE=3D3D20&lt;BR&gt;=3D<BR>&gt;&gt; <BR>&gt;&gt;&gt;style=3D3D3=  
D"PADDING-RIGHT:=3D20<BR>&gt;&gt;<BR>&gt;&gt;&gt;=20  
0px; PADDING-LEFT: 5px; MARGIN-LEFT: 5px; =  
=3D3D&lt;BR&gt;&gt;&lt;BORDER-LEFT:=20  
=3D<BR>&gt;&gt;#000000 2px=3D20<BR>&gt;&gt; solid; MARGIN-RIGHT:=20  
0px"&gt;&lt;BR&gt;&gt;&lt; &nbsp; &lt;DIV&gt;"LaMont"=3D20<BR>&gt;&gt;=20  
&lt;&lt;A=3D3D20&lt;BR&gt;&gt;&lt; &nbsp; =  
href=3D3D3D"&lt;A=3D20<BR>&gt;&gt;=20  
=  
=3D<BR>&gt;&gt;href=3D3D'mailto:jjdpro@ameritech.net"&gt;jjdpro@ameritech=  
..net&lt;/A'&gt;mailto:jjdp=3D<BR>&gt;&gt;ro@ameritech.net"&gt;jjdpro@amer=  
itech.net&lt;/A&lt;/A&gt;&gt;&gt;=3D20<BR >&gt;&gt;=20  
=3D3D&lt;BR&gt;&gt;&lt;wrote in=3D3D20&lt;BR&gt;&gt;&lt; &nbsp; message=20  
=3D<BR>&gt;&gt;&lt;A=3D3D20&lt;BR&gt;&gt;&lt; =3D20<BR>&gt;&gt;=20  
=3D3D&lt;BR&gt;&gt;&lt;href=3D3D3D"&lt;A=3D20<BR >&gt;&gt;=20  
=  
=3D<BR>&gt;&gt;href=3D3D'news:4404e5bf\$1 @linux"&gt;news:4404e5bf\$1 @linux&=

Hi=3D3 D=3D <BR>&gt;20'&gt;news:4404e=5bf\$1 @linux"&gt;news:4404e5bf\$1 @linux&lt;/A&gt;...&lt;/DIV&am p;=3D<BR>&gt; ;&gt; ;&lt;/BR&gt;Hi=3D3D20&lt;/A&gt;&am p; ;&lt;/BR&gt;&gt;=20 =3D20<BR>&gt; Chris,&lt;/BR&gt;Fresh install of win Xp/sp1. New = drives, new=20 =3D<BR>&gt;&gt;everything.=3D20<BR>&gt;&gt;=20 I'm&lt;/BR&gt;=3D3D&lt;/BR&gt;&gt;using=3D 3D20&lt;/BR&gt;&gt;&nbsp;=20 Apci,&lt;/BR&gt;not Standard =3D<BR>&gt;&gt;PC. Mother=3D20<BR>&gt;&gt; = Board=20 GA-K8NSC-939&lt;/BR&gt;nforce-3 ultra=3D3D20&lt;/BR&gt;&gt; = =3D20<BR>&gt;&gt;=20 250gb.&lt;/BR&gt;&lt;/BR&gt;-Maybe moving the magma(13 slot) to a=20 =3D<BR>&gt;&gt;differnt=3D20<BR>&gt;&gt;=20 =3D3D&lt;/BR&gt;&gt;&gt;slot.(It's=3D3D20&lt;/BR&a mp; ;&gt;&gt;&nbsp; currently=20 =3D<BR>&gt;&gt;residing&lt;/BR&gt;in PCI slot=3D20<BR>&gt;&gt; 4. = According to the=20 manual, slot 4 =3D3D&lt;/BR&gt;&gt;&gt;and 2=20 =3D<BR> &gt;&gt;are=3D3D20&lt;/BR&gt;&gt;&gt;&nbsp; p; not=3D20<BR>&gt;&gt; = shared.=20 Plus&lt;/BR&gt;even with the Sata controllers activated, = each=3D20<BR>&gt;&gt;=20 of&lt;/BR&gt;=3D3D&lt;/BR&gt;&gt;&gt;the=3D3D2 0&lt;/BR&gt;&gt;&nbsp; (4)eds = cards had=20 =3D<BR>&gt;&gt;their&lt;/BR&gt;own IRQ.=3D20<BR>&gt;&gt; However, 1 EDS = card shared=20 (IRQ = =3D<BR> &gt;&gt;16)&lt;/BR&gt;=3D3D&lt;/BR&gt; &gt;&gt;with=3D3D20&lt;/BR&gt;&gt;& =&nbsp;=20 the=3D20<BR>&gt;&gt; Matrox G450. Strange..&lt;/BR&gt;&lt;/BR&gt;I've = been looking=20 into this =3D<BR>&gt;&gt;PCI=3D20<BR>&gt;&gt;=20 =3D3D&lt;/BR&gt;&gt;&gt;latency=3D3D20&lt;/BR& gt;&gt;&nbsp; issues and = download an app=20 to=3D20<BR>&gt;&gt; look&lt;/BR&gt;and change soem of the PCI=20 =3D<BR> &gt;&gt;=3D3D&lt;/BR&gt;&gt;&gt;latency=3D3D2 0&lt;/BR&gt;&gt;& = =3D20<BR>&gt;&gt;=20 settings. &lt;/BR&gt;&lt;/BR&gt;The Sata controller had a setting of=20 =3D<BR>&gt;&gt;0(zero).=3D20<BR>&gt;&gt; EDS=20 =3D3D&lt;/BR&gt;&gt;&gt;scherzo=3D3D20&lt;/BR& gt;&gt;&nbsp; (32) = matrox=3D20<BR>&gt;&gt;=20 (64)..IDE&lt;/BR&gt;controller (0)..&lt;/BR&gt;&lt;/BR&gt;Thanks for your = =3D<BR>&gt;&gt;<BR>&gt;&gt; help=3D3D20&lt;/BR&gt;&gt;&nbsp;=20 =3D<BR> &gt;&gt;..LaMont&lt;/BR&gt;&lt;/BR&gt; &lt;/BR&gt;&lt;/BR&gt;=20 Ahris=3D20<BR>&gt;&gt; Ludwig &lt;/BR&gt;&lt;/BR&gt;&nbsp; =20 href=3D3D3D"&lt;/BR&gt;&lt;/BR&gt;=20 = =3D<BR>&gt;&gt;href=3D3D'mailto:chrisl@adkproaudio.com"&gt;chrisl@adkproa=



udio.com&lt;/A&gt;&gt;=3D3D20'&gt;=3D<BR>&gt;&gt;mailto:chrisl@adkproaudi=  
o.com"&gt;chrisl@adkproaudio.com&lt;/A&gt;&gt;=3D3D=3D<BR>&gt;&gt;20&lt;/=  
A&gt;&lt;BR&gt;&gt;=20  
=3D20<BR>&gt;&gt; wrote:&lt;BR&gt;&gt;&gt;Hi Lamont,&lt;BR&gt;&gt;&gt;Sorry to =  
here your=20  
having=3D20<BR>&gt;&gt;=20  
=  
=3D3D&lt;BR&gt;&gt;&gt;trouble.&lt;BR&gt;&gt;&gt;What=3D3D20&lt;BR&gt;&gt;&gt;&nbsp; =  
exact=20  
model =3D<BR>&gt;&gt;of the=3D20<BR>&gt;&gt; Gigabyte board do you =  
mean. The=20  
description=3D3D20&lt;BR&gt;&gt;&gt; =3D20<BR>&gt;&gt; =  
you&lt;BR&gt;&lt;BR&gt;&gt;&gt;have=20  
here is vague. Is it a K8NS=3D20<BR>&gt;&gt; =  
Ultra=3D3D20&lt;BR&gt;&gt;&gt;&nbsp;=20  
-939?&lt;BR&gt;&gt;&lt;BR&gt;&gt;&gt;Whe n you say =  
=3D<BR>&gt;&gt;you=3D20<BR>&gt;&gt;=20  
rebuilt do you mean you =  
=3D3D&lt;BR&gt;&gt;&gt;reinstalled=3D3D20&lt;BR&gt;&gt;&gt;&nbsp;=20  
=3D<BR>&gt;&gt;windows from=3D20<BR>&gt;&gt;=20  
=  
scratch?&lt;BR&gt;&gt;&lt;BR&gt;&gt;&gt; &lt;BR&gt;&gt;&gt;LaMont=3D20 <BR>&gt;&gt;=  
=20  
wrote:&lt;BR&gt;&gt;&gt; =  
=3D3D&lt;BR&gt;&gt;&gt;Hi=3D3D20&lt;BR&gt;&gt;&gt;&nbsp;=20  
=3D<BR>&gt;&gt; &gt;&gt;gang:&lt;BR&gt;&gt;&gt;=3D20 <BR>&gt;&gt; I 'm having =  
problems=20  
getting Paris to ip and =3D3D&lt;BR&gt;&gt;&gt;running.=3D20<BR>&gt;&gt;=20  
Paris=3D3D20&lt;BR&gt;&gt;&gt;&nbsp; will sometimes&lt;BR&gt;&gt;&gt; =  
star, only=20  
=3D<BR>&gt;&gt;to just=3D20<BR>&gt;&gt; freeze up and crash the=20  
=3D3D&lt;BR&gt;&gt;&gt;whole=3D3D20&lt;BR&gt;&gt;&gt; &gt;&nbsp; system. =  
=3D<BR>&gt;&gt;So,=20  
I=3D20<BR>&gt;&gt; thought&lt;BR&gt;&gt;my&lt;BR&gt;&gt;&gt; ; Asus-Amd XP=20  
combo(with=3D20<BR>&gt;&gt;=20  
=3D3D&lt;BR&gt;&gt;&gt;SATA-Firwire)=3D3D20&lt;BR&gt;&gt;&gt;&nbsp; was cause =  
too much IRQ=20  
=3D<BR>&gt;&gt;problems=3D20<BR>&gt;&gt; for&lt;BR&gt;&gt;&gt;=20  
PARis.&lt;BR&gt;&gt;&gt;=3D3D20&lt;BR&gt;&gt;&gt;&nbsp; =  
&lt;BR&gt;&gt;&gt;=20  
So, I rebuilt with my favorite stable=3D20<BR>&gt;&gt;=20  
=  
=3D3D&lt;BR&gt;&gt;&gt;mobo(Gigabyte).&lt;BR&gt;&gt;&gt;=3D3D20&lt;BR&gt;&gt;&gt;=  
&nbsp;=20  
=3D<BR>&gt;&gt;&lt;BR&gt;&gt;&gt;=3D20 <BR>&gt;&gt; Here's the skinny: =  
I just build=20  
a new Paris/Nuendo PC. =  
=3D<BR>&gt;&gt;=3D3D&lt;BR&gt;&gt;&gt;Great=3D20 <BR>&gt;&gt;=20

very=3D3D20<BR>&gt;&nbsp; very<BR>&gt;&gt; ; =  
Here are=20  
=3D<BR>&gt;&gt;the=3D20<BR>&gt;&gt; configs:<BR>&gt;&gt;=20  
=  
=3D<BR> &gt;&gt;=3D3D<BR>&gt;&gt;<BR>&am p;&gt;&gt;&gt;=3D3D20<BR>&gt;&gt;=  
=20  
=3D20<BR>&gt;&gt; -gigabyte mobo 939 Ultra250<BR>&gt;&gt;&gt; -Dual =  
core=20  
opteron=3D20<BR>&gt;&gt;=20  
=3D3D<BR>&gt;&gt;165<BR>&gt;&gt; &gt;=3D3D20<BR>&gt;&gt;&nbsp; =  
-2gig=20  
=3D<BR> &gt;&gt;ddr400<BR>&gt;&gt;&gt;=3D2 0 <BR>&gt;&gt; -sata =  
(onboard) 3 300 gig=20  
drives<BR>&gt;&gt;&gt; =3D3D<BR>&gt;&gt;&gt;-(1)=3D20<BR>&gt;&gt;=20  
RME=3D3D20<BR>&gt;&gt;&nbsp; Digi 96 <BR>&gt;&gt;&gt; -(1)Magma =  
card (4=20  
=3D<BR>&gt;&gt;card EDS)=3D20<BR>&gt;&gt; <BR>&gt;&gt;=20  
-Matrox=3D3D20<BR>&gt;&gt;&nbsp; =  
g450<BR>&gt;&gt;&gt;=3D20<BR>&gt;&gt;=20  
<BR>&gt;&gt;&gt; Well, Nuendo runs like a Deer!!! WOW..=20  
=3D<BR>&gt;&gt;=3D3D<BR>&gt;&gt;But=3D20 <BR>&gt;&gt;=20  
PAris=3D3D20<BR>&gt;&gt;&nbsp; is hit and miss. I=20  
=3D<BR>&gt;&gt;disabled:<BR>&gt;&gt;&gt; USB,=3D20<BR>&gt;&gt; SATA =  
raid..A=20  
little =3D3D<BR>&gt;&gt;better, but=3D3D20<BR>&gt;&gt;&nbsp; I,=20  
=3D<BR>&gt;&gt;starting to=3D20<BR>&gt;&gt; think that My =  
either<BR>&gt;&gt;&gt;=20  
my EdS cards or =  
=3D<BR>&gt;&gt;=3D3D<BR>&gt;&gt;Mec/442=3D20 <BR>&gt;&gt;=20  
are=3D3D20<BR>&gt;&gt;&nbsp; the problem. Just 2 weeks prior,=20  
the=3D20<BR>&gt;&gt; system<BR>&gt;was<BR>&gt;&gt;&gt; working=20  
=3D<BR> &gt;&gt;=3D3D<BR>&gt;&gt;fine.=3D3D20& amp;lt;&gt;&gt; =  
=3D20<BR>&gt;&gt;=20  
<BR>&gt;&gt;&gt; <BR>&gt;&gt;&gt; Note: In my studio I have a=20  
=3D<BR>&gt;&gt;master power=3D20<BR>&gt;&gt; =3D3D<BR>&gt;&gt;switch =  
  
that=3D3D20<BR>&gt;&gt;&nbsp; start up the=20  
=3D<BR> &gt;&gt;FURman<BR>&gt;&gt;&gt;=3D2 0 <BR>&gt;&gt; power =  
unit..The Magama=20  
and Mec units =3D3D<BR>&gt;&gt;were =  
=3D<BR> &gt;&gt;on=3D3D20<BR>&gt;&gt;&nbsp; =20  
when I=3D20<BR>&gt;&gt; started up the system.<BR>&gt;&gt;&gt; Maybe =  
PARis got=20  
a Jolt ??? I=3D20<BR>&gt;&gt; =  
=3D3D<BR>&gt;&gt;don;t=3D3D20<BR>&gt;&gt; &gt;&nbsp;=20  
know..<BR>&gt;&gt;&gt; Please=3D20<BR>&gt;&gt;=20  
help..Thanks<BR>&gt;&gt;&gt;=3D3D20<BR>&gt;&gt; =3D20<BR>&gt;&gt;=20  
=  
=

=3D<BR> &gt;&gt;&lt;BR&gt;&gt;&lt;BR&gt; &gt;&lt;BR&gt;&gt;&lt;BR&gt;&gt; &l=  
t;BR&gt;&gt;Chr=3D<BR> &gt;&gt;is&lt;BR&gt;&gt;&lt;BR&g t;&gt;--=3D20 <BR>&g=  
t;&gt;=20  
=3D3D&lt;BR&gt;&gt;&lt;BR&gt;&gt;Chr is=3D3D20&lt;BR&gt;&gt; =  
=3D20<BR>&gt;&gt;=20  
Ludwig&lt;BR&gt;&gt;&lt;BR&gt;&gt;AD K Pro=3D20<BR>&gt;&gt;=20  
Audio&lt;BR&gt;&gt;(859)=3D3D20&lt;BR&gt; ;&gt; =3D20<BR>&gt;&gt;=20  
=  
=3D<BR> &gt;&gt;=3D3D&lt;BR&gt;&gt;635-5762& lt;BR&gt;&gt;www.adkproaudio.c=  
om&lt;BR&gt;&gt;chrisl@=3D<BR> &gt;&gt;adkproaudio.com&lt;BR&gt;&lt;/BL =3D=  
3D&lt;BR&gt;&gt;OCKQUOTE&gt;&lt;/BODY&am p;gt;&lt;/=3D <BR>&gt;&gt;HTML&gt;&lt;=  
BR&gt;&gt;&lt;BR&gt;&gt;&lt;BR&g t;&lt;/BLOCKQUOTE&gt;&lt;/BODY&gt;&lt;/H T=  
ML&gt;<BR>&gt;&gt;<BR>&gt;&gt;<BR>&gt;&gt;=20  
<BR><BR>-- <BR>Chris Ludwig<BR>ADK<BR><A=20  
href=3D"mailto:chrisl@adkproaudio.com">chrisl@adkproaudio.com</A> =  
&lt;<A=20  
=  
href=3D"mailto:chrisl@adkproaudio.com">mailto:chrisl@adkproaudio.com</A>&=  
gt;<BR><A=20  
href=3D"http://www.adkproaudio.com">www.adkproaudio.com</A> &lt;<A=20  
=  
href=3D"http://www.adkproaudio.com/">http://www.adkproaudio.com/</A>&gt;<=  
BR>(859)=20  
635-5762</BLOCKQUOTE></BODY></HTML>

-----=\_NextPart\_000\_0029\_01C63D19.45777050--

---

Subject: Re: Paris Problems on new machine: Hey Chris Ludwig...!  
Posted by [Miguel Vigil \[1\]](#) on Wed, 01 Mar 2006 16:32:21 GMT  
[View Forum Message](#) <> [Reply to Message](#)

Hello Chris,

>> > not Standard PC. Mother Board GA-K8NSC-939

re above mobo, which does not have the firewire i/o,  
is there any major difference to the more expensive and  
elusive K8ns ultra pro you have touted?

TIA,

EI Miguel

"Chris Ludwig" <chrisl@adkproaudio.com> wrote in message  
news:4405b024@linux...  
> Hi Lamont,  
> Wow weird stuff. Glad its working now.  
>  
> Chris  
>  
>  
> LaMont wrote:  
>> Tom & Chris,  
>>  
>> I got it solved. It was the Magma Chasis's power supply was not "seated"  
>> into slot properly. Paris is working fine now.  
>> Thanks  
>>  
>> "Tom Bruhl" <arpegio@comcast.net> wrote:  
>>  
>>>  
>>>LM,  
>>>Can't wait to hear.  
>>>T.  
>>> "LaMont" <jjdpro@ameritech.net> wrote in message =  
>>>news:44052522@linux...  
>>>  
>>> HEY Tom,  
>>> I'm in the Prcess of moving th magma card to differnt slots..I'll let  
>>  
>> =  
>>  
>>>you  
>>> know what happens..  
>>>  
>>> "Tom Bruhl" <arpegio@comcast.net> wrote:  
>>> >  
>>> >  
>>> >LaMont,  
>>> >EDS1 with Matrox is a bad thing. I'd try different slots within  
>>> >the Magma to correct that. Have you tried any other slots on  
>>> >the mobo for the Magma card? That might be the first thing unless  
>>> >you know that won't help.  
>>> >Tom  
>>> > "LaMont" <jjdpro@ameritech.net> wrote in message =3D  
>>> >news:4404e5bf\$1@linux...  
>>> >  
>>> > Hi Chris,  
>>> > Fresh install of win Xp/sp1. New drives, new everything. I'm using  
>>

> > =  
> >  
> >>=3D  
> >> >Apci,  
> >> > not Standard PC. Mother Board GA-K8NSC-939  
> >> > nforce-3 ultra 250gb.  
> >> >  
> >> > -Maybe moving the magma(13 slot) to a differnt slot.(It's currently  
> >  
> > =  
> >  
> >>=3D  
> >> >residing  
> >> > in PCI slot 4. According to the manual, slot 4 and 2 are not =  
> >>shared. =3D  
> >> >Plus  
> >> > even with the Sata controllers activated, each of the (4)eds cards  
> >  
> > =  
> >  
> >>had  
> >> =3D  
> >> >their  
> >> > own IRQ. However, 1 EDS card shared (IRQ 16) with the Matrox G450.  
> >  
> > =  
> >  
> >>=3D  
> >> >Strange..  
> >> >  
> >> > I've been looking into this PCI latency issues and download an app  
> >  
> > =  
> >  
> >>to  
> >> =3D  
> >> >look  
> >> > and change soem of the PCI latency settings.=3D20  
> >> >  
> >> > The Sata controller had a setting of 0(zero). EDS scherzo (32) =  
> >>matrox  
> >> =3D  
> >> >(64)..IDE  
> >> > controller (0)..  
> >> >  
> >> > Thanks for your help ..LaMont  
> >> >  
> >> >

> > >  
> > > Ahris Ludwig <chrisl@adkproaudio.com> wrote:  
> > > >HI Lamont,  
> > > >Sorry to here your having trouble.  
> > > >What exact model of the Gigabyte board do you mean. The =  
> >>description =3D  
> >>you  
> >>>  
> >>> >have here is vague. Is it a K8NS Ultra -939?  
> >>> >  
> >>> >When you say you rebuilt do you mean you reinstalled windows from  
> >  
> > =  
> >  
> >>=3D  
> >> >scratch?  
> >>> >  
> >>> >  
> >>> >LaMont wrote:  
> >>> >> Hi gang:  
> >>> >> I 'm having problems getting Paris to ip and running. Paris will  
> >  
> > =  
> >  
> >>=3D  
> >> >sometimes  
> >> >> star, only to just freeze up and crash the whole system. So, I =  
> >>=3D  
> >> >thought  
> >>> my  
> >>> >> Asus-Amd XP combo(with SATA-Firwire) was cause too much IRQ =3D  
> >> >problems for  
> >>> >> PAris.  
> >>> >>=3D20  
> >>> >> So, I rebuilt with my favorite stable mobo(Gigabyte).  
> >>> >>=3D20  
> >>> >> Here's the skinny: I just build a new Paris/Nuendo PC. Great =  
> >>very =3D  
> >> >very  
> >>> fast:  
> >>> >> Here are the configs:  
> >>> >>=3D20  
> >>> >> -gigabyte mobo 939 Ultra250  
> >>> >> -Dual core opteron 165  
> >>> >> -2gig ddr400  
> >>> >> -sata (onboard) 3 300 gig drives  
> >>> >> -(1) RME Digi 96=3D20  
> >>> >> -(1)Magma card (4 card EDS)=3D20

> >> > >> -Matrox g450  
> >> > >>=3D20  
> >> > >> Well, Nuendo runs like a Deer!!! WOW.. But PAris is hit and =  
> >>miss. I  
> >> =3D  
> >> >disabled:  
> >> > >> USB, SATA raid..A little better, but I', starting to think that  
> >  
> > =  
> >  
> >>My  
> >> =3D  
> >> >either  
> >> > >> my EdS cards or Mec/442 are the problem. Just 2 weeks prior, the  
> >  
> > =  
> >  
> >>=3D  
> >> >system  
> >> > was  
> >> > >> working fine.=3D20  
> >> > >>=3D20  
> >> > >> Note: In my studio I have a master power switch that start up =  
> >>the =3D  
> >> >FUrman  
> >> > >> power unit..The Magama and Mec units were on when I started up =  
> >>the  
> >> =3D  
> >> >system.  
> >> > >> Maybe PAris got a Jolt ??? I don;t know..  
> >> > >> Please help..Thanks  
> >> > >>=3D20  
> >> > >  
> >> > >  
> >> > >  
> >> > >  
> >> > >  
> >> > >Chris  
> >> > >  
> >> > >=3D20  
> >> > >Chris Ludwig  
> >> > >  
> >> > >ADK Pro Audio  
> >> > >(859) 635-5762  
> >> > >www.adkproaudio.com  
> >> > >chrisl@adkproaudio.com  
> >> >  
> >> >  
> >> ><!DOCTYPE HTML PUBLIC "-//W3C//DTD HTML 4.0 Transitional//EN">

```

> >> ><HTML><HEAD>
> >> ><META http-equiv=3D3DContent-Type content=3D3D"text/html; =3D
> >> > charset=3D3Diso-8859-1">
> >> ><META content=3D3D"MSHTML 6.00.2800.1400" name=3D3DGENERATOR>
> >> ><STYLE></STYLE>
> >> ></HEAD>
> >> ><BODY bgColor=3D3D#ffffff>
> >> ><DIV><FONT face=3D3DArial size=3D3D2>LaMont,</FONT></DIV>
> >> ><DIV><FONT face=3D3DArial size=3D3D2>EDS1 with Matrox is a bad thing.
> >
> > =
> >
> >>=3D
> >> >I'd try=3D20
> >> >different slots within</FONT></DIV>
> >> ><DIV><FONT face=3D3DArial size=3D3D2>the Magma to correct that. Have
> >
> > =
> >
> >>=3D
> >> >you tried any=3D20
> >> >other slots on</FONT></DIV>
> >> ><DIV><FONT face=3D3DArial size=3D3D2>the mobo for the Magma card? =
> >> >That =3D
> >> >might be=3D20
> >> >the first thing unless</FONT></DIV>
> >> ><DIV><FONT face=3D3DArial size=3D3D2>you know that won't =
> >> >help.</FONT></DIV>
> >> ><DIV><FONT face=3D3DArial size=3D3D2>Tom</FONT></DIV>
> >> ><BLOCKQUOTE=3D20
> >> >style=3D3D"PADDING-RIGHT: 0px; PADDING-LEFT: 5px; MARGIN-LEFT: 5px; =
> >> >=3D
> >> >BORDER-LEFT: #000000 2px solid; MARGIN-RIGHT: 0px">
> >> > <DIV>"LaMont" <<A=3D20
> >> > href=3D3D"mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A>> =
> >> >=3D
> >> >wrote in=3D20
> >> > message <A=3D20
> >> > =3D
> >> =
> >>
>
>>>href=3D3D"news:4404e5bf$1@linux">news:4404e5bf$1@linux</A>...</DIV><BR>H=
> >>
> >>=i=3D20
> >> > Chris,<BR>Fresh install of win Xp/sp1. New drives, new everything.
> >
> > =

```



> >  
 > >>I'm  
 > >> =3D  
 > >> >using=3D20  
 > >> > Apci,<BR>not Standard PC. Mother Board GA-K8NSC-939<BR>nforce-3 =  
 > >>>ultra=3D20  
 > >> > 250gb.<BR><BR>-Maybe moving the magma(13 slot) to a differnt =3D  
 > >> >slot.(It's=3D20  
 > >> > currently residing<BR>in PCI slot 4. According to the manual, slot  
 > >  
 > > =  
 > >  
 > >>4 =3D  
 > >> >and 2 are=3D20  
 > >> > not shared. Plus<BR>even with the SATA controllers activated, each  
 > >  
 > > =  
 > >  
 > >>of  
 > >> =3D  
 > >> >the=3D20  
 > >> > (4)eds cards had their<BR>own IRQ. However, 1 EDS card shared (IRQ  
 > >  
 > > =  
 > >  
 > >>16)  
 > >> =3D  
 > >> >with=3D20  
 > >> > the Matrox G450. Strange..  
 > >>>I've been looking into this PCI =  
 > >>=3D  
 > >> >latency=3D20  
 > >> > issues and download an app to look<BR>and change soem of the PCI =  
 > >>=3D  
 > >> >latency=3D20  
 > >> > settings. <BR><BR>The SATA controller had a setting of 0(zero). EDS  
 > >  
 > > =  
 > >  
 > >>=3D  
 > >> >scherzo=3D20  
 > >> > (32) matrox (64)..IDE<BR>controller (0)..<BR><BR>Thanks for your =  
 > >>help=3D20  
 > >> > ..LaMont<BR><BR><BR><BR> Ahris Ludwig <<A=3D20  
 > >>> > =  
 >  
 >>href=3D3D"mailto:chrisl@adkproaudio.com">chrisl@adkproaudio.com</A>=3D20=  
 > >>  
 > >> > wrote:<BR>>HI Lamont,<BR>>Sorry to here your having =3D

> > > trouble.<BR>>What=3D20  
 > > > exact model of the Gigabyte board do you mean. The description=3D20  
 > > > you<BR><BR>>have here is vague. Is it a K8NS Ultra=3D20  
 > > > -939?<BR>><BR>>When you say you rebuilt do you mean you =3D  
 > > >reinstalled=3D20  
 > > > windows from scratch?<BR>><BR>><BR>>LaMont wrote:<BR>>> =3D  
 > > >Hi=3D20  
 > > > gang:<BR>>> I 'm having problems getting Paris to ip and =3D  
 > > >running. Paris=3D20  
 > > > will sometimes<BR>>> star, only to just freeze up and crash the =3D  
 > > >whole=3D20  
 > > > system. So, I thought<BR>my<BR>>> Asus-Amd XP combo(with =3D  
 > > >SATA-Firwire)=3D20  
 > > > was cause too much IRQ problems for<BR>>> PAris.<BR>>>=3D20  
 > > > <BR>>> So, I rebuilt with my favorite stable =3D  
 > > >mobo(Gigabyte).<BR>>>=3D20  
 > > > <BR>>> Here's the skinny: I just build a new Paris/Nuendo PC. =3D  
 > > >Great very=3D20  
 > > > very<BR>fast:<BR>>> Here are the configs:<BR>>> =3D  
 > > ><BR>>>=3D20  
 > > > -gigabyte mobo 939 Ultra250<BR>>> -Dual core opteron =3D  
 > > >165<BR>>>=3D20  
 > > > -2gig ddr400<BR>>> -sata (onboard) 3 300 gig drives<BR>>> =3D  
 > > >-(1) RME=3D20  
 > > > Digi 96 <BR>>> -(1)Magma card (4 card EDS) <BR>>> -Matrox=3D20  
 > > > g450<BR>>> <BR>>> Well, Nuendo runs like a Deer!!! WOW.. =3D  
 > > >But PAris=3D20  
 > > > is hit and miss. I disabled:<BR>>> USB, SATA raid..A little =3D  
 > > >better, but=3D20  
 > > > I', starting to think that My either<BR>>> my EdS cards or =3D  
 > > >Mec/442 are=3D20  
 > > > the problem. Just 2 weeks prior, the system<BR>was<BR>>> working =  
 > > >=3D  
 > > >fine.=3D20  
 > > > <BR>>> <BR>>> Note: In my studio I have a master power =3D  
 > > >switch that=3D20  
 > > > start up the FUrman<BR>>> power unit..The Magama and Mec units =3D  
 > > >were on=3D20  
 > > > when I started up the system.<BR>>> Maybe PAris got a Jolt ??? I =  
 > > >=3D  
 > > >>don;t=3D20  
 > > > know..<BR>>> Please help..Thanks<BR>>>=3D20  
 > > > <BR>><BR>><BR>><BR>><BR>>Chris<BR>><BR>>-- =3D  
 > > ><BR>>>Chris=3D20  
 > > > Ludwig<BR>><BR>>ADK Pro Audio<BR>>(859)=3D20  
 > > > =3D  
 > > >=  
 > > >

```

> >>>635-5762<BR>>www.adkproaudio.com<BR>>chrisl@adkproaudio.com<BR></BL=3D
> >>
> >> >OCKQUOTE></BODY></HTML>
> >> >
> >> >
> >>
> >>
> >><!DOCTYPE HTML PUBLIC "-//W3C//DTD HTML 4.0 Transitional//EN">
> >><HTML><HEAD>
> >><META http-equiv=3DContent-Type content=3D"text/html; =
> >> charset=3Diso-8859-1">
> >><META content=3D"MSHTML 6.00.2800.1400" name=3DGENERATOR>
> >><STYLE></STYLE>
> >></HEAD>
> >><BODY bgColor=3D#ffffff>
> >><DIV><FONT face=3DArial size=3D2>LM,</FONT></DIV>
> >><DIV><FONT face=3DArial size=3D2>Can't wait to hear.</FONT></DIV>
> >><DIV><FONT face=3DArial size=3D2>T.</FONT></DIV>
> >><BLOCKQUOTE=20
> >> style=3D"PADDING-RIGHT: 0px; PADDING-LEFT: 5px; MARGIN-LEFT: 5px; =
> >> BORDER-LEFT: #000000 2px solid; MARGIN-RIGHT: 0px">
> >> <DIV>"LaMont" <<A=20
> >> href=3D"mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A>> =
> >> wrote in=20
> >> message <A =
> >> href=3D"news:44052522@linux">news:44052522@linux</A>...</DIV><BR>HEY=20
> >> Tom,<BR>I'm in the Prcess of moving th magma card to differnt =
> >> slots..I'll let=20
> >> you<BR>know what happens..<BR><BR>"Tom Bruhl" <<A=20
> >> href=3D"mailto:arpegio@comcast.net">arpegio@comcast.net</A>>=20
> >> wrote:<BR>><BR>><BR>>LaMont,<BR>>EDS1 with Matrox is a bad =
> >>
> >> thing. I'd try different slots within<BR>>the Magma to =
> >> correct=20
> >> that. Have you tried any other slots on<BR>>the mobo for the =
> >> Magma=20
> >> card? That might be the first thing unless<BR>>you know that =
> >> won't=20
> >> help.<BR>>Tom<BR>> "LaMont" <<A=20
> >> href=3D"mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A>> =
> >> wrote in=20
> >> message =3D<BR>>news:4404e5bf$1@linux...<BR>><BR>> Hi=20
> >> Chris,<BR>> Fresh install of win Xp/sp1. New drives, new =
> >> everything.=20
> >> I'm using =3D<BR>>Apci,<BR>> not Standard PC. Mother Board =
> >>
> >> GA-K8NSC-939<BR>> nforce-3 ultra 250gb.<BR>><BR>> =
> >>-Maybe=20

```

> >> moving the magma(13 slot) to a differnt slot.(It's currently=20  
> >> =3D<BR>>residing<BR>> in PCI slot 4. According to the =  
> >>manual, slot 4=20  
> >> and 2 are not shared. =3D<BR>>Plus<BR>> even with the Sata =  
> >>  
> >> controllers activated, each of the (4)eds cards=20  
> >> had<BR>=3D<BR>>their<BR>> own IRQ. However, 1 EDS card =  
> >>shared (IRQ=20  
> >> 16) with the Matrox G450. =3D<BR>>Strange..  
> >><BR>><BR>> =  
> >>I've been=20  
> >> looking into this PCI latency issues and download an app=20  
> >> to<BR>=3D<BR>>look<BR>> and change soem of the PCI latency =  
> >>  
> >> settings.=3D20<BR>><BR>> The Sata controller had a setting =  
> >>of=20  
> >> 0(zero). EDS scherzo (32) matrox<BR>=3D<BR>>(64)..IDE<BR>> =  
> >>  
> >> controller (0)..<BR>><BR>> Thanks for your help=20  
> >> ..LaMont<BR>><BR>><BR>><BR>> Ahris Ludwig =  
> >><<A=20  
> >> href=3D"mailto:chrisl@adkproaudio.com">chrisl@adkproaudio.com</A>=20  
> >> wrote:<BR>> >Hi Lamont,<BR>> >Sorry to here =  
> >>your=20  
> >> having trouble.<BR>> >What exact model of the Gigabyte =  
> >>board do=20  
> >> you mean. The description =3D<BR>>you<BR>><BR>> =  
> >>  
> >>>have here is=20  
> >>  
> >> vague. Is it a K8NS Ultra -939?<BR>> ><BR>> =  
> >>  
> >>>When you=20  
> >>  
> >> say you rebuilt do you mean you reinstalled windows from=20  
> >> =3D<BR>>scratch?<BR>> ><BR>> =  
> >>  
> >>><BR>> =20  
> >>  
> >> >LaMont wrote:<BR>> >> Hi gang:<BR>> =  
> >>  
> >>>>I 'm=20  
> >>  
> >> having problems getting Paris to ip and running. Paris will=20  
> >> =3D<BR>>sometimes<BR>> >> star, only to just freeze =  
> >>up and=20  
> >> crash the whole system. So, I =3D<BR>>thought<BR>> =  
> >>my<BR>> =20  
> >> >> Asus-Amd XP combo(with SATA-Firwire) was cause too much IRQ=20

> > =3D<BR>>problems for<BR>> >> PAris.<BR>> =20  
> > >>=3D20<BR>> >> So, I rebuilt with my favorite =  
> >>stable=20  
> > mobo(Gigabyte).<BR>> >>=3D20<BR>> >> =  
> >>Here's the=20  
> > skinny: I just build a new Paris/Nuendo PC. Great very=20  
> > =3D<BR>>very<BR>> fast:<BR>> >> Here are =  
> >>the=20  
> > configs:<BR>> >>=3D20<BR>> >> -gigabyte =  
> >>mobo 939=20  
> > Ultra250<BR>> >> -Dual core opteron 165<BR>> =  
> >>  
> >>>=20  
> >>  
> >> -2gig ddr400<BR>> >> -sata (onboard) 3 300 gig=20  
> >> drives<BR>> >> -(1) RME Digi 96=3D20<BR>> =  
> >>  
> >>>=20  
> >>  
> >> -(1)Magma card (4 card EDS)=3D20<BR>> >> -Matrox=20  
> >> g450<BR>> >>=3D20<BR>> >> Well, Nuendo =  
> >>runs like a=20  
> >> Deer!!! WOW.. But PAris is hit and miss. =  
> >>I<BR>=3D<BR>>disabled:<BR>> =20  
> >> >> USB, SATA raid..A little better, but I', starting to think =  
> >>that=20  
> >> My<BR>=3D<BR>>either<BR>> >> my EdS cards or Mec/442 =  
> >>are the=20  
> >> problem. Just 2 weeks prior, the =3D<BR>>system<BR>> =20  
> >> was<BR>> >> working fine.=3D20<BR>> =20  
> >> >>=3D20<BR>> >> Note: In my studio I have a =  
> >>master power=20  
> >> switch that start up the =3D<BR>>FUrman<BR>> >> =  
> >>power=20  
> >> unit..The Magama and Mec units were on when I started up=20  
> >> the<BR>=3D<BR>>system.<BR>> >> Maybe PAris got a =  
> >>Jolt ??? I=20  
> >> don;t know..<BR>> >> Please help..Thanks<BR>> =20  
> >> >>=3D20<BR>> ><BR>> ><BR>> =20  
> >> ><BR>> ><BR>> >Chris<BR>> =20  
> >> ><BR>> >---=3D20<BR>> >Chris =  
> >>Ludwig<BR>> =20  
> >> ><BR>> >ADK Pro Audio<BR>> >(859)=20  
> >> 635-5762<BR>> >www.adkproaudio.com<BR>> =20  
> >> >chrisl@adkproaudio.com<BR>><BR>><BR>><!DOCTYPE HTML =  
> >>PUBLIC=20  
> >> "-//W3C//DTD HTML 4.0=20  
> >> Transitional//EN"><BR>><HTML><HEAD><BR>><META=20

```

> >> http-equiv=3D3DContent-Type content=3D3D"text/html";=20
> >> =3D<BR>> charset=3D3Diso-8859-1"><BR>><META =
> >> content=3D3D"MSHTML=20
> >> 6.00.2800.1400"=20
> >> =
> >> name=3D3DGENERATOR><BR>><STYLE></STYLE><BR>></HEA=
> >> D><BR>><BODY=20
> >> bgColor=3D3D#ffffff><BR>><DIV><FONT face=3D3DArial=20
> >> =
> >> size=3D3D2>LaMont,</FONT></DIV><BR>><DIV><FONT=
> >> =20
> >> face=3D3DArial size=3D3D2>EDS1 with Matrox is a bad thing. =
> >> =3D<BR>>I'd=20
> >> try=3D20<BR>>different slots=20
> >> within</FONT></DIV><BR>><DIV><FONT =
> >> face=3D3DArial=20
> >> size=3D3D2>the Magma to correct that. Have =3D<BR>>you tried=20
> >> any=3D20<BR>>other slots=20
> >> on</FONT></DIV><BR>><DIV><FONT face=3D3DArial=20
> >> size=3D3D2>the mobo for the Magma card? That =3D<BR>>might =
> >> be=3D20<BR>>the=20
> >> first thing unless</FONT></DIV><BR>><DIV><FONT =
> >>
> >> face=3D3DArial size=3D3D2>you know that won't=20
> >> help.</FONT></DIV><BR>><DIV><FONT =
> >> face=3D3DArial=20
> >> =
> >> size=3D3D2>Tom</FONT></DIV><BR>><BLOCKQUOTE=3D20<BR>=
> >>
> >>> style=3D3D"PADDING-RIGHT:=20
> >>
> >> 0px; PADDING-LEFT: 5px; MARGIN-LEFT: 5px; =3D<BR>>BORDER-LEFT: =
> >> #000000 2px=20
> >> solid; MARGIN-RIGHT: 0px"><BR>> <DIV>"LaMont"=20
> >> <<A=3D20<BR>> href=3D3D"<A=20
> >> =
>
>> href=3D'mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A'>mailto:jjdp=
> >> ro@ameritech.net">jjdpro@ameritech.net</A</A>>>=20
> >> =3D<BR>>wrote in=3D20<BR>> message =
> >> <A=3D20<BR>> =20
> >> =3D<BR>> href=3D3D"<A=20
> >> =
>
>> href=3D'news:4404e5bf$1@linux">news:4404e5bf$1@linux</A>...</DIV><BR>Hi=3D
=
> >> 20'>news:4404e5bf$1@linux">news:4404e5bf$1@linux</A>...</DIV&=
> >> gt;<BR>Hi=3D20</A><BR>> =20

```

> >> Chris, <BR>Fresh install of win Xp/sp1. New drives, new =  
> >>everything.=20  
> >> I'm <BR>=3D<BR>>using=3D20<BR>> Apci,<BR>not Standard =  
> >>PC. Mother=20  
> >> Board GA-K8NSC-939<BR>nforce-3 ultra=3D20<BR>> =20  
> >> 250gb.<BR><BR>-Maybe moving the magma(13 slot) to a =  
> >>different=20  
> >> =3D<BR>>slot.(It's=3D20<BR>> currently =  
> >>residing<BR>in PCI slot=20  
> >> 4. According to the manual, slot 4 =3D<BR>>and 2 =  
> >>are=3D20<BR>> not=20  
> >> shared. Plus<BR>even with the Sata controllers activated, each=20  
> >> of<BR>=3D<BR>>the=3D20<BR>> (4)eds cards had =  
> >>their<BR>own IRQ.=20  
> >> However, 1 EDS card shared (IRQ =  
> >>16)<BR>=3D<BR>>with=3D20<BR>> the=20  
> >> Matrox G450. Strange..<BR><BR>I've been looking into this =  
> >>PCI=20  
> >> =3D<BR>>latency=3D20<BR>> issues and download an app to=20  
> >> look<BR>and change soem of the PCI =  
> >>=3D<BR>>latency=3D20<BR>> =20  
> >> settings. <BR><BR>The Sata controller had a setting of =  
> >>0(zero).=20  
> >> EDS =3D<BR>>scherzo=3D20<BR>> (32) matrox=20  
> >> (64)..IDE<BR>controller (0)..<BR><BR>Thanks for your =  
> >>  
> >> help=3D20<BR>> =  
> >>..LaMont<BR><BR><BR><BR> Ahris=20  
> >> Ludwig <<A=3D20<BR>> href=3D3D"<A=20  
> >> =  
>  
>>href=3D'mailto:chrisl@adkproaudio.com">chrisl@adkproaudio.com</A>>=3D20'>=  
> >>mailto:chrisl@adkproaudio.com">chrisl@adkproaudio.com</A>>=3D=  
> >>20</A><BR>> =20  
> >> wrote:<BR>>HI Lamont,<BR>>Sorry to here your having=20  
> >> =3D<BR>>trouble.<BR>>What=3D20<BR>> exact model =  
> >>of the=20  
> >> Gigabyte board do you mean. The description=3D20<BR>> =20  
> >> you<BR><BR>>have here is vague. Is it a K8NS=20  
> >> Ultra=3D20<BR>> -939?<BR>><BR>>When you say =  
> >>you=20  
> >> rebuilt do you mean you =3D<BR>>reinstalled=3D20<BR>> =  
> >>windows from=20  
> >> scratch?<BR>><BR>><BR>>LaMont=20  
> >> wrote:<BR>> =3D<BR>>Hi=3D20<BR>> =  
> >>gang:<BR>>=20  
> >> I 'm having problems getting Paris to ip and =3D<BR>>running.=20  
> >> Paris=3D20<BR>> will sometimes<BR>>> star, only =

> >>to just=20  
 > >> freeze up and crash the =3D<BR>>whole=3D20<BR>> system. =  
 > >>So, I=20  
 > >> thought<BR>my<BR>>> Asus-Amd XP combo(with=20  
 > >> =3D<BR>>SATA-Firwire)=3D20<BR>> was cause too much IRQ =  
 > >>problems=20  
 > >> for<BR>>> PAris.<BR>>>=3D20<BR>> =20  
 > >> <BR>>> So, I rebuilt with my favorite stable=20  
 > >> =3D<BR>>mobo(Gigabyte).<BR>>>=3D20<BR>> =  
 > >><BR>>>=20  
 > >> Here's the skinny: I just build a new Paris/Nuendo PC. =  
 > >>=3D<BR>>Great=20  
 > >> very=3D20<BR>> very<BR>fast:<BR>>> Here are =  
 > >>the=20  
 > >> configs:<BR>>> =  
 > >>=3D<BR>><BR>>>=3D20<BR>> =20  
 > >> -gigabyte mobo 939 Ultra250<BR>>> -Dual core opteron=20  
 > >> =3D<BR>>165<BR>>>=3D20<BR>> -2gig =  
 > >>ddr400<BR>>>=20  
 > >> -sata (onboard) 3 300 gig drives<BR>>> =3D<BR>>-(1)=20  
 > >> RME=3D20<BR>> Digi 96 <BR>>> -(1)Magma card (4 =  
 > >>card EDS)=20  
 > >> <BR>>> -Matrox=3D20<BR>> g450<BR>>>=20  
 > >> <BR>>> Well, Nuendo runs like a Deer!!! WOW.. =  
 > >>=3D<BR>>But=20  
 > >> PAris=3D20<BR>> is hit and miss. I =  
 > >>disabled:<BR>>> USB,=20  
 > >> SATA raid..A little =3D<BR>>better, but=3D20<BR>> I', =  
 > >>starting to=20  
 > >> think that My either<BR>>> my EdS cards or =  
 > >>=3D<BR>>Mec/442=20  
 > >> are=3D20<BR>> the problem. Just 2 weeks prior, the=20  
 > >> system<BR>was<BR>>> working =  
 > >>=3D<BR>>fine.=3D20<BR>> =20  
 > >> <BR>>> <BR>>> Note: In my studio I have a =  
 > >>master power=20  
 > >> =3D<BR>>switch that=3D20<BR>> start up the =  
 > >>FUrman<BR>>>=20  
 > >> power unit..The Magama and Mec units =3D<BR>>were =  
 > >>on=3D20<BR>> when I=20  
 > >> started up the system.<BR>>> Maybe PAris got a Jolt ??? I=20  
 > >> =3D<BR>>don;t=3D20<BR>> know.<BR>>> Please=20  
 > >> help..Thanks<BR>>>=3D20<BR>> =20  
 > >> =  
 > >><BR>><BR>><BR>><BR>><BR>><BR>>Chr=  
 > >>is<BR>><BR>>--=20  
 > >> =3D<BR>><BR>>Chris=3D20<BR>> =20  
 > >> Ludwig<BR>><BR>>ADK Pro=20



> >> Audio<BR>>(859)=3D20<BR>> =20  
> >> =  
> >>=3D<BR>>635-5762<BR>>www.adkproaudio.com<BR>>chrisl@=  
> >>adkproaudio.com<BR></BL=3D<BR>>OCKQUOTE></BODY></=  
> >>HTML><BR>><BR>><BR></BLOCKQUOTE></BODY></HTML>  
> >>  
> >>  
> >  
>  
> --  
> Chris Ludwig  
> ADK  
> chrisl@adkproaudio.com <mailto:chrisl@adkproaudio.com>  
> www.adkproaudio.com <http://www.adkproaudio.com/>  
> (859) 635-5762

---

---

Subject: Re: Paris Problems on new machine: Hey Chris Ludwig...!  
Posted by [Chris Ludwig](#) on Wed, 01 Mar 2006 18:58:23 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Hi Miguel,

Yes quite a few differences.

The K8NS Ultra-939

nForce3 Ultra chip set 2000 mhz FSB  
4 x sata ports 2 of which are integrated on the Nvidia chip set.  
2 x lan both gigabit 1 is integrated on the nvidia chip set.  
3 x 1384b (2x 400 1x 800 ports)  
Dual\_BIOS

The K8NSC-939

NForce 3 250Gb chip set 1600 mhz FSB  
2x sata ports  
1x lan  
no firewire  
no dual bios

The only real major difference is the slower FSB.

Chris

Miguel Vigil wrote:

> Hello Chris,  
>  
>>>> not Standard PC. Mother Board GA-K8NSC-939  
>  
>  
> re above mobo, which does not have the firewire i/o,  
> is there any major difference to the more expensive and  
> elusive K8ns ultra pro you have touted?  
>  
> TIA,  
>  
> El Miguel  
>  
>  
>  
>  
>  
> "Chris Ludwig" <chrisl@adkproaudio.com> wrote in message  
> news:4405b024@linux...  
>> HI Lamont,  
>> Wow weird stuff. Glad its working now.  
>>  
>> Chris  
>>  
>>  
>> LaMont wrote:  
>>> Tom & Chris,  
>>>  
>>> I got it solved. It was the Magma Chasis's power supply was not "seated"  
>>> into slot properly. Paris is working fine now.  
>>> Thanks  
>>>  
>>> "Tom Bruhl" <arpeggio@comcast.net> wrote:  
>>>  
>>>> LM,  
>>>> Can't wait to hear.  
>>>> T.  
>>>> "LaMont" <jjdpro@ameritech.net> wrote in message =  
>>>> news:44052522@linux...  
>>>>  
>>>> HEY Tom,  
>>>> I'm in the Prcess of moving th magma card to differnt slots..I'll let  
>>> =  
>>>  
>>>> you  
>>>> know what happens..  
>>>>  
>>>> "Tom Bruhl" <arpeggio@comcast.net> wrote:

>>>>  
>>>> LaMont,  
>>>> EDS1 with Matrox is a bad thing. I'd try different slots within  
>>>> the Magma to correct that. Have you tried any other slots on  
>>>> the mobo for the Magma card? That might be the first thing unless  
>>>> you know that won't help.  
>>>> Tom  
>>>> "LaMont" <jjdpro@ameritech.net> wrote in message =3D  
>>>> news:4404e5bf\$1@linux...  
>>>>  
>>>> Hi Chris,  
>>>> Fresh install of win Xp/sp1. New drives, new everything. I'm using  
>>> =  
>>>  
>>>> =3D  
>>>> Apci,  
>>>> not Standard PC. Mother Board GA-K8NSC-939  
>>>> nforce-3 ultra 250gb.  
>>>>  
>>>> -Maybe moving the magma(13 slot) to a differnt slot.(It's currently  
>>> =  
>>>  
>>>> =3D  
>>>> residing  
>>>> in PCI slot 4. According to the manual, slot 4 and 2 are not =  
>>>> shared. =3D  
>>>> Plus  
>>>> even with the Sata controllers activated, each of the (4)eds cards  
>>> =  
>>>  
>>>> had  
>>>> =3D  
>>>>> their  
>>>>> own IRQ. However, 1 EDS card shared (IRQ 16) with the Matrox G450.  
>>> =  
>>>  
>>>> =3D  
>>>>> Strange..  
>>>>>  
>>>>> I've been looking into this PCI latency issues and download an app  
>>> =  
>>>  
>>>> to  
>>>> =3D  
>>>>> look  
>>>>> and change soem of the PCI latency settings.=3D20  
>>>>>  
>>>>> The Sata controller had a setting of 0(zero). EDS scherzo (32) =

>>>> matrox  
>>>> =3D  
>>>>> (64)..IDE  
>>>>> controller (0)..  
>>>>>  
>>>>> Thanks for your help ..LaMont  
>>>>>  
>>>>>  
>>>>>  
>>>>> Ahris Ludwig <chrisl@adkproaudio.com> wrote:  
>>>>> >HI Lamont,  
>>>>> >Sorry to here your having trouble.  
>>>>> >What exact model of the Gigabyte board do you mean. The =  
>>>> description =3D  
>>>>> you  
>>>>>  
>>>>> >have here is vague. Is it a K8NS Ultra -939?  
>>>>> >  
>>>>> >When you say you rebuilt do you mean you reinstalled windows from  
>>> =  
>>>  
>>>> =3D  
>>>>> scratch?  
>>>>> >  
>>>>> >  
>>>>> >LaMont wrote:  
>>>>> >> Hi gang:  
>>>>> >> I 'm having problems getting Paris to ip and running. Paris will  
>>> =  
>>>  
>>>> =3D  
>>>>> sometimes  
>>>>> >> star, only to just freeze up and crash the whole system. So, I =  
>>>> =3D  
>>>>> thought  
>>>>> my  
>>>>> >> Asus-Amd XP combo(with SATA-Firwire) was cause too much IRQ =3D  
>>>>> problems for  
>>>>> >> PAris.  
>>>>> >>=3D20  
>>>>> >> So, I rebuilt with my favorite stable mobo(Gigabyte).  
>>>>> >>=3D20  
>>>>> >> Here's the skinny: I just build a new Paris/Nuendo PC. Great =  
>>>> very =3D  
>>>>> very  
>>>>> fast:  
>>>>> >> Here are the configs:  
>>>>> >>=3D20

>>>> >> -gigabyte mobo 939 Ultra250  
>>>> >> -Dual core opteron 165  
>>>> >> -2gig ddr400  
>>>> >> -sata (onboard) 3 300 gig drives  
>>>> >> -(1) RME Digi 96=3D20  
>>>> >> -(1)Magma card (4 card EDS)=3D20  
>>>> >> -Matrox g450  
>>>> >>=3D20  
>>>> >> Well, Nuendo runs like a Deer!!! WOW.. But PAris is hit and =  
>>>> miss. I  
>>>> =3D  
>>>> disabled:  
>>>> >> USB, SATA raid..A little better, but I', starting to think that  
>>>> =  
>>>>  
>>>> My  
>>>> =3D  
>>>> either  
>>>> >> my EdS cards or Mec/442 are the problem. Just 2 weeks prior, the  
>>>> =  
>>>>  
>>>> =3D  
>>>> system  
>>>> was  
>>>> >> working fine.=3D20  
>>>> >>=3D20  
>>>> >> Note: In my studio I have a master power switch that start up =  
>>>> the =3D  
>>>> FUrman  
>>>> >> power unit..The Magama and Mec units were on when I started up =  
>>>> the  
>>>> =3D  
>>>> system.  
>>>> >> Maybe PAris got a Jolt ??? I don;t know..  
>>>> >> Please help..Thanks  
>>>> >>=3D20  
>>>> >  
>>>> >  
>>>> >  
>>>> >  
>>>> >Chris  
>>>> >  
>>>> >--=3D20  
>>>> >Chris Ludwig  
>>>> >  
>>>> >ADK Pro Audio  
>>>> >(859) 635-5762  
>>>> >www.adkproaudio.com

```

>>>> >chrisl@adkproaudio.com
>>>>
>>>>
>>>> <!DOCTYPE HTML PUBLIC "-//W3C//DTD HTML 4.0 Transitional//EN">
>>>> <HTML><HEAD>
>>>> <META http-equiv=3D3DContent-Type content=3D3D"text/html; =3D
>>>> charset=3D3Diso-8859-1">
>>>> <META content=3D3D"MSHTML 6.00.2800.1400" name=3D3DGENERATOR>
>>>> <STYLE></STYLE>
>>>> </HEAD>
>>>> <BODY bgColor=3D3D#ffffff>
>>>> <DIV><FONT face=3D3DArial size=3D3D2>LaMont,</FONT></DIV>
>>>> <DIV><FONT face=3D3DArial size=3D3D2>EDS1 with Matrox is a bad thing.
>>> =
>>>
>>>> =3D
>>>> I'd try=3D20
>>>> different slots within</FONT></DIV>
>>>> <DIV><FONT face=3D3DArial size=3D3D2>the Magma to correct that. Have
>>> =
>>>
>>>> =3D
>>>> you tried any=3D20
>>>> other slots on</FONT></DIV>
>>>> <DIV><FONT face=3D3DArial size=3D3D2>the mobo for the Magma card? =
>>>> That =3D
>>>> might be=3D20
>>>> the first thing unless</FONT></DIV>
>>>> <DIV><FONT face=3D3DArial size=3D3D2>you know that won't =
>>>> help.</FONT></DIV>
>>>> <DIV><FONT face=3D3DArial size=3D3D2>Tom</FONT></DIV>
>>>> <BLOCKQUOTE=3D20
>>>> style=3D3D"PADDING-RIGHT: 0px; PADDING-LEFT: 5px; MARGIN-LEFT: 5px; =
>>>> =3D
>>>> BORDER-LEFT: #000000 2px solid; MARGIN-RIGHT: 0px">
>>>> <DIV>"LaMont" <<A=3D20
>>>> href=3D3D"mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A>> =
>>>> =3D
>>>> wrote in=3D20
>>>> message <A=3D20
>>>> =3D
>>>> =
>>>>
>>>> href=3D3D"news:4404e5bf$1 @linux">news:4404e5bf$1 @linux</A>...</DIV><BR>H=
>>>>
>>>> i=3D20
>>>>> Chris,<BR>Fresh install of win Xp/sp1. New drives, new everything.
>>> =

```

>>>  
 >>>> I'm  
 >>>> =3D  
 >>>>> using=3D20  
 >>>>> Apci,<BR>not Standard PC. Mother Board GA-K8NSC-939<BR>nforce-3 =  
 >>>> ultra=3D20  
 >>>>> 250gb.<BR><BR>-Maybe moving the magma(13 slot) to a differnt =3D  
 >>>>> slot.(It's=3D20  
 >>>>> currently residing<BR>in PCI slot 4. According to the manual, slot  
 >>> =  
 >>>  
 >>>> 4 =3D  
 >>>>> and 2 are=3D20  
 >>>>> not shared. Plus<BR>even with the Sata controllers activated, each  
 >>> =  
 >>>  
 >>>> of  
 >>>> =3D  
 >>>>> the=3D20  
 >>>>> (4)eds cards had their<BR>own IRQ. However, 1 EDS card shared (IRQ  
 >>> =  
 >>>  
 >>>> 16)  
 >>>> =3D  
 >>>>> with=3D20  
 >>>>> the Matrox G450. Strange..<BR><BR>I've been looking into this PCI =  
 >>>> =3D  
 >>>>> latency=3D20  
 >>>>> issues and download an app to look<BR>and change soem of the PCI =  
 >>>> =3D  
 >>>>> latency=3D20  
 >>>>> settings. <BR><BR>The Sata controller had a setting of 0(zero). EDS  
 >>> =  
 >>>  
 >>>> =3D  
 >>>>> scherzo=3D20  
 >>>>> (32) matrox (64)..IDE<BR>controller (0)..<BR><BR>Thanks for your =  
 >>>> help=3D20  
 >>>>> ..LaMont<BR><BR><BR><BR> Ahris Ludwig <<A=3D20  
 >>>>> =  
 >>> href=3D3D"mailto:chrisl@adkproaudio.com">chrisl@adkproaudio.com</A>=3D20=  
 >>>>> wrote:<BR>>HI Lamont,<BR>>Sorry to here your having =3D  
 >>>>> trouble.<BR>>What=3D20  
 >>>>> exact model of the Gigabyte board do you mean. The description=3D20  
 >>>>> you<BR><BR>>have here is vague. Is it a K8NS Ultra=3D20  
 >>>>> -939?<BR>><BR>>When you say you rebuilt do you mean you =3D  
 >>>>> reinstalled=3D20  
 >>>>> windows from scratch?<BR>><BR>><BR>>LaMont wrote:<BR>>> =3D

>>>> Hi=3D20  
>>>> gang:<BR>>> I 'm having problems getting Paris to ip and =3D  
>>>> running. Paris=3D20  
>>>> will sometimes<BR>>> star, only to just freeze up and crash the =3D  
>>>> whole=3D20  
>>>> system. So, I thought<BR>my<BR>>> Asus-Amd XP combo(with =3D  
>>>> SATA-Firwire)=3D20  
>>>> was cause too much IRQ problems for<BR>>> PAris.<BR>>>=3D20  
>>>> <BR>>> So, I rebuilt with my favorite stable =3D  
>>>> mobo(Gigabyte).<BR>>>=3D20  
>>>> <BR>>> Here's the skinny: I just build a new Paris/Nuendo PC. =3D  
>>>> Great very=3D20  
>>>> very<BR>fast:<BR>>> Here are the configs:<BR>>> =3D  
>>>> <BR>>>=3D20  
>>>> -gigabyte mobo 939 Ultra250<BR>>> -Dual core opteron =3D  
>>>> 165<BR>>>=3D20  
>>>> -2gig ddr400<BR>>> -sata (onboard) 3 300 gig drives<BR>>> =3D  
>>>> -(1) RME=3D20  
>>>> Digi 96 <BR>>> -(1)Magma card (4 card EDS) <BR>>> -Matrox=3D20  
>>>> g450<BR>>> <BR>>> Well, Nuendo runs like a Deer!!! WOW.. =3D  
>>>> But PAris=3D20  
>>>> is hit and miss. I disabled:<BR>>> USB, SATA raid..A little =3D  
>>>> better, but=3D20  
>>>> I', starting to think that My either<BR>>> my EdS cards or =3D  
>>>> Mec/442 are=3D20  
>>>> the problem. Just 2 weeks prior, the system<BR>was<BR>>> working =  
>>>> =3D  
>>>> fine.=3D20  
>>>> <BR>>> <BR>>> Note: In my studio I have a master power =3D  
>>>> switch that=3D20  
>>>> start up the FUrman<BR>>> power unit..The Magama and Mec units =3D  
>>>> were on=3D20  
>>>> when I started up the system.<BR>>> Maybe PAris got a Jolt ??? I =  
>>>> =3D  
>>>> don;t=3D20  
>>>> know..<BR>>> Please help..Thanks<BR>>>=3D20  
>>>> <BR>>><BR>>><BR>>><BR>>><BR>>>Chris<BR>>><BR>>>-- =3D  
>>>> <BR>>>Chris=3D20  
>>>> Ludwig<BR>>><BR>>>ADK Pro Audio<BR>>>(859)=3D20  
>>>> =3D  
>>>> =  
>>>>  
>>>> 635-5762<BR>>>www.adkproaudio.com<BR>>>chrisl@adkproaudio.com<BR></BL=3D  
>>>> OCKQUOTE></BODY></HTML>  
>>>>  
>>>>  
>>>>  
>>>> <!DOCTYPE HTML PUBLIC "-//W3C//DTD HTML 4.0 Transitional//EN">



```

>>>> <HTML><HEAD>
>>>> <META http-equiv=3DContent-Type content=3D"text/html; =
>>>> charset=3Diso-8859-1">
>>>> <META content=3D"MSHTML 6.00.2800.1400" name=3DGENERATOR>
>>>> <STYLE></STYLE>
>>>> </HEAD>
>>>> <BODY bgColor=3D#ffffff>
>>>> <DIV><FONT face=3DArial size=3D2>LM,</FONT></DIV>
>>>> <DIV><FONT face=3DArial size=3D2>Can't wait to hear.</FONT></DIV>
>>>> <DIV><FONT face=3DArial size=3D2>T.</FONT></DIV>
>>>> <BLOCKQUOTE=20
>>>> style=3D"PADDING-RIGHT: 0px; PADDING-LEFT: 5px; MARGIN-LEFT: 5px; =
>>>> BORDER-LEFT: #000000 2px solid; MARGIN-RIGHT: 0px">
>>>> <DIV>"LaMont" <<A=20
>>>> href=3D"mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A>> =
>>>> wrote in=20
>>>> message <A =
>>>> href=3D"news:44052522@linux">news:44052522@linux</A>...</DIV><BR>HEY=20
>>>> Tom,<BR>I'm in the Prcess of moving th magma card to differnt =
>>>> slots..I'll let=20
>>>> you<BR>know what happens..<BR><BR>"Tom Bruhl" <<A=20
>>>> href=3D"mailto:arpegio@comcast.net">arpegio@comcast.net</A>>=20
>>>> wrote:<BR>><BR>><BR>>LaMont,<BR>>EDS1 with Matrox is a bad =
>>>>
>>>> thing. I'd try different slots within<BR>>the Magma to =
>>>> correct=20
>>>> that. Have you tried any other slots on<BR>>the mobo for the =
>>>> Magma=20
>>>> card? That might be the first thing unless<BR>>you know that =
>>>> won't=20
>>>> help.<BR>>Tom<BR>> "LaMont" <<A=20
>>>> href=3D"mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A>> =
>>>> wrote in=20
>>>> message =3D<BR>>news:4404e5bf$1@linux...<BR>><BR>> Hi=20
>>>> Chris,<BR>> Fresh install of win Xp/sp1. New drives, new =
>>>> everything.=20
>>>> I'm using =3D<BR>>Apci,<BR>> not Standard PC. Mother Board =
>>>>
>>>> GA-K8NSC-939<BR>> nforce-3 ultra 250gb.<BR>><BR>> =
>>>> -Maybe=20
>>>> moving the magma(13 slot) to a differnt slot.(It's currently=20
>>>> =3D<BR>>residing<BR>> in PCI slot 4. According to the =
>>>> manual, slot 4=20
>>>> and 2 are not shared. =3D<BR>>Plus<BR>> even with the Sata =
>>>>
>>>> controllers activated, each of the (4)eds cards=20
>>>> had<BR>=3D<BR>>their<BR>> own IRQ. However, 1 EDS card =
>>>> shared (IRQ=20

```

>>>> 16) with the Matrox G450. =3D<BR>>Strange..  
>>>> I've been=20  
>>>> looking into this PCI latency issues and download an app=20  
>>>> to<BR>=3D<BR>>look<BR>> and change soem of the PCI latency =  
>>>>  
>>>> settings.=3D20<BR>><BR>> The Sata controller had a setting =  
>>>> of=20  
>>>> 0(zero). EDS scherzo (32) matrox<BR>=3D<BR>>(64)..IDE<BR>> =  
>>>>  
>>>> controller (0)..<BR>><BR>> Thanks for your help=20  
>>>> ..LaMont<BR>><BR>><BR>><BR>> Ahris Ludwig =  
>>>> <<A=20  
>>>> href=3D"mailto:chrisl@adkproaudio.com">chrisl@adkproaudio.com</A>=20  
>>>> wrote:<BR>> >HI Lamont,<BR>> >Sorry to here =  
>>>> your=20  
>>>> having trouble.<BR>> >What exact model of the Gigabyte =  
>>>> board do=20  
>>>> you mean. The description =3D<BR>>you<BR>><BR>> =  
>>>>  
>>>>> have here is=20  
>>>> vague. Is it a K8NS Ultra -939?<BR>> ><BR>> =  
>>>>  
>>>>> When you=20  
>>>> say you rebuilt do you mean you reinstalled windows from=20  
>>>> =3D<BR>>scratch?<BR>> ><BR>> =  
>>>>  
>>>>> <BR>> =20  
>>>>> LaMont wrote:<BR>> >> Hi gang:<BR>> =  
>>>>>> I 'm=20  
>>>> having problems getting Paris to ip and running. Paris will=20  
>>>> =3D<BR>>sometimes<BR>> >> star, only to just freeze =  
>>>> up and=20  
>>>> crash the whole system. So, I =3D<BR>>thought<BR>> =  
>>>> my<BR>> =20  
>>>>>> Asus-Amd XP combo(with SATA-Firwire) was cause too much IRQ=20  
>>>> =3D<BR>>problems for<BR>> >> PAris.<BR>> =20  
>>>>>> =3D20<BR>> >> So, I rebuilt with my favorite =  
>>>> stable=20  
>>>> mobo(Gigabyte).<BR>> >>=3D20<BR>> >> =  
>>>> Here's the=20  
>>>> skinny: I just build a new Paris/Nuendo PC. Great very=20  
>>>> =3D<BR>>very<BR>> fast:<BR>> >> Here are =  
>>>> the=20  
>>>> configs:<BR>> >>=3D20<BR>> >> -gigabyte =  
>>>> mobo 939=20  
>>>> Ultra250<BR>> >> -Dual core opteron 165<BR>> =  
>>>>  
>>>>>> =20

>>>> -2gig ddr400<BR>> >> -sata (onboard) 3 300 gig=20  
 >>>> drives<BR>> >> -(1) RME Digi 96=3D20<BR>> =  
 >>>>  
 >>>>> =20  
 >>>> -(1)Magma card (4 card EDS)=3D20<BR>> >> -Matrox=20  
 >>>> g450<BR>> >>=3D20<BR>> >> Well, Nuendo =  
 >>>> runs like a=20  
 >>>> Deer!!! WOW.. But PARis is hit and miss. =  
 >>>> I<BR>=3D<BR>>disabled:<BR>> =20  
 >>>>> USB, SATA raid..A little better, but I', starting to think =  
 >>>> that=20  
 >>>> My<BR>=3D<BR>>either<BR>> >> my EdS cards or Mec/442 =  
 >>>> are the=20  
 >>>> problem. Just 2 weeks prior, the =3D<BR>>system<BR>> =20  
 >>>> was<BR>> >> working fine.=3D20<BR>> =20  
 >>>>> =3D20<BR>> >> Note: In my studio I have a =  
 >>>> master power=20  
 >>>> switch that start up the =3D<BR>>FURman<BR>> >> =  
 >>>> power=20  
 >>>> unit..The Magama and Mec units were on when I started up=20  
 >>>> the<BR>=3D<BR>>system.<BR>> >> Maybe PARis got a =  
 >>>> Jolt ??? I=20  
 >>>> don;t know..<BR>> >> Please help..Thanks<BR>> =20  
 >>>>> =3D20<BR>> ><BR>> ><BR>> =20  
 >>>>> <BR>> ><BR>> >Chris<BR>> =20  
 >>>>> <BR>> >--=3D20<BR>> >Chris =  
 >>>> Ludwig<BR>> =20  
 >>>>> <BR>> >ADK Pro Audio<BR>> >(859)=20  
 >>>> 635-5762<BR>> >www.adkproaudio.com<BR>> =20  
 >>>>> chrisl@adkproaudio.com<BR>><BR>><BR>><!DOCTYPE HTML =  
 >>>> PUBLIC=20  
 >>>> "-//W3C//DTD HTML 4.0=20  
 >>>> Transitional//EN"><BR>><HTML><HEAD><BR>><META=20  
 >>>> http-equiv=3D3DContent-Type content=3D3D"text/html;=20  
 >>>> =3D<BR>>charset=3D3Diso-8859-1"><BR>><META =  
 >>>> content=3D3D"MSHTML=20  
 >>>> 6.00.2800.1400"=20  
 >>>> =  
 >>>> name=3D3DGENERATOR><BR>><STYLE></STYLE><BR>></HEA=  
 >>>> D><BR>><BODY=20  
 >>>> bgColor=3D3D#ffffff><BR>><DIV><FONT face=3D3DArial=20  
 >>>> =  
 >>>> size=3D3D2>LaMont,</FONT></DIV><BR>><DIV><FONT=  
 >>>> =20  
 >>>> face=3D3DArial size=3D3D2>EDS1 with Matrox is a bad thing. =  
 >>>> =3D<BR>>>I'd=20  
 >>>> try=3D20<BR>>>different slots=20  
 >>>> within</FONT></DIV><BR>><DIV><FONT =

```

>>>> face=3D3DArial=20
>>>> size=3D3D2>the Magma to correct that. Have =3D<BR>>you tried=20
>>>> any=3D20<BR>>other slots=20
>>>> on</FONT></DIV><BR>><DIV><FONT face=3D3DArial=20
>>>> size=3D3D2>the mobo for the Magma card? That =3D<BR>>might =
>>>> be=3D20<BR>>the=20
>>>> first thing unless</FONT></DIV><BR>><DIV><FONT =
>>>>
>>>> face=3D3DArial size=3D3D2>you know that won't=20
>>>> help.</FONT></DIV><BR>><DIV><FONT =
>>>> face=3D3DArial=20
>>>> =
>>>> size=3D3D2>Tom</FONT></DIV><BR>><BLOCKQUOTE=3D20<BR>=
>>>>
>>>>> style=3D3D"PADDING-RIGHT:=20
>>>> 0px; PADDING-LEFT: 5px; MARGIN-LEFT: 5px; =3D<BR>>BORDER-LEFT: =
>>>> #000000 2px=20
>>>> solid; MARGIN-RIGHT: 0px"><BR>> <DIV>"LaMont"=20
>>>> <<A=3D20<BR>> href=3D3D"<A=20
>>>> =
>>> href=3D'mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A'>mailto:jjdp=
>>>> ro@ameritech.net">jjdpro@ameritech.net</A</A>>>=20
>>>> =3D<BR>>wrote in=3D20<BR>> message =
>>>> <A=3D20<BR>> =20
>>>> =3D<BR>>href=3D3D"<A=20
>>>> =
>>> href=3D'news:4404e5bf$1 @linux">news:4404e5bf$1 @linux</A>...</DIV><BR>Hi=3D
> =
>>>> 20'>news:4404e5bf$1 @linux">news:4404e5bf$1 @linux</A>...</DIV&=
>>>> gt;<BR>Hi=3D20</A><BR>> =20
>>>> Chris,<BR>Fresh install of win Xp/sp1. New drives, new =
>>>> everything.=20
>>>> I'm<BR>=3D<BR>>using=3D20<BR>> Apci,<BR>not Standard =
>>>> PC. Mother=20
>>>> Board GA-K8NSC-939<BR>nforce-3 ultra=3D20<BR>> =20
>>>> 250gb.<BR><BR>-Maybe moving the magma(13 slot) to a =
>>>> differnt=20
>>>> =3D<BR>>slot.(It's=3D20<BR>> currently =
>>>> residing<BR>in PCI slot=20
>>>> 4. According to the manual, slot 4 =3D<BR>>and 2 =
>>>> are=3D20<BR>> not=20
>>>> shared. Plus<BR>even with the Sata controllers activated, each=20
>>>> of<BR>=3D<BR>>the=3D20<BR>> (4)eds cards had =
>>>> their<BR>own IRQ.=20
>>>> However, 1 EDS card shared (IRQ =
>>>> 16)<BR>=3D<BR>>with=3D20<BR>> the=20
>>>> Matrox G450. Strange..<BR><BR>I've been looking into this =
>>>> PCI=20

```

>>>> latency issues and download an app to  
 >>>> look and change some of the PCI =  
 >>>> latency =  
 >>>> settings. <BR><BR>The Sata controller had a setting of =  
 >>>> 0(zero).=  
 >>>> EDS =scherzo= (32) matrox=  
 >>>> (64)..IDE controller (0)..<BR><BR>Thanks for your =  
 >>>>  
 >>>> help =  
 >>>> ..LaMont<BR><BR><BR><BR> Ahris=  
 >>>> Ludwig <<A= href="A=  
 >>>> =  
 >>> href="mailto:chrisl@adkproaudio.com">chrisl@adkproaudio.com</A>=  
 >>>> mailto:chrisl@adkproaudio.com">chrisl@adkproaudio.com</A>=  
 >>>> 20</A><BR>> =  
 >>>> wrote:<BR>>HI Lamont,<BR>>Sorry to here your having=  
 >>>> trouble.<BR>>What exact model =  
 >>>> of the=  
 >>>> Gigabyte board do you mean. The description =  
 >>>> you<BR><BR>>have here is vague. Is it a K8NS=  
 >>>> Ultra -939?<BR>><BR>>When you say =  
 >>>> you=  
 >>>> rebuilt do you mean you =reinstalled =  
 >>>> windows from=  
 >>>> scratch?<BR>><BR>><BR>>LaMont=  
 >>>> wrote:<BR>>> =Hi =  
 >>>> gang:<BR>>>=  
 >>>> I 'm having problems getting Paris to ip and =running.=  
 >>>> Paris will sometimes<BR>>> star, only =  
 >>>> to just=  
 >>>> freeze up and crash the =whole = system. =  
 >>>> So, I=  
 >>>> thought<BR>my<BR>>> Asus-Amd XP combo(with=  
 >>>> SATA-Firwire)= was cause too much IRQ =  
 >>>> problems=  
 >>>> for<BR>>> Paris.<BR>>>=  
 >>>> <BR>>> So, I rebuilt with my favorite stable=  
 >>>> mobo(Gigabyte).<BR>>> =  
 >>>> <BR>>>=  
 >>>> Here's the skinny: I just build a new Paris/Nuendo PC. =  
 >>>> Great=  
 >>>> very very<BR>> fast:<BR>>> Here are =  
 >>>> the=  
 >>>> configs:<BR>>> =  
 >>>> <BR>>>=  
 >>>> -gigabyte mobo 939 Ultra250<BR>>> -Dual core opteron=  
 >>>> 165<BR>>> -2gig =  
 >>>> ddr400<BR>>>=

>>>> -sata (onboard) 3 300 gig drives<BR>>> =3D<BR>>-(1)=20  
>>>> RME=3D20<BR>> Digi 96 <BR>>> -(1)Magma card (4 =  
>>>> card EDS)=20  
>>>> <BR>>> -Matrox=3D20<BR>> g450<BR>>>=20  
>>>> <BR>>> Well, Nuendo runs like a Deer!!! WOW.. =  
>>>> =3D<BR>>>But=20  
>>>> PAris=3D20<BR>> is hit and miss. I =  
>>>> disabled:<BR>>> USB,=20  
>>>> SATA raid..A little =3D<BR>>>better, but=3D20<BR>>> I', =  
>>>> starting to=20  
>>>> think that My either<BR>>> my EdS cards or =  
>>>> =3D<BR>>>Mec/442=20  
>>>> are=3D20<BR>>> the problem. Just 2 weeks prior, the=20  
>>>> system<BR>was<BR>>> working =  
>>>> =3D<BR>>>fine.=3D20<BR>>> =20  
>>>> <BR>>>> <BR>>>> Note: In my studio I have a =  
>>>> master power=20  
>>>> =3D<BR>>>switch that=3D20<BR>>> start up the =  
>>>> Furman<BR>>>>=20  
>>>> power unit..The Magma and Mec units =3D<BR>>>were =  
>>>> on=3D20<BR>>> when I=20  
>>>> started up the system.<BR>>>> Maybe PAris got a Jolt ??? I=20  
>>>> =3D<BR>>>don;t=3D20<BR>>> know..<BR>>>> Please=20  
>>>> help..Thanks<BR>>>>=3D20<BR>>>> =20  
>>>> =  
>>>> <BR>>>><BR>>>><BR>>>><BR>>>><BR>>>>Chr=  
>>>> is<BR>>>><BR>>>>--=20  
>>>> =3D<BR>>><BR>>>>Chris=3D20<BR>>>> =20  
>>>> Ludwig<BR>>>><BR>>>>ADK Pro=20  
>>>> Audio<BR>>>>(859)=3D20<BR>>>> =20  
>>>> =  
>>>> =3D<BR>>>635-5762<BR>>>www.adkproaudio.com<BR>>>chrisl@=  
>>>> adkproaudio.com<BR>>></BL=3D<BR>>>OCKQUOTE></BODY>></=  
>>>> HTML><BR>>>><BR>>>><BR>>>></BLOCKQUOTE></BODY>></HTML>  
>>>>  
>>>>  
>> --  
>> Chris Ludwig  
>> ADK  
>> chrisl@adkproaudio.com <mailto:chrisl@adkproaudio.com>  
>> www.adkproaudio.com <http://www.adkproaudio.com/>  
>> (859) 635-5762  
>  
>  
  
--  
Chris Ludwig

ADK Pro Audio  
(859) 635-5762  
www.adkproaudio.com  
chrisl@adkproaudio.com

---

---

Subject: Re: Paris Problems on new machine: Hey Chris Ludwig...!  
Posted by [lamont\[1\]](#) on Wed, 01 Mar 2006 23:14:08 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Chris,  
I tried to purchase the Pro board but could not find it.. Maybe for the best,  
to many things to disable. :)

Chris Ludwig <chrisl@adkproaudio.com> wrote:

>HI Miguel,  
>  
>Yes quite a few differences.  
>  
>The K8NS Ultra-939  
>  
>nForce3 Ultra chip set 2000 mhz FSB  
>4 x sata ports 2 of which are integrated on the Nvidia chip set.  
>2 x lan both gigabit 1 is integrated on the nvidia chip set.  
>3 x 1384b (2x 400 1x 800 ports)  
>Dual\_BIOS  
>  
>The K8NSC-939  
>  
>NForce 3 250Gb chip set 1600 mhz FSB  
>2x sata ports  
>1x lan  
>no firewire  
>no dual bios  
>  
>  
>The only real major difference is the slower FSB.  
>  
>  
>Chris  
>  
>Miguel Vigil wrote:  
>> Hello Chris,  
>>  
>>>> not Standard PC. Mother Board GA-K8NSC-939  
>>  
>>  
>> re above mobo, which does not have the firewire i/o,

>> is there any major difference to the more expensive and  
>> elusive K8ns ultra pro you have touted?  
>>  
>> TIA,  
>>  
>> El Miguel  
>>  
>>  
>>  
>>  
>>  
>> "Chris Ludwig" <chrisl@adkproaudio.com> wrote in message  
>> news:4405b024@linux...  
>>> HI Lamont,  
>>> Wow weird stuff. Glad its working now.  
>>>  
>>> Chris  
>>>  
>>>  
>>> LaMont wrote:  
>>>> Tom & Chris,  
>>>>  
>>>> I got it solved. It was the Magma Chasis's power supply was not "seated"  
>>>> into slot properly. Paris is working fine now.  
>>>> Thanks  
>>>>  
>>>> "Tom Bruhl" <arpeggio@comcast.net> wrote:  
>>>>  
>>>>> LM,  
>>>>> Can't wait to hear.  
>>>>> T.  
>>>>> "LaMont" <jjdpro@ameritech.net> wrote in message =  
>>>>> news:44052522@linux...  
>>>>>  
>>>>> HEY Tom,  
>>>>> I'm in the Prcess of moving th magma card to differnt slots..I'll let  
>>>> =  
>>>>  
>>>>> you  
>>>>> know what happens..  
>>>>>  
>>>>> "Tom Bruhl" <arpeggio@comcast.net> wrote:  
>>>>>>  
>>>>>> LaMont,  
>>>>>> EDS1 with Matrox is a bad thing. I'd try different slots within  
>>>>>> the Magma to correct that. Have you tried any other slots on  
>>>>>> the mobo for the Magma card? That might be the first thing unless  
>>>>>> you know that won't help.



>>>>> Tom  
>>>>> "LaMont" <jjdpro@ameritech.net> wrote in message =3D  
>>>>> news:4404e5bf\$1@linux...  
>>>>>  
>>>>> Hi Chris,  
>>>>> Fresh install of win Xp/sp1. New drives, new everything. I'm using  
>>>> =  
>>>>  
>>>>> =3D  
>>>>> Apci,  
>>>>> not Standard PC. Mother Board GA-K8NSC-939  
>>>>> nforce-3 ultra 250gb.  
>>>>>  
>>>>> -Maybe moving the magma(13 slot) to a differnt slot.(It's currently  
>>>> =  
>>>>  
>>>>> =3D  
>>>>> residing  
>>>>> in PCI slot 4. According to the manual, slot 4 and 2 are not =  
>>>>> shared. =3D  
>>>>> Plus  
>>>>> even with the Sata controllers activated, each of the (4)eds cards  
>>>> =  
>>>>  
>>>>> had  
>>>>> =3D  
>>>>> their  
>>>>> own IRQ. However, 1 EDS card shared (IRQ 16) with the Matrox G450.  
>>>> =  
>>>>  
>>>>> =3D  
>>>>> Strange..  
>>>>>  
>>>>> I've been looking into this PCI latency issues and download an app  
>>>> =  
>>>>  
>>>>> to  
>>>>> =3D  
>>>>> look  
>>>>> and change soem of the PCI latency settings.=3D20  
>>>>>  
>>>>> The Sata controller had a setting of 0(zero). EDS scherzo (32) =  
>>>>> matrox  
>>>>> =3D  
>>>>> (64)..IDE  
>>>>> controller (0)..  
>>>>>  
>>>>> Thanks for your help ..LaMont

>>>>>  
>>>>>  
>>>>>  
>>>>> Ahris Ludwig <chrisl@adkproaudio.com> wrote:  
>>>>> >HI Lamont,  
>>>>> >Sorry to here your having trouble.  
>>>>> >What exact model of the Gigabyte board do you mean. The =  
>>>>> description =3D  
>>>>> you  
>>>>>  
>>>>> >have here is vague. Is it a K8NS Ultra -939?  
>>>>> >  
>>>>> >When you say you rebuilt do you mean you reinstalled windows from  
>>>> =  
>>>>  
>>>>> =3D  
>>>>> scratch?  
>>>>> >  
>>>>> >  
>>>>> >LaMont wrote:  
>>>>> >> Hi gang:  
>>>>> >> I 'm having problems getting Paris to ip and running. Paris will  
>>>> =  
>>>>  
>>>>> =3D  
>>>>> sometimes  
>>>>> >> star, only to just freeze up and crash the whole system. So, I  
=  
>>>>> =3D  
>>>>> thought  
>>>>> my  
>>>>> >> Asus-Amd XP combo(with SATA-Firwire) was cause too much IRQ =3D  
>>>>> problems for  
>>>>> >> PAris.  
>>>>> >>=3D20  
>>>>> >> So, I rebuilt with my favorite stable mobo(Gigabyte).  
>>>>> >>=3D20  
>>>>> >> Here's the skinny: I just build a new Paris/Nuendo PC. Great =  
>>>>> very =3D  
>>>>> very  
>>>>> fast:  
>>>>> >> Here are the configs:  
>>>>> >>=3D20  
>>>>> >> -gigabyte mobo 939 Ultra250  
>>>>> >> -Dual core opteron 165  
>>>>> >> -2gig ddr400  
>>>>> >> -sata (onboard) 3 300 gig drives  
>>>>> >> -(1) RME Digi 96=3D20

>>>>> >> -(1)Magma card (4 card EDS)=3D20  
>>>>> >> -Matrox g450  
>>>>> >>=3D20  
>>>>> >> Well, Nuendo runs like a Deer!!! WOW.. But PARis is hit and =  
>>>>> miss. I  
>>>>> =3D  
>>>>> disabled:  
>>>>> >> USB, SATA raid..A little better, but I', starting to think that  
>>>> =  
>>>>  
>>>>> My  
>>>>> =3D  
>>>>> either  
>>>>> >> my EdS cards or Mec/442 are the problem. Just 2 weeks prior, the  
>>>> =  
>>>>  
>>>>> =3D  
>>>>> system  
>>>>> was  
>>>>> >> working fine.=3D20  
>>>>> >>=3D20  
>>>>> >> Note: In my studio I have a master power switch that start up  
=  
>>>>> the =3D  
>>>>> FUrman  
>>>>> >> power unit..The Magama and Mec units were on when I started up  
=  
>>>>> the  
>>>>> =3D  
>>>>> system.  
>>>>> >> Maybe PARis got a Jolt ??? I don;t know..  
>>>>> >> Please help..Thanks  
>>>>> >>=3D20  
>>>>> >  
>>>>> >  
>>>>> >  
>>>>> >  
>>>>> >  
>>>>> >Chris  
>>>>> >  
>>>>> >--=3D20  
>>>>> >Chris Ludwig  
>>>>> >  
>>>>> >ADK Pro Audio  
>>>>> >(859) 635-5762  
>>>>> >www.adkproaudio.com  
>>>>> >chrisl@adkproaudio.com  
>>>>>  
>>>>>

```

>>>>> <!DOCTYPE HTML PUBLIC "-//W3C//DTD HTML 4.0 Transitional//EN">
>>>>> <HTML><HEAD>
>>>>> <META http-equiv=3D3DContent-Type content=3D3D"text/html; =3D
>>>>> charset=3D3Diso-8859-1">
>>>>> <META content=3D3D"MSHTML 6.00.2800.1400" name=3D3DGENERATOR>
>>>>> <STYLE></STYLE>
>>>>> </HEAD>
>>>>> <BODY bgColor=3D3D#ffffff>
>>>>> <DIV><FONT face=3D3DArial size=3D3D2>LaMont,</FONT></DIV>
>>>>> <DIV><FONT face=3D3DArial size=3D3D2>EDS1 with Matrox is a bad thing.
>>>> =
>>>>
>>>> =3D
>>>>> I'd try=3D20
>>>>> different slots within</FONT></DIV>
>>>>> <DIV><FONT face=3D3DArial size=3D3D2>the Magma to correct that. Have
>>>> =
>>>>
>>>> =3D
>>>>> you tried any=3D20
>>>>> other slots on</FONT></DIV>
>>>>> <DIV><FONT face=3D3DArial size=3D3D2>the mobo for the Magma card?
=
>>>>> That =3D
>>>>> might be=3D20
>>>>> the first thing unless</FONT></DIV>
>>>>> <DIV><FONT face=3D3DArial size=3D3D2>you know that won't =
>>>>> help.</FONT></DIV>
>>>>> <DIV><FONT face=3D3DArial size=3D3D2>Tom</FONT></DIV>
>>>>> <BLOCKQUOTE=3D20
>>>>> style=3D3D"PADDING-RIGHT: 0px; PADDING-LEFT: 5px; MARGIN-LEFT: 5px;
=
>>>>> =3D
>>>>> BORDER-LEFT: #000000 2px solid; MARGIN-RIGHT: 0px">
>>>>> <DIV>"LaMont" <<A=3D20
>>>>> href=3D3D"mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A>>
=
>>>>> =3D
>>>>> wrote in=3D20
>>>>> message <A=3D20
>>>>> =3D
>>>>> =
>>>>>
>>>>> href=3D3D"news:4404e5bf$1@linux">news:4404e5bf$1@linux</A>...</DIV><BR>H=
>>>>>
>>>>> i=3D20
>>>>>> Chris,<BR>Fresh install of win Xp/sp1. New drives, new everything.
>>>> =

```

>>>>  
>>>>> I'm  
>>>>> =3D  
>>>>> using=3D20  
>>>>> Apci,<BR>not Standard PC. Mother Board GA-K8NSC-939<BR>nforce-3 =  
>>>>> ultra=3D20  
>>>>> 250gb.<BR><BR>-Maybe moving the magma(13 slot) to a differnt =3D  
>>>>> slot.(It's=3D20  
>>>>> currently residing<BR>in PCI slot 4. According to the manual, slot  
>>>> =  
>>>>  
>>>>> 4 =3D  
>>>>> and 2 are=3D20  
>>>>> not shared. Plus<BR>even with the SATA controllers activated, each  
>>>> =  
>>>>  
>>>>> of  
>>>>> =3D  
>>>>> the=3D20  
>>>>> (4)eds cards had their<BR>own IRQ. However, 1 EDS card shared (IRQ  
>>>> =  
>>>>  
>>>>> 16)  
>>>>> =3D  
>>>>> with=3D20  
>>>>> the Matrox G450. Strange..<BR><BR>I've been looking into this PCI  
=  
>>>>> =3D  
>>>>> latency=3D20  
>>>>> issues and download an app to look<BR>and change soem of the PCI  
=  
>>>>> =3D  
>>>>> latency=3D20  
>>>>> settings. <BR><BR>The SATA controller had a setting of 0(zero). EDS  
>>>> =  
>>>>  
>>>>> =3D  
>>>>> scherzo=3D20  
>>>>> (32) matrox (64)..IDE<BR>controller (0)..<BR><BR>Thanks for your  
=  
>>>>> help=3D20  
>>>>> ..LaMont<BR><BR><BR><BR> Ahris Ludwig <<A=3D20  
>>>>>> =  
>>>> href=3D3D"mailto:chrisl@adkproaudio.com">chrisl@adkproaudio.com</A>>=3D20=  
>>>>>> wrote:<BR>>HI Lamont,<BR>>Sorry to here your having =3D  
>>>>>> trouble.<BR>>What=3D20  
>>>>>> exact model of the Gigabyte board do you mean. The description=3D20  
>>>>>> you<BR><BR>>have here is vague. Is it a K8NS Ultra=3D20

>>>>> -939?<BR><BR>>When you say you rebuilt do you mean you =3D  
>>>>> reinstalled=3D20  
>>>>> windows from scratch?<BR><BR><BR>>LaMont wrote:<BR>>> =3D  
>>>>> Hi=3D20  
>>>>> gang:<BR>>> I 'm having problems getting Paris to ip and =3D  
>>>>> running. Paris=3D20  
>>>>> will sometimes<BR>>> star, only to just freeze up and crash the =3D  
>>>>> whole=3D20  
>>>>> system. So, I thought<BR>my<BR>>> Asus-Amd XP combo(with =3D  
>>>>> SATA-Firwire)=3D20  
>>>>> was cause too much IRQ problems for<BR>>> PAris.<BR>>>=3D20  
>>>>> <BR>>> So, I rebuilt with my favorite stable =3D  
>>>>> mobo(Gigabyte).<BR>>>=3D20  
>>>>> <BR>>> Here's the skinny: I just build a new Paris/Nuendo PC. =3D  
>>>>> Great very=3D20  
>>>>> very<BR>fast:<BR>>> Here are the configs:<BR>>> =3D  
>>>>> <BR>>>=3D20  
>>>>> -gigabyte mobo 939 Ultra250<BR>>> -Dual core opteron =3D  
>>>>> 165<BR>>>=3D20  
>>>>> -2gig ddr400<BR>>> -sata (onboard) 3 300 gig drives<BR>>> =3D  
>>>>> -(1) RME=3D20  
>>>>> Digi 96 <BR>>> -(1)Magma card (4 card EDS) <BR>>> -Matrox=3D20  
>>>>> g450<BR>>> <BR>>> Well, Nuendo runs like a Deer!!! WOW.. =3D  
>>>>> But PAris=3D20  
>>>>> is hit and miss. I disabled:<BR>>> USB, SATA raid..A little =3D  
>>>>> better, but=3D20  
>>>>> I', starting to think that My either<BR>>> my EdS cards or =3D  
>>>>> Mec/442 are=3D20  
>>>>> the problem. Just 2 weeks prior, the system<BR>was<BR>>> working  
=  
>>>>> =3D  
>>>>> fine.=3D20  
>>>>> <BR>>> <BR>>> Note: In my studio I have a master power =3D  
>>>>> switch that=3D20  
>>>>> start up the FURman<BR>>> power unit..The Magama and Mec units =3D  
>>>>> were on=3D20  
>>>>> when I started up the system.<BR>>> Maybe PAris got a Jolt ??? I  
=  
>>>>> =3D  
>>>>> don;t=3D20  
>>>>> know..<BR>>> Please help..Thanks<BR>>>=3D20  
>>>>> <BR>><BR>><BR>><BR>><BR>>Chris<BR>><BR>>-- =3D  
>>>>> <BR>>Chris=3D20  
>>>>> Ludwig<BR>><BR>>ADK Pro Audio<BR>>(859)=3D20  
>>>>> =3D  
>>>>> =  
>>>>>  
>>>>> 635-5762<BR>>www.adkproaudio.com<BR>>chrisl@adkproaudio.com<BR></BL=3D

```
>>>>> OCKQUOTE></BODY></HTML>
>>>>>
>>>>>
>>>>>
>>>>> <!DOCTYPE HTML PUBLIC "-//W3C//DTD HTML 4.0 Transitional//EN">
>>>>> <HTML><HEAD>
>>>>> <META http-equiv=3DContent-Type content=3D"text/html; =
>>>>> charset=3Diso-8859-1">
>>>>> <META content=3D"MSHTML 6.00.2800.1400" name=3DGENERATOR>
>>>>> <STYLE></STYLE>
>>>>> </HEAD>
>>>>> <BODY bgColor=3D#ffffff>
>>>>> <DIV><FONT face=3DArial size=3D2>LM,</FONT></DIV>
>>>>> <DIV><FONT face=3DArial size=3D2>Can't wait to hear.</FONT></DIV>
>>>>> <DIV><FONT face=3DArial size=3D2>T.</FONT></DIV>
>>>>> <BLOCKQUOTE=20
>>>>> style=3D"PADDING-RIGHT: 0px; PADDING-LEFT: 5px; MARGIN-LEFT: 5px; =
>>>>> BORDER-LEFT: #000000 2px solid; MARGIN-RIGHT: 0px">
>>>>> <DIV>"LaMont" <<A=20
>>>>> href=3D"mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A>> =
>>>>> wrote in=20
>>>>> message <A =
>>>>> href=3D"news:44052522@linux">news:44052522@linux</A>...</DIV><BR>HEY=20
>>>>> Tom,<BR>I'm in the Prcess of moving th magma card to differnt =
>>>>> slots..I'll let=20
>>>>> you<BR>know what happens..  
>>>>> <BR><BR>"Tom Bruhl" <<A=20
>>>>> href=3D"mailto:arpegio@comcast.net">arpegio@comcast.net</A>>=20
>>>>> wrote:<BR>><BR>><BR>>LaMont,<BR>>EDS1 with Matrox is a bad =
>>>>>
>>>>> thing. I'd try different slots within<BR>>the Magma to =
>>>>> correct=20
>>>>> that. Have you tried any other slots on<BR>>the mobo for the =
>>>>> Magma=20
>>>>> card? That might be the first thing unless<BR>>you know that =
>>>>> won't=20
>>>>> help.<BR>>Tom<BR>> "LaMont" <<A=20
>>>>> href=3D"mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A>> =
>>>>> wrote in=20
>>>>> message =3D<BR>>news:4404e5bf$1@linux...<BR>><BR>> Hi=20
>>>>> Chris,<BR>> Fresh install of win Xp/sp1. New drives, new =
>>>>> everything.=20
>>>>> I'm using =3D<BR>>Apci,<BR>> not Standard PC. Mother Board =
>>>>>
>>>>> GA-K8NSC-939<BR>> nforce-3 ultra 250gb.<BR>><BR>> =
>>>>> -Maybe=20
>>>>> moving the magma(13 slot) to a differnt slot.(It's currently=20
>>>>> =3D<BR>>residing<BR>> in PCI slot 4. According to the =
>>>>> manual, slot 4=20
```

>>>> and 2 are not shared. =3D<BR>>Plus<BR>> even with the Sata =  
>>>>  
>>>> controllers activated, each of the (4)eds cards=20  
>>>> had<BR>=3D<BR>>their<BR>> own IRQ. However, 1 EDS card =  
>>>> shared (IRQ=20  
>>>> 16) with the Matrox G450. =3D<BR>>Strange..  
>>>> I've been=20  
>>>> looking into this PCI latency issues and download an app=20  
>>>> to<BR>=3D<BR>>look<BR>> and change soem of the PCI latency =  
>>>>  
>>>> settings.=3D20<BR>><BR>> The Sata controller had a setting =  
>>>> of=20  
>>>> 0(zero). EDS scherzo (32) matrox<BR>=3D<BR>>(64)..IDE<BR>> =  
>>>>  
>>>> controller (0)..<BR>><BR>> Thanks for your help=20  
>>>> ..LaMont<BR>><BR>><BR>><BR>> Ahris Ludwig =  
>>>> <<A=20  
>>>> href=3D"mailto:chrisl@adkproaudio.com">chrisl@adkproaudio.com</A>=20  
>>>> wrote:<BR>> >HI Lamont,<BR>> >Sorry to here =  
>>>> your=20  
>>>> having trouble.<BR>> >What exact model of the Gigabyte =  
>>>> board do=20  
>>>> you mean. The description =3D<BR>>you<BR>><BR>> =  
>>>>  
>>>>> have here is=20  
>>>> vague. Is it a K8NS Ultra -939?<BR>> ><BR>> =  
>>>>  
>>>>> When you=20  
>>>> say you rebuilt do you mean you reinstalled windows from=20  
>>>> =3D<BR>>scratch?<BR>> ><BR>> =  
>>>>  
>>>>> <BR>> =20  
>>>>>> LaMont wrote:<BR>> >> Hi gang:<BR>> =  
>>>>>>> I 'm=20  
>>>> having problems getting Paris to ip and running. Paris will=20  
>>>> =3D<BR>>sometimes<BR>> >> star, only to just freeze =  
>>>> up and=20  
>>>> crash the whole system. So, I =3D<BR>>thought<BR>> =  
>>>> my<BR>> =20  
>>>>>>> Asus-Amd XP combo(with SATA-Firwire) was cause too much IRQ=20  
>>>> =3D<BR>>problems for<BR>> >> PAris.<BR>> =20  
>>>>>>> =3D20<BR>> >> So, I rebuilt with my favorite =  
>>>> stable=20  
>>>> mobo(Gigabyte).<BR>> >>=3D20<BR>> >> =  
>>>> Here's the=20  
>>>> skinny: I just build a new Paris/Nuendo PC. Great very=20  
>>>> =3D<BR>>very<BR>> fast:<BR>> >> Here are =  
>>>> the=20



```

>>>> configs:<BR>> >>=3D20<BR>> >> -gigabyte =
>>>> mobo 939=20
>>>> Ultra250<BR>> >> -Dual core opteron 165<BR>> =
>>>>
>>>>>> =20
>>>> -2gig ddr400<BR>> >> -sata (onboard) 3 300 gig=20
>>>> drives<BR>> >> -(1) RME Digi 96=3D20<BR>> =
>>>>
>>>>>> =20
>>>> -(1)Magma card (4 card EDS)=3D20<BR>> >> -Matrox=20
>>>> g450<BR>> >>=3D20<BR>> >> Well, Nuendo =
>>>> runs like a=20
>>>> Deer!!! WOW.. But PARIS is hit and miss. =
>>>> l<BR>=3D<BR>>disabled:<BR>> =20
>>>>>> USB, SATA raid..A little better, but I', starting to think =
>>>> that=20
>>>> My<BR>=3D<BR>>either<BR>> >> my EdS cards or Mec/442 =
>>>> are the=20
>>>> problem. Just 2 weeks prior, the =3D<BR>>system<BR>> =20
>>>> was<BR>> >> working fine.=3D20<BR>> =20
>>>>>> =3D20<BR>> >> Note: In my studio I have a =
>>>> master power=20
>>>> switch that start up the =3D<BR>>FUrman<BR>> >> =
>>>> power=20
>>>> unit..The Magama and Mec units were on when I started up=20
>>>> the<BR>=3D<BR>>system.<BR>> >> Maybe PARIS got a =
>>>> Jolt ??? I=20
>>>> don;t know..<BR>> >> Please help..Thanks<BR>> =20
>>>>>> =3D20<BR>> ><BR>> ><BR>> =20
>>>>>> <BR>> ><BR>> >Chris<BR>> =20
>>>>>> <BR>> >--=3D20<BR>> >Chris =
>>>>>> Ludwig<BR>> =20
>>>>>> <BR>> >ADK Pro Audio<BR>> >(859)=20
>>>>>> 635-5762<BR>> >www.adkproaudio.com<BR>> =20
>>>>>> chrisl@adkproaudio.com<BR>><BR>><BR>><!DOCTYPE HTML =
>>>>>> PUBLIC=20
>>>>>> "-//W3C//DTD HTML 4.0=20
>>>>>> Transitional//EN"><BR>><HTML><HEAD><BR>><META=20
>>>>>> http-equiv=3D3DContent-Type content=3D3D"text/html;=20
>>>>>> =3D<BR>>charset=3D3Diso-8859-1"><BR>><META =
>>>>>> content=3D3D"MSHTML=20
>>>>>> 6.00.2800.1400"=20
>>>>>> =
>>>>>> name=3D3DGENERATOR><BR>><STYLE></STYLE><BR>></HEA=
>>>>>> D><BR>><BODY=20
>>>>>> bgColor=3D3D#ffffff><BR>><DIV><FONT face=3D3DArial=20
>>>>>> =
>>>>>> size=3D3D2>LaMont,</FONT></DIV><BR>><DIV><FONT=

```

```

>>>> =20
>>>> face=3D3DArial size=3D3D2>EDS1 with Matrox is a bad thing. =
>>>> =3D<BR>>l'd=20
>>>> try=3D20<BR>>different slots=20
>>>> within</FONT></DIV><BR>><DIV><FONT =
>>>> face=3D3DArial=20
>>>> size=3D3D2>the Magma to correct that. Have =3D<BR>>you tried=20
>>>> any=3D20<BR>>other slots=20
>>>> on</FONT></DIV><BR>><DIV><FONT face=3D3DArial=20
>>>> size=3D3D2>the mobo for the Magma card? That =3D<BR>>might =
>>>> be=3D20<BR>>the=20
>>>> first thing unless</FONT></DIV><BR>><DIV><FONT =
>>>>
>>>> face=3D3DArial size=3D3D2>you know that won't=20
>>>> help.</FONT></DIV><BR>><DIV><FONT =
>>>> face=3D3DArial=20
>>>> =
>>>> size=3D3D2>Tom</FONT></DIV><BR>><BLOCKQUOTE=3D20<BR>=
>>>>
>>>>> style=3D3D"PADDING-RIGHT:=20
>>>>> 0px; PADDING-LEFT: 5px; MARGIN-LEFT: 5px; =3D<BR>>BORDER-LEFT: =
>>>>> #000000 2px=20
>>>>> solid; MARGIN-RIGHT: 0px"><BR>> <DIV>"LaMont"=20
>>>>> <<A=3D20<BR>> href=3D3D"<A=20
>>>>> =
>>>> href=3D'mailto:jjdpro@ameritech.net">jjdpro@ameritech.net</A'>mailto:jjdp=
>>>>> ro@ameritech.net">jjdpro@ameritech.net</A</A>>>=20
>>>>> =3D<BR>>wrote in=3D20<BR>> message =
>>>>> <A=3D20<BR>> =20
>>>>> =3D<BR>>href=3D3D"<A=20
>>>>> =
>>>> href=3D'news:4404e5bf$1 @linux">news:4404e5bf$1 @linux</A>...</DIV><BR>Hi=3D
>>>> =
>>>>> 20'>news:4404e5bf$1 @linux">news:4404e5bf$1 @linux</A>...</DIV&=
>>>>> gt;<BR>Hi=3D20</A><BR>> =20
>>>>> Chris,<BR>Fresh install of win Xp/sp1. New drives, new =
>>>>> everything.=20
>>>>> I'm<BR>=3D<BR>>using=3D20<BR>> Apci,<BR>not Standard =
>>>>> PC. Mother=20
>>>>> Board GA-K8NSC-939<BR>nforce-3 ultra=3D20<BR>> =20
>>>>> 250gb.<BR><BR>-Maybe moving the magma(13 slot) to a =
>>>>> differnt=20
>>>>> =3D<BR>>slot.(It's=3D20<BR>> currently =
>>>>> residing<BR>in PCI slot=20
>>>>> 4. According to the manual, slot 4 =3D<BR>>and 2 =
>>>>> are=3D20<BR>> not=20
>>>>> shared. Plus<BR>even with the Sata controllers activated, each=20
>>>>> of<BR>=3D<BR>>the=3D20<BR>> (4)eds cards had =

```

>>>> their<BR>own IRQ.=20  
>>>> However, 1 EDS card shared (IRQ =  
>>>> 16)<BR>=3D<BR>>with=3D20<BR>> the=20  
>>>> Matrox G450. Strange..<BR><BR>I've been looking into this =  
>>>> PCI=20  
>>>> =3D<BR>>latency=3D20<BR>> issues and download an app to=20  
>>>> look<BR>and change soem of the PCI =  
>>>> =3D<BR>>latency=3D20<BR>> =20  
>>>> settings. <BR><BR>The Sata controller had a setting of =  
>>>> 0(zero).=20  
>>>> EDS =3D<BR>>scherzo=3D20<BR>> (32) matrox=20  
>>>> (64)..IDE<BR>controller (0)..<BR><BR>Thanks for your =  
>>>>  
>>>> help=3D20<BR>> =  
>>>> ..LaMont<BR><BR><BR><BR> Ahris=20  
>>>> Ludwig <<A=3D20<BR>> href=3D3D"<A=20  
>>>> =  
>>>> href=3D'mailto:chrisl@adkproaudio.com">chrisl@adkproaudio.com</A>>=3D20'>=  
>>>> mailto:chrisl@adkproaudio.com">chrisl@adkproaudio.com</A>>=3D=  
>>>> 20</A><BR>> =20  
>>>> wrote:<BR>>HI Lamont,<BR>>Sorry to here your having=20  
>>>> =3D<BR>>trouble.<BR>>What=3D20<BR>> exact model =  
>>>> of the=20  
>>>> Gigabyte board do you mean. The description=3D20<BR>> =20  
>>>> you<BR><BR>>have here is vague. Is it a K8NS=20  
>>>> Ultra=3D20<BR>> -939?<BR>><BR>>When you say =  
>>>> you=20  
>>>> rebuilt do you mean you =3D<BR>>reinstalled=3D20<BR>> =  
>>>> windows from=20  
>>>> scratch?<BR>><BR>><BR>>LaMont=20  
>>>> wrote:<BR>>> =3D<BR>>Hi=3D20<BR>> =  
>>>> gang:<BR>>>=20  
>>>> I 'm having problems getting Paris to ip and =3D<BR>>running.=20  
>>>> Paris=3D20<BR>> will sometimes<BR>>> star, only =  
>>>> to just=20  
>>>> freeze up and crash the =3D<BR>>whole=3D20<BR>> system. =  
>>>> So, I=20  
>>>> thought<BR>my<BR>>> Asus-Amd XP combo(with=20  
>>>> =3D<BR>>SATA-Firwire)=3D20<BR>> was cause too much IRQ =  
>>>> problems=20  
>>>> for<BR>>> PAris.<BR>>>=3D20<BR>> =20  
>>>> <BR>>> So, I rebuilt with my favorite stable=20  
>>>> =3D<BR>>mobo(Gigabyte).<BR>>>=3D20<BR>> =  
>>>> <BR>>>=20  
>>>> Here's the skinny: I just build a new Paris/Nuendo PC. =  
>>>> =3D<BR>>Great=20  
>>>> very=3D20<BR>> very<BR>fast:<BR>>> Here are =  
>>>> the=20

>>>> configs:<BR>>> =  
 >>>> =3D<BR>><BR>>=3D20<BR>> =20  
 >>>> -gigabyte mobo 939 Ultra250<BR>>> -Dual core opteron=20  
 >>>> =3D<BR>>165<BR>>>=3D20<BR>> -2gig =  
 >>>> ddr400<BR>>>=20  
 >>>> -sata (onboard) 3 300 gig drives<BR>>> =3D<BR>>-(1)=20  
 >>>> RME=3D20<BR>> Digi 96 <BR>>> -(1)Magma card (4 =  
 >>>> card EDS)=20  
 >>>> <BR>>> -Matrox=3D20<BR>> g450<BR>>>=20  
 >>>> <BR>>> Well, Nuendo runs like a Deer!!! WOW.. =  
 >>>> =3D<BR>>But=20  
 >>>> PARis=3D20<BR>> is hit and miss. I =  
 >>>> disabled:<BR>>> USB,=20  
 >>>> SATA raid..A little =3D<BR>>better, but=3D20<BR>> I', =  
 >>>> starting to=20  
 >>>> think that My either<BR>>> my EdS cards or =  
 >>>> =3D<BR>>Mec/442=20  
 >>>> are=3D20<BR>> the problem. Just 2 weeks prior, the=20  
 >>>> system<BR>was<BR>>> working =  
 >>>> =3D<BR>>fine.=3D20<BR>> =20  
 >>>> <BR>>> <BR>>> Note: In my studio I have a =  
 >>>> master power=20  
 >>>> =3D<BR>>switch that=3D20<BR>> start up the =  
 >>>> FUrman<BR>>>=20  
 >>>> power unit..The Magama and Mec units =3D<BR>>were =  
 >>>> on=3D20<BR>> when I=20  
 >>>> started up the system.<BR>>> Maybe PARis got a Jolt ??? I=20  
 >>>> =3D<BR>>don;t=3D20<BR>> know..<BR>>> Please=20  
 >>>> help..Thanks<BR>>>=3D20<BR>> =20  
 >>>> =  
 >>>> <BR>><BR>><BR>><BR>><BR>>Chr=  
 >>>> is<BR>><BR>>--=20  
 >>>> =3D<BR>><BR>>Chris=3D20<BR>> =20  
 >>>> Ludwig<BR>><BR>>ADK Pro=20  
 >>>> Audio<BR>>>(859)=3D20<BR>> =20  
 >>>> =  
 >>>> =3D<BR>>635-5762<BR>>www.adkproaudio.com<BR>>chrisl@=  
 >>>> adkproaudio.com<BR></BL=3D<BR>>OCKQUOTE></BODY></=  
 >>>> HTML><BR>><BR>><BR></BLOCKQUOTE></BODY></HTML>  
 >>>>  
 >>>>  
 >>> --  
 >>> Chris Ludwig  
 >>> ADK  
 >>> chrisl@adkproaudio.com <mailto:chrisl@adkproaudio.com>  
 >>> www.adkproaudio.com <http://www.adkproaudio.com/>  
 >>> (859) 635-5762  
 >>

>>  
>  
>--  
>Chris Ludwig  
>  
>ADK Pro Audio  
>(859) 635-5762  
>www.adkproaudio.com  
>chrisl@adkproaudio.com

---