Subject: Re: ASIO DRIVER current status ? Posted by mikeaudet on Tue, 20 Feb 2018 15:54:39 GMT View Forum Message <> Reply to Message

So...I've been working on a few things...one of which is laying the groundwork for a new scherzo to support a 64 bit ASIO, but I took a bit of a detour and decided to see if I could clean up a couple of things in the 32 bit ASIO...and....

I got 32 sample buffer sizes working!!!

## File Attachments

File	e Attachmei	nts							
_) 32	2-samples!.	jpg,	downloaded	d 7818	times				
🗿 Aud	io/MIDI Setup								×
					13				
			Latency Meas	suremen	t Tool				
		1	furn down the vol audio equipment t	ume on y o a very l	our ow level.				
	S	elect two	channels below an	d connect	them using a (	cable.			
	Output channel	syste	em:playback_4						
	Input channel	syste	em:capture_4						
	On	ce the cl	hannels are connect	ted, click th	ne "Measure" l	outton.			
	Wh	en satisi	fied with the results	, click the '	"Use results" l	button.			
			oundtrip latenc itency: -96 sam			150 ms)			
	Measure		Use results	в	lack to setting	s (ignore	result	5)	