Subject: new motherboard confusion
Posted by Graham Duncan on Mon, 12 Nov 2007 19:37:49 GMT
View Forum Message <> Reply to Message

Hello everyone,

A few questions...

I see that the Intel P35 boards need 1.8v RAM... so what is recommended here? It seems like most of the "good" RAM (Corsair or Super Talent) is 2.1v.

P35 motherboard:

http://www.newegg.com/Product/Product.aspx?Item=N82E16813121 314

And now I'm horribly confused about PCle 1x vs 16x slots. Obviously the 16x is for video... but on some motherboards there are 3 16x slots and NO 1x slots. Does anyone know if PCle cards such as the RME and UAD1e stuff will work in a 16x slot?

975 motherboard:

http://www.newegg.com/Product/Product.aspx?Item=N82E16813121 060

This will be with a Q6600 processor...

Thanks,

Graham