
Subject: Found the USB over current problem=-thanks Dave ;o)

Posted by [Deej \[1\]](#) on Sat, 06 May 2006 03:33:22 GMT

[View Forum Message](#) <> [Reply to Message](#)

The issue seems to be in the v1017 bios itself. I just rolled back to the v1014 bios and I'm up and running.

WTF is with ASUS anyway? It seems that they have added an over current warning that emulates an over current scenario and shuts their system down.....genius.....pure genius.....

Thanks for the suggestion Dave. I would have never thought to do this if you hadn't suggested it.

;oP
