
Subject: It's stranger than fiction around here sometimes

Posted by [Deej \[4\]](#) on Thu, 08 Mar 2007 20:19:13 GMT

[View Forum Message](#) <> [Reply to Message](#)

Well, my Lexicon PCM 91 quit passing signal reliably last night. After troubleshooting it, my RME ADI-DD, my harness from the ADI4-DD to the outboard processors and putting in calls to Morgan, CBI and Synthax, I found the problem. The WC cable that was feeding the ADI8-DD from the GenX-6 that is distributing WC from my Mytek clock was full of punctures. Either there's bad studiocat behaviour going on or a bad mouse or other vermin that the bad studiocat should be attending to. This is, by far, one of the wierdest studio occurrences I've had yet. This was a very expensive Zaolla 75 ohm WC cable and I would have definitely noticed if it would have been punctured prior to my installing it.

;oP

Subject: Re: It's stranger than fiction around here sometimes

Posted by [John \[1\]](#) on Fri, 09 Mar 2007 00:28:23 GMT

[View Forum Message](#) <> [Reply to Message](#)

This means your setup is still to complicated. Sell half and see how it works.
Rinse and repeat. hehe

Subject: Re: It's stranger than fiction around here sometimes

Posted by [rick](#) on Fri, 09 Mar 2007 09:55:42 GMT

[View Forum Message](#) <> [Reply to Message](#)

try having ghosts...and i'm not the only one who sees the shadows moving about.

On Thu, 8 Mar 2007 13:19:13 -0700, "DJ" <www.aarrrrggghhh!!!.com> wrote:

>Well, my Lexicon PCM 91 quit passing signal reliably last night. After
>troubleshooting it, my RME ADI-DD, my harness from the ADI4-DD to the
>outboard processors and putting in calls to Morgan, CBI and Synthax, I found
>the problem. The WC cable that was feeding the ADI8-DD from the GenX-6 that
>is distributing WC from my Mytek clock was full of punctures. Either there's
>bad studiocat behaviour going on or a bad mouse or other vermin that the bad
>studiocat should be attending to. This is, by far, one of the wierdest
>studio occurrences I've had yet. This was a very expensive Zaolla 75 ohm WC
>cable and I would have definitely noticed if it would have been punctured
>prior to my installing it.
>

>;oP

>

>

Subject: Re: It's stranger than fiction around here sometimes

Posted by [John \[1\]](#) on Fri, 09 Mar 2007 13:07:57 GMT

[View Forum Message](#) <> [Reply to Message](#)

Just play the Zeppelin Immigrant's Song from Zep3 at 105 db. Ghost hate that and leave permanently.

Ah, ah,

We come from the land of the ice and snow,
from the midnight sun where the hot springs blow.

The hammer of the gods

Will drive our ships to new lands,

To fight the horde, singing and crying:

Valhalla, I am coming!

On we sweep with threshing oar,

Our only goal will be the western shore.

Ah, ah,

We come from the land of the ice and snow,
from the midnight sun where the hot springs blow.

How soft your fields so green,

Can whisper tales of gore,

Of how we calmed the tides of war.

We are your overlords.

On we sweep with threshing oar,

Our only goal will be the western shore.

So now you'd better stop and rebuild all your ruins,

For peace and trust can win the day

Despite of all your losing.

Subject: Re: It's stranger than fiction around here sometimes

Posted by [rick](#) on Fri, 09 Mar 2007 17:45:01 GMT

[View Forum Message](#) <> [Reply to Message](#)

if they can deal with some of the bands that come though here then
that ain't nuthin'

On 9 Mar 2007 23:07:57 +1000, "John" <no@no.com> wrote:

>

>Just play the Zeppelin Immigrant's Song from Zep3 at 105 db. Ghost hate that
>and leave permanently.

>
>Ah, ah,
>We come from the land of the ice and snow,
>from the midnight sun where the hot springs blow.
>The hammer of the gods
>Will drive our ships to new lands,
>To fight the horde, singing and crying:
>Valhalla, I am coming!
>On we sweep with threshing oar,
>Our only goal will be the western shore.
>Ah, ah,
>We come from the land of the ice and snow,
>from the midnight sun where the hot springs blow.
>How soft your fields so green,
>Can whisper tales of gore,
>Of how we calmed the tides of war.
>We are your overlords.
>On we sweep with threshing oar,
>Our only goal will be the western shore.
>So now you'd better stop and rebuild all your ruins,
>For peace and trust can win the day
>Despite of all your losing.
>

Subject: Re: It's stranger than fiction around here sometimes
Posted by [excelav](#) on Fri, 09 Mar 2007 18:10:47 GMT
[View Forum Message](#) <> [Reply to Message](#)

Yeah, they hate Britney Spears Too!

"John" <no@no.com> wrote:

>
>Just play the Zeppelin Immigrant's Song from Zep3 at 105 db. Ghost hate
that
>and leave permanently.
>
>Ah, ah,
>We come from the land of the ice and snow,
>from the midnight sun where the hot springs blow.
>The hammer of the gods
>Will drive our ships to new lands,
>To fight the horde, singing and crying:
>Valhalla, I am coming!
>On we sweep with threshing oar,
>Our only goal will be the western shore.
>Ah, ah,
>We come from the land of the ice and snow,

>from the midnight sun where the hot springs blow.
>How soft your fields so green,
>Can whisper tales of gore,
>Of how we calmed the tides of war.
>We are your overlords.
>On we sweep with threshing oar,
>Our only goal will be the western shore.
>So now youd better stop and rebuild all your ruins,
>For peace and trust can win the day
>Despite of all your losing.
>
>

Subject: Re: It's stranger than fiction around here sometimes
Posted by [Sarah](#) on Fri, 09 Mar 2007 23:21:19 GMT
[View Forum Message](#) <> [Reply to Message](#)

Is it bad that I have no idea what you're talking about? :)

Sarah

"DJ" <www.aarrrrggghhh!!!.com> wrote in message news:45f06fde\$1@linux...
> Well, my Lexicon PCM 91 quit passing signal reliably last night. After
> troubleshooting it, my RME ADI-DD, my harness from the ADI4-DD to the
> outboard processors and putting in calls to Morgan, CBI and Synthax, I
> found the problem. The WC cable that was feeding the ADI8-DD from the
> GenX-6 that is distributing WC from my Mytek clock was full of punctures.
> Either there's bad studiocat behaviour going on or a bad mouse or other
> vermin that the bad studiocat should be attending to. This is, by far, one
> of the wierdest studio occurrences I've had yet. This was a very expensive
> Zaolla 75 ohm WC cable and I would have definitely noticed if it would
> have been punctured prior to my installing it.
>
> ;oP
>
>
>

Subject: Re: It's stranger than fiction around here sometimes
Posted by [Deej \[4\]](#) on Sat, 10 Mar 2007 02:01:04 GMT
[View Forum Message](#) <> [Reply to Message](#)

Ok.....hmmmm.....letsee.....

PCM 91 = outboard reverb processor

RME ADI4-DD=ADAT to AES format converter which allows 4 x devices with AES inputs and outputs to interface with the optical ports on an audio card

harness=the cabling that attaches the AES devices to the RME ADI4-DD

GENX-6=module that takes a word clock signal from another device, splits it 6 ways and then feeds it to six different devices

Zaolla 75ohm WC cable=a pretty darned expensive piece of silver wire covered with rubber and having BNC connectors on either end to connect to other devices with similar connectors.

bad studiocat=little grey horror who likes to leave the carcasses of dead rodents in my chair as a present upon occasion.

hmmm.....not sure if this is clear even now after looking at it.

;o)

"Sarah" <sarahjane@sarahtonin.com> wrote in message news:45f1ec0b@linux...

> Is it bad that I have no idea what you're talking about? :)

>

> Sarah

>

>

> "DJ" <www.aarrrrggghhh!!!.com> wrote in message news:45f06fde\$1@linux...

>> Well, my Lexicon PCM 91 quit passing signal reliably last night. After
>> troubleshooting it, my RME ADI-DD, my harness from the ADI4-DD to the
>> outboard processors and putting in calls to Morgan, CBI and Synthax, I
>> found the problem. The WC cable that was feeding the ADI8-DD from the
>> GenX-6 that is distributing WC from my Mytek clock was full of punctures.
>> Either there's bad studiocat behaviour going on or a bad mouse or other
>> vermin that the bad studiocat should be attending to. This is, by far,
>> one of the wierdest studio occurrences I've had yet. This was a very
>> expensive Zaolla 75 ohm WC cable and I would have definitely noticed if
>> it would have been punctured prior to my installing it.

>>

>> ;oP

>>

>>

>>

>

>

Subject: Re: It's stranger than fiction around here sometimes
Posted by [Sarah](#) on Sat, 10 Mar 2007 07:39:21 GMT
[View Forum Message](#) <> [Reply to Message](#)

Uh yeah, thanks for clearing that up. :)

Sarah

PS: Does your bad studiocat leave the rodents in good condition, aside from being dead? My cat leaves them on my front doormat looking completely undamaged. I think she just plays with them til they die of fright. I thought about saving them last winter and making an all mouse nativity scene, or maybe mouse Santa and reindeer.

"DJ" <www.aarrrrggghhh!!!.com> wrote in message news:45f21179\$1@linux...
> Ok.....hmmmm.....letsee.....
>
> PCM 91 = outboard reverb processor
>
> RME ADI4-DD=ADAT to AES format converter which allows 4 x devices with AES
> inputs and outputs to interface with the optical ports on an audio card
>
> harness=the cabling that attaches the AES devices to the RME ADI4-DD
>
> GENX-6=module that takes a word clock signal from another device, spiits
> it 6 ways and then feeds it to six different devices
>
> Zaolla 75ohm WC cable=a pretty darned expensive piece of silver wire
> covered with rubber and having BNC connectors on either end to connect to
> other devices with similar connectors.
>
> bad studiocat=little grey horror who likes to leave the carcasses of dead
> rodents in my chair as a present upon occasion.
>
> hmmmm.....not sure if this is clear even now after looking at it.
>
> ;o)
>
>
>
> "Sarah" <sarahjane@sarahtonin.com> wrote in message news:45f1ec0b@linux...
>> Is it bad that I have no idea what you're talking about? :)
>>
>> Sarah
>>
>>
>> "DJ" <www.aarrrrggghhh!!!.com> wrote in message news:45f06fde\$1@linux...
>>> Well, my Lexicon PCM 91 quit passing signal reliably last night. After
>>> troubleshooting it, my RME ADI-DD, my harness from the ADI4-DD to the

>>> outboard processors and putting in calls to Morgan, CBI and Synthax, I
>>> found the problem. The WC cable that was feeding the ADI8-DD from the
>>> GenX-6 that is distributing WC from my Mytek clock was full of
>>> punctures. Either there's bad studiocat behaviour going on or a bad
>>> mouse or other vermin that the bad studiocat should be attending to.
>>> This is, by far, one of the wierdest studio occurrences I've had yet.
>>> This was a very expensive Zaolla 75 ohm WC cable and I would have
>>> definitely noticed if it would have been punctured prior to my
>>> installing it.
>>>
>>> ;oP
>>>
>>>
>>>
>>
>>
>
>

Subject: Re: It's stranger than fiction around here sometimes

Posted by [rick](#) on Sat, 10 Mar 2007 11:50:13 GMT

[View Forum Message](#) <> [Reply to Message](#)

ours just ate the heads...kinda weird. then a cayote came and invited
her to lunch. she must have liked what they were serving as she never
came back.

On Fri, 9 Mar 2007 23:39:21 -0800, "Sarah" <sarahjane@sarahtonin.com>
wrote:

>Uh yeah, thanks for clearing that up. :)
>
>Sarah
>
>PS: Does your bad studiocat leave the rodents in good condition, aside from
>being dead? My cat leaves them on my front doormat looking completely
>undamaged. I think she just plays with them til they die of fright. I
>thought about saving them last winter and making an all mouse nativity
>scene, or maybe mouse Santa and reindeer.
>
>"DJ" <www.aarrrrggghhh!!!.com> wrote in message news:45f21179\$1@linux...
>> Ok.....hmmmm.....letsee.....
>>
>> PCM 91 = outboard reverb processor
>>
>> RME ADI4-DD=ADAT to AES format converter which allows 4 x devices with AES

>> inputs and outputs to interface with the optical ports on an audio card
>>
>> harness=the cabling that attaches the AES devices to the RME ADI4-DD
>>
>> GENX-6=module that takes a word clock signal from another device, spiits
>> it 6 ways and then feeds it to six different devices
>>
>> Zaolla 75ohm WC cable=a pretty darned expensive piece of silver wire
>> covered with rubber and having BNC connectors on either end to connect to
>> other devices with similar connectors.
>>
>> bad studiocat=little grey horror who likes to leave the carcasses of dead
>> rodents in my chair as a present upon occasion.
>>
>> hmmm.....not sure if this is clear even now after looking at it.
>>
>> ;o)
>>
>>
>>
>> "Sarah" <sarahjane@sarahtonin.com> wrote in message news:45f1ec0b@linux...
>>> Is it bad that I have no idea what you're talking about? :)
>>>
>>> Sarah
>>>
>>>
>>> "DJ" <www.aarrrrggghhh!!!.com> wrote in message news:45f06fde\$1@linux...
>>>> Well, my Lexicon PCM 91 quit passing signal reliably last night. After
>>>> troubleshooting it, my RME ADI-DD, my harness from the ADI4-DD to the
>>>> outboard processors and putting in calls to Morgan, CBI and Synthax, I
>>>> found the problem. The WC cable that was feeding the ADI8-DD from the
>>>> GenX-6 that is distributing WC from my Mytek clock was full of
>>>> punctures. Either there's bad studiocat behaviour going on or a bad
>>>> mouse or other vermin that the bad studiocat should be attending to.
>>>> This is, by far, one of the wierdest studio occurrences I've had yet.
>>>> This was a very expensive Zaolla 75 ohm WC cable and I would have
>>>> definitely noticed if it would have been punctured prior to my
>>>> installing it.
>>>>
>>>> ;oP
>>>>
>>>>
>>>>
>>>
>>>
>>
>>
>

Subject: Re: It's stranger than fiction around here sometimes
Posted by [Bill Lorentzen](#) on Sat, 10 Mar 2007 12:33:22 GMT
[View Forum Message](#) <> [Reply to Message](#)

My old cat would go right under the console and start biting my cables when she was pissed at me.

"DJ" <www.aarrrrggghhh!!!.com> wrote in message news:45f06fde\$1@linux...
> Well, my Lexicon PCM 91 quit passing signal reliably last night. After
> troubleshooting it, my RME ADI-DD, my harness from the ADI4-DD to the
> outboard processors and putting in calls to Morgan, CBI and Synthax, I
> found the problem. The WC cable that was feeding the ADI8-DD from the
> GenX-6 that is distributing WC from my Mytek clock was full of punctures.
> Either there's bad studiocat behaviour going on or a bad mouse or other
> vermin that the bad studiocat should be attending to. This is, by far, one
> of the wierdest studio occurrences I've had yet. This was a very expensive
> Zaolla 75 ohm WC cable and I would have definitely noticed if it would
> have been punctured prior to my installing it.
>
> ;oP
>
>
>

Subject: Re: It's stranger than fiction around here sometimes
Posted by [Tom Bruhl](#) on Sat, 10 Mar 2007 19:12:25 GMT
[View Forum Message](#) <> [Reply to Message](#)

This is a multi-part message in MIME format.

-----=_NextPart_000_00BC_01C7631E.20C1F7E0
Content-Type: text/plain;
charset="iso-8859-1"
Content-Transfer-Encoding: quoted-printable

Hence the term "old" cat.

"Bill Lorentzen" <bill@lorentzen.ws> wrote in message =
news:45f2a57c@linux...

My old cat would go right under the console and start biting my cables =
when=20
she was pissed at me.

"DJ" <www.aarrrrggghhh!!!.com> wrote in message =

news:45f06fde\$1@linux...

> Well, my Lexicon PCM 91 quit passing signal reliably last night. =
After=20
> troubleshooting it, my RME ADI-DD, my harness from the ADI4-DD to =
the=20
> outboard processors and putting in calls to Morgan, CBI and Synthax, =
I=20
> found the problem. The WC cable that was feeding the ADI8-DD from =
the=20
> GenX-6 that is distributing WC from my Mytek clock was full of =
punctures.=20
> Either there's bad studiocat behaviour going on or a bad mouse or =
other=20
> vermin that the bad studiocat should be attending to. This is, by =
far, one=20
> of the wierdest studio occurrences I've had yet. This was a very =
expensive=20
> Zaolla 75 ohm WC cable and I would have definitely noticed if it =
would=20
> have been punctured prior to my installing it.
>
> ;oP
>
>
>=20

I choose Polesoft Lockspam to fight spam, and you?

<http://www.polesoft.com/refer.html>

-----=_NextPart_000_00BC_01C7631E.20C1F7E0

Content-Type: text/html;

charset="iso-8859-1"

Content-Transfer-Encoding: quoted-printable

```
<!DOCTYPE HTML PUBLIC "-//W3C//DTD HTML 4.0 Transitional//EN">
<HTML><HEAD>
<META http-equiv=3DContent-Type content=3D"text/html; =
charset=3Diso-8859-1">
<META content=3D"MSHTML 6.00.2800.1400" name=3DGENERATOR>
<STYLE></STYLE>
</HEAD>
<BODY bgColor=3D#ffffff>
<DIV><FONT face=3DArial size=3D2>Hence the term "old" cat.</FONT></DIV>
<DIV><FONT face=3DArial size=3D2></FONT>&nbsp;</DIV>
<DIV>&nbsp;</DIV>
<BLOCKQUOTE=20
```


Posted by [Deej \[4\]](#) on Sat, 10 Mar 2007 20:19:02 GMT

[View Forum Message](#) <> [Reply to Message](#)

bad studio cat is messy.....bits and pieces everywhere.....plus hairballs and other regurgitated stuff. She's of the opinion that whatever is offered should be equally appreciated.....because she's a cat.

;o)

"Sarah" <sarahjane@sarahtonin.com> wrote in message news:45f260c2@linux...

> Uh yeah, thanks for clearing that up. :)

>

> Sarah

>

> PS: Does your bad studiocat leave the rodents in good condition, aside

> from being dead? My cat leaves them on my front doormat looking

> completely undamaged. I think she just plays with them til they die of

> fright. I thought about saving them last winter and making an all mouse

> nativity scene, or maybe mouse Santa and reindeer.

>

> "DJ" <www.aarrrrggghhh!!!.com> wrote in message news:45f21179\$1@linux...

>> Ok.....hmmmm.....letsee.....

>>

>> PCM 91 = outboard reverb processor

>>

>> RME ADI4-DD=ADAT to AES format converter which allows 4 x devices with

>> AES inputs and outputs to interface with the optical ports on an audio

>> card

>>

>> harness=the cabling that attaches the AES devices to the RME ADI4-DD

>>

>> GENX-6=module that takes a word clock signal from another device, spiits

>> it 6 ways and then feeds it to six different devices

>>

>> Zaolla 75ohm WC cable=a pretty darned expensive piece of silver wire

>> covered with rubber and having BNC connectors on either end to connect to

>> other devices with similar connectors.

>>

>> bad studiocat=little grey horror who likes to leave the carcasses of dead

>> rodents in my chair as a present upon occasion.

>>

>> hmmm.....not sure if this is clear even now after looking at it.

>>

>> ;o)

>>

>>

>>

>> "Sarah" <sarahjane@sarahtonin.com> wrote in message

>> news:45f1ec0b@linux...

>>> Is it bad that I have no idea what you're talking about? :)
>>>
>>> Sarah
>>>
>>>
>>> "DJ" <www.aarrrrggghhh!!!.com> wrote in message news:45f06fde\$1@linux...
>>>> Well, my Lexicon PCM 91 quit passing signal reliably last night. After
>>>> troubleshooting it, my RME ADI-DD, my harness from the ADI4-DD to the
>>>> outboard processors and putting in calls to Morgan, CBI and Synthax, I
>>>> found the problem. The WC cable that was feeding the ADI8-DD from the
>>>> GenX-6 that is distributing WC from my Mytek clock was full of
>>>> punctures. Either there's bad studiocat behaviour going on or a bad
>>>> mouse or other vermin that the bad studiocat should be attending to.
>>>> This is, by far, one of the wierdest studio occurrences I've had yet.
>>>> This was a very expensive Zaolla 75 ohm WC cable and I would have
>>>> definitely noticed if it would have been punctured prior to my
>>>> installing it.
>>>>
>>>> ;oP
>>>>
>>>>
>>>>
>>>>
>>>
>>>
>>
>>
>
>
