Subject: Re: ASIO DRIVER current status ? Posted by mikeaudet on Tue, 20 Feb 2018 15:54:39 GMT View Forum Message <> Reply to Message

So...I've been working on a few things...one of which is laying the groundwork for a new scherzo to support a 64 bit ASIO, but I took a bit of a detour and decided to see if I could clean up a couple of things in the 32 bit ASIO...and....

I got 32 sample buffer sizes working!!!

File Attachments

Audio/MIDI Setup					×
	Latency Measu	rement Tool			
	Turn down the volun audio equipment to				
Sel	ect two channels below and (connect them using a cable.			
Output channel	system:playback_4				
Input channel	system:capture_4				
Once	the channels are connected	l, click the "Measure" button			
When	satisfied with the results, c	lick the "Use results" button			
	ted roundtrip latency: nic latency: -96 sampl		ns)		
Measure	Use results	Back to settings (i	gnore results)	