

---

Subject: trouble with 442 on 2nd EDS card...

Posted by [uptown jimmy](#) on Sat, 14 Aug 2010 18:12:31 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Howdy.

Got the 442 installed per Kerry's instructions, everything syncs properly. Got a Kurzweil Rumour synced via SPDIF to the MEC on card 1, got a Kurzweil Mangler via SPDIF to the 442 on card 2. Everything works flawlessly, except:

I'm not getting any digital signal to/from the Mangler on the 442. I think I have the settings correct, the physical and virtual patching correct. Got the Mangler set to the same settings as the Rumour except that the Mangler is set to 20 bit because it's attached to the 442, which is 20 bit.

Any ideas? Am I missing some weird Paris quirk?

Jimmy

---