
Subject: Mike I tried your Studiocontrol DLL - found some probs
Posted by [Dimitrios](#) on Tue, 16 Sep 2008 16:28:19 GMT

[View Forum Message](#) <> [Reply to Message](#)

Hi,
I tried it.
The spdif out on main mec does not work !
When I put the dll everything works fine.
Something meeses up with spdif out.
Hope this helps.
Regards,
Dimitrios

Subject: Re: Mike I tried your Studiocontrol DLL - found some probs
Posted by [kerryg](#) on Tue, 16 Sep 2008 18:04:17 GMT

[View Forum Message](#) <> [Reply to Message](#)

I'll give my own SP/DIF a try to see if I can duplicate it.

- k

On 2008-09-16 09:28:19 -0700, "Dimitrios" <musurgio@otenet.gr> said:

>
> Hi,
> I tried it.
> The spdif out on main mec does not work !
> When I put the dll everything works fine.
> Something meeses up with spdif out.
> Hope this helps.
> Regards,
> Dimitrios

Subject: Re: Mike I tried your Studiocontrol DLL - found some probs
Posted by [kerryg](#) on Tue, 16 Sep 2008 18:23:57 GMT

[View Forum Message](#) <> [Reply to Message](#)

SP/DIF output works perfectly over here into the RME on my Mac. Single processor Athlon running double Bundle III, two 8i cards (I pulled the ADAT card a few days ago while we did troubleshooting and haven't got around to putting it back in yet).

- Kerry

On 2008-09-16 11:04:17 -0700, KerryGalloway <kg@kerrygalloway.com> said:

> I'll give my own SP/DIF a try to see if I can duplicate it.
>
> - k
>
> On 2008-09-16 09:28:19 -0700, "Dimitrios" <musurgio@otenet.gr> said:
>
>>
>> Hi,
>> I tried it.
>> The spdif out on main mec does not work !
>> When I put the dll everything works fine.
>> Something meeses up with spdif out.
>> Hope this helps.
>> Regards,
>> Dimitrios

Subject: Re: Mike I tried your Studiocontrol DLL - found some probs
Posted by [Mike Audet](#) on Wed, 17 Sep 2008 00:42:53 GMT
[View Forum Message](#) <> [Reply to Message](#)

Hi Dimitrios.

Thanks so much for testing it. I'm having some similar problems here. I'm trying to debug exactly what function is sending the UART data too fast. I'll let you know as soon as I have something new.

Thanks again!

Mike

"Dimitrios" <musurgio@otenet.gr> wrote:
>
>Hi,
>I tried it.
>The spdif out on main mec does not work !
>When I put the dll everything works fine.
>Something meeses up with spdif out.
>Hope this helps.
>Regards,
>Dimitrios

Subject: Re: Mike I tried your Studiocontrol DLL - found some probs
Posted by [Mike Audet](#) on Wed, 17 Sep 2008 01:26:18 GMT
[View Forum Message](#) <> [Reply to Message](#)

Ok..I sorted that one out. The issue with the digital out I was having was between the keyboard and the chair. I was trying to patch in the wrong submix. I'm ok with the SPDIF.

I'll have a new build to try soon.

Thanks again for trying the build!

Mike

"Mike Audet" <mike@...> wrote:

>

>Hi Dimitrios.

>

>Thanks so much for testing it. I'm having some similar problems here.

I'm

>trying to debug exactly what function is sending the UART data too fast.

> I'll let you know as soon as I have something new.

>

>Thanks again!

>

>Mike

>

>"Dimitrios" <musurgio@otenet.gr> wrote:

>>

>>Hi,

>>I tried it.

>>The spdif out on main mec does not work !

>>When I put the dll everything works fine.

>>Something meeses up with spdif out.

>>Hope this helps.

>>Regards,

>>Dimitrios

>
