Subject: Re: ASIO DRIVER current status ? Posted by mikeaudet on Tue, 20 Feb 2018 15:54:39 GMT View Forum Message <> Reply to Message

So...I've been working on a few things...one of which is laying the groundwork for a new scherzo to support a 64 bit ASIO, but I took a bit of a detour and decided to see if I could clean up a couple of things in the 32 bit ASIO...and....

I got 32 sample buffer sizes working!!!

File Attachments

| Audio/MIDI Setup – Latency Measurement Tool Turn down the volume on your audio equipment to a very low level. Select two channels below and connect them using a cable. Output channel system:playback_4 | × |
|---|---|
| Turn down the volume on your audio equipment to a very low level. Select two channels below and connect them using a cable. | |
| Turn down the volume on your audio equipment to a very low level. Select two channels below and connect them using a cable. | |
| Turn down the volume on your audio equipment to a very low level. Select two channels below and connect them using a cable. | |
| | |
| Output channel system playback 4 | |
| | |
| Input channel system:capture_4 | |
| Once the channels are connected, click the "Measure" button. | |
| When satisfied with the results, click the "Use results" button. | |
| Detected roundtrip latency: 183 samples (4.150 ms) Systemic latency: -96 samples (-2.177 ms) | |
| Measure Use results Back to settings (ignore results) | |
| | |