Subject: Re: ASIO DRIVER current status ? Posted by mikeaudet on Tue, 20 Feb 2018 15:54:39 GMT View Forum Message <> Reply to Message

So...I've been working on a few things...one of which is laying the groundwork for a new scherzo to support a 64 bit ASIO, but I took a bit of a detour and decided to see if I could clean up a couple of things in the 32 bit ASIO...and....

I got 32 sample buffer sizes working!!!

File Attachments

Audio/MIDI Setup				
			- 🗉	×
	Latency Measu	rement Tool		
	Turn down the volun audio equipment to			
Sel	ect two channels below and (connect them using a cable.		
Output channel	system:playback_4			
Input channel	system:capture_4			
Once	e the channels are connected	l, click the "Measure" button.		
When	n satisfied with the results, c	lick the "Use results" button.		
	ted roundtrip latency: mic latency: -96 sampl	183 samples (4.150 ms) es (-2.177 ms)		
Measure	Use results	Back to settings (ignore r	esults)	