Subject: Re: ASIO DRIVER current status ? Posted by mikeaudet on Tue, 20 Feb 2018 15:54:39 GMT View Forum Message <> Reply to Message

So...I've been working on a few things...one of which is laying the groundwork for a new scherzo to support a 64 bit ASIO, but I took a bit of a detour and decided to see if I could clean up a couple of things in the 32 bit ASIO...and....

I got 32 sample buffer sizes working!!!

File Attachments

<u>File Attachmen</u>					
1) 32-samples!.j	pg, downloaded	2976 times			
🧐 Audio/MIDI Setup				o ×	
Latency Measurement Tool					
	Turn down the volu audio equipment to				
Sel	ect two channels below and	connect them using a cable.			
Output channel	system:playback_4				
Input channel	system:capture_4				
Once the channels are connected, click the "Measure" button.					
When satisfied with the results, click the "Use results" button.					
Detected roundtrip latency: 183 samples (4.150 ms) Systemic latency: -96 samples (-2.177 ms)					
Measure	Use results	Back to settings (ignor	e results)		