

---

Subject: PSCL for today

Posted by [Mike Audet](#) on Wed, 13 Aug 2008 03:01:53 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hi guys,

I put some locks on the card UART, so the IF2s should now work properly, if they ever didn't.

I also changed a static buffer to a regular buffer because it was shared among many purposes, and it looked like they could trip on each other.

---