Subject: It's stranger than fiction around here sometimes Posted by Deej [4] on Thu, 08 Mar 2007 20:19:13 GMT View Forum Message <> Reply to Message

Well, my Lexicon PCM 91 quit passing signal reliably last night. After troubleshooting it, my RME ADI-DD, my harness from the ADI4-DD to the outboard processors and putting in calls to Morgan, CBI and Synthax, I found the problem. The WC cable that was feeding the ADI8-DD from the GenX-6 that is distributing WC from my Mytek clock was full of punctures. Either there's bad studiocat behaviour going on or a bad mouse or other vermin that the bad studiocat should be attending to. This is, by far, one of the wierdest studio occurrences I've had yet. This was a very expensive Zaolla 75 ohm WC cable and I would have definitely noticed if it would have been punctured prior to my installing it.

;oP

Subject: Re: It's stranger than fiction around here sometimes Posted by John [1] on Fri, 09 Mar 2007 00:28:23 GMT View Forum Message <> Reply to Message

This means your setup is still to complicated. Sell half and see how it works. Rinse and repeat. hehe

Subject: Re: It's stranger than fiction around here sometimes Posted by rick on Fri, 09 Mar 2007 09:55:42 GMT View Forum Message <> Reply to Message

try having ghosts...and i'm not the only one who sees the shadows moving about.

On Thu, 8 Mar 2007 13:19:13 -0700, "DJ" <www.aarrrrggghhh!!!.com> wrote:

>Well, my Lexicon PCM 91 quit passing signal reliably last night. After
>troubleshooting it, my RME ADI-DD, my harness from the ADI4-DD to the
>outboard processors and putting in calls to Morgan, CBI and Synthax, I found
>the problem. The WC cable that was feeding the ADI8-DD from the GenX-6 that
>is distributing WC from my Mytek clock was full of punctures. Either there's
>bad studiocat behaviour going on or a bad mouse or other vermin that the bad
>studio occurrences I've had yet. This was a very expensive Zaolla 75 ohm WC
>cable and I would have definitely noticed if it would have been punctured
>prior to my installing it.

>

Subject: Re: It's stranger than fiction around here sometimes Posted by John [1] on Fri, 09 Mar 2007 13:07:57 GMT View Forum Message <> Reply to Message

Just play the Zeppelin Immigrant's Song from Zep3 at 105 db. Ghost hate that and leave permanently.

Ah, ah,

We come from the land of the ice and snow, from the midnight sun where the hot springs blow. The hammer of the gods Will drive our ships to new lands, To fight the horde, singing and crying: Valhalla, I am coming! On we sweep with threshing oar, Our only goal will be the western shore. Ah. ah. We come from the land of the ice and snow, from the midnight sun where the hot springs blow. How soft your fields so green, Can whisper tales of gore, Of how we calmed the tides of war. We are your overlords. On we sweep with threshing oar, Our only goal will be the western shore. So now youd better stop and rebuild all your ruins, For peace and trust can win the day Despite of all your losing.

Subject: Re: It's stranger than fiction around here sometimes Posted by rick on Fri, 09 Mar 2007 17:45:01 GMT View Forum Message <> Reply to Message

if they can deal with some of the bands that come though here then that ain't nuthin'

On 9 Mar 2007 23:07:57 +1000, "John" <no@no.com> wrote:

>

>Just play the Zeppelin Immigrant's Song from Zep3 at 105 db. Ghost hate that >and leave permanently.

>

>Ah, ah,

>We come from the land of the ice and snow,

>from the midnight sun where the hot springs blow.

>The hammer of the gods

>Will drive our ships to new lands,

>To fight the horde, singing and crying:

>Valhalla, I am coming!

>On we sweep with threshing oar,

>Our only goal will be the western shore.

>Ah, ah,

>We come from the land of the ice and snow,

>from the midnight sun where the hot springs blow.

>How soft your fields so green,

>Can whisper tales of gore,

>Of how we calmed the tides of war.

>We are your overlords.

>On we sweep with threshing oar,

>Our only goal will be the western shore.

>So now youd better stop and rebuild all your ruins,

>For peace and trust can win the day

>Despite of all your losing.

>

Subject: Re: It's stranger than fiction around here sometimes Posted by excelav on Fri, 09 Mar 2007 18:10:47 GMT View Forum Message <> Reply to Message

Yeah, they hate Britney Spears Too!

"John" <no@no.com> wrote:

>

>Just play the Zeppelin Immigrant's Song from Zep3 at 105 db. Ghost hate that

>and leave permanently.

>

>Ah, ah,

>We come from the land of the ice and snow,

>from the midnight sun where the hot springs blow.

>The hammer of the gods

>Will drive our ships to new lands,

>To fight the horde, singing and crying:

>Valhalla, I am coming!

>On we sweep with threshing oar,

>Our only goal will be the western shore.

>Ah, ah,

>We come from the land of the ice and snow,

>from the midnight sun where the hot springs blow. >How soft your fields so green, >Can whisper tales of gore, >Of how we calmed the tides of war. >We are your overlords. >On we sweep with threshing oar, >Our only goal will be the western shore. >So now youd better stop and rebuild all your ruins, >For peace and trust can win the day >Despite of all your losing. >

>

Subject: Re: It's stranger than fiction around here sometimes Posted by Sarah on Fri, 09 Mar 2007 23:21:19 GMT View Forum Message <> Reply to Message

Is it bad that I have no idea what you're talking about? :)

Sarah

"DJ" <www.aarrrrggghhh!!!.com> wrote in message news:45f06fde\$1@linux... > Well, my Lexicon PCM 91 guit passing signal reliably last night. After > troubleshooting it, my RME ADI-DD, my harness from the ADI4-DD to the > outboard processors and putting in calls to Morgan, CBI and Synthax, I > found the problem. The WC cable that was feeding the ADI8-DD from the > GenX-6 that is distributing WC from my Mytek clock was full of punctures. > Either there's bad studiocat behaviour going on or a bad mouse or other > vermin that the bad studiocat should be attending to. This is, by far, one > of the wierdest studio occurrences I've had yet. This was a very expensive > Zaolla 75 ohm WC cable and I would have definitely noticed if it would > have been punctured prior to my installing it. > > ;oP

- >
- >
- >

Subject: Re: It's stranger than fiction around here sometimes Posted by Deej [4] on Sat, 10 Mar 2007 02:01:04 GMT View Forum Message <> Reply to Message

Ok.....hmmmm.....letsee.....

PCM 91 = outboard reverb processor

RME ADI4-DD=ADAT to AES format converter which allows 4 x devices with AES inputs and outputs to interface with the optical ports on an audio card

harness=the cabling that attaches the AES devices to the RME ADI4-DD

GENX-6=module that takes a word clock signal from another device, spiits it 6 ways and then feeds it to six different devices

Zaolla 75ohm WC cable=a pretty darned expensive piece of silver wire covered with rubber and having BNC connectors on either end to connect to other devices with similar connectors.

bad studiocat=little grey horror who likes to leave the carcasses of dead rodents in my chair as a present upon occasion.

hmmm.....not sure if this is clear even now after looking at it.

;0)

"Sarah" <sarahjane@sarahtonin.com> wrote in message news:45f1ec0b@linux... > Is it bad that I have no idea what you're talking about? :)

>

> Sarah

>

>

"DJ" <www.aarrrrggghhh!!!.com> wrote in message news:45f06fde\$1@linux...
Well, my Lexicon PCM 91 quit passing signal reliably last night. After
troubleshooting it, my RME ADI-DD, my harness from the ADI4-DD to the
outboard processors and putting in calls to Morgan, CBI and Synthax, I
found the problem. The WC cable that was feeding the ADI8-DD from the
GenX-6 that is distributing WC from my Mytek clock was full of punctures.
Either there's bad studiocat behaviour going on or a bad mouse or other
vermin that the bad studiocat should be attending to. This is, by far,
one of the wierdest studio occurrences I've had yet. This was a very
expensive Zaolla 75 ohm WC cable and I would have definitely noticed if
it would have been punctured prior to my installing it.

>>

>> ;oP

>>

>>

>> >

>

Subject: Re: It's stranger than fiction around here sometimes Posted by Sarah on Sat, 10 Mar 2007 07:39:21 GMT View Forum Message <> Reply to Message

Uh yeah, thanks for clearing that up. :)

Sarah

PS: Does your bad studiocat leave the rodents in good condition, aside from being dead? My cat leaves them on my front doormat looking completely undamaged. I think she just plays with them til they die of fright. I thought about saving them last winter and making an all mouse nativity scene, or maybe mouse Santa and reindeer.

"DJ" <www.aarrrrggghhh!!!.com> wrote in message news:45f21179\$1@linux... > Ok.....hmmmm.....letsee..... > > PCM 91 = outboard reverb processor > > RME ADI4-DD=ADAT to AES format converter which allows 4 x devices with AES > inputs and outputs to interface with the optical ports on an audio card > > harness=the cabling that attaches the AES devices to the RME ADI4-DD > > GENX-6=module that takes a word clock signal from another device, spiits > it 6 ways and then feeds it to six different devices > > Zaolla 75ohm WC cable=a pretty darned expensive piece of silver wire > covered with rubber and having BNC connectors on either end to connect to > other devices with similar connectors. > > bad studiocat=little grey horror who likes to leave the carcasses of dead > rodents in my chair as a present upon occasion. > > hmmm.....not sure if this is clear even now after looking at it. > > ;0) > > > > "Sarah" <sarahjane@sarahtonin.com> wrote in message news:45f1ec0b@linux... >> Is it bad that I have no idea what you're talking about? :) >> >> Sarah >> >> >> "DJ" <www.aarrrrggghhh!!!.com> wrote in message news:45f06fde\$1@linux... >>> Well, my Lexicon PCM 91 quit passing signal reliably last night. After >>> troubleshooting it, my RME ADI-DD, my harness from the ADI4-DD to the

>>> outboard processors and putting in calls to Morgan, CBI and Synthax, I >>> found the problem. The WC cable that was feeding the ADI8-DD from the >>> GenX-6 that is distributing WC from my Mytek clock was full of >>> punctures. Either there's bad studiocat behaviour going on or a bad >>> mouse or other vermin that the bad studiocat should be attending to. >>> This is, by far, one of the wierdest studio occurrences I've had yet. >>> This was a very expensive Zaolla 75 ohm WC cable and I would have >>> definitely noticed if it would have been punctured prior to my >>> installing it. >>> >>> ;oP >>> >>> >>> >> >> > >

Subject: Re: It's stranger than fiction around here sometimes Posted by rick on Sat, 10 Mar 2007 11:50:13 GMT View Forum Message <> Reply to Message

ours just ate the heads...kinda weird. then a cayote came and invited her to lunch. she must have liked what they were serving as she never came back.

```
On Fri, 9 Mar 2007 23:39:21 -0800, "Sarah" <sarahjane@sarahtonin.com> wrote:
```

>Uh yeah, thanks for clearing that up. :)

>

>Sarah

>

>PS: Does your bad studiocat leave the rodents in good condition, aside from >being dead? My cat leaves them on my front doormat looking completely >undamaged. I think she just plays with them til they die of fright. I >thought about saving them last winter and making an all mouse nativity >scene, or maybe mouse Santa and reindeer.

>

>"DJ" <www.aarrrrggghhh!!!.com> wrote in message news:45f21179\$1@linux...

>> Ok.....hmmmm.....letsee.....

>>

>> PCM 91 = outboard reverb processor

>>

>> RME ADI4-DD=ADAT to AES format converter which allows 4 x devices with AES

>> inputs and outputs to interface with the optical ports on an audio card >> >> harness=the cabling that attaches the AES devices to the RME ADI4-DD >> >> GENX-6=module that takes a word clock signal from another device, spiits >> it 6 ways and then feeds it to six different devices >> >> Zaolla 75ohm WC cable=a pretty darned expensive piece of silver wire >> covered with rubber and having BNC connectors on either end to connect to >> other devices with similar connectors. >> >> bad studiocat=little grey horror who likes to leave the carcasses of dead >> rodents in my chair as a present upon occasion. >> >> hmmm.....not sure if this is clear even now after looking at it. >> >> :0) >> >> >> >> "Sarah" <sarahjane@sarahtonin.com> wrote in message news:45f1ec0b@linux... >>> Is it bad that I have no idea what you're talking about? :) >>> >>> Sarah >>> >>> >>> "DJ" <www.aarrrrggghhh!!!.com> wrote in message news:45f06fde\$1@linux... >>>> Well, my Lexicon PCM 91 guit passing signal reliably last night. After >>>> troubleshooting it, my RME ADI-DD, my harness from the ADI4-DD to the >>>> outboard processors and putting in calls to Morgan, CBI and Synthax, I >>>> found the problem. The WC cable that was feeding the ADI8-DD from the >>>> GenX-6 that is distributing WC from my Mytek clock was full of >>>> punctures. Either there's bad studiocat behaviour going on or a bad >>>> mouse or other vermin that the bad studiocat should be attending to. >>>> This is, by far, one of the wierdest studio occurrences I've had yet. >>>> This was a very expensive Zaolla 75 ohm WC cable and I would have >>>> definitely noticed if it would have been punctured prior to my >>>> installing it. >>>> >>>> ;oP >>>> >>>> >>>> >>> >>> >> >> >

Subject: Re: It's stranger than fiction around here sometimes Posted by Bill Lorentzen on Sat, 10 Mar 2007 12:33:22 GMT View Forum Message <> Reply to Message

My old cat would go right under the console and start biting my cables when she was pissed at me.

"DJ" <www.aarrrrggghhh!!!.com> wrote in message news:45f06fde\$1@linux...
Well, my Lexicon PCM 91 quit passing signal reliably last night. After
troubleshooting it, my RME ADI-DD, my harness from the ADI4-DD to the
outboard processors and putting in calls to Morgan, CBI and Synthax, I
found the problem. The WC cable that was feeding the ADI8-DD from the
GenX-6 that is distributing WC from my Mytek clock was full of punctures.
Either there's bad studiocat behaviour going on or a bad mouse or other
vermin that the bad studiocat should be attending to. This is, by far, one
of the wierdest studio occurrences I've had yet. This was a very expensive
Zaolla 75 ohm WC cable and I would have definitely noticed if it would
have been punctured prior to my installing it.

- >
- >
- >

Subject: Re: It's stranger than fiction around here sometimes Posted by Tom Bruhl on Sat, 10 Mar 2007 19:12:25 GMT View Forum Message <> Reply to Message

This is a multi-part message in MIME format.

-----=_NextPart_000_00BC_01C7631E.20C1F7E0 Content-Type: text/plain; charset="iso-8859-1" Content-Transfer-Encoding: quoted-printable

Hence the term "old" cat.

"Bill Lorentzen" <bill@lorentzen.ws> wrote in message = news:45f2a57c@linux...

My old cat would go right under the console and start biting my cables = when=20

she was pissed at me.

"DJ" <www.aarrrrggghhh!!!.com> wrote in message =

news:45f06fde\$1@linux...

> Well, my Lexicon PCM 91 quit passing signal reliably last night. = After=20

> troubleshooting it, my RME ADI-DD, my harness from the ADI4-DD to = the=20

> found the problem. The WC cable that was feeding the ADI8-DD from = the=20

> GenX-6 that is distributing WC from my Mytek clock was full of = punctures.=20

> Either there's bad studiocat behaviour going on or a bad mouse or = other=20

> vermin that the bad studiocat should be attending to. This is, by = far, one=20

> of the wierdest studio occurrences I've had yet. This was a very = expensive=20

> Zaolla 75 ohm WC cable and I would have definitely noticed if it = would=20

> have been punctured prior to my installing it.

> > ;oP > >

```
>=20
```

I choose Polesoft Lockspam to fight spam, and you? http://www.polesoft.com/refer.html -----= NextPart 000 00BC 01C7631E.20C1F7E0 Content-Type: text/html; charset="iso-8859-1" Content-Transfer-Encoding: quoted-printable <!DOCTYPE HTML PUBLIC "-//W3C//DTD HTML 4.0 Transitional//EN"> <HTML><HEAD> <META http-equiv=3DContent-Type content=3D"text/html; = charset=3Diso-8859-1"> <META content=3D"MSHTML 6.00.2800.1400" name=3DGENERATOR> <STYLE></STYLE> </HEAD> <BODY bgColor=3D#ffffff> <DIV>Hence the term "old" cat.</DIV> <DIV> </DIV>

<DIV> </DIV>

<BLOCKQUOTE=20

style=3D"PADDING-RIGHT: 0px; PADDING-LEFT: 5px; MARGIN-LEFT: 5px; = BORDER-LEFT: #000000 2px solid; MARGIN-RIGHT: 0px"> <DIV>"Bill Lorentzen" &It;<A=20 href=3D"mailto:bill@lorentzen.ws">bill@lorentzen.ws> wrote in = message <A=20 href=3D"news:45f2a57c@linux">news:45f2a57c@linux...</DIV>My old = cat would go=20 right under the console and start biting my cables when
she was = pissed at=20 me.

"DJ" &It;<A=20 href=3D"http://www.aarrrrggghhh!!!.com">www.aarrrrggghhh!!!.com> = wrote in=20 message <A =href=3D"news:45f06fde\$1@linux">news:45f06fde\$1@linux...
>=20 Well, my Lexicon PCM 91 quit passing signal reliably last night. After =
> troubleshooting it, my RME ADI-DD, my harness from the = ADI4-DD to the=20
> outboard processors and putting in calls to Morgan, CBI and = Synthax,=20 I
> found the problem. The WC cable that was feeding the = ADI8-DD from=20 the
> GenX-6 that is distributing WC from my Mytek clock was = full of=20 punctures.
> Either there's bad studiocat behaviour going on or = a bad=20 mouse or other
> vermin that the bad studiocat should be = attending to.=20 This is, by far, one
> of the wierdest studio occurrences I've = had vet.=20 This was a very expensive
> Zaolla 75 ohm WC cable and I would = have=20 definitely noticed if it would
> have been punctured prior to = my=20 installing it.
>
> ;oP
>
>
>

</BLOCKQUOTE> <DIV>

I choose Polesoft Lockspam to fight spam, = and=20 vou?
<A=20 href=3D"http://www.polesoft.com/refer.html">http://www.polesoft.com/refer= ..html </DIV></BODY ></HTML> -----=_NextPart_000_00BC_01C7631E.20C1F7E0--

Subject: Re: It's stranger than fiction around here sometimes

Posted by Deej [4] on Sat, 10 Mar 2007 20:19:02 GMT View Forum Message <> Reply to Message

bad studio cat is messy......bits and pieces everywhere.....plus hairballs and other regurtgitated stuff. She's of the opinion that whatever is offered should be equally appreciated......because she's a cat.

;0)

"Sarah" <sarahjane@sarahtonin.com> wrote in message news:45f260c2@linux... > Uh yeah, thanks for clearing that up. :)

>

> Sarah

>

> PS: Does your bad studiocat leave the rodents in good condition, aside > from being dead? My cat leaves them on my front doormat looking > completely undamaged. I think she just plays with them til they die of > fright. I thought about saving them last winter and making an all mouse > nativity scene, or maybe mouse Santa and reindeer. > > "DJ" <www.aarrrrggghhh!!!.com> wrote in message news:45f21179\$1@linux... >> Ok.....hmmmm.....letsee..... >> >> PCM 91 = outboard reverb processor >> >> RME ADI4-DD=ADAT to AES format converter which allows 4 x devices with >> AES inputs and outputs to interface with the optical ports on an audio >> card >> >> harness=the cabling that attaches the AES devices to the RME ADI4-DD >> >> GENX-6=module that takes a word clock signal from another device, spiits >> it 6 ways and then feeds it to six different devices >> >> Zaolla 75ohm WC cable=a pretty darned expensive piece of silver wire >> covered with rubber and having BNC connectors on either end to connect to >> other devices with similar connectors. >> >> bad studiocat=little grey horror who likes to leave the carcasses of dead >> rodents in my chair as a present upon occasion. >> >> hmmm.....not sure if this is clear even now after looking at it. >> >> ;0) >> >> >> >> "Sarah" <sarahjane@sarahtonin.com> wrote in message >> news:45f1ec0b@linux...

>>> Is it bad that I have no idea what you're talking about? :) >>> >>> Sarah >>> >>> >>> "DJ" <www.aarrrrggghhh!!!.com> wrote in message news:45f06fde\$1@linux... >>>> Well, my Lexicon PCM 91 quit passing signal reliably last night. After >>>> troubleshooting it, my RME ADI-DD, my harness from the ADI4-DD to the >>>> outboard processors and putting in calls to Morgan, CBI and Synthax, I >>>> found the problem. The WC cable that was feeding the ADI8-DD from the >>>> GenX-6 that is distributing WC from my Mytek clock was full of >>>> punctures. Either there's bad studiocat behaviour going on or a bad >>>> mouse or other vermin that the bad studiocat should be attending to. >>>> This is, by far, one of the wierdest studio occurrences I've had yet. >>>> This was a very expensive Zaolla 75 ohm WC cable and I would have >>>> definitely noticed if it would have been punctured prior to my >>>> installing it. >>>> >>>> ;oP >>>> >>>> >>>> >>> >>> >> >> > >

Page 13 of 13 ---- Generated from The PARIS Forums