

---

Subject: error 1/1 - help!

Posted by [Edna Sloan](#) on Mon, 12 Feb 2007 04:38:11 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I attempted to move Paris to an older AMD based computer, to free up my P4 for VSTis. I went thru the installation as outlined for 3.0 under XP, although I didn't get the scherzo installed til last. Anyway, now I am getting the failure to load Paris engine, error 1/1, which as far as I can find out means that Paris is not finding the scherzo driver. There are no conflicts showing in device manager, and the scherzo is listed in System Devices as "working." Video card (G400 matrox) is on an irq by itself. Anyone have any hints as to what I can try?

---

---

Subject: Re: error 1/1 - help!

Posted by [Aaron Allen](#) on Mon, 12 Feb 2007 05:25:47 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

1/1 means the software doesn't recognize a usable hardware set. Check IRQ sharing, make sure that you see the EDS in the hardware list correctly, and make sure the connection from the MEC to the EDS is all good. Be very sure of these things, and be methodical and you'll find it.

AA

"RiverLake Farms" <edna@texomaonline.com> wrote in message news:45cfef8b@linux...

>I attempted to move Paris to an older AMD based computer, to free up my P4  
>for VSTis. I went thru the installation as outlined for 3.0 under XP,  
>although I didn't get the scherzo installed til last. Anyway, now I am  
>getting the failure to load Paris engine, error 1/1, which as far as I can  
>find out means that Paris is not finding the scherzo driver. There are no  
>conflicts showing in device manager, and the scherzo is listed in System  
>Devices as "working." Video card (G400 matrox) is on an irq by itself.  
>Anyone have any hints as to what I can try?  
>

---

---

Subject: Re: error 1/1 - help!

Posted by [Edna Sloan](#) on Mon, 12 Feb 2007 14:04:48 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Thanks Aaron. It has its own IRQ, not shared. The EDS was detected, as I got the "found new hardware, multimedia audio controller" thing. However, it didn't want to accept the scherzo as a driver - I had to manually force it to accept it, as per instructions for manual installation. It did then put it in system devices and says its working properly. I also have the

midi driver in DM under sound. I might try changing the pci slot, its now in slot one, and a different video card.

"Aaron Allen" <know-spam@not\_here.dude> wrote in message news:45cffaaa\$1@linux...

> 1/1 means the software doesn't recognize a usable hardware set. Check IRQ  
> sharing, make sure that you see the EDS in the hardware list correctly,  
> and make sure the connection from the MEC to the EDS is all good. Be very  
> sure of these things, and be methodical and you'll find it.

>

> AA

>

> "RiverLake Farms" <edna@texomaonline.com> wrote in message  
> news:45cfef8b@linux...

>>I attempted to move Paris to an older AMD based computer, to free up my P4  
>>for VSTis. I went thru the installation as outlined for 3.0 under XP,  
>>although I didn't get the scherzo installed til last. Anyway, now I am  
>>getting the failure to load Paris engine, error 1/1, which as far as I can  
>>find out means that Paris is not finding the scherzo driver. There are no  
>>conflicts showing in device manager, and the scherzo is listed in System  
>>Devices as "working." Video card (G400 matrox) is on an irq by itself.  
>>Anyone have any hints as to what I can try?

>>

>

>

---

Subject: Re: error 1/1 - help!

Posted by [Aaron Allen](#) on Mon, 12 Feb 2007 14:24:26 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Almost assured that slot one is sharing with your video card. Move to slot 2 or 3.

AA

"RiverLake Farms" <edna@texomaonline.com> wrote in message news:45d0745e@linux...

> Thanks Aaron. It has its own IRQ, not shared. The EDS was detected, as I  
> got the "found new hardware, multimedia audio controller" thing. However,  
> it didn't want to accept the scherzo as a driver - I had to manually force  
> it to accept it, as per instructions for manual installation. It did then  
> put it in system devices and says its working properly. I also have the  
> midi driver in DM under sound. I might try changing the pci slot, its now  
> in slot one, and a different video card.

> "Aaron Allen" <know-spam@not\_here.dude> wrote in message  
> news:45cffaaa\$1@linux...

>> 1/1 means the software doesn't recognize a usable hardware set. Check IRQ

>> sharing, make sure that you see the EDS in the hardware list correctly,  
>> and make sure the connection from the MEC to the EDS is all good. Be very  
>> sure of these things, and be methodical and you'll find it.  
>>  
>> AA  
>>  
>> "RiverLake Farms" <edna@texomaonline.com> wrote in message  
>> news:45cfef8b@linux...  
>>>I attempted to move Paris to an older AMD based computer, to free up my P4  
>>>for VSTis. I went thru the installation as outlined for 3.0 under XP,  
>>>although I didn't get the scherzo installed til last. Anyway, now I am  
>>>getting the failure to load Paris engine, error 1/1, which as far as I  
>>>can find out means that Paris is not finding the scherzo driver. There  
>>>are no conflicts showing in device manager, and the scherzo is listed in  
>>>System Devices as "working." Video card (G400 matrox) is on an irq by  
>>>itself. Anyone have any hints as to what I can try?  
>>>  
>>  
>>  
>  
>

---

Subject: Re: error 1/1 - help!  
Posted by [neil\[1\]](#) on Mon, 12 Feb 2007 15:32:22 GMT  
[View Forum Message](#) <> [Reply to Message](#)

Yup, 99.997% chance of this being the case... I was never able to get an EDS card working right in slot #1 on either mobo I had in my older Paris rig, and when I assembled my recent one I didn't even try it - set up like a dream with no problems.

Neil

"Aaron Allen" <know-spam@not\_here.dude> wrote:  
>Almost assured that slot one is sharing with your video card. Move to slot  
>2  
>or 3.  
>  
>AA  
>  
>  
>"RiverLake Farms" <edna@texomaonline.com> wrote in message  
>news:45d0745e@linux...  
>> Thanks Aaron. It has its own IRQ, not shared. The EDS was detected,  
>> as I  
>> got the "found new hardware, multimedia audio controller" thing. However,



Subject: Re: error 1/1 - help!

Posted by [Edna Sloan](#) on Mon, 12 Feb 2007 23:43:49 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Thanks guys. I'll switch the slot. I did have it in slot 1 in my previous P4 machine(with Nforce 2 video card) and it worked great.

"Neil" <IOUOIU@OIU.com> wrote in message news:45d07a76\$1@linux...

>

> Yup, 99.997% chance of this being the case... I was never able  
> to get an EDS card working right in slot #1 on either mobo I  
> had in my older Paris rig, and when I assembled my recent one I  
> didn't even try it - set up like a dream with no problems.

>

> Neil

>

>

> "Aaron Allen" <know-spam@not\_here.dude> wrote:

>>Almost assured that slot one is sharing with your video card. Move to slot

> 2

>>or 3.

>>

>>AA

>>

>>

>>"RiverLake Farms" <edna@texomaonline.com> wrote in message

>>news:45d0745e@linux...

>>> Thanks Aaron. It has its own IRQ, not shared. The EDS was detected,

> as I

>>> got the "found new hardware, multimedia audio controller" thing.

>>> However,

>

>>> it didn't want to accept the scherzo as a driver - I had to manually

>>> force

>

>>> it to accept it, as per instructions for manual installation. It did

> then

>>> put it in system devices and says its working properly. I also have the

>

>>> midi driver in DM under sound. I might try changing the pci slot, its

> now

>>> in slot one, and a different video card.

>>> "Aaron Allen" <know-spam@not\_here.dude> wrote in message

>>> news:45cffaaa\$1@linux...

>>>> 1/1 means the software doesn't recognize a usable hardware set. Check

> IRQ

>>>> sharing, make sure that you see the EDS in the hardware list correctly,

>

>>>> and make sure the connection from the MEC to the EDS is all good. Be

> very  
>>>> sure of these things, and be methodical and you'll find it.  
>>>>  
>>>> AA  
>>>>  
>>>> "RiverLake Farms" <edna@texomaonline.com> wrote in message  
>>>> news:45cfef8b@linux...  
>>>>>I attempted to move Paris to an older AMD based computer, to free up my  
> P4  
>>>>>for VSTis. I went thru the installation as outlined for 3.0 under XP,  
>  
>>>>>although I didn't get the scherzo installed til last. Anyway, now I  
> am  
>>>>>getting the failure to load Paris engine, error 1/1, which as far as  
> I  
>>>>>can find out means that Paris is not finding the scherzo driver. There  
>  
>>>>>are no conflicts showing in device manager, and the scherzo is listed  
> in  
>>>>>System Devices as "working." Video card (G400 matrox) is on an irq by  
>  
>>>>>itself. Anyone have any hints as to what I can try?  
>>>>>  
>>>>  
>>>>  
>>>>  
>>>  
>>>  
>>  
>>  
>>  
>  
>

---

Subject: Re: error 1/1 - help!

Posted by [michael](#) on Mon, 12 Feb 2007 23:50:38 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

hy guys,

i always have the same problem and i cant see the eds in the hardware list,  
ive used the driver of interlok and the other drivers they'll found here  
at the newsgroups!

can anybody help me with an actually set up for xp using???

my sytem is a pc intel 2,4 ghz 1056 ram and asrock p4i65g motherboard

i hope that anybody can help me

michael

"Aaron Allen" <know-spam@not\_here.dude> wrote:

>Almost assured that slot one is sharing with your video card. Move to slot

2

>or 3.

>  
>AA  
>  
>  
>"RiverLake Farms" <edna@texomaonline.com> wrote in message  
>news:45d0745e@linux...  
>> Thanks Aaron. It has its own IRQ, not shared. The EDS was detected,  
as I  
>> got the "found new hardware, multimedia audio controller" thing. However,  
  
>> it didn't want to accept the scherzo as a driver - I had to manually force  
  
>> it to accept it, as per instructions for manual installation. It did  
then  
>> put it in system devices and says its working properly. I also have the  
  
>> midi driver in DM under sound. I might try changing the pci slot, its  
now  
>> in slot one, and a different video card.  
>> "Aaron Allen" <know-spam@not\_here.dude> wrote in message  
>> news:45cffaaa\$1@linux...  
>>> 1/1 means the software doesn't recognize a usable hardware set. Check  
IRQ  
>>> sharing, make sure that you see the EDS in the hardware list correctly,  
  
>>> and make sure the connection from the MEC to the EDS is all good. Be  
very  
>>> sure of these things, and be methodical and you'll find it.  
>>>  
>>> AA  
>>>  
>>> "RiverLake Farms" <edna@texomaonline.com> wrote in message  
>>> news:45cfef8b@linux...  
>>>>I attempted to move Paris to an older AMD based computer, to free up my  
P4  
>>>>for VSTis. I went thru the installation as outlined for 3.0 under XP,  
  
>>>>although I didn't get the scherzo installed til last. Anyway, now I  
am  
>>>>getting the failure to load Paris engine, error 1/1, which as far as  
I  
>>>>can find out means that Paris is not finding the scherzo driver. There  
  
>>>>are no conflicts showing in device manager, and the scherzo is listed  
in  
>>>>System Devices as "working." Video card (G400 matrox) is on an irq by  
  
>>>>itself. Anyone have any hints as to what I can try?

>>>>  
>>>  
>>>  
>>  
>>  
>  
>

---

Subject: Re: error 1/1 - help!

Posted by [Edna Sloan](#) on Tue, 13 Feb 2007 01:36:26 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Well changing to slot 2 did cause a change: as its booting into the software, the mec will sync but then I get the error message 7/7. The c-16 never lights. I guess I might try another video card (non matrox) and see if that helps.

I did try another scsi cable, no effect. I hope I haven't damaged the eds card somehow.

"RiverLake Farms" <edna@texomaonline.com> wrote in message news:45d0fc0d@linux...

> Thanks guys. I'll switch the slot. I did have it in slot 1 in my  
> previous P4 machine(with Nforce 2 video card) and it worked great.

>

> "Neil" <IOUOIU@OIU.com> wrote in message news:45d07a76\$1@linux...

>>

>> Yup, 99.997% chance of this being the case... I was never able  
>> to get an EDS card working right in slot #1 on either mobo I  
>> had in my older Paris rig, and when I assembled my recent one I  
>> didn't even try it - set up like a dream with no problems.

>>

>> Neil

>>

>>

>> "Aaron Allen" <know-spam@not\_here.dude> wrote:

>>>Almost assured that slot one is sharing with your video card. Move to

>>>slot

>> 2

>>>or 3.

>>>

>>>AA

>>>

>>>

>>>"RiverLake Farms" <edna@texomaonline.com> wrote in message

>>>news:45d0745e@linux...

>>>> Thanks Aaron. It has its own IRQ, not shared. The EDS was detected,

>> as I



>>>> got the "found new hardware, multimedia audio controller" thing.  
>>>> However,  
>>  
>>>> it didn't want to accept the scherzo as a driver - I had to manually  
>>>> force  
>>  
>>>> it to accept it, as per instructions for manual installation. It did  
>> then  
>>>> put it in system devices and says its working properly. I also have  
>>>> the  
>>  
>>>> midi driver in DM under sound. I might try changing the pci slot, its  
>> now  
>>>> in slot one, and a different video card.  
>>>> "Aaron Allen" <know-spam@not\_here.dude> wrote in message  
>>>> news:45cffaaa\$1@linux...  
>>>>> 1/1 means the software doesn't recognize a usable hardware set. Check  
>> IRQ  
>>>>> sharing, make sure that you see the EDS in the hardware list  
>>>>> correctly,  
>>  
>>>>> and make sure the connection from the MEC to the EDS is all good. Be  
>> very  
>>>>> sure of these things, and be methodical and you'll find it.  
>>>>>  
>>>>> AA  
>>>>>  
>>>>> "RiverLake Farms" <edna@texomaonline.com> wrote in message  
>>>>> news:45cfef8b@linux...  
>>>>>> I attempted to move Paris to an older AMD based computer, to free up my  
>> P4  
>>>>>> for VSTis. I went thru the installation as outlined for 3.0 under XP,  
>>  
>>>>>> although I didn't get the scherzo installed til last. Anyway, now I  
>> am  
>>>>>> getting the failure to load Paris engine, error 1/1, which as far as  
>> I  
>>>>>> can find out means that Paris is not finding the scherzo driver.  
>>>>>> There  
>>  
>>>>>> are no conflicts showing in device manager, and the scherzo is listed  
>> in  
>>>>>> System Devices as "working." Video card (G400 matrox) is on an irq by  
>>  
>>>>>> itself. Anyone have any hints as to what I can try?  
>>>>>>  
>>>>>>  
>>>>>>

>>>>  
>>>>  
>>>  
>>>  
>>  
>  
>

---

Subject: Re: error 1/1 - help!

Posted by [Aaron Allen](#) on Tue, 13 Feb 2007 02:34:40 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Before you do that remove ALL instances of scherzo in the hardware list in safe mode. Make it reinstall completely. 7/7 still means it doesn't see a card.

AA

"RiverLake Farms" <edna@texomaonline.com> wrote in message news:45d11671@linux...

> Well changing to slot 2 did cause a change: as its booting into the  
> software, the mec will sync but then I get the error message 7/7. The  
> c-16 never lights. I guess I might try another video card (non matrox)  
> and see if that helps.  
> I did try another scsi cable, no effect. I hope I haven't damaged the eds  
> card somehow.

>  
> "RiverLake Farms" <edna@texomaonline.com> wrote in message  
> news:45d0fc0d@linux...

>> Thanks guys. I'll switch the slot. I did have it in slot 1 in my  
>> previous P4 machine(with Nforce 2 video card) and it worked great.

>>  
>> "Neil" <IOUOIU@OIU.com> wrote in message news:45d07a76\$1@linux...

>>>  
>>> Yup, 99.997% chance of this being the case... I was never able  
>>> to get an EDS card working right in slot #1 on either mobo I  
>>> had in my older Paris rig, and when I assembled my recent one I  
>>> didn't even try it - set up like a dream with no problems.

>>>  
>>> Neil

>>>  
>>>

>>> "Aaron Allen" <know-spam@not\_here.dude> wrote:

>>>> Almost assured that slot one is sharing with your video card. Move to  
>>>> slot  
>>>> 2

>>>>or 3.  
>>>>  
>>>>AA  
>>>>  
>>>>  
>>>>"RiverLake Farms" <edna@texomaonline.com> wrote in message  
>>>>news:45d0745e@linux...  
>>>>> Thanks Aaron. It has its own IRQ, not shared. The EDS was detected,  
>>>> as I  
>>>>> got the "found new hardware, multimedia audio controller" thing.  
>>>>> However,  
>>>>  
>>>>> it didn't want to accept the scherzo as a driver - I had to manually  
>>>>> force  
>>>>  
>>>>> it to accept it, as per instructions for manual installation. It did  
>>>> then  
>>>>> put it in system devices and says its working properly. I also have  
>>>>> the  
>>>>  
>>>>> midi driver in DM under sound. I might try changing the pci slot, its  
>>>> now  
>>>>> in slot one, and a different video card.  
>>>>> "Aaron Allen" <know-spam@not\_here.dude> wrote in message  
>>>>> news:45cffaaa\$1@linux...  
>>>>>> 1/1 means the software doesn't recognize a usable hardware set. Check  
>>>> IRQ  
>>>>>> sharing, make sure that you see the EDS in the hardware list  
>>>>>> correctly,  
>>>>  
>>>>>> and make sure the connection from the MEC to the EDS is all good. Be  
>>>> very  
>>>>>> sure of these things, and be methodical and you'll find it.  
>>>>>>  
>>>>>> AA  
>>>>>>  
>>>>>>> "RiverLake Farms" <edna@texomaonline.com> wrote in message  
>>>>>>> news:45cfef8b@linux...  
>>>>>>>>I attempted to move Paris to an older AMD based computer, to free up  
>>>>>>>>my  
>>>> P4  
>>>>>>>>for VSTis. I went thru the installation as outlined for 3.0 under  
>>>>>>>>XP,  
>>>>  
>>>>>>>>although I didn't get the scherzo installed til last. Anyway, now I  
>>>> am  
>>>>>>>>getting the failure to load Paris engine, error 1/1, which as far as  
>>>> I

