Subject: Re: ASIO DRIVER current status ? Posted by mikeaudet on Tue, 20 Feb 2018 15:54:39 GMT View Forum Message <> Reply to Message

So...I've been working on a few things...one of which is laying the groundwork for a new scherzo to support a 64 bit ASIO, but I took a bit of a detour and decided to see if I could clean up a couple of things in the 32 bit ASIO...and....

I got 32 sample buffer sizes working!!!

File Attachments

) 32-samples!.j	og, downloaded	7488 times	
Audio/MIDI Setup			□ ×
	Latency Measu	rement Tool	
	Turn down the volu audio equipment to		
Sele	ect two channels below and	connect them using a cable.	
Output channel	system:playback_4		
Input channel	system:capture_4		
Once	the channels are connected	d, click the "Measure" button.	
When	satisfied with the results, (click the "Use results" button.	
	ted roundtrip latency: nic latency: -96 samp	183 samples (4.150 ms) les (-2.177 ms)	
Measure	Use results	Back to settings (ignore resul	ts)
J			