
Subject: a small but positive Pulsar development
Posted by [DJ](#) on Sat, 11 Nov 2006 06:24:56 GMT

[View Forum Message](#) <> [Reply to Message](#)

I have just tested a 30" STDM cable and it works. There was some question as to whether this length would be a problem. This will allow me to use 2 x Pulsar's in my 7 slot Magma and on in a mobo PCI slot in a similar configuration as I was doing with the RME HDSP cards. My 3rd Pulsar card will be here next week. Unless there is an issue with a 24" cable run between the 1st and 2nd Pulsar cards and only a 6" cable run between the 2nd and third card, I should be good to go.

This is good news and if it works, it will save me a lot of hassles.

;o)

Subject: Re: a small but positive Pulsar development
Posted by [gene lennon](#) on Sat, 11 Nov 2006 16:42:26 GMT

[View Forum Message](#) <> [Reply to Message](#)

"DJ" <nowayjose@dude.net> wrote:

>I have just tested a 30" STDM cable and it works. There was some question as

>to whether this length would be a problem. This will allow me to use 2 x

>Pulsar's in my 7 slot Magma and on in a mobo PCI slot in a similar
>configuration as I was doing with the RME HDSP cards. My 3rd Pulsar card
>will be here next week. Unless there is an issue with a 24" cable run
>between the 1st and 2nd Pulsar cards and only a 6" cable run between the
2nd

>and third card, I should be good to go.

>
>This is good news and if it works, it will save me a lot of hassles.

>
>;o)
>

DJ,

Did you ever find a substitute source for Magma flat ribbon cables? I am missing one and I need to get that box working.

Gene

Subject: Re: a small but positive Pulsar development
Posted by [DJ](#) on Sat, 11 Nov 2006 17:04:43 GMT

[View Forum Message](#) <> [Reply to Message](#)

Gene,

I'm looking but can't seem to find it.

Deej

"Gene Lennon" <glennon@NOSPmyrealbox.com> wrote in message
news:4555ef62\$1@linux...

>
> "DJ" <nowayjose@dude.net> wrote:
> >I have just tested a 30" STDM cable and it works. There was some question
> as
> >to whether this length would be a problem. This will allow me to use 2
> x
> >Pulsar's in my 7 slot Magma and on in a mobo PCI slot in a similar
> >configuration as I was doing with the RME HDSP cards. My 3rd Pulsar card
> >will be here next week. Unless there is an issue with a 24" cable run
> >between the 1st and 2nd Pulsar cards and only a 6" cable run between the
> 2nd
> >and third card, I should be good to go.
> >
> >This is good news and if it works, it will save me a lot of hassles.
> >
> >;o)
> >
>
> DJ,
> Did you ever find a substitute source for Magma flat ribbon cables? I am
> missing one and I need to get that box working.
> Gene
>

Subject: Re: a small but positive Pulsar development

Posted by [DJ](#) on Sat, 11 Nov 2006 17:27:23 GMT

[View Forum Message](#) <> [Reply to Message](#)

Gene,

CS Electronics (949) 475-9100

Good luck

;o)

"Gene Lennon" <glennon@NOSPmyrealbox.com> wrote in message
news:4555ef62\$1@linux...

>
> "DJ" <nowayjose@dude.net> wrote:
> >I have just tested a 30" STDM cable and it works. There was some question
> as
> >to whether this length would be a problem. This will allow me to use 2
> x
> >Pulsar's in my 7 slot Magma and on in a mobo PCI slot in a similar
> >configuration as I was doing with the RME HDSP cards. My 3rd Pulsar card
> >will be here next week. Unless there is an issue with a 24" cable run
> >between the 1st and 2nd Pulsar cards and only a 6" cable run between the
> 2nd
> >and third card, I should be good to go.
> >
> >This is good news and if it works, it will save me a lot of hassles.
> >
> >;o)
> >
>
> DJ,
> Did you ever find a substitute source for Magma flat ribbon cables? I am
> missing one and I need to get that box working.
> Gene
>

Subject: Re: a small but positive Pulsar development
Posted by [gene lennon](#) on Sat, 11 Nov 2006 18:38:51 GMT
[View Forum Message](#) <> [Reply to Message](#)

"DJ" <nowayjose@dude.net> wrote:
>Gene,
>
>CS Electronics (949) 475-9100
>
>Good luck
>
>;o)
>
>
>"Gene Lennon" <glennon@NOSPmyrealbox.com> wrote in message
>news:4555ef62\$1@linux...
>>
>> "DJ" <nowayjose@dude.net> wrote:
>> >I have just tested a 30" STDM cable and it works. There was some question
>> as
>> >to whether this length would be a problem. This will allow me to use
>> 2
>> x

>> >Pulsar's in my 7 slot Magma and on in a mobo PCI slot in a similar
>> >configuration as I was doing with the RME HDSP cards. My 3rd Pulsar card
>> >will be here next week. Unless there is an issue with a 24" cable run
>> >between the 1st and 2nd Pulsar cards and only a 6" cable run between
the
>> 2nd
>> >and third card, I should be good to go.
>> >
>> >This is good news and if it works, it will save me a lot of hassles.
>> >
>> >);o)
>> >
>>
>> DJ,
>> Did you ever find a substitute source for Magma flat ribbon cables? I
am
>> missing one and I need to get that box working.
>> Gene
>>
>

Thanks
Gene
