

---

Subject: Power Mac G4 1.25 DUal Processor Dual Boot PCI problem

Posted by [Michael Lunser](#) on Sat, 01 Mar 2008 10:16:46 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hello Paris Users,

I recently installed to EDS 1000's in a MDD Dual boot Power Mac and I keep getting an error message that the EDS cards are not connected right. If I use one at a time, both cards work individually in any of the available PCI slots. When I install both cards I get the message. I have double checked my inter-connections but still get the message. Even if I install both cards and do not make the inter-connections, I still get the error message. Any help? Please?

Thanks

Michael

---