

---

Subject: Re: Can't Record in 442 and MEC simultaneously... HELP!!!

Posted by [Tom Bruhl](#) on Mon, 16 Feb 2009 21:12:48 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hi John,

Is the 442 showing up in the patchbay? Routing all correct?

Clock cables hooked up? Other audio plays on Card B?

Hmmm?

Tom

"John Cookman" <jcookman@sagu.edu> wrote in message news:4999d0af\$1@linux...

>

> Hey guys, can anyone help me with this issue? I have a MEC with one 8in  
> card

> and a 442 hooked up to two EDS-1000 cards. I am getting signals to all my  
> inputs on both units. My MEC inputs are assigned to Submix A and my 442  
> are assigned to submix B. I can record on the MEC all channels but I can  
> not get the 442 to receive a signal in the software. I see the signal  
> coming

> through on the 442 hardware but it will not come through on the Mix B  
> section.

>

> Can anyone help me get this going?

>

> Thanks,

> John Cookman

---

---

Subject: Can't Record in 442 and MEC simultaneously... HELP!!!

Posted by [John Cookman](#) on Mon, 16 Feb 2009 21:46:39 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hey guys, can anyone help me with this issue? I have a MEC with one 8in card and a 442 hooked up to two EDS-1000 cards. I am getting signals to all my inputs on both units. My MEC inputs are assigned to Submix A and my 442 are assigned to submix B. I can record on the MEC all channels but I can not get the 442 to receive a signal in the software. I see the signal coming through on the 442 hardware but it will not come through on the Mix B section.

Can anyone help me get this going?

Thanks,

John Cookman

---

---

Subject: Re: Can't Record in 442 and MEC simultaneously... HELP!!!

Posted by [Tom Bruhl](#) on Mon, 16 Feb 2009 21:55:47 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

John,

I'm not sure how the EDS 1000 plays into this. I thought it didn't allow effects and that was the only difference from a 1000X.???

I know I had this same sort of problem with three cards and 2 Mecs. The second Mec had to be connected to the first and last EDS cards for them to work properly. Doesn't seem like this is your problem with only two cards though.

I hope someone else can chime in here. I know 442s can be finicky in multi card systems. Some say that it has to be connected to the Master card. Might try that and put the Mec on card B just to see.

Good luck,  
Tom

"john cookman" <jcookman@sagu.com> wrote in message news:4999e377\$1@linux...

>

> yes. everything works as it should except i can't get Mixer B to show any  
> signal from the 442 when i enable record on the mixer.

>

> tracks play from mixer B like normal.

>

> the 442 shows up in the patchbay... and i can route the 442 to mixer B.

>

> i connected the MEC to card B and i have the same problem. i see signal  
> on the mec. i route it to Mixer B and record enable but i get no signal  
> showing in Mixer B.

>

> i connected the 442 to card A and it works as it should... meaning i can  
> record through the 442 like normal.

>

> i've also flip flopped the cards pci slots and the same thing happens. so  
> its not one of the cards.

>

> also both the mec and the 442 work with both cards when i only have 1  
> installed.

> then when i both both back in... no matter which in the master... the  
> problem

> occurs.

>

> i have and eds-1000X and a eds-1000. could this be the issue... running

> to different type cards?  
>  
> i've had this system for a long time but it hasn't been setup for a couple  
> years. i got a paris system back in the 1.0 days... very early.  
>  
> sorry for the long post... thanks for everyone's time. i'm just stuck.  
> maybe all this description will help one of you guys think of something i  
> haven't.  
>  
> thanks.  
>  
> john  
>  
>  
> "Tom Bruhl" <arpegio@comcast.net> wrote:  
>>Hi John,  
>>  
>>Is the 442 showing up in the patchbay? Routing all correct?  
>>Clock cables hooked up? Other audio plays on Card B?  
>>Hmmm?  
>>  
>>Tom  
>  
>  
>>  
>>  
>>"John Cookman" <jcookman@sagu.edu> wrote in message  
>>news:4999d0af\$1@linux...  
>>>  
>>> Hey guys, can anyone help me with this issue? I have a MEC with one 8in  
>  
>>> card  
>>> and a 442 hooked up to two EDS-1000 cards. I am getting signals to all  
> my  
>>> inputs on both units. My MEC inputs are assigned to Submix A and my 442  
>>> are assigned to submix B. I can record on the MEC all channels but I  
> can  
>>> not get the 442 to receive a signal in the software. I see the signal  
>  
>>> coming  
>>> through on the 442 hardware but it will not come through on the Mix B  
>  
>>> section.  
>>>  
>>> Can anyone help me get this going?  
>>>  
>>> Thanks,  
>>> John Cookman

>>  
>>  
>

---

Subject: Re: Can't Record in 442 and MEC simultaneously... HELP!!!

Posted by [john cookman\[1\]](#) on Mon, 16 Feb 2009 23:06:47 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

yes. everything works as it should except i can't get Mixer B to show any signal from the 442 when i enable record on the mixer.

tracks play from mixer B like normal.

the 442 shows up in the patchbay... and i can route the 442 to mixer B.

i connected the MEC to card B and i have the same problem. i see signal on the mec. i route it to Mixer B and record enable but i get no signal showing in Mixer B.

i connected the 442 to card A and it works as it should... meaning i can record through the 442 like normal.

i've also flip flopped the cards pci slots and the same thing happens. so its not one of the cards.

also both the mec and the 442 work with both cards when i only have 1 installed. then when i both both back in... no matter which in the master... the problem occurs.

i have and eds-1000X and a eds-1000. could this be the issue... running to different type cards?

i've had this system for a long time but it hasn't been setup for a couple years. i got a paris system back in the 1.0 days... very early.

sorry for the long post... thanks for everyone's time. i'm just stuck. maybe all this description will help one of you guys think of something i haven't.

thanks.

john

"Tom Bruhl" <arpeggio@comcast.net> wrote:

>Hi John,

>

>Is the 442 showing up in the patchbay? Routing all correct?

>Clock cables hooked up? Other audio plays on Card B?

>Hmmm?

>

>Tom

>

>

>"John Cookman" <jcookman@sagu.edu> wrote in message news:4999d0af\$1@linux...

>>

>> Hey guys, can anyone help me with this issue? I have a MEC with one 8in

>> card

>> and a 442 hooked up to two EDS-1000 cards. I am getting signals to all  
my

>> inputs on both units. My MEC inputs are assigned to Submix A and my 442

>> are assigned to submix B. I can record on the MEC all channels but I

can

>> not get the 442 to receive a signal in the software. I see the signal

>> coming

>> through on the 442 hardware but it will not come through on the Mix B

>> section.

>>

>> Can anyone help me get this going?

>>

>> Thanks,

>> John Cookman

>

>

---

Subject: Re: Can't Record in 442 and MEC simultaneously... HELP!!!

Posted by [john cookman\[1\]](#) on Mon, 16 Feb 2009 23:37:37 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

thanks Tom.

yeah i did that... put the 442 on card A and mec on card B. the 442 works  
fine that way... but then i can't get the mec inputs to record on card B.

it's very strange.

john

"Tom Bruhl" <arpeggio@comcast.net> wrote:

>John,

>

>I'm not sure how the EDS 1000 plays into this. I thought  
>it didn't allow effects and that was the only difference from  
>a 1000X.???

>

>I know I had this same sort of problem with three cards and 2 Mecs.  
>The second Mec had to be connected to the first and last EDS cards  
>for them to work properly. Doesn't seem like this is your problem  
>with only two cards though.

>

>I hope someone else can chime in here. I know 442s can be finicky  
>in multi card systems. Some say that it has to be connected to the Master  
>card. Might try that and put the Mec on card B just to see.

>

>Good luck,

>Tom

>

>

>"john cookman" <jcookman@sagu.com> wrote in message news:4999e377\$1@linux...

>>

>> yes. everything works as it should except i can't get Mixer B to show  
any

>> signal from the 442 when i enable record on the mixer.

>>

>> tracks play from mixer B like normal.

>>

>> the 442 shows up in the patchbay... and i can route the 442 to mixer B.

>>

>> i connected the MEC to card B and i have the same problem. i see signal  
>> on the mec. i route it to Mixer B and record enable but i get no signal  
>> showing in Mixer B.

>>

>> i connected the 442 to card A and it works as it should... meaning i can  
>> record through the 442 like normal.

>>

>> i've also flip flopped the cards pci slots and the same thing happens.

so

>> its not one of the cards.

>>

>> also both the mec and the 442 work with both cards when i only have 1

>> installed.

>> then when i both both back in... no matter which in the master... the

>> problem  
>> occurs.  
>>  
>> i have and eds-1000X and a eds-1000. could this be the issue... running  
>> to different type cards?  
>>  
>> i've had this system for a long time but it hasn't been setup for a couple  
>> years. i got a paris system back in the 1.0 days... very early.  
>>  
>> sorry for the long post... thanks for everyone's time. i'm just stuck.  
>> maybe all this description will help one of you guys think of something  
i  
>> haven't.  
>>  
>> thanks.  
>>  
>> john  
>>  
>>  
>> "Tom Bruhl" <arpeggio@comcast.net> wrote:  
>>>Hi John,  
>>>  
>>>Is the 442 showing up in the patchbay? Routing all correct?  
>>>Clock cables hooked up? Other audio plays on Card B?  
>>>Hmmm?  
>>>  
>>>Tom  
>>  
>>  
>>>  
>>>  
>>>"John Cookman" <jcookman@sagu.edu> wrote in message  
>>>news:4999d0af\$1@linux...  
>>>>  
>>>> Hey guys, can anyone help me with this issue? I have a MEC with one  
8in  
>>  
>>>> card  
>>>> and a 442 hooked up to two EDS-1000 cards. I am getting signals to  
all  
>> my  
>>>> inputs on both units. My MEC inputs are assigned to Submix A and my  
442  
>>>> are assigned to submix B. I can record on the MEC all channels but  
I  
>> can  
>>>> not get the 442 to receive a signal in the software. I see the signal

>>  
>>>> coming  
>>>> through on the 442 hardware but it will not come through on the Mix  
B  
>>  
>>>> section.  
>>>>  
>>>> Can anyone help me get this going?  
>>>>  
>>>> Thanks,  
>>>> John Cookman  
>>>  
>>>  
>>  
>  
>

---

---

Subject: Re: Can't Record in 442 and MEC simultaneously... HELP!!!  
Posted by [kerryg](#) on Tue, 17 Feb 2009 02:27:49 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

If my recollection is accurate, EDS1000 and EDS 1000x are the same card, the "x" just indicated cards that were sold with crossover cables (the ribbon connectors that connect the EDS cards inside the computer); the ones without FX daughterboards are EDS500 cards.

How are your ribbon connections between the cards, all solid? No bent or oxidized pins etc?

- K

On 2/16/09 3:06 PM, in article 4999e377\$1@linux, "john cookman" <jcookman@sagu.com> wrote:

>  
> yes. everything works as it should except i can't get Mixer B to show any  
> signal from the 442 when i enable record on the mixer.  
>  
> tracks play from mixer B like normal.  
>  
> the 442 shows up in the patchbay... and i can route the 442 to mixer B.  
>  
> i connected the MEC to card B and i have the same problem. i see signal  
> on the mec. i route it to Mixer B and record enable but i get no signal  
> showing in Mixer B.  
>  
> i connected the 442 to card A and it works as it should... meaning i can



> record through the 442 like normal.  
>  
> i've also flip flopped the cards pci slots and the same thing happens. so  
> its not one of the cards.  
>  
> also both the mec and the 442 work with both cards when i only have 1  
> installed.  
> then when i both both back in... no matter which in the master... the problem  
> occurs.  
>  
> i have and eds-1000X and a eds-1000. could this be the issue... running  
> to different type cards?  
>  
> i've had this system for a long time but it hasn't been setup for a couple  
> years. i got a paris system back in the 1.0 days... very early.  
>  
> sorry for the long post... thanks for everyone's time. i'm just stuck.  
> maybe all this description will help one of you guys think of something i  
> haven't.  
>  
> thanks.  
>  
> john  
>  
>  
> "Tom Bruhl" <arpeggio@comcast.net> wrote:  
>> Hi John,  
>>  
>> Is the 442 showing up in the patchbay? Routing all correct?  
>> Clock cables hooked up? Other audio plays on Card B?  
>> Hmmm?  
>>  
>> Tom  
>  
>  
>>  
>>  
>> "John Cookman" <jcookman@sagu.edu> wrote in message news:4999d0af\$1 @linux...  
>>>  
>>> Hey guys, can anyone help me with this issue? I have a MEC with one 8in  
>  
>>> card  
>>> and a 442 hooked up to two EDS-1000 cards. I am getting signals to all  
> my  
>>> inputs on both units. My MEC inputs are assigned to Submix A and my 442  
>>> are assigned to submix B. I can record on the MEC all channels but I  
> can  
>>> not get the 442 to receive a signal in the software. I see the signal

>  
>>> coming  
>>> through on the 442 hardware but it will not come through on the Mix B  
>  
>>> section.  
>>>  
>>> Can anyone help me get this going?  
>>>  
>>> Thanks,  
>>> John Cookman  
>>  
>>  
>

---

Subject: Re: Can't Record in 442 and MEC simultaneously... HELP!!!  
Posted by [JeffH](#) on Tue, 17 Feb 2009 03:03:48 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

john,

Are you using a word clock or did you connect the word clock connectors on the two units? Also, if you could post a screen shot of the patch bay.

Jeff

> thanks Tom.  
>  
> yeah i did that... put the 442 on card A and mec on card B. the 442 works  
> fine that way... but then i can't get the mec inputs to record on card B.  
> it's very strange.  
>  
> john  
>  
>  
>  
>  
>  
>  
>  
> "Tom Bruhl" <arpegio@comcast.net> wrote:  
>  
>>John,  
>>  
>>I'm not sure how the EDS 1000 plays into this. I thought  
>>it didn't allow effects and that was the only difference from  
>>a 1000X.???  
>>

>>I know I had this same sort of problem with three cards and 2 Mecs.  
>>The second Mec had to be connected to the first and last EDS cards  
>>for them to work properly. Doesn't seem like this is your problem  
>>with only two cards though.  
>>  
>>I hope someone else can chime in here. I know 442s can be finicky  
>>in multi card systems. Some say that it has to be connected to the Master  
>>card. Might try that and put the Mec on card B just to see.  
>>  
>>Good luck,  
>>Tom  
>>  
>>  
>>"john cookman" <jcookman@sagu.com> wrote in message news:4999e377\$1@linux...  
>>  
>>>yes. everything works as it should except i can't get Mixer B to show  
>  
> any  
>  
>>>signal from the 442 when i enable record on the mixer.  
>>>  
>>>tracks play from mixer B like normal.  
>>>  
>>>the 442 shows up in the patchbay... and i can route the 442 to mixer B.  
>>>  
>>>i connected the MEC to card B and i have the same problem. i see signal  
>>>on the mec. i route it to Mixer B and record enable but i get no signal  
>>>showing in Mixer B.  
>>>  
>>>i connected the 442 to card A and it works as it should... meaning i can  
>>>record through the 442 like normal.  
>>>  
>>>i've also flip flopped the cards pci slots and the same thing happens.  
>  
> so  
>  
>>>its not one of the cards.  
>>>  
>>>also both the mec and the 442 work with both cards when i only have 1  
>  
>  
>>>installed.  
>>>then when i both both back in... no matter which in the master... the  
>  
>  
>>>problem  
>>>occurs.  
>>>

>>>i have and eds-1000X and a eds-1000. could this be the issue... running  
>>>to different type cards?  
>>>  
>>>i've had this system for a long time but it hasn't been setup for a couple  
>>>years. i got a paris system back in the 1.0 days... very early.  
>>>  
>>>sorry for the long post... thanks for everyone's time. i'm just stuck.  
>>>maybe all this description will help one of you guys think of something  
>  
> i  
>  
>>>haven't.  
>>>  
>>>thanks.  
>>>  
>>>john  
>>>  
>>>  
>>>"Tom Bruhl" <arpegio@comcast.net> wrote:  
>>>  
>>>>Hi John,  
>>>>  
>>>>Is the 442 showing up in the patchbay? Routing all correct?  
>>>>Clock cables hooked up? Other audio plays on Card B?  
>>>>Hmmm?  
>>>>  
>>>>Tom  
>>>>  
>>>>  
>>>>>"John Cookman" <jcookman@sagu.edu> wrote in message  
>>>>>news:4999d0af\$1@linux...  
>>>>>  
>>>>>Hey guys, can anyone help me with this issue? I have a MEC with one  
>  
> 8in  
>  
>>>>>card  
>>>>>and a 442 hooked up to two EDS-1000 cards. I am getting signals to  
>  
> all  
>  
>>>my  
>>>  
>>>>>inputs on both units. My MEC inputs are assigned to Submix A and my  
>  
> 442  
>

>>>>are assigned to submix B. I can record on the MEC all channels but  
>  
> I  
>  
>>>can  
>>>  
>>>>not get the 442 to receive a signal in the software. I see the signal  
>>>  
>>>>coming  
>>>>through on the 442 hardware but it will not come through on the Mix  
>  
> B  
>  
>>>>section.  
>>>>  
>>>>Can anyone help me get this going?  
>>>>  
>>>>Thanks,  
>>>>John Cookman  
>>>>  
>>>>  
>>  
>

---

---

Subject: Re: Can't Record in 442 and MEC simultaneously... HELP!!!

Posted by [JeffH](#) on Tue, 17 Feb 2009 05:17:49 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

john

I think it is a 75 ohm cable. If the mec is connectd to card A, go from the Mec word CLock out to the 442 WC in (at least in my mind. Haven't had Paris out for a couple months)

:-)

Jeff

wrote:

> i do not have word clock connected. i don't remember which end needs to be  
> terminated.

>

> i get a screen shot of the patch bay up in a few minutes.

>

> thanks.

>

> john

>  
>  
> Jeff Hoover <jkhoover@excite.com> wrote:  
>  
>>john,  
>>  
>>Are you using a word clock or did you connect the word clock connectors  
>  
>  
>>on the two units? Also, if you could post a screen shot of the patch bay.  
>>  
>>Jeff  
>>  
>>  
>>  
>>>thanks Tom.  
>>>  
>>>yeah i did that... put the 442 on card A and mec on card B. the 442 works  
>>>fine that way... but then i can't get the mec inputs to record on card  
>  
> B.  
>  
>>> it's very strange.  
>>>  
>>>john  
>>>  
>>>  
>>>  
>>>  
>>>  
>>>  
>>>  
>>>"Tom Bruhl" <arpeggio@comcast.net> wrote:  
>>>  
>>>  
>>>>John,  
>>>>  
>>>>I'm not sure how the EDS 1000 plays into this. I thought  
>>>>it didn't allow effects and that was the only difference from  
>>>>a 1000X.???  
>>>>  
>>>>I know I had this same sort of problem with three cards and 2 Mecs.  
>>>>The second Mec had to be connected to the first and last EDS cards  
>>>>for them to work properly. Doesn't seem like this is your problem  
>>>>with only two cards though.  
>>>>  
>>>>I hope someone else can chime in here. I know 442s can be finicky  
>>>>in multi card systems. Some say that it has to be connected to the Master  
>>>>card. Might try that and put the Mec on card B just to see.

>>>>  
>>>>Good luck,  
>>>>Tom  
>>>>  
>>>>  
>>>>"john cookman" <jcookman@sagu.com> wrote in message news:4999e377\$1@linux...  
>>>>  
>>>>  
>>>>>yes. everything works as it should except i can't get Mixer B to show  
>>>  
>>>any  
>>>  
>>>  
>>>>>signal from the 442 when i enable record on the mixer.  
>>>>>  
>>>>>tracks play from mixer B like normal.  
>>>>>  
>>>>>the 442 shows up in the patchbay... and i can route the 442 to mixer  
>  
> B.  
>  
>>>>>i connected the MEC to card B and i have the same problem. i see signal  
>>>>>on the mec. i route it to Mixer B and record enable but i get no signal  
>>>>>showing in Mixer B.  
>>>>>  
>>>>>i connected the 442 to card A and it works as it should... meaning i  
>  
> can  
>  
>>>>>record through the 442 like normal.  
>>>>>  
>>>>>i've also flip flopped the cards pci slots and the same thing happens.  
>>>  
>>> so  
>>>  
>>>  
>>>>>its not one of the cards.  
>>>>>  
>>>>>also both the mec and the 442 work with both cards when i only have 1  
>>>  
>>>  
>>>>>installed.  
>>>>>then when i both both back in... no matter which in the master... the  
>>>  
>>>  
>>>>>problem  
>>>>>occurs.  
>>>>>

>>>>i have and eds-1000X and a eds-1000. could this be the issue... running  
>>>>to different type cards?  
>>>>  
>>>>i've had this system for a long time but it hasn't been setup for a couple  
>>>>years. i got a paris system back in the 1.0 days... very early.  
>>>>  
>>>>sorry for the long post... thanks for everyone's time. i'm just stuck.  
>>>>maybe all this description will help one of you guys think of something  
>>>  
>>>i  
>>>  
>>>  
>>>>haven't.  
>>>>  
>>>>thanks.  
>>>>  
>>>>john  
>>>>  
>>>>  
>>>>"Tom Bruhl" <arpeggio@comcast.net> wrote:  
>>>>  
>>>>  
>>>>>Hi John,  
>>>>>  
>>>>>Is the 442 showing up in the patchbay? Routing all correct?  
>>>>>Clock cables hooked up? Other audio plays on Card B?  
>>>>>Hmmm?  
>>>>>  
>>>>>Tom  
>>>>>  
>>>>>  
>>>>>"John Cookman" <jcookman@sagu.edu> wrote in message  
>>>>>news:4999d0af\$1@linux...  
>>>>>  
>>>>>  
>>>>>>Hey guys, can anyone help me with this issue? I have a MEC with one  
>>>  
>>>8in  
>>>  
>>>  
>>>>>>card  
>>>>>>and a 442 hooked up to two EDS-1000 cards. I am getting signals to  
>>>  
>>>all  
>>>  
>>>  
>>>>>my  
>>>>>



>>>>  
>>>>>>inputs on both units. My MEC inputs are assigned to Submix A and my  
>>>  
>>>442  
>>>  
>>>  
>>>>>>are assigned to submix B. I can record on the MEC all channels but  
>>>  
>>>I  
>>>  
>>>  
>>>>>can  
>>>>>  
>>>>>  
>>>>>>not get the 442 to receive a signal in the software. I see the signal  
>>>>>  
>>>>>>coming  
>>>>>>through on the 442 hardware but it will not come through on the Mix  
>>>  
>>>B  
>>>  
>>>  
>>>>>>section.  
>>>>>>  
>>>>>>Can anyone help me get this going?  
>>>>>>  
>>>>>>Thanks,  
>>>>>>John Cookman  
>>>>>>  
>>>>>>  
>

---

Subject: Re: Can't Record in 442 and MEC simultaneously... HELP!!!

Posted by [john\[5\]](#) on Tue, 17 Feb 2009 05:23:17 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

i do not have word clock connected. i don't remember which end needs to be terminated.

i get a screen shot of the patch bay up in a few minutes.

thanks.

john

Jeff Hoover <[jkhoover@excite.com](mailto:jkhoover@excite.com)> wrote:

>john,  
>  
>Are you using a word clock or did you connect the word clock connectors  
  
>on the two units? Also, if you could post a screen shot of the patch bay.  
>  
>Jeff  
>  
>  
>> thanks Tom.  
>>  
>> yeah i did that... put the 442 on card A and mec on card B. the 442 works  
>> fine that way... but then i can't get the mec inputs to record on card  
B.  
>> it's very strange.  
>>  
>> john  
>>  
>>  
>>  
>>  
>>  
>>  
>> "Tom Bruhl" <arpeggio@comcast.net> wrote:  
>>  
>>>John,  
>>>  
>>>I'm not sure how the EDS 1000 plays into this. I thought  
>>>it didn't allow effects and that was the only difference from  
>>>a 1000X.???  
>>>  
>>>I know I had this same sort of problem with three cards and 2 Mecs.  
>>>The second Mec had to be connected to the first and last EDS cards  
>>>for them to work properly. Doesn't seem like this is your problem  
>>>with only two cards though.  
>>>  
>>>I hope someone else can chime in here. I know 442s can be finicky  
>>>in multi card systems. Some say that it has to be connected to the Master  
>>>card. Might try that and put the Mec on card B just to see.  
>>>  
>>>Good luck,  
>>>Tom  
>>>  
>>>  
>>>"john cookman" <jcookman@sagu.com> wrote in message news:4999e377\$1@linux...  
>>>  
>>>>yes. everything works as it should except i can't get Mixer B to show  
>>

>> any  
>>  
>>>>signal from the 442 when i enable record on the mixer.  
>>>>  
>>>>tracks play from mixer B like normal.  
>>>>  
>>>>the 442 shows up in the patchbay... and i can route the 442 to mixer  
B.  
>>>>  
>>>>i connected the MEC to card B and i have the same problem. i see signal  
>>>>on the mec. i route it to Mixer B and record enable but i get no signal  
>>>>showing in Mixer B.  
>>>>  
>>>>i connected the 442 to card A and it works as it should... meaning i  
can  
>>>>record through the 442 like normal.  
>>>>  
>>>>i've also flip flopped the cards pci slots and the same thing happens.  
>>  
>> so  
>>  
>>>>its not one of the cards.  
>>>>  
>>>>also both the mec and the 442 work with both cards when i only have 1  
>>  
>>  
>>>>installed.  
>>>>then when i both both back in... no matter which in the master... the  
>>  
>>  
>>>>problem  
>>>>occurs.  
>>>>  
>>>>i have and eds-1000X and a eds-1000. could this be the issue... running  
>>>>to different type cards?  
>>>>  
>>>>i've had this system for a long time but it hasn't been setup for a couple  
>>>>years. i got a paris system back in the 1.0 days... very early.  
>>>>  
>>>>sorry for the long post... thanks for everyone's time. i'm just stuck.  
>>>>maybe all this description will help one of you guys think of something  
>>  
>> i  
>>  
>>>>haven't.  
>>>>  
>>>>thanks.  
>>>>

>>>>john  
>>>>  
>>>>  
>>>>"Tom Bruhl" <arpegio@comcast.net> wrote:  
>>>>  
>>>>>Hi John,  
>>>>>  
>>>>>Is the 442 showing up in the patchbay? Routing all correct?  
>>>>>Clock cables hooked up? Other audio plays on Card B?  
>>>>>Hmmm?  
>>>>>  
>>>>>Tom  
>>>>>  
>>>>>  
>>>>>  
>>>>>"John Cookman" <jcookman@sagu.edu> wrote in message  
>>>>>news:4999d0af\$1@linux...  
>>>>>  
>>>>>>Hey guys, can anyone help me with this issue? I have a MEC with one  
>>  
>> 8in  
>>  
>>>>>>card  
>>>>>>>and a 442 hooked up to two EDS-1000 cards. I am getting signals to  
>>  
>> all  
>>  
>>>>my  
>>>>>  
>>>>>>inputs on both units. My MEC inputs are assigned to Submix A and my  
>>  
>> 442  
>>  
>>>>>>>are assigned to submix B. I can record on the MEC all channels but  
>>  
>> I  
>>  
>>>>can  
>>>>>  
>>>>>>>not get the 442 to receive a signal in the software. I see the signal  
>>>>>  
>>>>>>>coming  
>>>>>>>through on the 442 hardware but it will not come through on the Mix  
>>  
>> B  
>>  
>>>>>>>section.  
>>>>>>>

>>>>>Can anyone help me get this going?  
>>>>>  
>>>>>Thanks,  
>>>>>John Cookman  
>>>>>  
>>>>>  
>>>  
>>

---

---

Subject: Re: Can't Record in 442 and MEC simultaneously... HELP!!!  
Posted by [Aaron Allen](#) on Tue, 17 Feb 2009 05:52:58 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

This is going to be the problem. Gotta have that word clock bro. Go from word clock out of whatever you have on card A (MEC, 442) into the word clock in of whatever you have on card B (MEC, 442).  
AA

"john" <[john@john.com](mailto:john@john.com)> wrote in message [news:499a3bb5\\$1@linux...](mailto:news:499a3bb5$1@linux...)  
>  
> i do not have word clock connected. i don't remember which end needs to  
> be  
> terminated.  
>  
> i get a screen shot of the patch bay up in a few minutes.  
>  
> thanks.  
>  
> john  
>  
>  
> Jeff Hoover <[jkhoover@excite.com](mailto:jkhoover@excite.com)> wrote:  
>>john,  
>>  
>>Are you using a word clock or did you connect the word clock connectors  
>  
>>on the two units? Also, if you could post a screen shot of the patch  
>>bay.  
>>  
>>Jeff  
>>  
>>  
>>> thanks Tom.  
>>>  
>>> yeah i did that... put the 442 on card A and mec on card B. the 442  
>>> works

>>> fine that way... but then i can't get the mec inputs to record on card  
> B.  
>>> it's very strange.  
>>>  
>>> john  
>>>  
>>>  
>>>  
>>>  
>>>  
>>>  
>>> "Tom Bruhl" <arpeggio@comcast.net> wrote:  
>>>  
>>>>John,  
>>>>  
>>>>I'm not sure how the EDS 1000 plays into this. I thought  
>>>>it didn't allow effects and that was the only difference from  
>>>>a 1000X.???  
>>>>  
>>>>I know I had this same sort of problem with three cards and 2 Mecs.  
>>>>The second Mec had to be connected to the first and last EDS cards  
>>>>for them to work properly. Doesn't seem like this is your problem  
>>>>with only two cards though.  
>>>>  
>>>>I hope someone else can chime in here. I know 442s can be finicky  
>>>>in multi card systems. Some say that it has to be connected to the  
>>>>Master  
>>>>card. Might try that and put the Mec on card B just to see.  
>>>>  
>>>>Good luck,  
>>>>Tom  
>>>>  
>>>>  
>>>>"john cookman" <jcookman@sagu.com> wrote in message  
>>>>news:4999e377\$1@linux...  
>>>>  
>>>>>yes. everything works as it should except i can't get Mixer B to show  
>>>>  
>>>> any  
>>>>  
>>>>>signal from the 442 when i enable record on the mixer.  
>>>>>  
>>>>>tracks play from mixer B like normal.  
>>>>>  
>>>>>the 442 shows up in the patchbay... and i can route the 442 to mixer  
> B.  
>>>>>  
>>>>>i connected the MEC to card B and i have the same problem. i see

>>>>signal  
>>>>on the mec. i route it to Mixer B and record enable but i get no  
>>>>signal  
>>>>showing in Mixer B.  
>>>>  
>>>>i connected the 442 to card A and it works as it should... meaning i  
> can  
>>>>record through the 442 like normal.  
>>>>  
>>>>i've also flip flopped the cards pci slots and the same thing happens.  
>>>  
>>> so  
>>>  
>>>>its not one of the cards.  
>>>>  
>>>>also both the mec and the 442 work with both cards when i only have 1  
>>>  
>>>  
>>>>installed.  
>>>>then when i both both back in... no matter which in the master... the  
>>>  
>>>  
>>>>problem  
>>>>occurs.  
>>>>  
>>>>i have and eds-1000X and a eds-1000. could this be the issue...  
>>>>running  
>>>>to different type cards?  
>>>>  
>>>>i've had this system for a long time but it hasn't been setup for a  
>>>>couple  
>>>>years. i got a paris system back in the 1.0 days... very early.  
>>>>  
>>>>sorry for the long post... thanks for everyone's time. i'm just stuck.  
>>>>maybe all this description will help one of you guys think of something  
>>>  
>>> i  
>>>  
>>>>haven't.  
>>>>  
>>>>thanks.  
>>>>  
>>>>john  
>>>>  
>>>>  
>>>>"Tom Bruhl" <arpeggio@comcast.net> wrote:  
>>>>  
>>>>>Hi John,

>>>>>  
>>>>>Is the 442 showing up in the patchbay? Routing all correct?  
>>>>>Clock cables hooked up? Other audio plays on Card B?  
>>>>>Hmmm?  
>>>>>  
>>>>>Tom  
>>>>>  
>>>>>  
>>>>>  
>>>>>"John Cookman" <jcookman@sagu.edu> wrote in message  
>>>>>news:4999d0af\$1@linux...  
>>>>>  
>>>>>>Hey guys, can anyone help me with this issue? I have a MEC with one  
>>>  
>>> 8in  
>>>  
>>>>>>card  
>>>>>>and a 442 hooked up to two EDS-1000 cards. I am getting signals to  
>>>  
>>> all  
>>>  
>>>>>my  
>>>>>  
>>>>>>inputs on both units. My MEC inputs are assigned to Submix A and my  
>>>  
>>> 442  
>>>  
>>>>>>are assigned to submix B. I can record on the MEC all channels but  
>>>  
>>> I  
>>>  
>>>>>can  
>>>>>  
>>>>>>not get the 442 to receive a signal in the software. I see the  
>>>>>>signal  
>>>>>  
>>>>>>coming  
>>>>>>through on the 442 hardware but it will not come through on the Mix  
>>>  
>>> B  
>>>  
>>>>>>section.  
>>>>>>  
>>>>>>>Can anyone help me get this going?  
>>>>>>>  
>>>>>>>Thanks,  
>>>>>>>John Cookman  
>>>>>>>



>>>>>  
>>>>  
>>>  
>

---

Subject: Re: Can't Record in 442 and MEC simultaneously... HELP!!!  
Posted by [EK Sound](#) on Tue, 17 Feb 2009 22:09:28 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

It should work fine without termination, but if you want to, you can put a 75 Ohm terminator at the output of the last device.

David.

john cookman wrote:

> that was it! word clock did it... i just need to make sure i don't need a  
> termination somewhere.

>  
> thanks guys!

>  
>  
>  
>  
> "john cookman" <[john@john.com](mailto:john@john.com)> wrote:

>> ok i will try this. doesn't something have to be terminated?

>>  
>> thanks aaron.

>>  
>> "Aaron Allen" <[know-spam@not\\_here.dude](mailto:know-spam@not_here.dude)> wrote:  
>>> This is going to be the problem. Gotta have that word clock bro. Go from  
>>> word clock out of whatever you have on card A (MEC, 442) into the word  
> clock  
>>> in of whatever you have on card B (MEC, 442).

>>> AA

>>>

>>>

>>> "john" <[john@john.com](mailto:john@john.com)> wrote in message [news:499a3bb5\\$1@linux...](news:499a3bb5$1@linux...)

>>>> i do not have word clock connected. i don't remember which end needs  
>> to

>>>> be

>>>> terminated.

>>>>

>>>> i get a screen shot of the patch bay up in a few minutes.

>>>>

>>>> thanks.

>>>>

>>>> john

>>>>  
>>>>  
>>>> Jeff Hoover <jkhoover@excite.com> wrote:  
>>>>> john,  
>>>>>  
>>>>> Are you using a word clock or did you connect the word clock connectors  
>>>>> on the two units? Also, if you could post a screen shot of the patch  
>>>>> bay.  
>>>>>  
>>>>> Jeff  
>>>>>  
>>>>>  
>>>>>> thanks Tom.  
>>>>>>  
>>>>>> yeah i did that... put the 442 on card A and mec on card B. the 442  
>>>>>> works  
>>>>>> fine that way... but then i can't get the mec inputs to record on card  
>>>>> B.  
>>>>>> it's very strange.  
>>>>>>  
>>>>>> john  
>>>>>>  
>>>>>>  
>>>>>>  
>>>>>>  
>>>>>>  
>>>>>>  
>>>>>> "Tom Bruhl" <arpeggio@comcast.net> wrote:  
>>>>>>  
>>>>>>> John,  
>>>>>>>  
>>>>>>> I'm not sure how the EDS 1000 plays into this. I thought  
>>>>>>> it didn't allow effects and that was the only difference from  
>>>>>>> a 1000X.???  
>>>>>>>  
>>>>>>> I know I had this same sort of problem with three cards and 2 Mecs.  
>>>>>>> The second Mec had to be connected to the first and last EDS cards  
>>>>>>> for them to work properly. Doesn't seem like this is your problem  
>>>>>>> with only two cards though.  
>>>>>>>  
>>>>>>> I hope someone else can chime in here. I know 442s can be finicky  
>>>>>>> in multi card systems. Some say that it has to be connected to the  
>>>>>>> Master  
>>>>>>> card. Might try that and put the Mec on card B just to see.  
>>>>>>>  
>>>>>>> Good luck,  
>>>>>>> Tom  
>>>>>>>

>>>>>>  
>>>>>> "john cookman" <jcookman@sagu.com> wrote in message  
>>>>>> news:4999e377\$1@linux...  
>>>>>>  
>>>>>>> yes. everything works as it should except i can't get Mixer B to  
> show  
>>>>>> any  
>>>>>>  
>>>>>>> signal from the 442 when i enable record on the mixer.  
>>>>>>>  
>>>>>>> tracks play from mixer B like normal.  
>>>>>>>  
>>>>>>> the 442 shows up in the patchbay... and i can route the 442 to mixer  
>>>> B.  
>>>>>>> i connected the MEC to card B and i have the same problem. i see  
>  
>>>>>>> signal  
>>>>>>> on the mec. i route it to Mixer B and record enable but i get no  
>  
>>>>>>> signal  
>>>>>>> showing in Mixer B.  
>>>>>>>  
>>>>>>> i connected the 442 to card A and it works as it should... meaning  
>> i  
>>>> can  
>>>>>>> record through the 442 like normal.  
>>>>>>>  
>>>>>>> i've also flip flopped the cards pci slots and the same thing happens.  
>>>>>> so  
>>>>>>  
>>>>>>> its not one of the cards.  
>>>>>>>  
>>>>>>>> also both the mec and the 442 work with both cards when i only have  
>> 1  
>>>>>>  
>>>>>>>> installed.  
>>>>>>>> then when i both both back in... no matter which in the master...  
> the  
>>>>>>>  
>>>>>>>> problem  
>>>>>>>> occurs.  
>>>>>>>>  
>>>>>>>> i have and eds-1000X and a eds-1000. could this be the issue...  
>>>>>>>> running  
>>>>>>>> to different type cards?  
>>>>>>>>  
>>>>>>>>> i've had this system for a long time but it hasn't been setup for  
> a

>>>>>>> couple  
>>>>>>> years. i got a paris system back in the 1.0 days... very early.  
>>>>>>>  
>>>>>>> sorry for the long post... thanks for everyone's time. i'm just stuck.  
>>>>>>> maybe all this description will help one of you guys think of something  
>>>>>>> i  
>>>>>>>  
>>>>>>> haven't.  
>>>>>>>  
>>>>>>> thanks.  
>>>>>>>  
>>>>>>> john  
>>>>>>>  
>>>>>>>  
>>>>>>> "Tom Bruhl" <arpeggio@comcast.net> wrote:  
>>>>>>>  
>>>>>>>> Hi John,  
>>>>>>>>  
>>>>>>>>> Is the 442 showing up in the patchbay? Routing all correct?  
>>>>>>>>> Clock cables hooked up? Other audio plays on Card B?  
>>>>>>>>> Hmmm?  
>>>>>>>>>  
>>>>>>>>> Tom  
>>>>>>>>>  
>>>>>>>>> "John Cookman" <jcookman@sagu.edu> wrote in message  
>>>>>>>>> news:4999d0af\$1@linux...  
>>>>>>>>>  
>>>>>>>>>> Hey guys, can anyone help me with this issue? I have a MEC with  
>> one  
>>>>>> 8in  
>>>>>>>  
>>>>>>>>>> card  
>>>>>>>>>>> and a 442 hooked up to two EDS-1000 cards. I am getting signals  
>> to  
>>>>>>> all  
>>>>>>>>  
>>>>>>>>>> my  
>>>>>>>>>>>  
>>>>>>>>>>>>> inputs on both units. My MEC inputs are assigned to Submix A and  
>> my  
>>>>>>> 442  
>>>>>>>>>  
>>>>>>>>>>>>> are assigned to submix B. I can record on the MEC all channels  
> but  
>>>>>>>> I  
>>>>>>>>>  
>>>>>>>>>>>>> can  
>>>>>>>>>>>>>>>

>>>>>>>>> not get the 442 to receive a signal in the software. I see the  
>  
>>>>>>>>> signal  
>>>>>>>>> coming  
>>>>>>>>> through on the 442 hardware but it will not come through on the  
> Mix  
>>>>>> B  
>>>>>>>  
>>>>>>>>> section.  
>>>>>>>>>  
>>>>>>>>> Can anyone help me get this going?  
>>>>>>>>>  
>>>>>>>>> Thanks,  
>>>>>>>>> John Cookman  
>>>>>>>>>  
>>>  
>

---

Subject: Re: Can't Record in 442 and MEC simultaneously... HELP!!!  
Posted by [john\[5\]](#) on Tue, 17 Feb 2009 22:20:44 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

ok i will try this. doesn't something have to be terminated?

thanks aaron.

"Aaron Allen" <know-spam@not\_here.dude> wrote:

>This is going to be the problem. Gotta have that word clock bro. Go from

>word clock out of whatever you have on card A (MEC, 442) into the word clock

>in of whatever you have on card B (MEC, 442).

>AA

>

>

>"john" <john@john.com> wrote in message news:499a3bb5\$1@linux...

>>

>> i do not have word clock connected. i don't remember which end needs  
to

>> be

>> terminated.

>>

>> i get a screen shot of the patch bay up in a few minutes.

>>

>> thanks.

>>

>> john

>>  
>>  
>> Jeff Hoover <jkhoover@excite.com> wrote:  
>>> john,  
>>>  
>>> Are you using a word clock or did you connect the word clock connectors  
>>  
>>> on the two units? Also, if you could post a screen shot of the patch  
  
>>> bay.  
>>>  
>>> Jeff  
>>>  
>>>  
>>>> thanks Tom.  
>>>>  
>>>> yeah i did that... put the 442 on card A and mec on card B. the 442  
  
>>>> works  
>>>> fine that way... but then i can't get the mec inputs to record on card  
>> B.  
>>>> it's very strange.  
>>>>  
>>>> john  
>>>>  
>>>>  
>>>>  
>>>>  
>>>>  
>>>>  
>>>> "Tom Bruhl" <arpeggio@comcast.net> wrote:  
>>>>  
>>>>> John,  
>>>>>  
>>>>> I'm not sure how the EDS 1000 plays into this. I thought  
>>>>> it didn't allow effects and that was the only difference from  
>>>>> a 1000X.???  
>>>>>  
>>>>> I know I had this same sort of problem with three cards and 2 Mecs.  
>>>>> The second Mec had to be connected to the first and last EDS cards  
>>>>> for them to work properly. Doesn't seem like this is your problem  
>>>>> with only two cards though.  
>>>>>  
>>>>> I hope someone else can chime in here. I know 442s can be finicky  
>>>>> in multi card systems. Some say that it has to be connected to the  
  
>>>>> Master  
>>>>> card. Might try that and put the Mec on card B just to see.

>>>>  
>>>>Good luck,  
>>>>Tom  
>>>>  
>>>>  
>>>>"john cookman" <jcookman@sagu.com> wrote in message  
>>>>news:4999e377\$1@linux...  
>>>>  
>>>>>yes. everything works as it should except i can't get Mixer B to show  
>>>>  
>>>> any  
>>>>  
>>>>>signal from the 442 when i enable record on the mixer.  
>>>>>  
>>>>>tracks play from mixer B like normal.  
>>>>>  
>>>>>the 442 shows up in the patchbay... and i can route the 442 to mixer  
>> B.  
>>>>>  
>>>>>i connected the MEC to card B and i have the same problem. i see  
>>>>>signal  
>>>>>on the mec. i route it to Mixer B and record enable but i get no  
>>>>>signal  
>>>>>showing in Mixer B.  
>>>>>  
>>>>>i connected the 442 to card A and it works as it should... meaning  
>> i  
>> can  
>>>>>record through the 442 like normal.  
>>>>>  
>>>>>i've also flip flopped the cards pci slots and the same thing happens.  
>>>>  
>>>> so  
>>>>  
>>>>>its not one of the cards.  
>>>>>  
>>>>>also both the mec and the 442 work with both cards when i only have  
>> 1  
>>>>  
>>>>  
>>>>>installed.  
>>>>>then when i both both back in... no matter which in the master... the  
>>>>  
>>>>  
>>>>>problem  
>>>>>occurs.  
>>>>>  
>>>>>i have and eds-1000X and a eds-1000. could this be the issue...

>>>>>running  
>>>>>to different type cards?  
>>>>>  
>>>>>i've had this system for a long time but it hasn't been setup for a  
  
>>>>>couple  
>>>>>years. i got a paris system back in the 1.0 days... very early.  
>>>>>  
>>>>>sorry for the long post... thanks for everyone's time. i'm just stuck.  
>>>>>maybe all this description will help one of you guys think of something  
>>>>  
>>>> i  
>>>>  
>>>>>haven't.  
>>>>>  
>>>>>thanks.  
>>>>>  
>>>>>john  
>>>>>  
>>>>>  
>>>>>"Tom Bruhl" <arpeggio@comcast.net> wrote:  
>>>>>  
>>>>>>Hi John,  
>>>>>>  
>>>>>>>Is the 442 showing up in the patchbay? Routing all correct?  
>>>>>>>Clock cables hooked up? Other audio plays on Card B?  
>>>>>>>Hmmm?  
>>>>>>>  
>>>>>>>Tom  
>>>>>>>  
>>>>>>>  
>>>>>>>  
>>>>>>>"John Cookman" <jcookman@sagu.edu> wrote in message  
>>>>>>>news:4999d0af\$1@linux...  
>>>>>>>  
>>>>>>>>Hey guys, can anyone help me with this issue? I have a MEC with  
one  
>>>>  
>>>> 8in  
>>>>  
>>>>>>>card  
>>>>>>>>and a 442 hooked up to two EDS-1000 cards. I am getting signals  
to  
>>>>  
>>>> all  
>>>>  
>>>>>>>my  
>>>>>>>



>>>>>>>inputs on both units. My MEC inputs are assigned to Submix A and  
my  
>>>>  
>>>> 442  
>>>>  
>>>>>>>are assigned to submix B. I can record on the MEC all channels but  
>>>>  
>>>> I  
>>>>  
>>>>>>>can  
>>>>>>>  
>>>>>>>not get the 442 to receive a signal in the software. I see the  
>>>>>>>signal  
>>>>>>>  
>>>>>>>coming  
>>>>>>>through on the 442 hardware but it will not come through on the Mix  
>>>>  
>>>> B  
>>>>  
>>>>>>>section.  
>>>>>>>  
>>>>>>>Can anyone help me get this going?  
>>>>>>>  
>>>>>>>Thanks,  
>>>>>>>John Cookman  
>>>>>>>  
>>>>>>>  
>>>>>  
>>>>  
>>>>  
>>  
>  
>

---

Subject: Re: Can't Record in 442 and MEC simultaneously... HELP!!!  
Posted by [john cookman\[2\]](#) on Tue, 17 Feb 2009 22:40:31 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

that was it! word clock did it... i just need to make sure i don't need a  
termination somewhere.

thanks guys!

"john cookman" <[john@john.com](mailto:john@john.com)> wrote:  
>

>ok i will try this. doesn't something have to be terminated?  
>  
>thanks aaron.  
>  
>"Aaron Allen" <know-spam@not\_here.dude> wrote:  
>>This is going to be the problem. Gotta have that word clock bro. Go from  
>  
>>word clock out of whatever you have on card A (MEC, 442) into the word  
clock  
>  
>>in of whatever you have on card B (MEC, 442).  
>>AA  
>>  
>>  
>>"john" <john@john.com> wrote in message news:499a3bb5\$1@linux...  
>>>  
>>> i do not have word clock connected. i don't remember which end needs  
>to  
>>> be  
>>> terminated.  
>>>  
>>> i get a screen shot of the patch bay up in a few minutes.  
>>>  
>>> thanks.  
>>>  
>>> john  
>>>  
>>>  
>>> Jeff Hoover <jkhoover@excite.com> wrote:  
>>>>john,  
>>>>  
>>>>Are you using a word clock or did you connect the word clock connectors  
>>>>  
>>>>on the two units? Also, if you could post a screen shot of the patch  
>  
>>>>bay.  
>>>>  
>>>>Jeff  
>>>>  
>>>>  
>>>>> thanks Tom.  
>>>>>  
>>>>> yeah i did that... put the 442 on card A and mec on card B. the 442  
>  
>>>>> works  
>>>>> fine that way... but then i can't get the mec inputs to record on card  
>>>> B.  
>>>>> it's very strange.

>>>>  
>>>> john  
>>>>  
>>>>  
>>>>  
>>>>  
>>>>  
>>>>  
>>>>  
>>>> "Tom Bruhl" <arpeggio@comcast.net> wrote:  
>>>>  
>>>>>John,  
>>>>>  
>>>>>I'm not sure how the EDS 1000 plays into this. I thought  
>>>>>it didn't allow effects and that was the only difference from  
>>>>>a 1000X.???  
>>>>>  
>>>>>I know I had this same sort of problem with three cards and 2 Mecs.  
>>>>>The second Mec had to be connected to the first and last EDS cards  
>>>>>for them to work properly. Doesn't seem like this is your problem  
>>>>>with only two cards though.  
>>>>>  
>>>>>I hope someone else can chime in here. I know 442s can be finicky  
>>>>>in multi card systems. Some say that it has to be connected to the  
>  
>>>>>Master  
>>>>>card. Might try that and put the Mec on card B just to see.  
>>>>>  
>>>>>Good luck,  
>>>>>Tom  
>>>>>  
>>>>>  
>>>>>"john cookman" <jcookman@sagu.com> wrote in message  
>>>>>news:4999e377\$1@linux...  
>>>>>  
>>>>>>yes. everything works as it should except i can't get Mixer B to  
show  
>>>>>  
>>>>> any  
>>>>>  
>>>>>>signal from the 442 when i enable record on the mixer.  
>>>>>>  
>>>>>>tracks play from mixer B like normal.  
>>>>>>  
>>>>>>the 442 shows up in the patchbay... and i can route the 442 to mixer  
>>> B.  
>>>>>>  
>>>>>>>i connected the MEC to card B and i have the same problem. i see

>>>>>>signal  
>>>>>>on the mec. i route it to Mixer B and record enable but i get no

>>>>>>signal  
>>>>>>showing in Mixer B.  
>>>>>>  
>>>>>>i connected the 442 to card A and it works as it should... meaning  
>i  
>>> can  
>>>>>>record through the 442 like normal.  
>>>>>>  
>>>>>>i've also flip flopped the cards pci slots and the same thing happens.  
>>>>>>  
>>>>> so  
>>>>>>  
>>>>>>its not one of the cards.  
>>>>>>  
>>>>>>also both the mec and the 442 work with both cards when i only have  
>1  
>>>>>>  
>>>>>>  
>>>>>>installed.  
>>>>>>then when i both both back in... no matter which in the master...  
the  
>>>>>>  
>>>>>>  
>>>>>>problem  
>>>>>>occurs.  
>>>>>>  
>>>>>>i have and eds-1000X and a eds-1000. could this be the issue...  
>>>>>>running  
>>>>>>to different type cards?  
>>>>>>  
>>>>>>i've had this system for a long time but it hasn't been setup for  
a  
>  
>>>>>>couple  
>>>>>>years. i got a paris system back in the 1.0 days... very early.  
>>>>>>  
>>>>>>sorry for the long post... thanks for everyone's time. i'm just stuck.  
>>>>>>maybe all this description will help one of you guys think of something  
>>>>>>  
>>>>> i  
>>>>>>  
>>>>>>haven't.  
>>>>>>  
>>>>>>thanks.  
>>>>>>

>>>>>>john  
>>>>>>  
>>>>>>  
>>>>>>"Tom Bruhl" <arpeggio@comcast.net> wrote:  
>>>>>>  
>>>>>>>Hi John,  
>>>>>>>  
>>>>>>>>Is the 442 showing up in the patchbay? Routing all correct?  
>>>>>>>>Clock cables hooked up? Other audio plays on Card B?  
>>>>>>>>Hmmm?  
>>>>>>>>  
>>>>>>>>Tom  
>>>>>>>>  
>>>>>>>>  
>>>>>>>>"John Cookman" <jcookman@sagu.edu> wrote in message  
>>>>>>>>news:4999d0af\$1@linux...  
>>>>>>>>  
>>>>>>>>>Hey guys, can anyone help me with this issue? I have a MEC with  
>one  
>>>>>  
>>>>> 8in  
>>>>>  
>>>>>>>>card  
>>>>>>>>>and a 442 hooked up to two EDS-1000 cards. I am getting signals  
>to  
>>>>>  
>>>>> all  
>>>>>  
>>>>>>>>my  
>>>>>>>>  
>>>>>>>>>inputs on both units. My MEC inputs are assigned to Submix A and  
>my  
>>>>>  
>>>>> 442  
>>>>>  
>>>>>>>>>are assigned to submix B. I can record on the MEC all channels  
>but  
>>>>>  
>>>>> I  
>>>>>  
>>>>>>>>can  
>>>>>>>>  
>>>>>>>>>not get the 442 to receive a signal in the software. I see the  
  
>>>>>>>>>signal  
>>>>>>>>>  
>>>>>>>>>>coming



>>"Aaron Allen" <know-spam@not\_here.dude> wrote:  
>>>This is going to be the problem. Gotta have that word clock bro. Go from  
>>  
>>>word clock out of whatever you have on card A (MEC, 442) into the word  
> clock  
>>  
>>>in of whatever you have on card B (MEC, 442).  
>>>AA  
>>>  
>>>  
>>>"john" <john@john.com> wrote in message news:499a3bb5\$1@linux...  
>>>>  
>>>> i do not have word clock connected. i don't remember which end needs  
>>>to  
>>>> be  
>>>> terminated.  
>>>>  
>>>> i get a screen shot of the patch bay up in a few minutes.  
>>>>  
>>>> thanks.  
>>>>  
>>>> john  
>>>>  
>>>>  
>>>> Jeff Hoover <jkhoover@excite.com> wrote:  
>>>>>john,  
>>>>>  
>>>>>Are you using a word clock or did you connect the word clock connectors  
>>>>>  
>>>>>on the two units? Also, if you could post a screen shot of the patch  
>>  
>>>>>bay.  
>>>>>  
>>>>>Jeff  
>>>>>  
>>>>>  
>>>>>> thanks Tom.  
>>>>>>  
>>>>>> yeah i did that... put the 442 on card A and mec on card B. the 442  
>>  
>>>>>> works  
>>>>>> fine that way... but then i can't get the mec inputs to record on  
>>>>>> card  
>>>> B.  
>>>>>> it's very strange.  
>>>>>>  
>>>>>> john  
>>>>>>>

>>>>>  
>>>>>  
>>>>>  
>>>>>  
>>>>>  
>>>>> "Tom Bruhl" <arpegio@comcast.net> wrote:  
>>>>>  
>>>>>>John,  
>>>>>>  
>>>>>>I'm not sure how the EDS 1000 plays into this. I thought  
>>>>>>it didn't allow effects and that was the only difference from  
>>>>>>a 1000X.???  
>>>>>>  
>>>>>>I know I had this same sort of problem with three cards and 2 Mecs.  
>>>>>>The second Mec had to be connected to the first and last EDS cards  
>>>>>>for them to work properly. Doesn't seem like this is your problem  
>>>>>>with only two cards though.  
>>>>>>  
>>>>>>I hope someone else can chime in here. I know 442s can be finicky  
>>>>>>in multi card systems. Some say that it has to be connected to the  
>>  
>>>>>>Master  
>>>>>>card. Might try that and put the Mec on card B just to see.  
>>>>>>  
>>>>>>Good luck,  
>>>>>>Tom  
>>>>>>  
>>>>>>  
>>>>>>"john cookman" <jcookman@sagu.com> wrote in message  
>>>>>>news:4999e377\$1@linux...  
>>>>>>  
>>>>>>>yes. everything works as it should except i can't get Mixer B to  
> show  
>>>>>>  
>>>>>>> any  
>>>>>>>  
>>>>>>>signal from the 442 when i enable record on the mixer.  
>>>>>>>  
>>>>>>>tracks play from mixer B like normal.  
>>>>>>>  
>>>>>>>the 442 shows up in the patchbay... and i can route the 442 to mixer  
>>>> B.  
>>>>>>>  
>>>>>>>i connected the MEC to card B and i have the same problem. i see  
>  
>>>>>>>signal  
>>>>>>>on the mec. i route it to Mixer B and record enable but i get no  
>



>>>>>>>signal  
>>>>>>>showing in Mixer B.  
>>>>>>>  
>>>>>>>i connected the 442 to card A and it works as it should... meaning  
>>i  
>>>> can  
>>>>>>>record through the 442 like normal.  
>>>>>>>  
>>>>>>>i've also flip flopped the cards pci slots and the same thing  
>>>>>>>happens.  
>>>>>>>  
>>>>>>> so  
>>>>>>>  
>>>>>>>its not one of the cards.  
>>>>>>>  
>>>>>>>also both the mec and the 442 work with both cards when i only have  
>>1  
>>>>>>>  
>>>>>>>  
>>>>>>>installed.  
>>>>>>>>then when i both both back in... no matter which in the master...  
> the  
>>>>>>>  
>>>>>>>  
>>>>>>>problem  
>>>>>>>occurs.  
>>>>>>>  
>>>>>>>i have and eds-1000X and a eds-1000. could this be the issue...  
>>>>>>>running  
>>>>>>>to different type cards?  
>>>>>>>  
>>>>>>>i've had this system for a long time but it hasn't been setup for  
> a  
>>  
>>>>>>>couple  
>>>>>>>years. i got a paris system back in the 1.0 days... very early.  
>>>>>>>  
>>>>>>>sorry for the long post... thanks for everyone's time. i'm just  
>>>>>>>stuck.  
>>>>>>>maybe all this description will help one of you guys think of  
>>>>>>>something  
>>>>>>>  
>>>>>>> i  
>>>>>>>  
>>>>>>>haven't.  
>>>>>>>  
>>>>>>>thanks.  
>>>>>>>



