Subject: ADAT sync with RME interface Posted by n0samples on Fri, 31 Jul 2015 14:28:03 GMT View Forum Message <> Reply to Message

For some reason my patchbay does not recognize the ADAT card. Paris is set to 48 khz and the connecting device (rme babyface) as well but the sync button does not light up.

Sometimes the second light in the ADAT blinks, other times it stays dark.

Is it common for the MEC to not see the ADAT on the patchbay? What am I missing?

Subject: Re: ADAT sync with RME interface Posted by danielcornelius on Fri, 31 Jul 2015 14:54:35 GMT View Forum Message <> Reply to Message

Do you have switched a "MEC Modules-\*" into Patchbay workspace and klick on it ? Because that wass reason at me why i don't see an Input card.