

---

Subject: more info

Posted by [Sharon](#) on Sat, 23 Jun 2007 19:22:08 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

also, it seems to be just the EDS compressor on insert that isn't working -  
gates, delay, nolimit, etc work on the inserts

the compressor doesn't work though (?)

Thanks!

---