
Subject: OK, I must be doing something wrong
Posted by [pbraun](#) on Tue, 22 Dec 2009 03:26:41 GMT
[View Forum Message](#) <> [Reply to Message](#)

I finally got around to actually playing with the new XP system, and I seem to have a few glitches.

2 EDS cards
2 MEC's with no cards
2 C16's (blackface).

When I fire up a project, for some reason both C16's tie to Card A.

Also, I can't get the track record arm button to work now - I can hold it down and hit any channel and nothing happens. I have to arm them on the screen with the mouse.

Right now, I have a single-card project set up as I'm transferring a cassette to CD for someone. Maybe I need to set up a Mixer B and assign to MEC B before the second C16 will un-mirror the first one? I may try that when I'm done.

Help?
