Subject: Phase Inversion

Posted by Ted Gerber on Mon, 09 Jun 2014 16:47:54 GMT

View Forum Message <> Reply to Message

Hi Folks -

This must be old news that I - for some reason - have not heard, but when testing some routing options through external gear from Paris, I found some phase issues. This led to a check of inverting the same signal on two adjacent channels with all parameters identical. The signal does not come close to cancelling, either when running to outside processing, (thot it might be a problem with cabling or the external box) or within Paris. The same tracks do cancel in other DAWs.

is this a known issue? Anyone with more experience than me in this?

Thanks

ted

Subject: Re: Phase Inversion

Posted by Ted Gerber on Mon, 09 Jun 2014 23:38:25 GMT

View Forum Message <> Reply to Message

solved -

thot I'd checked everything, but i hadn't !!!!

EQ Trim was different on the left track. the EQ module was hidden, which must offer a good explanation for my befuddled state : }

thanks for reading