Subject: Re: ASIO DRIVER current status ? Posted by mikeaudet on Tue, 20 Feb 2018 15:54:39 GMT View Forum Message <> Reply to Message

So...I've been working on a few things...one of which is laying the groundwork for a new scherzo to support a 64 bit ASIO, but I took a bit of a detour and decided to see if I could clean up a couple of things in the 32 bit ASIO...and....

I got 32 sample buffer sizes working!!!

File Attachments

Audio/MIDI Setup					×
	Latency Measu	irement Tool			
	Turn down the volu audio equipment to				
Sele	ect two channels below and	connect them using a cable.			
Output channel	system:playback_4				
Input channel	system:capture_4				
Once	the channels are connecte	d, click the "Measure" button.			
When	satisfied with the results.	click the "Use results" button.			
	ted roundtrip latency nic latency: -96 samp	: 183 samples (4.150 ms les (-2.177 ms))		
Measure	Use results	Back to settings (igno	ore results	;)	