Subject: ADAT Error

Posted by danielcornelius on Sun, 12 Aug 2012 14:25:10 GMT

View Forum Message <> Reply to Message

Hi there.

i did recieved 2 adat cards now. One for each of my both mecs.

I would like to connect one of the adat card to a universal audio preamp twin finity 4-710d. The Pre amp has got a digitial toslink output, but no sync socket. Is this the reason to get error message:

"Error setting enable for ADAT tracks. Error code 33/21"

Subject: Re: ADAT Error

Posted by kerryg on Sun, 12 Aug 2012 21:45:52 GMT

View Forum Message <> Reply to Message

A few things: what is your digital clock master? PARIS or the 710? Make sure your settings and cabling are appropriate. Also, don't use PARIS' ADAT control window - just treat it the same as if it were eight analog inputs to the mixer.

Subject: Re: ADAT Error

Posted by danielcornelius on Sun, 19 Aug 2012 19:15:18 GMT

View Forum Message <> Reply to Message

Sorry for late replay, but i was on journey(Holiday)!

So the Paris is Master, Sync by Wordclock, because i have got 2 Mecs.

The 710 configs the same like Paris (48KHz 24bit). I used the Adat Window and at least Mikes driver don't work. So i use a beta Version 3.0 then it runs.

I used Mikes Driver and the mistake 1/1 appeared, when the Adat Cards are installed in the Mecs.

Did you got a hint to use Mikes Driver again?